

ASS. REC. BY:

REF: CS/CT118017898/Gvd3ed

Special Instruction:

Surveyor: Guo Qianqian

ASSIGNMENT (Office)

Meimien

From (Person): Catherine Chiaof CTIDate/Time: 3/10/18 @ 1:24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 2879G

Insured:

GBC 9612K

at Workshop no/s

Cheng Hwe Motor

Tel:

6481 2001

of

Blk 1019 # 01-374 / 382 Yishun Ind. Park A

Policy No:

DMCV SN 3022751801

Claim No:

SNM18D044161C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/09/2018hsp: Cheng Hwe (AMK)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 2:10pm @ 3/10/18

Person Contacted:

DanlynVehicle IN/OUT

Date/Time

Action/Instruction (-) Estimate

SJM 2879G - XGBC 9612K - X.27/11/18LS \$1850 confirmed by email (Ref 812.65, 31/1)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s **cheng Hae Motor**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **\$9000**
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **5** days Res: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SJMR8796** Yr Regn: **26 Dec 2008**
 Type: **M/Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Vios** C.C. **1497**
 Colour: **Silver** A/C: Insured / Std / NI / NA
 Sp. Reading: **128696** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR053HY9305093110**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **195/55R15**
 R: **11**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FALKEN**
 Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **03-10-18**
 Survey held at **w/s** **3pm**
 Des. of Damages: **Frt** / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
\$2050

RECEIVED 27 NOV 2018.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) **27/11- typist**

Report Format : **merimen**

Lump Sum / I.B.I: (\$ **1850/2**)

Days Of Repair: **5**

Resurvey No. of Trip: **—**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee
 Transportation
 S - RS \$
 Photos
 Other

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Exp Auth'd	Status
Main	02 Oct 2018 Sendback Est	02 Oct 2018 14:50 S\$2,662.65	03 Oct 2018 13:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MB BAMBOO PRODUCT INDUSTRIES, Co. Reg. No.: 53206913K		
Main Claimant:	TEO KOK ENG, ID: S0067485J		
Vehicle Reg. No.:	SJM2879G	Date of Loss:	13/09/2018 20:00 - :59 [116 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04461C02	Policy/Cover Note No.:	DMCVSN3022751801
Vehicle Reg. No. (Insured):	GBC9612K	Policy No. (Claimant):	5094333860
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Adj Asg. Remarks:	EST \$2849.04, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7485J
Vehicle Details	
Vehicle No.:	SJM2879G
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZX839698
Chassis No.:	MR053HY9305093110
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,900.00
Original Registration Date:	26 Dec 2008
First Registration Date:	26 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$11,900.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2018
PARF Rebate Amount:	\$5,950.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,200.00
COE Rebate Amount:	\$141.00
Total Rebate Amount:	\$6,091.00

The information contained herein is correct as at 02 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/09/2018 14:48
Date Of Accident	13/09/2018 20:05
Exact Location Of Accident	TPE TOWARDS PASIR RIS DRIVE 12
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM2879G
Insured/Policyholder	
Name Of Registered Owner	TEO KOK ENG
NRIC No	S0067485J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96807779
Alternative Phone No	OTHERS-96807779
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094333860
Cover Note Number	18/09/2017 - 25/12/2018
Driver	
Name of Driver	TEO KOK ENG
NRIC No	S0067485J
Date Of Birth	13/05/1951
Occupation	OUTDOOR
Date Of Driving Pass	15/09/1971
Driving Experience	46 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96807779
Fax Number	
Contact Number	OTHERS-96807779
Email Address	NOEMAIL

Address	BLK 148 SIMEI ST 1 #05-131
Postcode	520148
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOP AT THE SLIP ROAD TO LOOK OUT FOR VEHICLES ON THE RIGHT. TRAFFIC WAS CLEAR ON THE RIGHT AND BEFORE I COULD MOVE OFF, MOTOR VAN GBC9612K CAME FROM BEHIND AND HIT ONTO MY VEHICLE REAR PORTION. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC9612K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	97471616
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

VEHICLE NO.:

INSURER

DATE & TIME:

SJM 28796

NTUC

13/09/2018 @ 2005

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A: SJM 28796
 (alone)

B: GGC 9612K
 Hp: 97471616
 Chinese male (alone)

Vehicle No: SJM 28796 (NTUC)
Date & Time: 13/09/2018 @ 2005 (clear/dry)

I stop at the slip road to look out for vehicles on the right. Traffic was clear on the right and before i could move off, motor van 6BC 9612K came from behind and hit onto my vehicle rear portion. No one was injured.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: IAWK
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

Claim Reference:
Assessment Number: CSJM2879
Version: CHENGHOE/1
Date Calculated: 02/10/2018 05:47

Full Report - V1
Registration: SJM2879G
Printed: 02/10/2018 14:28

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	13/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:	TP/CHINA	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	E
Model Sheet Number:	YF3 02
Registration:	SJM2879G
Registration Month:	December
Registration Year:	2008
VIN Number:	MR053HY9305093110
Odometer:	Not Known
Colour:	Other
Engine Number:	
Fuel Level:	%

Model Specs

FROM 10/2008	AIR CONDITIONING
ELECTRIC SIDE WINDOW	ELEC RR DOOR LOCKING
MIRROR W/NDICATOR	FRONT DOOR TWEETER
FOG LAMPS	REAR ARMREST
1.5 LTR 80 KW	4-SPEED AUTOMATIC
PASSENGER AIRBAG	ABS
TYRES 185/60 HR 15	WHEELS 5.5J X 14
REAR DISC BRAKES	REAR SPOILER
EQUIPMENT "E" GRADE	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	02/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJM2879
Version: CHENGHOE/1
Date Calculated: 02/10/2018 05:47

Full Report - V1
Registration: SJM2879G
Printed: 02/10/2018 14:28



Addresses

Repairer

Name : CHENG HOE MOTOR PTE LTD
Address :
NO 10, AMK IND PK 2A
01-04
Post Code : 568047

Cost Summary

Total Labour	\$1,192.80
Total Paint/Material	\$200.85
Total Parts	\$1,009.00
Total of Additional Costs	\$260.00
Excess:	TBA
Grand Total Exc GST:	\$2,662.65
7 % GST:	\$186.39
Grand Total Inc GST:	\$2,849.04

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
B420)	R + R REAR BUMPER REINFORCEMENT	1.0	4.20
B290	RENEW REAR END PANEL (BUMPER REMOVED)	35.0	147.00
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		
NO NUMBER	REMOVE AND REFIT BOOTLID TRIM	2.0	8.40
750171	RENEW BADGE "TOYOTA"	2.0	8.40
750171	RENEW BADGE	2.0	8.40
B360	REMOVE BOOT LID SPOILER	7.0	29.40
B410	R + R REAR BUMPER	4.0	16.80
B420)	RENEW REAR BUMPER	1.0	4.20
NO NUMBER	R + R R/R BUMPER REFLECTOR	3.0	12.60
743061)	R + R REAR PARCEL SHELF TRIM	3.0	12.60
3481	REPAIR L/R SIDE PANEL	20.0*	84.00
3482	REPAIR R/R SIDE PANEL	40.0*	168.00
3901	REPAIR REAR FLOOR PANEL	30.0*	126.00
3990	REPAIR R/R SIDE MEMBER CPL	25.0*	105.00

LABOUR COST

Total Work Units	175.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJM2879

Version: CHENGHOE/1

Date Calculated: 02/10/2018 05:47

Full Report - V1

Registration: SJM2879G

Printed: 02/10/2018 14:28

Sub Total	17.5HRS	\$735.00
Paint Labour	10.9HRS	\$457.80
Total Labour	28.4HRS	\$1,192.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2711	REAR PANEL NEW PART PAINTING	21.0	
2581	REAR BUMPER NEW PART PAINT K1R	10.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	12.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	12.0	
2931	BOOTLID SURFACE PAINT	8.0	
2979	BOOTLID TRIM SURFACE PAINT PLAST.	3.0	
3045	REAR SPOILER SURFACE PAINT PLAST.	6.0	
3901	REAR FLOOR PANEL SURFACE PAINT	7.0	
LABOUR COST - PAINT			
	TIME(PAINT)	79.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	109.0	
	Total Paintwork Labour	10.9HRS	\$457.80
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting		\$25.85
	New Part Painting - Plastic K1R		\$48.22
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$37.85
	Surface Paint Plastic		\$19.03
	Repair Painting		\$32.30
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$200.85
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$200.85

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
2581	1	REAR BUMPER / <i>re</i>	52159 0D983		170.00*
2620	1	R/R BUMPER BRACKET / <i>me</i>	52575 0D070		32.00*
2622	1	R/R OUT BUMPER BRKT / <i>me</i>	52155 0D030		18.00*
2711	1	REAR PANEL / <i>me</i>	58307 0D101		210.00*
2944	1	BOOTLID SEAL / <i>TV</i>	64461 0D050		60.00*
3013	1	REAR MANUFACT BADGE / <i>me</i>	90975 02063		22.00*
3014	1	VERSION BADGE / <i>me</i>	75444 0D090		45.00*
3016	1	BADGE / <i>me</i>	75432 0D010		18.00*
3017	1	MODEL STICKER / <i>me</i>	75442 0D070		22.00*
3282	1	R/R LAMP ASSY / <i>me</i>	81550 0D220		95.00*
3292	1	R/R REFLECTOR / <i>me</i>	81910 0D010		35.00*
4982	1	RIGHT LUGGAGE BIN / <i>me</i>	64995 0D040		85.00*
4985	1	END PANEL TRIM / <i>me</i>	58387 0D010		80.00*
1000	1	RR LAMP SEAL / <i>me</i>	Renew		17.00*

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJM2879
Version: CHENGHOE/1
Date Calculated: 02/10/2018 05:47

Full Report - V1
Registration: SJM2879G
Printed: 02/10/2018 14:28

f: OEM Parts	Sub Total	\$909.00
g: Original	Sundry Parts (Fixed)	\$100.00
h: Secondhand	Total Parts	\$1,009.00
p: Parallel		
x: Exchange		

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSORS SPECIALIST / <i>QW</i>	0%	\$200.00
Corr Prot Materials External / <i>MC</i>		\$60.00
Total Extras		\$260.00

Final Calculation

Total Parts	\$1,009.00
Labour	
Total Panel/Mechanical	\$735.00 <i>441</i>
Total Paintwork	\$457.80 <i>407.40</i>
Total Labour	\$1,192.80
Additional Costs	
Corr Prot Materials External	\$60.00
Cost of Specialist	\$200.00
Total of Additional Costs	\$260.00
Total Paint/Material Costs	\$200.85 <i>184.70</i>
Grand Total Excludes GST	\$2,662.65
GST @ 7 %	\$186.39
Grand Total Includes GST	\$2,849.04

Assessment Notes

lump sum repair.
After repair photos.
5 Days.
Guo Qiang - 82880282
Guo Qiang @ lkkauto.com
03/10/18.

2557.65
20% 2050

[Signature]
5/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: CSJM2879
Version: CHENGHOE/2
Date Calculated: 22/10/2018 06:57

Full Report - V1
Registration: SJM2879G
Printed: 22/10/2018 13:57

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	13/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	6 day(s)
Policy Number:	TP/CHINA	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle	Model Specs
Manufacturer: TOYOTA	FROM 10/2008
Model: Vios	ELECTRIC SIDE WINDOW
Sub Model: E	MIRROR W/INDICATOR
Model Sheet Number: YF3 02	FOG LAMPS
Registration: SJM2879G	1.5 LTR 80 KW
Registration Month: December	PASSENGER AIRBAG
Registration Year: 2008	TYRES 185/60 HR 15
VIN Number: MR053HY9305093110	REAR DISC BRAKES
Odometer: Not Known	EQUIPMENT "E" GRADE
Colour: Other	TWO COAT PEARL/MICA
Engine Number:	AIR CONDITIONING
Fuel Level: %	ELEC RR DOOR LOCKING
	FRONT DOOR TWEETER
	REAR ARMREST
	4-SPEED AUTOMATIC
	ABS
	WHEELS 5.5J X 14
	REAR SPOILER
	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 02/10/2018
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

Claim Reference:

Full Report - V1



Assessment Number: CSJM2879

Registration: SJM2879G

Version: CHENGHOE/2

Printed: 22/10/2018 13:57

Date Calculated: 22/10/2018 06:57



Addresses

Repairer

Name : CHENG HOE MOTOR PTE LTD

Address :

NO 10, AMK IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$848.40
Total Paint/Material	\$184.70
Total Parts	\$1,009.00
Total of Additional Costs	\$260.00
Excess:	TBA
Grand Total Exc GST:	\$2,302.10
7 % GST:	\$161.15
Grand Total Inc GST:	\$2,463.25

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR

Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B420)	R + R REAR BUMPER REINFORCEMENT	1.0	4.20
B290	RENEW REAR END PANEL (BUMPER REMOVED)	35.0	147.00
	INCLUDES: BOTH REAR LAMPS, FLOOR MAT BOOT COMPARTMENT AND ALL TRIMS IN REPAIR AREA REMOVE AND REFIT		
NO NUMBER	REMOVE AND REFIT BOOTLID TRIM	2.0	8.40
750171	RENEW BADGE "TOYOTA"	2.0	8.40
750171	RENEW BADGE	2.0	8.40
B360	REMOVE BOOT LID SPOILER	7.0	29.40
B410	R + R REAR BUMPER	4.0	16.80
B420)	RENEW REAR BUMPER	1.0	4.20
NO NUMBER	R + R R/R BUMPER REFLECTOR	3.0	12.60
743061)	R + R REAR PARCEL SHELF TRIM	3.0	12.60
3482	REPAIR R/R SIDE PANEL	30.0*	126.00
3901	REPAIR REAR FLOOR PANEL	15.0*	63.00

LABOUR COST

Total Work Units	105.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	10.5HRS	\$441.00
Paint Labour	9.7HRS	\$407.40

Claim Reference:

Full Report - V1

Assessment Number: CSJM2879

Registration: SJM2879G

Version: CHENGHOE/2

Printed: 22/10/2018 13:57

Date Calculated: 22/10/2018 06:57

Total Labour

20.2HRS

\$848.40

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2711	REAR PANEL NEW PART PAINTING	21.0	
2581	REAR BUMPER NEW PART PAINT K1R	10.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	12.0	
2931	BOOTLID SURFACE PAINT	8.0	
2979	BOOTLID TRIM SURFACE PAINT PLAST.	3.0	
3045	REAR SPOILER SURFACE PAINT PLAST.	6.0	
3901	REAR FLOOR PANEL SURFACE PAINT	7.0	
LABOUR COST - PAINT			
TIME(PAINT)		67.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		97.0	
Total Paintwork Labour		9.7HRS	\$407.40
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$25.85
New Part Painting - Plastic K1R			\$48.22
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$37.85
Surface Paint Plastic			\$19.03
Repair Painting			\$16.15
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$184.70
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$184.70

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3016	1	BADGE	75432 0D010		0%	18.00*
2944	1	BOOTLID SEAL	64461 0D050		0%	60.00*
4985	1	END PANEL TRIM	58387 0D010		0%	80.00*
3017	1	MODEL STICKER	75442 0D070		0%	22.00*
2620	1	R/R BUMPER BRACKET	52575 0D070		0%	32.00*
3282	1	R/R LAMP ASSY	81550 0D220		0%	95.00*
2622	1	R/R OUT BUMPER BRKT	52155 0D030		0%	18.00*
3292	1	R/R REFLECTOR	81910 0D010		0%	35.00*
2581	1	REAR BUMPER	52159 0D983		0%	170.00*
3013	1	REAR MANUFACT BADGE	90975 02063		0%	22.00*
2711	1	REAR PANEL	58307 0D101		0%	210.00*
4982	1	RIGHT LUGGAGE BIN	64995 0D040		0%	85.00*
1000	1	RR LAMP SEAL	Renew		0%	17.00*
3014	1	VERSION BADGE	75444 0D090		0%	45.00*
f: OEM Parts		Sub Total				\$909.00
g: Original		Sundry Parts		(Fixed)		\$100.00
h: Secondhand		Total Parts				\$1,009.00

Claim Reference:

Full Report - V1

Assessment Number: CSJM2879

Registration: SJM2879G

Version: CHENGHOE/2

Printed: 22/10/2018 13:57

Date Calculated: 22/10/2018 06:57

p: Parallel
x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSORS SPECIALIST	0%	\$200.00
Corr Prot Materials External		\$60.00
Total Extras		\$260.00

Final Calculation

Total Parts		\$1,009.00
Labour		
Total Panel/Mechanical	\$441.00	
Total Paintwork	\$407.40	
Total Labour		\$848.40
Additional Costs		
Corr Prot Materials External	\$60.00	
Cost of Specialist	\$200.00	
Total of Additional Costs		\$260.00
Total Paint/Material Costs		\$184.70
Grand Total Excludes GST		\$2,302.10
GST @ 7 %		\$161.15
Grand Total Includes GST		\$2,463.25

Assessment Notes

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 27 November 2018 2:39 PM
To: 'Efeeda (Cheng Hoe -Yishun)'
Cc: SUR
Subject: RE: SJM 2879G-DOA: 13/9/2018

Dear Efeeda,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, 27 November 2018 1:11 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SJM 2879G-DOA: 13/9/2018

Hi Veron,

Confirmed as below.

Thank u.

Rgds
Efeeda
Cheng Hoe Motor PL

From: Veron Chen (LKKAUTO)
Sent: Monday, October 22, 2018 2:08 PM
To: chmotor@singnet.com.sg
Cc: SUR
Subject: SJM 2879G-DOA: 13/9/2018

Dear Efeeda,

WITHOUT PREJUDICE

Offer Lump Sum \$1850/- @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

•
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018 Sendback Est	02 Oct 2018 14:50 \$2,662.65	03 Oct 2018 13:24 Edit Adj Rpt	\$1,850.00 Edit Estimates	\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: MB BAMBOO PRODUCT INDUSTRIES , Co. Reg. No.: 53206913K									
Main Claimant: TEO KOK ENG , ID: S00674851									
Vehicle Reg. No.: SJM2879G		Date of Loss: 13/09/2018 20:00 - :59 [116 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04461C02		Policy/Cover Note No.: DMCVSN3022751801							
Vehicle Reg. No. (Insured): GBC9612K		Policy No. (Claimant): 5094333860							
		Excess: \$0.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Bk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/10/2018]									
Adj Asg. Remarks: EST \$2849.04, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJM2879G (SNM18D04461C02)
[GBC9612K]
TP
TEO KOK ENG
Sep 13 2018 8:00PM
[MB BAMBOO PRODUCT INDUSTRIES]
Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	14/09/18 16:18	Accident Statement	 Load HTM		
2	02/10/18 14:14	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>	
3	02/10/18 14:15	Accident Statement Addm. #1	 Load HTM		
4	02/10/18 14:50	Repairer Estimates	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	14/09/18 16:15	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	14/09/18 16:15	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	14/09/18 16:15	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	14/09/18 16:15	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	14/09/18 16:15	SCENE PHOTO [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	14/09/18 16:15	SCENE PHOTO [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	14/09/18 16:14	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	14/09/18 16:14	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	03/10/18 13:21	OI GIA	 Load PDF		

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	14/09/18 16:18	Accident Statement	 Load HTM		
2	02/10/18 14:14	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>	
3	02/10/18 14:15	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	14/09/18 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	14/09/18 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	14/09/18 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	14/09/18 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	14/09/18 16:15	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
6	14/09/18 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	14/09/18 16:15	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
8	14/09/18 16:15	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	14/09/18 16:14	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	14/09/18 16:14	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18017898/GVD3E2

Date: 28/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3022751801
Claimant Vehicle No:	SJM2879G	Insured Vehicle No:	GBC9612K
Date of Loss:	13/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04461C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2879G		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX839698
Reg. Date:	26/12/2008 (Man. Year: 2008)	Chassis No:	MR053HY9305093110
Colour:	Silver	Odometer:	128696 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	909.00	909.00	0.00	0.00
Miscellaneous Items	300.00	300.00	0.00	0.00
Labour	1,453.65	1,093.10	360.55	24.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,662.65	2,302.10	360.55	13.54
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	2,662.65	1,850.00	812.65	30.52
+ GST 7.00/7.00% (S\$)	186.39	129.50	56.89	30.52
Nett Amount (S\$)	2,849.04	1,979.50	869.54	30.52

INSPECTION

Date of Assignment:	03/10/2018 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	03/10/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial Park A
		Singapore 768761
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2018)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM2879G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE	Necessary	18.00 F	*18.00 F
2	1	NA	*BOOTLID SEAL	Torn	60.00 F	*60.00 F
3	1	NA	*END PANEL TRIM	Deformed	80.00 F	*80.00 F
4	1	NA	*MODEL STICKER	Necessary	22.00 F	*22.00 F
5	1	NA	*R/R BUMPER BRACKET	Necessary	32.00 F	*32.00 F
6	1	NA	*R/R LAMP ASSY	Scratched	95.00 F	*95.00 F
7	1	NA	*R/R OUT BUMPER BRKT	Necessary	18.00 F	*18.00 F
8	1	NA	*R/R REFLECTOR	Scratched	35.00 F	*35.00 F
9	1	NA	*REAR BUMPER	Deformed	170.00 F	*170.00 F
10	1	NA	*REAR MANUFACT BADGE	Necessary	22.00 F	*22.00 F
11	1	NA	*REAR PANEL	Buckled	210.00 F	*210.00 F
12	1	NA	*RIGHT LUGGAGE BIN	Cut	85.00 F	*85.00 F
13	1	NA	*RR LAMP SEAL	Necessary	17.00 F	*17.00 F
14	1	NA	*VERSION BADGE	Necessary	45.00 F	*45.00 F
Total Parts (S\$)					909.00	909.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	SPECIALIST REVERSE SENSORS (DAMAGED)	200.00	200.00
2	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			300.00	300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	457.80	407.40
2	Total Paint Materials	New	260.85	244.70
3	Total Panel/Mechanical Labour	New	735.00	441.00
Gross Labour Cost (S\$)			1,453.65	1,093.10

Report was unsubmitted during this print-out.

< END OF ESTIMATES >