

15/9/2010

INS. CASE OWNER:

CC 3 ASM. AXA1801

LKK:  
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

TP GIA REPORT: YES / NO

Final? Yes / No

SKP 517B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans  
Cab.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

7/10/18  
TH

SKP 517B - 40/11/19/2019/5/Eubs DVT 14/11/19

SKP 9821H -

\* Grant claim.

- TRANS-CAB VS TRANS-CAB

OI rear-ended to TP. Send letter to OI.

24/10/18

12/11/19

- UPLDAD 14 IN OC.

28/08/19

- FOR BULK SETTLEMENT

- PER E TO. ATTEND.

09/08/19

- ORIGINAL TP LOD IN

- UPLDAD UPLDAD 14 IN OC

- AXA APPROVED UPLDAD 14 ON 28/01/19

- SEND 1st OFFER TO TP.

15/08/19

- TP ACCEPTED OFFER. ALL DONE IN ORDER.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

VIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

3,100.00

(4 days)

Reduction:

92 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

SS

100.

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

3,100.00

Loss of Rental (LOR):

SS

397.28

(4 days)

x 99.32

Loss of Use (LOU):

SS

(S-50 x 4 days)

- TP 01

Loss of Income (LOI):

SS

(S x 4 days)

-

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,714.28

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

3,714.28

Name 1:

-

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

Email

Call

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3,750.00

COPY SENT  
16/11/19

TRANS-CAB AUTO SERVICES PTE LTD





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                            |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|--|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                              | Ref : CC3/ASM18017904/Gub3 |                                                                                     |  |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811                                                                                      |                                                                              | Date : 03-10-2018          |  |  |
|                                                                                                                                        |                                                                              | Code : ASM                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                            |                                                                                     |  |
| Insured Veh.                                                                                                                           | SHB 9821H                                                                    | Veh. Inspected             | SHF 577B                                                                            |  |
| Policy No.                                                                                                                             |                                                                              | Coverage (\$)              | 0.00                                                                                |  |
| Claim No.                                                                                                                              |                                                                              | Excess (\$)                | 0.00                                                                                |  |
| Assign From                                                                                                                            |                                                                              | Assign Date                | 03/10/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                            |                                                                                     |  |
| Make & Model                                                                                                                           |                                                                              | c.c                        | 0                                                                                   |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.               |                                                                                     |  |
| Chassis No.                                                                                                                            |                                                                              | Colour                     |                                                                                     |  |
| Odometer                                                                                                                               | -                                                                            | Steering                   |                                                                                     |  |
| Brakes                                                                                                                                 |                                                                              | Modification               |                                                                                     |  |
| General                                                                                                                                |                                                                              |                            |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                            |                                                                                     |  |
|                                                                                                                                        | Size                                                                         | Make                       | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         |                                                                              |                            | mm                                                                                  |  |
| L/H Front Tyre                                                                                                                         |                                                                              |                            | mm                                                                                  |  |
| R/H Rear Tyre                                                                                                                          |                                                                              |                            | mm                                                                                  |  |
| L/H Rear Tyre                                                                                                                          |                                                                              |                            | mm                                                                                  |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                            |                                                                                     |  |
|                                                                                                                                        |                                                                              |                            |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                            |                                                                                     |  |
| Accident Date                                                                                                                          | 30/09/2018                                                                   | Inspection Date            | 02/10/2018                                                                          |  |
| Survey held at                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                            |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                            |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                            |                                                                                     |  |

**Trans-cab Auto Services Pte Ltd****AAD1810-026**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHF 577B**

VF1ABL15AUC278416

RENAULT

LATITUDE

30.9.2018

**AXA**

| PART |                                               | LIST |            |
|------|-----------------------------------------------|------|------------|
| 1    | 1 BUMPER COVER REAR / <i>CH</i>               | \$   | 1,108.46 / |
| 2    | 1 BUMPER LOWER REAR / <i>CH</i>               | \$   | 768.84 /   |
| 3    | 1 BUMPER BRACKET CTR REAR X                   | \$   | 113.47     |
| 4    | 1 BUMPER BRACKET SIDE RH REAR X               | \$   | 135.97     |
| 5    | 1 BUMPER RETAINER RH REAR X                   | \$   | 44.99      |
| 6    | 1 BUMPER REFLECTOR RH X                       | \$   | 43.61      |
| 7    | 1 BUMPER BRACKET SIDE LH REAR X               | \$   | 135.97     |
| 8    | 1 BUMPER RETAINER LH REAR / <i>rec</i>        | \$   | 44.99 /    |
| 9    | 1 BUMPER REFLECTOR LH / <i>scr</i>            | \$   | 43.61 /    |
| 10   | 1 BUMPER BEAM REAR ? / <i>BT</i>              | \$   | 777.52 /   |
| 11   | 1 BUMPER BEAM BRACKET LH REAR X               | \$   | 225.95     |
| 12   | 1 BUMPER BEAM BRACKET RH REAR X               | \$   | 225.95     |
| 13   | 1 OUTER PANEL REAR (End Panel) X <i>repar</i> | \$   | 1,471.77   |
| 14   | 1 OUTER PANEL REAR (End Panel) TRIM X         | \$   | 404.56     |
| 15   | 1 TAILLAMP RH X                               | \$   | 552.55     |
| 16   | 1 TAILLAMP PANEL RH X                         | \$   | 986.70     |
| 17   | 1 TAILLAMP LH X                               | \$   | 552.55     |
| 18   | 1 TAILLAMP PANEL LH X                         | \$   | 986.70     |
| 19   | 1 BOOT REAR X                                 | \$   | 2,872.68   |
| 20   | 1 BOOT FINISHER X                             | \$   | 470.06     |
| 21   | 1 BOOT WHEATERSTRIP X <i>TN</i>               | \$   | 323.05 /   |
| 22   | 1 BOOT REFLECTOR LAMP LH X                    | \$   | 493.35     |
| 23   | 1 BOOT REFLECTOR LAMP RH X                    | \$   | 493.35     |
| 24   | 1 BOOT BADGE 'RENAULT' X                      | \$   | 225.36     |
| 25   | 1 BOOT BADGE X                                | \$   | 225.36     |
| 26   | 1 BOOT STRUT LH X                             | \$   | 276.08     |
| 27   | 1 BOOT STRUT RH X                             | \$   | 276.08     |
| 28   | 1 BOOT HINGE LH X                             | \$   | 367.84     |
| 29   | 1 BOOT HINGE RH X                             | \$   | 367.84     |

**Trans-cab Auto Services Pte Ltd****AAD1810-026**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

|    |                   |   |    |        |
|----|-------------------|---|----|--------|
| 30 | 1 BOOT INNER TRIM | X | \$ | 586.45 |
| 31 | 1 BOOT SWITCH     | X | \$ | 168.13 |
| 32 | 1 BOOT LOCK       | X | \$ | 202.67 |
| 33 | 1 BOOT LOCK CATCH | X | \$ | 74.40  |

} NN

|     |    |                         |
|-----|----|-------------------------|
|     | \$ | 16,046.87 <sup>86</sup> |
| 10% | \$ | 7.44                    |
|     | \$ | 16,039.43               |

14442.17

**Special Nett**

|    |                                     |    |    |        |     |
|----|-------------------------------------|----|----|--------|-----|
| 1  | 1SET PARKING AID                    | DM | \$ | 700.00 | 200 |
| 2  | 1SET REAR BUMPER CLIP               | MC | \$ | 66.00  | -   |
| 3  | 1SET BUMPER BRACKET CTR CLIP        | X  | \$ | 33.00  |     |
| 4  | 1SET BUMPER BRACKET SIDE CLIP RH RR | X  | \$ | 10.00  |     |
| 5  | 1SET BUMPR RETAINER RH CLIP RR      | X  | \$ | 20.00  |     |
| 6  | 1SET BUMPR BRACKET SIDE CLIP LH RR  | X  | \$ | 10.00  |     |
| 7  | 1SET BUMPR RETAINER CLIP LH RR      | X  | \$ | 20.00  |     |
| 8  | 1SET BUMPER LOWER REAR RIVET        | X  | \$ | 22.00  |     |
| 9  | 1SET BUMPER LOWER REAR CLIP         | X  | \$ | 66.00  |     |
| 10 | 1 EXHAUST MOUNTING REAR             | X  | \$ | 17.82  |     |
| 11 | 2 REAR WINDSCREEN SELANT            | X  | \$ | 80.00  |     |
| 12 | 1 WINDSCREEN MOULDING               | X  | \$ | 100.00 |     |
| 13 | 1 REAR WINDSCREEN INNER SPONGE SEAL | X  | \$ | 100.00 |     |

} NN

**TOTAL \$ 1,244.82****TOTAL PARTS \$ 17,284.25**

15666.99

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 400

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of Parts,  
Adjust And Realign The Same

\$ 2,200.00 400

**Trans-cab Auto Services Pte Ltd****AAD1810-026**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

|                                                                                      |    |        |    |    |
|--------------------------------------------------------------------------------------|----|--------|----|----|
| To Rust-Proofing Of The Affected Areas.                                              | \$ | 170.00 | X  | NN |
| To reinstall rear bumper parking sensor.                                             | \$ | 170.00 | 40 |    |
| To transfer of bootlid fittings, attachments and perform water seepage test.         | \$ | 170.00 | X  |    |
| To repair and realign rear exhaust pipe.                                             | \$ | 170.00 | X  |    |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | 170.00 | X  | NN |
| To transfer of rear end panel fittings, attachment and perform water seepage test.   | \$ | 170.00 | X  |    |
| To transfer of rear windscreen fittings and conduct water seepage test.              | \$ | 170.00 | X  |    |
| To check steering geometry and computer wheel alignment                              | \$ | 220.00 | X  |    |

4 Days.

**TOTAL \$ 6,610.00**

Lump sum repair

**Over All Total \$ 39,933.69****(LUMP SUM)**

After repair photos.

**Repair Days****10 DAYS**

Gino Ricq - 8488 0282

02/10/18.

LKK A to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## Service Request Details

Claim

S8M00Y10

Reference

None 

Loss Date

September 30, 2018

Request Date

October 5, 2018

Due Date

October 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*Trans Cab*

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SHF577B

Make

TPVD RENAULT

Model

LATITUDE-2.0L (A)

## Service Address

No.2 ANG MO KIO STREET 63, , 569111

## Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

## Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

## Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

## TYPE



## SENT

10/5/18 10:48 AM

## FROM

LOH Cynthia

## SUBJECT

PROCEED DS

## BODY

ID-H2R / TP EXCESS \$5000



**Trans-Cab Services Pte Ltd**

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

LCC

Our Ref : AAD1810-026

Your Ref : SHB9821H

Date : 14.December 2018

**AXA INSURANCE S PTE LTD**

Dear Sir/Madam,

**ACCIDENT INVOLVING SHF0577B AND SHB9821H ON 30/09/18 10:20 PM ALONG AIRPORT BOULEVARD T2 TAXI QUEUE**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

|    |                                                            |    |          |
|----|------------------------------------------------------------|----|----------|
| 1. | Cost of Repair (inclusive of 7% GST)                       | \$ | 3,317.00 |
| 2. | Loss of Rental for <u>5</u> days @ \$ <u>99.32</u> per day | \$ | 496.60   |
| 3. | Loss of Income for ____ days @ \$____ per day              | \$ | 0.00     |
| 4. | LTA Search Fee                                             | \$ | 0.00     |
| 5. | Survey Fee                                                 | \$ | 0.00     |
|    | Total                                                      | \$ | 3,813.60 |

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

**Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.**

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to [claims@transcab.com.sg](mailto:claims@transcab.com.sg) (6603 1259)

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                      |        |                  |
|-------------------|----------------------|--------|------------------|
| Vehicle No:       | SHB 9821H (Insd veh) | Model: | RENAULT LATITUDE |
|                   | SHF 577B (TP veh)    |        |                  |
| Date of Accident: | 30/09/2018           |        |                  |

|                       |   |                              |                                        |
|-----------------------|---|------------------------------|----------------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate       | : | \$                           | 23,857.78                              |
| Final Repair Cost     | : | \$                           | 3,317.00                               |
| Loss of Token Sum     | : | \$                           | days at \$0.00 per day                 |
| Rental (if any)       | : | \$                           | 397.28 4 days                          |
| LTA / GIA Search Fee  | : | \$                           |                                        |

|         |   |    |  |
|---------|---|----|--|
| Others: | : | \$ |  |
|---------|---|----|--|

|                      |   |    |          |
|----------------------|---|----|----------|
|                      | : | \$ |          |
| Final Settlement Sum | : | \$ | 3,714.28 |

|                                                                                                                     |  |                                                  |                             |                         |
|---------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------|-----------------------------|-------------------------|
| Is Third Party Workshop GIA Registered?                                                                             |  | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO | (Kindly indicate below) |
| A) For Non GIA Registered Workshop:                                                                                 |  | Agreed Liability _____ (%)                       |                             |                         |
| B) For GIA Registered Workshop:                                                                                     |  | BOLA Applicable: Yes/ No BOLA Scenario No: _____ |                             |                         |
| BOLA Liability: _____ 100 _____ (%)                                                                                 |  | Assessed Liability (*): _____ (%)                |                             |                         |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                |  |                                                  |                             |                         |
| Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63 SINGAPORE 569111 |  |                                                  |                             |                         |

| Payment Instruction: Payee's Breakdown |                                 |   |             |
|----------------------------------------|---------------------------------|---|-------------|
| 1)                                     | TRANS-CAB AUTO SERVICES PTE LTD | : | \$ 3,714.28 |

NUR SHAQILAH BTE ABDOL  
WAHAB

27/05/2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM18017904/Ghb3s2

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811  
ATTN: CYNTHIA LOH

Date : 27-05-2019



Code : ASM

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | SHB 9821H    | Veh. Inspected | SHF 577B   |
| Policy No.   | VPX/P1680520 | Coverage (\$)  | 0.00       |
| Claim No.    | S8M00Y1O     | Excess (\$)    | 0.00       |
| Assign From  |              | Assign Date    | 02/10/2018 |

#### 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | RENAULT LATITUDE  | c.c          | 1995     |
| Engine No.   | HIDDEN            | Year of Reg. | 2014     |
| Chassis No.  | VF1ABL15AUC278416 | Colour       | RED      |
| Odometer     | 718335            | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

#### 3. Conditions of Tyres

|                | Size      | Make | Balance |
|----------------|-----------|------|---------|
| R/H Front Tyre | 215/60R16 | GITI | 5 mm    |
| L/H Front Tyre | 215/60R16 | GITI | 5 mm    |
| R/H Rear Tyre  | 215/60R16 | GITI | 5 mm    |
| L/H Rear Tyre  | 215/60R16 | GITI | 5 mm    |

#### 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

#### 5. General Information

|                |                                                                              |                 |            |
|----------------|------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 30/09/2018                                                                   | Inspection Date | 02/10/2018 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |            |

#### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 577B

| Qty | Description of Parts                           | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                    |                      |                           |                   |
| 1   | BUMPER COVER REAR (CONSISTENT)                 | CRACKED              | 1,108.46                  | 1,108.46          |
| 1   | BUMPER LOWER REAR (CONSISTENT)                 | CUT                  | 768.84                    | 768.84            |
| 1   | BUMPER BRACKET CTR REAR (CONSISTENT)           | NOT NECESSARY        | 113.47                    | -                 |
| 1   | BUMPER BRACKET SIDE RH REAR (CONSISTENT)       | NOT NECESSARY        | 135.97                    | -                 |
| 1   | BUMPER RETAINER RH REAR (CONSISTENT)           | NOT NECESSARY        | 44.99                     | -                 |
| 1   | BUMPER REFLECTOR RH (CONSISTENT)               | NOT NECESSARY        | 43.61                     | -                 |
| 1   | BUMPER BRACKET SIDE LH REAR (CONSISTENT)       | NOT NECESSARY        | 135.97                    | -                 |
| 1   | BUMPER RETAINER LH REAR (CONSISTENT)           | NECESSARY            | 44.99                     | 44.99             |
| 1   | BUMPER REFLECTOR LH (CONSISTENT)               | SCRATCHED            | 43.61                     | 43.61             |
| 1   | BUMPER BEAM REAR (CONSISTENT)                  | BENT                 | 777.52                    | 777.52            |
| 1   | BUMPER BEAM BRACKET LH REAR (CONSISTENT)       | NOT NECESSARY        | 225.95                    | -                 |
| 1   | BUMPER BEAM BRACKET RH REAR (CONSISTENT)       | NOT NECESSARY        | 225.95                    | -                 |
| 1   | OUTER PANEL REAR (END PANEL) (CONSISTENT)      | TO REPAIR SEE LABOUR | 1,471.77                  | -                 |
| 1   | OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT) | NOT NECESSARY        | 404.56                    | -                 |
| 1   | TAILLAMP RH (CONSISTENT)                       | NOT NECESSARY        | 552.55                    | -                 |
| 1   | TAILLAMP PANEL RH (CONSISTENT)                 | NOT NECESSARY        | 986.70                    | -                 |
| 1   | TAILLAMP LH (CONSISTENT)                       | NOT NECESSARY        | 552.55                    | -                 |
| 1   | TAILLAMP PANEL LH (CONSISTENT)                 | NOT NECESSARY        | 986.70                    | -                 |
| 1   | BOOT REAR (CONSISTENT)                         | NOT NECESSARY        | 2,872.68                  | -                 |
| 1   | BOOT FINISHER (CONSISTENT)                     | NOT NECESSARY        | 470.06                    | -                 |
| 1   | BOOT WEATHERSTRIP                              | TORN                 | 323.05                    | 323.05            |
| 1   | BOOT REFLECTOR LAMP LH (CONSISTENT)            | NOT NECESSARY        | 493.35                    | -                 |
| 1   | BOOT REFLECTOR LAMP RH (CONSISTENT)            | NOT NECESSARY        | 493.35                    | -                 |
| 1   | BOOT BADGE 'RENAULT' (CONSISTENT)              | NOT NECESSARY        | 225.36                    | -                 |
| 1   | BOOT BADGE (CONSISTENT)                        | NOT NECESSARY        | 225.36                    | -                 |
| 1   | BOOT STRUT LH (CONSISTENT)                     | NOT NECESSARY        | 276.08                    | -                 |
| 1   | BOOT STRUT RH (CONSISTENT)                     | NOT NECESSARY        | 276.08                    | -                 |
| 1   | BOOT HINGE LH (CONSISTENT)                     | NOT NECESSARY        | 367.84                    | -                 |
| 1   | BOOT HINGE RH (CONSISTENT)                     | NOT NECESSARY        | 367.84                    | -                 |
| 1   | BOOT INNER TRIM (CONSISTENT)                   | NOT NECESSARY        | 586.45                    | -                 |

Report Ref No. CC3/ASM18017904/Ghb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                                                                                                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | BOOT SWITCH (CONSISTENT)                                                                                                                                                            | NOT NECESSARY | 168.13                    | -                 |
| 1   | BOOT LOCK (CONSISTENT)                                                                                                                                                              | NOT NECESSARY | 202.67                    | -                 |
| 1   | BOOT LOCK CATCH (CONSISTENT)                                                                                                                                                        | NOT NECESSARY | 74.40                     | -                 |
|     | LESS 10% DISCOUNT                                                                                                                                                                   |               | -1,604.69                 | -306.65           |
|     |                                                                                                                                                                                     |               | 14,442.17                 | 2,759.82          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                                                    |               |                           |                   |
| 1   | SET PARKING AID (SN) (CONSISTENT)                                                                                                                                                   | DAMAGED       | 700.00                    | 200.00            |
| 1   | SET REAR BUMPER CLIP (SN) (CONSISTENT)                                                                                                                                              | NECESSARY     | 66.00                     | 66.00             |
| 1   | SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)                                                                                                                                       | NOT NECESSARY | 33.00                     | -                 |
| 1   | SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)                                                                                                                                | NOT NECESSARY | 10.00                     | -                 |
| 1   | SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)                                                                                                                                    | NOT NECESSARY | 20.00                     | -                 |
| 1   | SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)                                                                                                                                | NOT NECESSARY | 10.00                     | -                 |
| 1   | SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)                                                                                                                                    | NOT NECESSARY | 20.00                     | -                 |
| 1   | SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)                                                                                                                                       | NOT NECESSARY | 22.00                     | -                 |
| 1   | SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)                                                                                                                                        | NOT NECESSARY | 66.00                     | -                 |
| 1   | EXHAUST MOUNTING REAR (SN) (CONSISTENT)                                                                                                                                             | NOT NECESSARY | 17.82                     | -                 |
| 2   | REAR WINDSCREEN SEALANT (SN) (CONSISTENT)                                                                                                                                           | NOT NECESSARY | 80.00                     | -                 |
| 1   | WINDSCREEN MOULDING (SN) (CONSISTENT)                                                                                                                                               | NOT NECESSARY | 100.00                    | -                 |
| 1   | REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)                                                                                                                                 | NOT NECESSARY | 100.00                    | -                 |
|     |                                                                                                                                                                                     |               | 1,244.82                  | 266.00            |
|     | <b><u>LABOUR</u></b>                                                                                                                                                                |               |                           |                   |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                   |               | 3,000.00                  | 400.00            |
|     | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF OUTER PANEL REAR (END PANEL). |               | 2,200.00                  | 400.00            |
|     | TO RUST PROOFING OF THE AFFECTED AREAS.                                                                                                                                             | NOT NECESSARY | 170.00                    | -                 |
|     | TO REINSTALL REAR BUMPER PARKING SENSOR.                                                                                                                                            |               | 170.00                    | 40.00             |
|     | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                        | NOT NECESSARY | 170.00                    | -                 |
|     | TO REPAIR AND REALIGN REAR EXHAUST PIPE.                                                                                                                                            | NOT NECESSARY | 170.00                    | -                 |

Report Ref No. CC3/ASM18017904/Ghb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. | NOT NECESSARY | 170.00                    | -                 |
|                                                                             | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.   | NOT NECESSARY | 170.00                    | -                 |
|                                                                             | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.              | NOT NECESSARY | 170.00                    | -                 |
|                                                                             | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                             | NOT NECESSARY | 220.00                    | -                 |
|                                                                             |                                                                                      |               | 6,610.00                  | 840.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                                      |               | <b>22,296.99</b>          | <b>3,865.82</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                      |               |                           | <b>3,100.00</b>   |

Report Ref No. CC3/ASM18017904/Ghb3s2

**XING GUO QIANG****M.MATAI, AMSAE-A****Automotive Assessor****HO LEONG CHUAN****Automotive Assessor****DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.