

Trans-cab Auto Services Pte Ltd**AAD1810-026**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 577B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 577B

VF1ABL15AUC278416

RENAULT

LATITUDE

30.9.2018

AXA

PART		LIST	
1	1 BUMPER COVER REAR / <i>CPH</i>	\$	1,108.46
2	1 BUMPER LOWER REAR / <i>Got</i>	\$	768.84
3	1 BUMPER BRACKET CTR REAR X	\$	113.47
4	1 BUMPER BRACKET SIDE RH REAR X	\$	135.97
5	1 BUMPER RETAINER RH REAR X	\$	44.99
6	1 BUMPER REFLECTOR RH X	\$	43.61
7	1 BUMPER BRACKET SIDE LH REAR X	\$	135.97
8	1 BUMPER RETAINER LH REAR / <i>re</i>	\$	44.99
9	1 BUMPER REFLECTOR LH / <i>scr</i>	\$	43.61
10	1 BUMPER BEAM REAR / <i>BT</i>	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR X	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR X	\$	225.95
13	1 OUTER PANEL REAR (End Panel) X <i>reput</i>	\$	1,471.77
14	1 OUTER PANEL REAR (End Panel) TRIM X	\$	404.56
15	1 TAILLAMP RH X	\$	552.55
16	1 TAILLAMP PANEL RH X	\$	986.70
17	1 TAILLAMP LH X	\$	552.55
18	1 TAILLAMP PANEL LH X	\$	986.70
19	1 BOOT REAR X	\$	2,872.68
20	1 BOOT FINISHER X	\$	470.06
21	1 BOOT WHEATERSTRIP X <i>TN</i>	\$	323.05
22	1 BOOT REFLECTOR LAMP LH X	\$	493.35
23	1 BOOT REFLECTOR LAMP RH X	\$	493.35
24	1 BOOT BADGE 'RENAULT' X	\$	225.36
25	1 BOOT BADGE X	\$	225.36
26	1 BOOT STRUT LH X	\$	276.08
27	1 BOOT STRUT RH X	\$	276.08
28	1 BOOT HINGE LH X	\$	367.84
29	1 BOOT HINGE RH X	\$	367.84

Trans-cab Auto Services Pte Ltd

AAD1810-026

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 577B

30	1 BOOT INNER TRIM	X	} NN	\$	586.45
31	1 BOOT SWITCH	X		\$	168.13
32	1 BOOT LOCK	X		\$	202.67
33	1 BOOT LOCK CATCH	X		\$	74.40
				\$	16,046.87
				10% \$	7.44
				\$	16,039.43

Specical Nett

1	1SET PARKING AID	DM		\$	700.00	200
2	1SET REAR BUMPER CLIP	MC		\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	X	} NN	\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X		\$	10.00	
5	1SET BUMEP R RETAINER RH CLIP RR	X		\$	20.00	
6	1SET BUMEP R BRACKET SIDE CLIP LH RR	X		\$	10.00	
7	1SET BUMEP R RETAINER CLIP LH RR	X		\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	X		\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	X		\$	66.00	
10	1 EXHAUST MOUNTING REAR	X		\$	17.82	
11	2 REAR WINDSCREEN SELANT	X		\$	80.00	
12	1 WINDSCREEN MOULDING	X		\$	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00		
TOTAL				\$	1,244.82	

TOTAL PARTS	\$	17,284.25
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	400
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	400

Trans-cab Auto Services Pte Ltd**AAD1810-026**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 577B

To Rust-Proofing Of The Affected Areas.	\$	170.00	X NN
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X NN
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X

TOTAL \$ 6,610.00**Over All Total \$ 39,933.69****(LUMP SUM)****Repair Days****10 DAYS**

4 Days.
umpsm repair
After repair photos.
Gino Ricq - 8488 0282
02/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: