

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1339/2018/PH
Date : 4-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Koh Suat Hoon
Address : Blk 470 Jurong West St 41
#14-425
Singapore 640470
Telephone : (HP) 91130042
Type of Claim : Third Party Claims
Policy No. : PNPV 2018-00003606
Vehicle No : **SKS 314 P**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Mar-15
Engine No : CZC 232967
Chassis No : WAUZZZ8V7F1094525
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Sep-18
Place of Accident : Bukit Batok MSCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 314 P.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓	
2	To dismantle lhs front door panel trim. To remove and transfer lhs wing mirror assy.	S/N \$ 300.00 X.	
3	To dismantle and renew lhs front door. To repair lhs side member. Reinstall all parts removed.	\$ 1,200.00 1300. ✓	750. Door, side member : 1100
4	To respray lhs front door, lhs wing mirror cover, lhs door handle and lhs side member.	\$ 1,900.00 ✓	Micro 120 Handle 80
5	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES - FRONT		: \$ <u>3,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 314 P.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT DOOR - LH <i>perked</i>	\$ 2,190.00	✓
2	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$ 206.00	?
3	SOUND ABSORBER <i>?</i>	\$ 42.00	?
4	OUTER DOOR SEAL - LH <i>per</i>	\$ 139.00	✓
5	BONDING AGENT <i>?</i>	\$ 43.00	?
6	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
7	DOOR CATCH <i>new</i>	\$ 92.00	X
8	COVER FOR DOOR CATCH <i>new</i>	\$ 13.00	X
9	DOOR SEAL, INNER <i>new</i>	\$ 139.00	X
10	POWER WINDOW REGULATOR W/O MOTOR <i>new</i>	\$ 232.00	X
11	DOOR HANDLE, EXTERIOR - LH <i>Repr</i>	\$ 207.00	X
12	HOUSING - FRONT LH <i>Repr</i>	\$ 26.00	X
13	MOUNTING BAR <i>new</i>	\$ 143.00	X
14	SUNDRIES <i>?</i>	\$ 300.00	X
TOTAL SPARE PARTS CHARGES		\$ 3,836.00	
TOTAL LABOUR CHARGES		\$ 3,872.00	
GRAND TOTAL		\$ 7,708.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Lij
Surveyed Date : 09/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 0\$ Pays

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant