

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/10/2018 16:42

JOB-NO: 50111002

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA0649D

TRANS: AUTO

CHASSIS: KMHLB41UMGU093622

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU672446

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00	Y		1600
2 R&R FRT WINDSCREEN & PILLAR GARNISH	1.00	180.00	0.00	180.00	Y		100
3 REMOVE & REFIT ENGINE & GEAR BOX & ENGINE MOUNTING	1.00	350.00	0.00	350.00	Y		200? photo
4 REMOVE & REFIT WIRE HARNESS & FUSE BOX	1.00	350.00	0.00	350.00	Y		200? photo
5 REMOVE & REFIT DASH BOARD ASSY	1.00	350.00	0.00	350.00	Y		200? photo
6 REMOVE & REFIT CONDENSER & RADIATOR & TURBO	1.00	250.00	0.00	250.00	Y		120? photo
7 MOUNT WORKBENCH & ALIGNMENTS CHASSIS & REPLACE CHASSIS & SUPPORT PANEL	1.00	350.00	0.00	350.00	Y		250? photo
8 CONDUCT WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y		70? X
9 TOP UP AIR-CON GAS 134A	1.00	160.00	0.00	160.00	Y		100
10 TOP UP RADIATOR COOLANT 4L & BLEEDING	1.00	180.00	0.00	180.00	Y		100
11 TOWING SERVICE	1.00	100.00	0.00	100.00	Y		80
12 RESPRAY FRT BUMPER	1.00	220.00	0.00	220.00	Y		200
13 RESPRAY FRT FENDER LHS	1.00	220.00	0.00	220.00	Y		200
14 RESPRAY FRT FENDER RHS	1.00	220.00	0.00	220.00	Y		200
15 RESPRAY FRT BONNET	1.00	220.00	0.00	220.00	Y		200
16 RESPRAY FRT CHASSIS	1.00	420.00	0.00	420.00	Y		300
17 RESPRAY FRT WHEEL HOUSE PANEL	1.00	420.00	0.00	420.00	Y		200
18 RESPRAY WINDSCREEN PILLAR & GARNISH	1.00	220.00	0.00	220.00	Y		150
19 DIAGNOSTIC & RESETTING FAULT CODE	1.00	250.00	0.00	250.00	Y		150
20 ADJUST HEAD LAMP AIM & RESETTING AUTOMATIC CONTROL	1.00	250.00	0.00	250.00	Y		150
21 RESPRAY SIDE SKIRT LHS	1.00	230.00	0.00	230.00	Y		200
TOTAL:		7,560.00	0.00	7,560.00			
MATERIALS							
1 FRT BUMPER V3	1.00	599.68	119.94	479.74	L	Y	M/S
2 FRT BUMPER RETAINER LHS	1.00	48.32	9.66	38.66	L	Y	M/S
3 FRT BUMPER RETAINER RHS	1.00	48.32	9.66	38.66	L	Y	M/S
4 FRT BUMPER TOP SEAL	1.00	32.20	6.44	25.76	L	Y	M/S
5 FRT BUMPER TOWING CAP	1.00	21.92	4.38	17.54	L	Y	M/S
6 FRT BUMPER SENSOR COVER LHS	1.00	19.38	3.88	15.50	L	Y	M/S
7 FRT BUMPER SENSOR COVER RHS	1.00	19.38	3.88	15.50	L	Y	M/S

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
8 RADIATOR GRILLE	1.00	1,110.10 ✓	222.02	888.08	L	Y	mis ✓
9 RADIATOR GRILLE LOGO	1.00	142.84 ✓	28.57	114.27	L	Y	mis ✓
10 FRT BUMPER RADIATOR GRILLE CHROME	1.00	121.77 ✓	24.35	97.42	L	Y	mis ✓
11 FRT BUMPER HEAD LAMP BRACKET LHS	1.00	42.32 ✓	8.46	33.86	L	Y	ah ✓
12 FRT BUMPER HEAD LAMP BRACKET RHS	1.00	42.32 ✓	8.46	33.86	L	Y	ah ✓
13 FRT BUMPER FOG LAMP COVER LHS	1.00	178.55 ✓	35.71	142.84	L	Y	mis ✓
14 FRT BUMPER FOG LAMP COVER RHS	1.00	178.55 ✓	35.71	142.84	L	Y	mis ✓
15 FRT BUMPER AIR DUCT LHS	1.00	103.63 ✓	20.73	82.90	L	Y	mis ✓
16 FRT BUMPER AIR DUCT RHS	1.00	103.63 ✓	20.73	82.90	L	Y	mis ✓
17 FRT BUMPER LOWER LIP	1.00	82.63 ✓	16.53	66.10	L	Y	mis ✓
18 FRT BUMPER TOP GARNISH	1.00	105.83 ✓	21.17	84.66	L	Y	tn ✓
19 FRT ENGINE LOWER COVER	1.00	344.88 ✓	68.98	275.90	L	Y	tn ✓
20 FRT ENGINE SIDE COVER LHS	1.00	112.83 ✓	22.57	90.26	L	Y	X an ✓
21 FRT ENGINE SIDE COVER RHS	1.00	112.83 ✓	22.57	90.26	L	Y	de ✓
22 FRT BUMPER UPPER AIR DUCT	1.00	235.45 ✓	47.09	188.36	L	Y	X an ✓
23 FRT FENDER RHS	1.00	659.50 ✓	131.90	527.60	L	Y	bt ✓
24 FRT FENDER INNER SHIELD RHS	1.00	185.12 ✓	37.02	148.10	L	Y	mis ✓
25 FRONT WHEEL HOUSE PANEL RHS	1.00	678.55 ✓	135.71	542.84	L	Y	Rp ✓
26 FRONT FENDER BRACKET RHS	1.00	55.12 ✓	11.02	44.10	L	Y	X an ✓
27 HEAD LAMP LOWER PANEL RHS	1.00	189.88 ✓	37.98	151.90	L	Y	an ✓
28 WIPER TANK	1.00	108.76 ✓	21.75	87.01	L	Y	X ✓
29 WIPER TANK LEVER SENSOR	1.00	78.43 ✓	15.69	62.74	L	Y	X } X
30 WIPER TANK CAP	1.00	8.00 ✓	1.60	6.40	L	Y	X } X
31 FRONT FENDER LHS	1.00	659.50 ✓	131.90	527.60	L	Y	bt ✓
32 FRONT FENDER INNER SHIELD LHS	1.00	185.12 ✓	37.02	148.10	L	Y	tn ✓
33 FRT FENDER STAND GARNISH LHS	1.00	55.89 ✓	11.18	44.71	L	Y	X an ✓
34 FRT FENDER BRACKET LHS	1.00	55.12 ✓	11.02	44.10	L	Y	X an ✓
35 FRT HEAD LAMP LOWER LHS	1.00	189.88 ✓	37.98	151.90	L	Y	de ✓
36 FRT FENDER UPPER RUBBER LHS	1.00	36.01 ✓	7.20	28.81	L	Y	de ✓
37 FRT FENDER QTR GARNISH LHS	1.00	113.55 ✓	22.71	90.84	L	Y	X an ✓
38 FRT WHEEL HOUSE PANEL LHS	1.00	678.55 ✓	135.71	542.84	L	Y	Rp ✓
39 FRT REINFORCEMENT	1.00	482.21 ✓	96.44	385.77	L	Y	bt ✓
40 FRT REINFORCEMENT SPONGE	1.00	99.86 ✓	19.97	79.89	L	Y	mis ✓
41 HORN LHS	1.00	123.83 ✓	24.77	99.06	L	Y	an ✓
42 HORN RHS	1.00	123.83 ✓	24.77	99.06	L	Y	an ✓
43 CONDENSER AIR GUARD LHS	1.00	74.58 ✓	14.92	59.66	L	Y	an ✓
44 CONDENSER AIR GUARD RHS	1.00	74.58 ✓	14.92	59.66	L	Y	an ✓
45 FRT SUPPORT PANEL	1.00	962.87 ✓	192.57	770.30	L	Y	an ✓
46 CONDENSER	1.00	927.55 ✓	185.51	742.04	L	Y	an ✓
47 RADIATOR	1.00	1,140.60 ✓	228.12	912.48	L	Y	i bt ✓
48 RADIATOR FAN COWLING	1.00	355.40 ✓	71.08	284.32	L	Y	i an ✓
49 FAN BLADE	1.00	73.51 ✓	14.70	58.81	L	Y	i X an ✓
50 TURBO INTERCOOLER	1.00	1,089.55 ✓	217.91	871.64	L	Y	X X an ✓
51 TURBO TOP HOSE	1.00	343.20 ✓	68.64	274.56	L	Y	X X an ✓
52 TURBO LOWER HOSE	1.00	277.29 ✓	55.46	221.83	L	Y	X X an ✓
53 BONNET	1.00	1,912.68 ✓	382.54	1,530.14	L	Y	bt ✓
54 BONNET DAMPER LHS	1.00	76.45 ✓	15.29	61.16	L	Y	X an ✓
55 BONNET DAMPER RHS	1.00	76.45 ✓	15.29	61.16	L	Y	X an ✓
56 BONNET HINGE LHS	1.00	55.85 ✓	11.17	44.68	L	Y	bt ✓
57 BONNET HINGE RHS	1.00	55.85 ✓	11.17	44.68	L	Y	bt ✓
58 BONNET INSULATOR	1.00	196.50 ✓	39.30	157.20	L	Y	X an ✓
59 BONNET LOCK	1.00	79.90 ✓	15.98	63.92	L	Y	X an ✓
60 BONNET SENSOR LHS	1.00	63.55 ✓	12.71	50.84	L	Y	mis ✓
61 BONNET STRIP	1.00	33.88 ✓	6.78	27.10	L	Y	X ✓
62 BONNET STRIP LHS	1.00	23.97 ✓	4.79	19.18	L	Y	X ✓
63 BONNET STRIP RHS	1.00	23.97 ✓	4.79	19.18	L	Y	X ✓
64 BONNET STOPPER X2	1.00	25.19 ✓	5.04	20.15	L	Y	X ✓
65 HEAD LAMP LHS	1.00	1,808.10 ✓	361.62	1,446.48	L	Y	ura ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
66 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	OK
67 FRT WINDSCREEN	1.00	1,317.80	263.56	1,054.24	L	Y	OK
68 FRONT WINDSCREEN MOULDING	1.00	65.38	13.08	52.30	L	Y	OK
69 FRONT WINDSCREEN MOULDING LHS	1.00	57.21	11.44	45.77	L	Y	OK
70 FRONT WINDSCREEN MOULDING RHS	1.00	57.21	11.44	45.77	L	Y	OK
71 WIPER TOP GARNISH	1.00	222.60	44.52	178.08	L	Y	OK
72 WIPER TOP GARNISH SIDE COVER LHS	1.00	28.32	5.66	22.66	L	Y	X
73 WINDSCREEN PILLAR GARNISH LHS	1.00	183.30	36.66	146.64	L	Y	X
74 WINDSCREEN PILLAR GARNISH RHS	1.00	183.30	36.66	146.64	L	Y	X
75 AIR RESONATOR	1.00	181.60	36.32	145.28	L	Y	X
76 WINDSCREEN PILLAR LHS	1.00	1,745.50	349.10	1,396.40	L	Y	OK
77 FRT CHASSIS LHS	1.00	1,260.70	252.14	1,008.56	L	Y	OK
78 REPAIR CHASSIS RHS	1.00	0.00	0.00	0.00	L	Y	X
79 WATER PUMP pulley.	1.00	293.20	58.64	234.56	L	Y	OK
80 AIR-COND COMPRESSOR	1.00	2,578.00	515.60	2,062.40	L	Y	X
81 TENSIONER PULLEY	1.00	103.88	20.78	83.10	L	Y	OK
82 FAN BELT	1.00	75.70	15.14	60.56	L	Y	OK
83 GROUNDING CABLE	1.00	32.88	6.58	26.30	L	Y	X
84 ENGINE MOUNTING (ENGINE SIDE)	1.00	456.30	91.26	365.04	L	Y	X
85 SIDE SKIRT RHS	1.00	695.88	139.18	556.70	L	Y	OK
86 BATTERY	1.00	260.00	0.00	260.00	S	Y	X
87 RADIATOR LOWER HOSE	1.00	0.00	0.00	0.00	S	Y	X
88 RADIATOR TOP HOSE	1.00	0.00	0.00	0.00	S	Y	X
89 FRT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	OK
90 FRT NUMBER PLATE CASING	1.00	18.00	0.00	18.00	S	Y	OK
91 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	OK
92 FRONT WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	OK
93 FRT WINDSCREEN COMFORT STICKER	1.00	85.00	0.00	85.00	S	Y	OK
94 FRT WINDSCREEN ERP & VIDEO RECORDER STICKER	1.00	55.00	0.00	55.00	S	Y	OK
95 FRONT FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	OK
96 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	OK
97 FRT BUMPER BOLT SET (MISSING)	1.00	60.00	0.00	60.00	S	Y	OK
TOTAL:		30,345.40	934.51	24,410.89			

TOTAL PARTS & LABOUR : 37,905.40 5,934.51 31,970.89

EXCESS/LOADING:\$ 0.00

No. Of Day: 12

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 3/10/18

SURVEYED BY: [Signature]

CONTACT NO: 9748744 FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: