

Your Ref: 18.24658 PD-O

Date: 10th Oct 2018

Our Ref : CS3/ASM17020781/Bvbe2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 3818R**INSURED VEHICLE: SLB 5937L****ACCIDENT DATE: 28/10/2017**

We thank you for your instruction on 03/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 3818R from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SLA 3818R and SLB 5937L.
- c) Final Repair Bill of SLA 3818R from M/s Twincar Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SLA 3818R.

Pre-Repair Inspection Date : 31/10/2017 at M/s Twincar Automotive Pte Ltd, 2 Kaki Bukit Ave 2,
#01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLA 3818R
Make & Model : Toyota Harrier Elegance 2.0 A
Year of Registration : 2016
Chassis Number : ZSU600076941
Engine Capacity : 1986 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.