


SMRT Accident Vehicle Repair Estimates


SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705
FAX Number - 53685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/10/2018 User ID : PohSuan

	Section A - Accident Details
Registration Number	SHB689H
Case Reference Number	TAX/09/18/2123
Registration Date	12/09/14
Company Type	SMRT Taxis Pte Ltd
Make	ТОУОТА
Model	PRIUS
Name of Driver	LOCK CHIN WAH
Type of Accident	Head To Side
Accident Date and Time	26/09/18 8:15 AM
Accident Reported Date and Time	26/09/18 10:13 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No ,
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098073
Special Instruction to ARC,if any	DOOR HARD TO OPEN /NTUC - LKK
Prepared Date and Time	27/09/18 8:24 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	





70 M



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592 Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 13/10/2018 User ID : PohSuan

Summary of Repair Estima	ates	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,674.00	\$450.00
Total Spare Part Cost	\$3,758.06	\$1,934.50
Total Other Cost	\$360.00	(\$534.50)
TOTAL COST	\$6,468.06	\$2,250.00 (15)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Naz (4KK)/NTUC
ARC / Surveyor Sign Off Dat	е	
Signature	d	M
Remarks		LUMP SUM REPAIR 3 DAYS AFTER REPAIR PHOTOS

Section C - Quotation and Accident Invoice Details					
Quotation Number	Invoice Number				
Quotation Date	Invoice Date				
Invoice Amount	Prepared Date				

	Section D - Details of Repair Estimates				
Part 1 - Labour Works					
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable			
TO REPAIR FRONT LH PORTION	\$676.00	\$400.00			
Total Labour	\$676.00	\$400.00			

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT WHEEL HOUSE RH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$450.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number ; 68662672

Date Generated : 13/10/2018 User ID

: PohSuan

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor	\$0.00	(\$554.52)		
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00		
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00		
TO WASH AND VACUUM	\$60.00	\$0.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
Total Other Costs	\$360.00	(\$534.52)		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119- 47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	/
		52115- 47040	BUMPER SUPPORT F/RH	0.00	\$76.40	25.00	\$0.00	Replace	Check	X
		81511- 47050	LENS & BODY, FR TURN RH	0.00	\$511.80	25.00	\$0.00	Replace	Not Given	X
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	/
		53102- 47020	BUMPER GRILLE SUB- ASSY, LOWER	0.00	\$311.10	25.00	\$0.00	Replace	Check	X
		52127- 47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	25.00	\$0.00	Replace	Not Given	X
		76851- 47020	BUMPER LIP FRT	0.00	\$139.60	25.00	\$0.00	Replace	Check	X
		53801- 47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	/
		53875- 47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	/
		75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	/
		53710- 12030	FENDER APRON FRT/RH	0.00	\$168.10	25.00	\$0.00	Replace	Not Given	X
		42611 47140(Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	25.00	\$0.00	Replace	Repair	R
		81130- 47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/
		67001- 47070	DOOR FRT/RH	0.00	\$894.40	25.00	\$0.00	Replace	Not Given	X
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
otal					\$6,039.91		\$1,934.52			

Added Chara	Dome	Material	Illana	ALL	C	Cinned off
Added Spare	Parts /	wateriai	usage.	Arter	Surveyo	r Signea on

Part Number	Portion	Stock Number	Part Name	Quantity	List Price	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									