



**JOO HAK KEE AUTO PTE LTD**  
 裕合记汽车私人有限公司  
 SINCE 1986

Surveyed by/Company : \_\_\_\_\_  
 Contact Number : \_\_\_\_\_  
 Date/Time : \_\_\_\_\_  
 Licensed Automotive Surveyor's Sign : \_\_\_\_\_

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: TAN PENG CHAN  
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 POLICY NO: 5063356048-04  
 REFERENCE: TP CLAIM  
 DATE OF ACCIDENT: 29/09/2018

Roh Kim.  
 TP AXA.

KLISA6979B690259

**REPAIR ESTIMATE**

Est. No. : E18100002  
 Date : 02/10/2018  
 Vehicle Num. : SJU7790C

No	Description	Qty	U/P	Amt
<b>Section: LIST ITEMS</b>				
1	REAR BUMPER <i>Rehnd</i>	1.00	776.00	776.00 ✓
2	REAR BUMPER REINFORCEMENT <i>Rehnd</i>	1.00	776.00	776.00 ✓
3	REAR BUMPER SIDE RETAINER <i>ne</i>	2.00	776.00	<del>1,552.00</del> 70 ✓
4	REAR BUMPER SPONGE <i>ne</i>	1.00	225.00	225.00 +
5	BOOTLID <i>Rehnd</i>	1.00	1,440.00	<del>1,440.00</del> 1037 ✓
6	BOOTLID INNER LOCK <i>Rehnd</i>	1.00	100.00	100.00 ✓
7	BOOTLID LOCK STRIKER <i>ne</i>	1.00	16.00	16.00 ✗
8	BOOTLID GARNISH <i>ne</i>	1.00	142.00	142.00 ✗
9	BOOTLID HINGE <i>ne</i>	2.00	65.00	130.00 +
10	BOOTLID 'AVEO' EMBLEM <i>2</i>	1.00	28.00	28.00 -
11	BOOTLID 'LS' EMBLEM <i>2</i>	1.00	28.00	28.00 -
12	BOOTLID LOGO EMBLEM <i>1</i>	1.00	69.00	69.00 -
13	BOOTLID 'CHEVROLET' EMBLEM <i>ne</i>	1.00	39.00	39.00 -
14	TAILLAMP <i>lt</i>	2.00	441.00	882.00 -
15	REAR END PANEL <i>Rehnd</i>	1.00	618.00	618.00 ✓
16	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1.00	38.00	38.00 ✓
17	REAR NO PLATE <i>ne</i>	1.00	50.00	50.00 +

3877  
 3489.30

**Amt** S\$ 6,909.00  
**Discount (10.00%)** S\$ 690.90  
**Subtotal** S\$ 6,218.10

**Section: LABOUR**

18	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	1,000.00	1,000.00 <i>800</i>
19	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	1,000.00	1,000.00 <i>800</i>

Continue on next page...





JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: TAN PENG CHAN
INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO: 5063356048-04
REFERENCE: TP CLAIM
DATE OF ACCIDENT: 29/09/2018

Est. No. : E18100002
Date : 02/10/2018
Vehicle Num. : SJU7790C

Table with 5 columns: No, Description, Qty, U/P, Amt. Row 1: 20 TO DISMANTLE AND REFIT BOOTLID COMPONENTS 1.00 60.00 60.00

1660

Amt S\$ 2,060.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,060.00

Adrian King
L/S 03/10/18
OSR

Total: \$49.30
L/S: A.I.K.

Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Handwritten signature



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 6,218.10
LABOUR Subtotal S\$ 2,060.00
Total S\$ 8,278.10

