

ASS. REC. BY:

REF: Cst/CTI 18017928/T19d3 n2

Special Instruction:

Surveyor: Murmen

ASSIGNMENT (Office)

From (Person): Catherine Chia

of CTI

Date/Time: 3/10/18 @ 3:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 4153E

Insured: GBF 3639H

at Workshop m/s: Sin Sheng Engineering

Tel: 6863 9595

of 3 Teeh Park Crescent

Policy No: DMCVSN1663301802

Claim No: SNM18D04736C02

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 01/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement: 4/10/18

Date/Time: 4:09pm @ 3/10/18

Person Contacted: Jugen


Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBG 4153E-X
	GBF 3639H-X

Garage: Taufhi REF: CTF

ASSIGNMENT

From: _____ Date: 4/10/18
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBG 4153E
 at Workshop m/s: Sin Sheng Engineering
 of: 3tech park Crescent
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up)
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: GBG 4153E Yr Regn: 2017 Aug.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota fuel c.c. 2402
 Colour: yellow A/C: Insured / Std / NI / NA
 Sp. Reading: 4803 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDH 2010222094
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nit / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 4/10/18
 Survey held at: Sin Sheng
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>01/11/18</u>	<u>Confirmed r/p \$5,233.60 @ 5 days with Taufhi. (\$2,555.91 red - 33%)</u>

RECEIVED 05 NOV 2018

2/11/2018

Date/Time. File Pass to? 02/11/18
 1) Typ 34 Preli. Report Final Report
 Date/Time. File Return to? _____
 2) _____
 Report Format: _____
 Lump Sum / I.B.I: (\$ 5,233.60 p/p)
 Days Of Repair: 5
 Resurvey No. of Trip: 2
 Add Fee: Site Insp (\$ _____) Interview (\$ _____) Tech. Invs (\$ _____) Weekend (\$ _____)
 Survey Fee: _____
 Transportation: _____ \$ + RS _____ \$
 Photos: _____
 Others: _____
 TOTAL: _____

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		03 Oct 2018 15:31 Assign				New Assignment Cancel Case

[Main](#) [Reference](#) [Claim Details](#) [Documents](#) [Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOLDBELL LEASING PTE LTD		
Vehicle Reg. No.:	GBG4153E	Date of Loss:	01/10/2018 00:00 - :59
Claim Type:	TP / SNM18D04736C02	Policy/Cover Note No.:	DMCVSN1663301802
Vehicle Reg. No. (Insured):	GBF3639H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Monday, 5 November 2018 9:22 AM
To: Shirley Hiew (LKK Auto)
Cc: Admin A; Taufikh (LKK Auto); LKK_Surveyor
Subject: Re: Accident Involving GBG4153E with GBF3639H on 01/10/2018 (CTI REF: SNM18D04736C02)

Noted

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Mon, 5 Nov 2018 at 08:50, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Susan

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Saturday, 3 November 2018 11:45 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Taufikh (LKK Auto) <Taufikh@lkkauto.com>; LKK_Surveyor <sur@lkkauto.com>
Subject: Re: Accident Involving GBG4153E with GBF3639H on 01/10/2018 (CTI REF: SNM18D04736C02)

Yes, confirmed.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Fri, 2 Nov 2018 at 17:43, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Susan,

Please confirm final fig of \$ 5, 233.60 (part by part) @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Tuesday, 23 October 2018 4:46 PM
To: Taufikh (LKK Auto) <taufikh@lkkauto.com>; LKK_Surveyor <sur@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: Accident Involving GBG4153E with GBF3639H on 01/10/2018 (CTI REF: SNM18D04736C02)

Hi Mr Taufikh,

REMINDER.

Please have your finalized amount.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Thu, 11 Oct 2018 at 10:36, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr Taufikh,

Please find attached and have your finalized please.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Wed, 10 Oct 2018 at 14:09, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr Taufikh,

Please find attached.

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

On Fri, 5 Oct 2018 at 15:40, sinsheng engineering services <sinsheng1981@gmail.com> wrote:

Hi Mr Taufikh,

Please find attached.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 3 Oct 2018 at 15:27, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Catherine Thia

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: sinsheng engineerservices [mailto:sinsheng1981@gmail.com]

Sent: Wednesday, 3 October, 2018 3:17 PM

To: Lucas Lee

Subject: Re: Accident Involving GBG4153E with GBF3639H on 01/10/2018 (CTI REF: SNM18D04736C02)

Hi Mr Lucas,

We are selected Mr Chua Wei Jie.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 3 Oct 2018 at 13:55, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Catherine Thia

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: sinsheng engineering services [mailto:sinsheng1981@gmail.com]
Sent: Wednesday, 3 October, 2018 10:07 AM
To: Claims Dept of CTI
Subject: Accident Involving GBG4153E with GBF3639H on 01/10/2018

Dear Officer In Charge,

We are repairer of vehicle GBG4153E. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipted of this email.

Enclose Accident Statement and LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection

Kindly assist to revert the liability issue if direct settlement is in order.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002618

Date : 03/10/2018

Vehicle Num. : GBC4153E

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010222094/1KD2707559

Accident Date : 01/10/2018

Claim No. :

Reference : GBF3639H

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	REAR DOOR ASSY		2,150.50 <i>ht</i>
2.	1	REAR DOOR LOCK		275.10 <i>ht</i>
3.	1	CENTRE LOCKING		395.20 <i>xnn</i>
4.	1	REAR DOOR PARTITION		295.45 <i>xnn</i>
5.	1	TOYOTA EMBLEM		53.20 <i>ht</i>
6.	1	REAR END PANEL		585.90 <i>RX</i>
7.	1	REAR END PANEL INNER		572.10 <i>Ry</i>
8.	1	REAR BUMPER		677.40 <i>de</i>
9.	2	BUMPER SIDE BRACKET	123.50	247.00 <i>de</i>
10.	1	STEP PANEL		365.40 <i>? ht</i>
11.	1	REAR DOOR WEATHERSTRIP		321.10 <i>? de</i>
12.	1	REAR DOOR GARNISH		365.20 <i>act</i>
13.	2	REAR LAMP		731.80 <i>RH etc</i>
		List Total S\$:		4820.80
		25.00% Discount S\$:		1,758.84
				3615.60
		NETT ITEMS :		
1.	1	REVERSE SENSOR		200 250.00 <i>cm</i>
2.	1	70km/h Sticker		20.00 <i>ht</i>
3.	1	8 PAX STICKER		20.00 <i>ht</i>

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002618

Date : 03/10/2018

Vehicle Num. : GBC4153E

Make/Model : TOYOTA KDH 201-2017

Chassis/Eng# : KDH2010222094/1KD2707559

Accident Date : 01/10/2018

Claim No. :

Reference : GBF3639H

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

4.	1	REAR WINDSCREEN SEALANT		40.00 <i>nee</i>
5.	1	NUMBER PLATE WITH CASING		40.00 <i>ht</i>

Nett Total S\$: 370.00
10.00% Discount S\$: 37.00

333.00

LABOUR :
TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS
,
TO PANEL BEAT/REPAIR REAR BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
,
SPRAY PAINTING
,
TO APPLY TUFF KOTE
,
TO CHECK WIRING
,
TO APPLY NEW LOGO
,
LOSS OF USE : 7 DAYS @ \$ 120/DAY

Labour Total S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

120.00 ✓
~~100.00~~ 500
850.00
450.
650.00
30
100.00
30
80.00
200
380.00
1330.

2,180.00

101 - 320 - 288

Total S\$: 7,789.51

SIN SHENG ENGINEERING SERVICES

Taylor 97495749
-wp'
4/10/18 1645
Reasoning before paint
5 days
su@lkkauto.com

5233.60
5 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017928/T1SD3N2
Date: 09/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1663301802
Claimant Vehicle No :	GBG4153E	Insured Vehicle No :	GBF3639H
Date of Loss:	01/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04736C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG4153E	Engine No:	1KD2707559
Make & Model:	TOYOTA HIACE, 3.0 D DX TURBO MT 2WD 4DR (M)	Chassis No:	KDH2010222094
Reg. Date:	03/08/2017 (Man. Year: 2017)	Odometer:	48003 km
Colour:	Yellow		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,609.51	3,903.60	1,705.91	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,330.00	850.00	38.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,789.51	5,233.60	2,555.91	32.81
+ GST 7.00/7.00% (S\$)	545.27	366.35	178.92	32.81
Nett Amount (S\$)	8,334.78	5,599.95	2,734.83	32.81

INSPECTION

Date of Assignment:	03/10/2018	
Date Inspected:	04/10/2018 Inspected At:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Nov 2018)
Parts:	N/A TOYOTA HIACE 3.0 D DX TURBO MT 2WD 4DR (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG4153E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR ASSY	Bent	2,150.50 FL	*2,150.50 FL
2	1		*REAR DOOR LOCK	Bent	275.10 FL	*275.10 FL
3	1		*CENTRE LOCKING	Not Necessary	395.20 FL	*- FL
4	1		*REAR DOOR PARTITION	Not Necessary	295.45 FL	*- FL
5	1		*TOYOTA EMBLEM	Necessary	53.20 FL	*53.20 FL
6	1		*REAR END PANEL	Repair	585.90 FL	*- FL
7	1		*REAR END PANEL INNER	Repair	572.10 FL	*- FL
8	1		*REAR BUMPER	Deformed	677.40 FL	*677.40 FL
9	2		*BUMPER SIDE BRACKET	Necessary	247.00 FL	*247.00 FL
10	1		*STEP PANEL	Bent	365.40 FL	*365.40 FL
11	1		*REAR DOOR WEATHERSTRIP	Deformed	321.10 FL	*321.10 FL
12	1		*REAR DOOR GARNISH	Cut	365.20 FL	*365.20 FL
13	1		*REAR LAMP	O/s Cracked/N/s Not Necessary	731.80 FL	*365.90 FL
14	1		*REVERSE SENSOR	Cracked	250.00 FN	*200.00 FN
15	1		*70KM/H STICKER	Necessary	20.00 FN	*20.00 FN
16	1		*8 PAX STICKER	Necessary	20.00 FN	*20.00 FN
17	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FN	*40.00 FN
18	1		*NUMBER PLATE WITH CASING	Bent	40.00 FN	*40.00 FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	7,405.35	5,140.80
- List Item Discount on L Items 25.00/25.00% (\$)	1,758.84	1,205.20
- Nett Item Discount on N Items 10.00/10.00% (\$)	37.00	32.00
Total Parts (\$)	5,609.51	3,903.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO PANEL BEAT/REPAIR REAR BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS	New	850.00	500.00
3	SPRAY PAINTING	New	650.00	450.00
4	TO APPLY TUFF KOTE	New	100.00	30.00
5	TO CHECK WIRING	New	80.00	30.00
6	TO APPLY NEW LOGO	New	380.00	200.00
Gross Labour Cost (S\$)			2,180.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >