



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SKP8912B

Perry

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition Per Unit	Our Estimates
1	1 pc	Lower Bumper		\$2,200.00 <i>DE</i>
2	2pcs	Rear Bumper Retainer	<i>price? - { \$350.00</i>	\$700.00 X
3	1pc	Rear Bumper Protector Guard Plate		\$1,800.00 <i>cut</i>
4	1pc	Reverse Sensor Set		\$388.00 <i>AM</i>
5	1pc	Rear Exhaust End Pipe		\$380.00 <i>BL</i>
Parts Total :				

price? - { \$350.00

\$2,200.00 DE
\$700.00 X
\$1,800.00 cut
\$388.00 AM
\$380.00 BL

} 10%

R - 4768
? - 0
L - 800



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SKP8912B

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	To Straighten, Repair, Re-Alignment of Rear Boot Tailgate and Re-informant Bar	\$680.00 X
2	Spray Painting to Rear Bumper and Body Structure	\$650.00 400
3	Labour to Remove & Re-Install Replaced Parts	\$300.00
4	Dianostic of In-car eletrical system and check wiring to ensure Rear Reverse Cam and Sensor is in good working Con	\$250.00 100
Labour Total :		<u>\$1,880.00</u>
Total (Parts & Labour) :		<u><u>\$7,348.00</u></u>

For Lump Sum Repairs

The estimated amount calculated is **\$7,348.00**

Under normal circumstances, the repairs should be completed within a reasonable period Of 6 Working Days. (Exclude waiting days of PRI, Sunday and Public Holiday)

RASUL
Hp 90010068
3 days
4S
03/10/18 @ 1220
Ready after repair