

ASS. REC. BY:

REF:

CS/CT118017931/Acd312

Special Instruction:

Surveyor
Meimen

Adrian

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time:

31/01/18 @ 3:16pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGL 8747E

Insured:

SLH 29564

at Workshop m/s

~~Ho Beng~~ Sin Ho

Tel:

8186 2100

of

BLK 3020A # 01-33 Ubi Rd 1

Policy No:

DMPCSN1675091701

Claim No:

SNM18D04742C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/10/2018

CA / REV / REP. / REV 24 HRS

(up)

4/10/18 @ Morning

H.O.D. Endorsement:

Date/Time:

3:52pm @ 31/01/18

Person Contacted:

Mr. Tan

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 8747E-X

SLH 29564-X

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGL8747E Yr Regn: 2018 June
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota ~~Altis~~ Vios C.C. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 1237 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR2B23F3301132081
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: 185/60R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 07/10/18
 Survey held at 1-to Benz
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP China.</u>
<u>25/2/19</u>	<u>Confirmed 12 \$3700f and 6 days with repainer. (Red 3246.35, 462.)</u> <u>Part price checked by Adrian. (Our system no record)</u>

RECEIVED 26 FEB 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 6

1)

☐ : Final ReportResurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$ _____) S + RS. \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.I: (\$ 3700f)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		03 Oct 2018 15:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:				[Created by insurer]	
Main Claimant:	SAU WEE WEE				
Vehicle Reg. No.:	SLH8747E		Date of Loss:	02/10/2018 00:00 - :59	
Claim Type:	TP / SNM18D04742C02		Policy/Cover Note No.:	DMPCSN1675091701	
Vehicle Reg. No. (Insured):	SLH2956U		Policy No. (Claimant):		
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100		Excess:	S\$0.00	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]				
Adj Asg. Remarks:	NO EST, CASE WITH SJE.				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Notice Of Accident

Date : 3-Oct-2018

WITHOUT PREJUDICE

Our ref : SGL8747E

Your ref : SLH2956U

To :
China Taiping Insurance (S) Pte Ltd

3 Anson Rd

#16-00 Springleaf Tower

Singapore 079909

Attn : Motor Claims Department

Dear Sir/ Madam,

CLAIMANT: SAU WEE WEE

ACCIDENT INVOLVING SGL8747E & SLH2956U ON 4 AUGUST 2017 ALONG SLIP ROAD
MARINE VISTA - MARINE PARADE RD AT ABOUT 1435HRS

We are instructed by Sau Wee Wee to notify you (the insured of SGL8747E) of a road accident on 2 Oct 2018 at along MARINE VISTA - MARINE PARADE RD at about 1435hrs involving our client's vehicle registration number SGL8747E and vehicle registration number SLH2956U driven by your insured at the material time.

As a result of the accident, our client's vehicle SGL8747E has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall use independent surveyor as the joint pre-repair survey as a single joint expert and proceed to repair the vehicle without further reference to you.

Note: Car is at the workshop, location - Block 3020A #01-33 Ubi Road 1, Singapore 408714

Your faithfully,

CK. Tan
Tel : 81862100

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2018 10:37
Date Of Accident	02/10/2018 14:35
Exact Location Of Accident	SLIP ROAD MARINE VISTA - MARINE PARADE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL8747E
Insured/Policyholder	
Name Of Registered Owner	SAU WEE WEE
NRIC No	S7413344D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96727456
Alternative Phone No	OTHERS-96727456

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2145030
Cover Note Number	

Driver

Name of Driver	SAU WEE WEE
NRIC No	S7413344D
Date Of Birth	29/04/1974
Occupation	INDOOR
Date Of Driving Pass	06/06/2006
Driving Experience	12 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96727456
Fax Number	
Contact Number	OTHERS-96727456
Email Address	NOEMAIL

Address	160 HAIG ROAD #04-05
Postcode	438795
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : PAX 1
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH2956U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescindate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any fines reported may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my work place and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set forth in this Form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers, my work place, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, inquiries, reports or notices to me, which could involve disclosure of certain personal data about me to third parties, delivery of the claim as well as on the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims collectively the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers, lawyer/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for any or some of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their representatives herein), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN/ID:

31/10/18

Sketch Plan #2

SKETCH PLAN

Vehicle
A-SGL 8747
B-364 29

Legend
Vehicle
Bicycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached.

DECLARATION

[illegible]

Policyholder's Signature _____

Costs & Charges

Contract Signature

(If driver is not the policyholder)

Gate & Tunnel

Reporting Certain Personnel's Signatures

Abstract

STATIONED NO. 3

3/10/18.

Accident Sketch Plan Pg. 1

Statement by Sau Wee Wee (Driver of Vehicle SGL 8747E)

On 2 Oct 2018 at around 2.35pm, I (vehicle number SGL 8747E, Toyota Vios) exited ECP Marine Vista, going towards the slip road to exit to Marine Parade

ERROR DETECTED PAGE

Notice Of Accident

Date : 3-Oct-2018

WITHOUT PREJUDICE

Our ref : SGL8747E

Your ref : SLH2956U

To :
China Taiping Insurance (S) Pte Ltd

3 Anson Rd

#16-00 Springleaf Tower

Singapore 079909

Attn : Motor Claims Department

Dear Sir/ Madam,

CLAIMANT: SAU WEE WEE

**ACCIDENT INVOLVING SGL8747E & SLH2956U ON 4 AUGUST 2017 ALONG SLIP ROAD
MARINE VISTA - MARINE PARADE RD AT ABOUT 1435HRS**

We are instructed by Sau Wee Wee to notify you (the insured of SGL8747E) of a road accident on 2 Oct 2018 at along MARINE VISTA - MARINE PARADE RD at about 1435hrs involving our client's vehicle registration number SGL8747E and vehicle registration number SLH2956U driven by your insured at the material time.

As a result of the accident, our client's vehicle SGL8747E has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall use independent surveyor as the joint pre-repair survey as a single joint expert and proceed to repair the vehicle without further reference to you.

**Note: Car is at the workshop, location - Block 3020A #01-33 Ubi Road 1,
Singapore 408714**

Your faithfully,

CK. Tan
Tel : 81862100

Sin Ho Auto

Block 3020 A #01-33, Ubi Road 1, Singapore 408714

Tel (HP): 81862100 (Ah Tan) Fax: 6743 1964

Email: ck.tan888@live.com.sg

Customer Vehicle detail

Car Number : SGL8747E Car Model : Toyota Vios
Chassis Number : MR2B23F3301132081 Registration Year : 29-Jun-2018
Engine Number : 2NR5236675
Insurance Company : AXA Insurance Singapore Pte Ltd

TP Chinn. Janice.

Third Party Vehicle detail

Car Number : SLH2956U Car Model : Toyota Harrier
Insurance Company : China Taiping Insurance Pte Ltd

Estimation of repair cost

Item	Part Description	Qty	Unit Price	Price
1	Rear bootlid <i>Dented</i>	1	\$ 887.40	\$ 887.40 ✓
2	Rear bootlid hinge LH <i>3 new</i>	1	\$ 95.50	\$ 95.50 x
3	Rear bootlid hinge RH	1	\$ 95.50	\$ 95.50 x
4	Rear bootlid emblem "Toyota logo" <i>3 new</i>	1	\$ 77.30	\$ 77.30 ✓
5	Rear bootlid emblem "VIOS"	1	\$ 65.80	\$ 65.80 ✓
6	Rear bootlid emblem "E"	1	\$ 58.70	\$ 58.70 ✓
7	Rear bootlid garnish <i>new</i>	1	\$ 172.30	\$ 172.30 +
8	Rear bootlid lock <i>Dented</i>	1	\$ 121.50	\$ 121.50 ✓
9	Rear bootlid rubber <i>at</i>	1	\$ 154.20	\$ 154.20 ✓
10	Rear bootlid lamp LH <i>new</i>	1	\$ 221.50	\$ 221.50 x
11	Rear bootlid lamp RH <i>cracked</i>	1	\$ 221.50	\$ 221.50 ✓
12	Tail lamp RH <i>cracked</i>	1	\$ 457.30	\$ 457.30 ✓ 395
13	Rear bumper <i>Dented</i>	1	\$ 988.70	\$ 988.70 ✓ 5110
14	Clip, rear bumper <i>new</i>	10	\$ 3.00	\$ 30.00 ✓
15	Rear bumper side retainer LH <i>3 new</i>	1	\$ 59.70	\$ 59.70 ✓
16	Rear bumper side retainer RH	1	\$ 59.70	\$ 59.70 ✓
17	Rear bumper inner bracket LH <i>new</i>	1	\$ 52.10	\$ 52.10 x
18	Rear bumper inner bracket RH <i>Dented</i>	1	\$ 52.10	\$ 52.10 ✓
19	Rear end panel <i>Dented</i>	1	\$ 652.50	\$ 652.50 ✓
20	Rear end panel top garnish <i>Dented</i>	1	\$ 78.50	\$ 78.50 ✓
Sub Total				\$ 4,601.80
Less 25%				\$ 1,150.45
Total				\$ 3,451.35
Special Nett item				
1	Supply 1 set of reverse sensor <i>Dented</i>	1	\$ 250.00	\$ 250.00 ✓ 250
2	End panel sealant kit <i>new</i>	1	\$ 50.00	\$ 50.00 ✓
3	Boot lid sealant kit	1	\$ 40.00	\$ 40.00 x
4	Supply rear license plate <i>3 new</i>	1	\$ 45.00	\$ 45.00 x
Total				\$ 385.00

250

Labour

1	Remove & reinstall rear upholstery to facilitate repair	\$ 120.00 60.
2	Remove & replace reverse sensor.	\$ 50.00 ✓
3	Set up vehicle on puller work bench to facilitate repair	\$ 350.00 X
4	Remove & replace damage parts. Pull, cut & weld on rear end panel and extension sidemember. Repair, pull and strenghten rear floor panel and both rear fender panel. Adjust and align body gap.	\$ 1,200.00 800
5	Supply paint material, labour and equipment to carry out spray paint work on LH & RH rear fender, rear bootlid, rear bumper, rear end panel, rear floor panel. Carry out preparation work of sanding, masking and putty filling before spray paint; and polishing after spray painting (Paint system: 2K solvent base)	\$ 1,200.00 800
6	Transfer boot lid mechanism and wiring onto replacement panel	\$ 100.00 60.
7	Apply rust coating on affecting area	\$ 50.00 40.
8	Check lightings, wiring and light socket connection.	\$ 40.00 30

Total \$ 3,110.00

Grand Total \$ 6,946.35

Remarks:

1. Survey location : No. 1 Kaki Bukit Ave 6 #01-107 Autobay@Kaki Bukit Singapore 417883
2. Contact person : Adrian Ho - 9036 6145

Adrian

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4658.75.

h/s: 3.7K

06 Days






































...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Oct 2018		03 Oct 2018 15:16 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: SAU WEE WEE									
Vehicle Reg. No.: SGL8747E		Date of Loss: 02/10/2018 00:00 - :59 [3 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04742C02		Policy/Cover Note No.: DMPCSN1675091701							
Vehicle Reg. No. (Insured): SLH2956U		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/10/2018]									
Adj Asg. Remarks: NO EST, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGL8747E (SNM18D04742C02)
[SLH2956U]
TP
SAU WEE WEE
Oct 2 2018 12:00AM
[-]
Ho Beng Trading

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
17	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
18	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
19	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
20	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
21	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
22	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
23	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
24	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
25	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
26	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
27	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
28	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
29	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
30	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
31	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
32	25/02/19 15:27	General View						 Load JPG	<input checked="" type="checkbox"/>	
33	25/02/19 15:27	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>	
34	25/02/19 15:27	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>	
35	25/02/19 15:27	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>	
36	25/02/19 15:27	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>	
37	25/02/19 15:27	Reinspection Photo						 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	25/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	25/02/19 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/10/18 15:16	PRS WITH TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017931/ACD3E2

Date: 26/02/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1675091701

Claimant Vehicle
No: SGL8747EInsured Vehicle
No: SLH2956U

Date of Loss: 02/10/2018

Nature of Claim: TP

Claim
No: SNM18D04742C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL8747E

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 2NR5236675

Reg. Date: 29/06/2018 (Man. Year: 2018)

Chassis No: MR2B23F3301132081

Colour: Silver

Odometer: 1237 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,836.35	2,818.75	1,017.60	26.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,840.00	1,270.00	40.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,946.35	4,658.75	2,287.60	32.93
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	6,946.35	3,700.00	3,246.35	46.73

INSPECTION

Date of Assignment: 03/10/2018

Date Inspected: 04/10/2018 Inspected At:

Ho Beng Trading (HQ)
Blk 3020A #01-33, Ubi Road 1
Singapore 408714

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL8747E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	887.40 FL	*887.40 FL
2	1		*REAR BOOTLID HINGE LH	Not Necessary	95.50 FL	*- FL
3	1		*REAR BOOTLID HINGE RH	Not Necessary	95.50 FL	*- FL
4	1		*REAR BOOTLID EMBLEM TOYOTA LOGO	Necessary	77.30 FL	*77.30 FL
5	1		*REAR BOOTLID EMBLEM VIOS	Necessary	65.80 FL	*65.80 FL
6	1		*REAR BOOTLID EMBLEM E	Necessary	58.70 FL	*58.70 FL
7	1		*REAR BOOTLID GARNISH	Not Necessary	172.30 FL	*- FL
8	1		*REAR BOOTLID LOCK	Damaged	121.50 FL	*121.50 FL
9	1		*REAR BOOTLID RUBBER	Cut	154.20 FL	*154.20 FL
10	1		*REAR BOOTLID LAMP LH	Not Necessary	221.50 FL	*- FL
11	1		*REAR BOOTLID LAMP RH	Cracked	221.50 FL	*221.50 FL
12	1		*TAIL LAMP RH	Cracked	457.30 FL	*395.00 FL
13	1		*REAR BUMPER	Deformed	988.70 FL	*511.10 FL
14	10		*CLIP, REAR BUMPER	Necessary	30.00 FL	*30.00 FL
15	1		*REAR BUMPER SIDE RETAINER LH	Necessary	59.70 FL	*59.70 FL
16	1		*REAR BUMPER SIDE RETAINER RH	Necessary	59.70 FL	*59.70 FL
17	1		*REAR BUMPER INNER BRACKET LH	Not Necessary	52.10 FL	*- FL
18	1		*REAR BUMPER INNER BRACKET RH	Dented	52.10 FL	*52.10 FL
19	1		*REAR END PANEL	Dented	652.50 FL	*652.50 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	78.50 FL	*78.50 FL
21	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
22	1		*END PANEL SEALANT KIT	Necessary	50.00 FS	*50.00 FS
23	1		*BOOT LID SEALANT KIT	Not Necessary	40.00 FS	*- FS
24	1		*REAR LICENSE PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,986.80	3,675.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,150.45	856.25
Total Parts (S\$)	3,836.35	2,818.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE REVERSE SENSOR	New	50.00	50.00
2	SET UP VEHICLE ON PULLER WORK BENCH TO FACILITATE REPAIR	New	350.00	0.00
3	REMOVE & REPLACE DAMAGE PARTS. PULL, CUT & WELD ON REAR END PANEL AND EXTENSION SIDEMEMBER. REPAIR, PULL AND STRENGTHEN REAR FLOOR PANEL AND BOTH REAR FENDER PANEL ADJUST AND ALIGN BODY GAP	New	1,200.00	800.00
4	SUPPLY PAINT MATERIAL, LABOUR AND EQUIPMENT TO CARRY OUT SPRAY PAINT WORK ON LH & RH REAR FENDER, REAR BOOTLID, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, CARRY OUT PREPARATION WORK OF SANDING, MASKING AND PUTTY FILLING BEFORE SPRAY PAINT, AND POLISHING AFTER SPRAY PAINTING (PAINT SYSTEM: 2K SOLVENT BASE)	New	1,200.00	800.00
5	TRANSFER BOOT LID MECHANISM AND WIRING ONTO REPLACEMENT PANEL	New	100.00	60.00
6	APPLY RUST COATING ON AFFECTING AREA	New	50.00	40.00
7	CHECK LIGHTINGS, WIRING AND LIGHT SOCKER CONNECTION	New	40.00	30.00
8	REMOVE & REINSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
Gross Labour Cost (S\$)			3,110.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >