



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM: SLN 9448 S
MAKE & MODEL: MITSUBISHI OUTLANDER
MILEAGE:
TYRE:
CHASSIS NUM:

4/10/18
not allowed
12/5/18 12:00
the other 12/5/18

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR TAILGATE 300500 —		984.00 —
2	REAR TAILGATE WINDSCREEN MOULDING ne —		111.00 —
3	REAR TAILGATE CHROME Cne —		466.00 —
4	REAR TAILGATE LOGO ne —		39.00 —
5	REAR TAILGATE EMBLEM 'OUTLANDER' ne —		86.00 —
6	REAR TAILGATE EMBLEM 'C&C' ne —		32.00 —
7	REAR TAILGATE LAMP L+R @397.00 cne —		794.00 —
8	REAR TAILGATE GARNISH L+R @66.00 25 X		132.00 X
9	REAR TAILGATE SWITCH 11 X		65.00 X
10	REAR TAILGATE INNER TRIM TOP 11 X		260.00 X
11	REAR TAILGATE INNER TRIM BOTTOM 11 X		158.00 X
12	REAR TAILGATE DAMPER L+R 11 X		182.00 X
13	REAR TAILGATE WIPER MOTOR 11 X		314.00 X
14	REAR TAILGATE WEATHERSTRIP 2w1 —		192.00 —
15	REAR TAILGATE LOCK 20/shld —		428.00 —
16	REAR TAILGATE INNER SWITCH 11 X		65.00 X
17	REAR TAILGATE INNER HANDLE 11 X		182.00 X
18	TAILLAMP L+R @563.00 11 X		1126.00 X
19	TAILLAMP PANEL L+R 2 X		78.00 X
20	REAR BUMPER 115 —		873.00 —
21	REAR BUMPER REFLECTOR L+R @50.50 cne/4m1 —		101.00 —
22	REAR BUMPER REINFORCEMENT BAR 3rd —		255.00 —
23	REAR BUMPER RETAINER L+R @20.00 2nd —		40.00 —
24	REAR BUMPER BRACKET L+R 3rd —		71.00 —
25	REAR BUMPER SPONGE 25 X		— X
25	REAR FENDER 2 X		1165.00 X
26	REAR FENDER INNER TRIM 11 X		802.00 X
27	REAR FENDER COWLING 11 X		30.00 X
28	END PANEL 300500 —		469.00 —
29	END PANEL TOP GARNISH 2w1 —		192.00 —
30	REAR EXHAUST PIPE 2 X		548.00 X
31	REAR EXHAUST MOUNTING 11 X		20.00 X
32	REAR EXHAUST GASKET 11 X		20.00 X
33	REAR EXHAUST HEAT SEAL 11 X		69.00 X
30	FLOOR PANEL 2 X		714.00 X
31	FLOOR PANEL TOP BOARD 11 X		266.00 X
32	FRONT BONNET 3rd —		997.00 —
33	FRONT BONNET EMBLEM ne —		86.00 —
34	FRONT GRILLE LOGO cna —		41.00 —

35	FRONT GRILLE CHROME	cna ✓		571.00 ✓
36	FRONT GRILLE BASE	NS X		— X
37	HEADLAMP L+R	holder cna ✓ @1670.00		3340.00 ✓
37	FRONT BUMPER	Dis ✓		855.00 ✓
38	FRONT BUMPER GRILLE	Turn ✓		299.00 ✓
39	FRONT BUMPER	Replaced X		X
40	FRONT BUMPER FOG LAMP GRILLE	cna ✓		71.00 ✓
41	FRONT BUMPER FOG LAMP	11 X		393.00 X
42	FRONT BUMPER FOG LAMP GRILLE CHROME	cm ✓		35.00 ✓
43	FRONT BUMPER SIDE CHROME SET L+R	cm ✓ @198.00		396.00 ✓
44	FRONT BUMPER LOWER	DO/DE		334.00 ✓
45	FRONT BUMPER REINFORCEMENT BAR	Bul ✓		671.00 ✓
46	FRONT BUMPER SPONGE	NS X		— X
47	FRONT BUMPER	Replaced X		855.00 X
48	FRONT FENDER L+R	2 X @663.00		1326.00 X
49	FRONT FENDER COWLING L+R	11 X @148.00		296.00 X
50	FRONT SUPPORT PANEL	DO/DE ✓		622.00 ✓
51	AIR CON CONDENSER	Bent/cna ✓		945.00 ✓
52	RADIATOR	SNX		984.00 X
53	RADIATOR FAN COWLING	11 X		233.00 X
	front bumper top retainer	Bent ✓		182.00 ✓
		P-14578		
		50%		
		7289.00	SDP	
			SUBTOTAL	\$ -
			LESS 10%	\$ -
			PARTS TOTAL	\$ -
SPECIAL NETT			QTY	PRICE
1	FRONT NUMBER PLATE	Bent 40	1	\$ 120.00
2	REAR NUMBER PLATE	11 X	1	\$ 120.00
3	REAR WINDSCREEN SEALANT	new 40	1	\$ 120.00
4	REVERSE SENSOR	shrub 200	4	\$ 600.00
5	REVERSE CAM	shrub 350	1	\$ 850.00
6	REAR END PANEL SEALANT	new 50	1	\$ 120.00
7	SPARE WHEEL PANEL SEALANT	11 X	1	\$ 120.00
8	RADIATOR COOLANT	new 30	1	\$ 120.00
9	FRONT BUMPER CLIPS	new 50	10	\$ 100.00
10	FRONT FENDER COWLING CLIPS	11 X	10	\$ 100.00
11	REAR BUMPER CLIPS	new 50	10	\$ 100.00
12	REAR FENDER COWLING CLIPS	11 X	10	\$ 100.00
13	REAR FENDER INNER TRIM CLIPS	11 X	10	\$ 100.00
14	BOOTLID INNER TRIM CLIPS	11 X	10	\$ 100.00
		810		
			SPECIAL NETT TOTAL	\$ 2,770.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1500	1	\$ 4,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	1	\$ 3,000.00

[illegible]

P - 7289.00
S.N + 810.00
Labour + 3930.00

12029