




Accident Photo



Accident Photo



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1130/2018/GW
Date : 27-Sep-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kathikeyan S/O Puniamoorthy
Address : 4 Cashew Terrace
Singapore 679542
Telephone : HP +65 91288996
Type of Claim : Own Damage Claims
Policy No. : 1700073452
Vehicle No : **SBG 388 X**
Model Code : Audi A5 SB 2.0 TFSI S- Tronic
Model / Year : Nov-17
Engine No : CVK 048464
Chassis No : WAUZZZF6JA040600
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Sep-18
Place of Accident : North-South Expressway 33 KM Marker Towards JB

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBG 388 X

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	/ ✓
2	To dismantle and renew rear bumper. Re-organise rear crash managemen components. Reinstall all parts removed.	\$ 1,050.00	550 500 ✓
3	To respray rear bumper.	\$ 900.00	550 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 388 X.

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remark
1	REAR BUMPER / TN	\$ 2,190.00	1752
2	REAR BUMPER FIXING PARTS ? x NN	\$ 142.00	
3	REAR BUMPER TRIM / LT	\$ 878.00	702
4	REAR BUMPER SECURING STRIP ? x NN	\$ 191.00	152.80
5	REAR BUMPER INNER CLIP ? x NN	11 \$ 407.00	
6	REAR BUMPER OUTER CLIP ? x NN	4 \$ 148.00	
7	REAR LIGHT REFLECTOR-LH/RH X NN	2 \$ 70.00	
8	REAR BUMPER CARRIER ? x	\$ 786.00	
9	REAR BUMPER SEAL ? x	2 \$ 24.00	
10	REAR BUMPER GUIDE SECTION-LH/RH ? x NN	2 \$ 74.00	
11	REAR BUMPER UPPER GUDIE SECTION-LH/RH ? x NN	2 \$ 38.00	
12	REAR BUMPER SENSOR X	2 \$ 421.00	
13	REAR BUMPER SENSOR SEAL RING X NN	4 \$ 14.00	
14	SUNDRIES ? x NN	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 5,683.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 8,185.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Lim Qiang - 82880282*
Surveyed Date : *03/10/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *before paint photos.  3/10/18*
~~Not~~ Authorised.
3 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1130/2018/GW
Date : 27-Sep-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang

3 days - ok - JB - 15 Jan 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kathikeyan S/O Puniamoorthy
Address : 4 Cashew Terrace
Singapore 679542
Telephone : HP +65 91288996
Type of Claim : Own Damage Claims
Policy No. : 1700073452
Vehicle No : **SBG 388 X**
Model Code : Audi A5 SB 2.0 TFSI S- Tronic
Model / Year : Nov-17
Engine No : CVK 048464
Chassis No : WAUZZZF6JA040600
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Sep-18
Place of Accident : North-South Expressway 33 KM Marker Towards JB

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBG 388 X

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash managemen components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
3	To respray rear bumper.	\$	900.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		∴ \$	2,502.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 388 X.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,190.00	\$ 1,752.00
2	REAR BUMPER FIXING PARTS	\$ 142.00	
3	REAR BUMPER TRIM	\$ 878.00	\$ 702.00
4	REAR BUMPER SECURING STRIP (NEC)	\$ 191.00	\$ 152.80
5	REAR BUMPER INNER CLIP	11 \$ 407.00	
6	REAR BUMPER OUTER CLIP	4 \$ 148.00	
7	REAR LIGHT REFLECTOR-LH/RH	2 \$ 70.00	
8	REAR BUMPER CARRIER	\$ 786.00	
9	REAR BUMPER SEAL	2 \$ 24.00	
10	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 74.00	
11	REAR BUMPER UPPER GUDIE SECTION-LH/RH	2 \$ 38.00	
12	REAR BUMPER SENSOR	2 \$ 421.00	
13	REAR BUMPER SENSOR SEAL RING	4 \$ 14.00	
14	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 5,683.00	\$ 2,606.80
TOTAL LABOUR CHARGES		\$ 2,502.00	\$ 1,602.00
GRAND TOTAL		\$ 8,185.00	\$ 4,208.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 17 January 2019 9:23 AM
To: 'Boo seng yak'; Guo Qiang (LKKAuto); SUR; Carrine Leong;
jjayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SBG388X - OD AIG - SURVEYED 3 OCT 18

Dear Mr Boo,

Confirm repair cost of \$4,208.80 before excess \$600 and GST @ 3 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, 15 January 2019 6:08 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong
<carrine.leong@premiumauto.com.sg>; jjayee.yap@premiumauto.com.sg; Chang Chee Sing
<claims@premiumauto.com.sg>
Subject: FINAL REVISION - SBG388X - OD AIG - SURVEYED 3 OCT 18

Hi Guo Qiang and all,

Revised estimate is attached.

Please confirm repair cost of \$4208.80 @ 3 days

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SBG 388 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1130/2018/MAS

15 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SBG 388 X, Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SBG 388 X**, claimant, **Mr. Karthikeyan S/o Puniamoorthy**, please find the related document per attached.

1. A copy of the Original invoice no. 85013432 – S\$3,861.42
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SBG 388 X

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
 281 Alexandra Road,
 Singapore 159938
 Main Telephone: 6836 2223
 Main Telefax: 6471 3733

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone: 6388 2223
 Telefax: 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408609
 Telephone: 6388 3333

Customer Service
 Service Appointment
 24-hour Breakdown Service
 Email: customer.care@premiumauto.com.sg
 6366 2223
 9628 1233

INSURANCE INVOICE
 Company Reg. No. 199902271W
 GST Reg. No. 199902271W

Page 1 18:13

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013432 Date: 11/02/2019 Order: SBG0388X Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SBG0388X (V 35706) Regn Date: 13/11/2017 Mileage: 23617 WIP No.: 26509
 Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF56JA040600 Engine: CVK 048464 Dept: U
 VSB No.:
 You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W6807067N GRU	COVER	1.00	2190.00	1,752.00
X	A8W6807900	STRIP	1.00	191.00	152.00
X	A8W6853551A 2ZZ	(A) (SK)MOLDING(09/10)	1.00	877.50	702.00

Parts	2,606.00	Sub-Total	3,608.80
Labour	0.00	7% GST	252.62
Sublet	1,602.00	Grand Total	3,861.42
Menus	0.00		
Lubricant	0.00		

Received by

For & on behalf of
 Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SBG 388 X

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1130/2018/KS
9TH January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SPORTSBACK 2.0 TFSI
Vehicle Chassis No. : WAUZZZF56JA040600
Vehicle Regn No. : **SBG 388 X**
Vehicle Mileage : 26509 KM
Vehicle Owner : Mr. Karthikeyan S/O Puniamoorthy
Certificate No : 1700073452
Own Damage Excess : **S\$ 642.00 (Inclusive 7% GST)**
Accident Date : 23/9/2018
Place : North-south Expressway (Malaysia)
Repair Cost : \$ 3,861.42
WIP No. : 26509
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

9/1/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Sep 2018		04 Oct 2018 10:24 Edit Adj Rpt	S\$4,208.80 Edit Estimates	S\$4,208.80 View Rpt		Pending for Survey Report Cancel Case

Main
Reference
Claim Details
Documents
[Show All](#)

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured: **KARTHIKEYAN S/O PUNIAMOORTHY**, ID: S8609924A, Tel: +6591288996, Email: kart0022@gmail.com

Vehicle Reg. No.: SBG388X	Date of Loss: 23/09/2018 17:00 - :59 [10 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 5648865109SG	Policy/Cover Note No.: 1700073452 (Comprehensive)
	Excess: S\$600.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Loo, Tong Shing**] TongShing.Loo@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... **[Final Rpt due 15/10/2018]**

Driver/Custodian: **KARTHIKEYAN S/O PUNIAMOORTHY** (32 / Male), NRIC: S8609924A, Tel: +6591288996

[View All](#)
[Compose Case Mail](#)

- ASSOCIATED MAIL RECEIVED**
- AIG_SG (16/10/2018): **SBG388X / OD / 23/09/2018 / Coverage & Excess update**
 - AIG_SG (10/10/2018): **SBG388X / OD / 23/09/2018 / Coverage & Excess update**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBG388X (5648865109SG)
OD
Sep 23 2018 5:45PM
[KARTHIKEYAN S/O PUNIAMOORTHY]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼
			1 per page ▼ <input checked="" type="checkbox"/>
Video			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	11/10/18 08:01	Video - Accident	<input checked="" type="checkbox"/> Load MP4
			3 per page ▼ <input checked="" type="checkbox"/>
Photos/Images			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
2	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
3	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
4	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
5	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
6	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
7	04/10/18 13:04	General View	<input checked="" type="checkbox"/> Load JPG
8	04/10/18 13:04	Chassis Number	<input checked="" type="checkbox"/> Load JPG
9	04/10/18 13:04	Odometer Reading	<input checked="" type="checkbox"/> Load JPG
			1 per page ▼ <input checked="" type="checkbox"/>
Documentation			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail
1	04/10/18 11:13	Singapore Accident Statement	<input checked="" type="checkbox"/> Load PDF
2	04/10/18 11:14	Police Report	<input checked="" type="checkbox"/> Load PDF
3	04/10/18 11:14	MARK ESTIMATE	<input checked="" type="checkbox"/> Load PDF
4	08/10/18 12:31	Certificate of Insurance	<input checked="" type="checkbox"/> Load PDF
5	10/10/18 14:31	Driver's Driving License	<input checked="" type="checkbox"/> Load JPG
6	20/02/19 17:10	DISCHARGE VOUCHER	<input checked="" type="checkbox"/> Load PDF
7	20/02/19 17:10	WORKSHOP INVOICE	<input checked="" type="checkbox"/> Load PDF

Linked Accident Report Documents

			View View in Browser ▼
			1 per page ▼ <input checked="" type="checkbox"/>
Assessment Reports			
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail
1	25/09/18 21:06	Accident Statement	<input checked="" type="checkbox"/> Load HTM
			3 per page ▼ <input checked="" type="checkbox"/>
Photos/Images			
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail
1	25/09/18 15:00	Police Report	<input checked="" type="checkbox"/> Load JPG
2	25/09/18 15:00	Police Report	<input checked="" type="checkbox"/> Load JPG
3	25/09/18 15:00	Police Report	<input checked="" type="checkbox"/> Load JPG
4	25/09/18 15:00	Police Report	<input checked="" type="checkbox"/> Load JPG
5	25/09/18 15:00	Police Report	<input checked="" type="checkbox"/> Load JPG
6	25/09/18 15:19	Accident Photo	<input checked="" type="checkbox"/> Load JPG

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
7	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 15:19	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	25/09/18 14:59	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 14:59	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 14:59	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18017978/GVBS2
Date: 20/02/2019

REFERENCE

Insured/Claimant: KARTHIKEYAN S/O PUNIAMOORTHY Policy No: 1700073452
Date of Loss: 23/09/2018 Nature of Claim: OD Claim No: 5648865109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBG388X** Engine No: CVK048464
Make & Model: AUDI A5, 2.0 SPORTBACK (A) Chassis No: WAUZZZF56JA040600
Reg. Date: 13/11/2017 (Man. Year: 2017) Odometer: 18701 km
Colour: Black
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$182,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35ZR19 Rear Tyre Size: 255/35ZR19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,683.00	2,606.80	3,076.20	54.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,185.00	4,208.80	3,976.20	48.58
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,585.00	3,608.80	3,976.20	52.42
+ GST 7.00/7.00% (S\$)	530.95	252.62	278.33	52.42
Nett Amount (S\$)	8,115.95	3,861.42	4,254.53	52.42

INSPECTION

Date of Assignment: 04/10/2018
Date Inspected: 03/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Torn	2,190.00 FS	*1,752.00 FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	142.00 FS	*- FS	
3	1		*REAR BUMPER TRIM	Cut	878.00 FS	*702.00 FS	
4	1		*REAR BUMPER SECURING STRIP	Necessary	191.00 FS	*152.80 FS	
5	11		*REAR BUMPER INNER CLIP	Not Necessary	407.00 FS	*- FS	
6	4		*REAR BUMPER OUTER CLIP	Not Necessary	148.00 FS	*- FS	
7	2		*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS	
8	1		*REAR BUMPER CARRIER	Not Necessary	786.00 FS	*- FS	
9	2		*REAR BUMPER SEAL	Not Necessary	24.00 FS	*- FS	
10	2		*REAR BUMPER GUIDE SECTION - LH/RH	Not Necessary	74.00 FS	*- FS	
11	2		*REAR BUMPER UPPER GUIDE SECTION - LH/RH	Not Necessary	38.00 FS	*- FS	
12	2		*REAR BUMPER SENSOR	Not Necessary	421.00 FS	*- FS	
13	4		*REAR BUMPER SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS	
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS	
					Total Parts (S\$)	5,683.00	2,606.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER.	New	900.00	550.00
4	TO CARRY OUR DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >