

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1130/2018/GW
Date : 27-Sep-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kathikeyan S/O Puniamoorthy
Address : 4 Cashew Terrace
Singapore 679542
Telephone : HP +65 91288996
Type of Claim : Own Damage Claims
Policy No. : 1700073452
Vehicle No : **SBG 388 X**
Model Code : Audi A5 SB 2.0 TFSI S- Tronic
Model / Year : Nov-17
Engine No : CVK 048464
Chassis No : WAUZZZF6JA040600
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Sep-18
Place of Accident : North-South Expressway 33 KM Marker Towards JB

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBG 388 X

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	/
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	550 500
3	To respray rear bumper.	\$ 900.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 2,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 388 X.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER / TN	\$ 2,190.00	
2	REAR BUMPER FIXING PARTS ?	\$ 142.00	
3	REAR BUMPER TRIM / GT	\$ 878.00	
4	REAR BUMPER SECURING STRIP ?	\$ 191.00	
5	REAR BUMPER INNER CLIP ?	11 \$ 407.00	
6	REAR BUMPER OUTER CLIP ?	4 \$ 148.00	
7	REAR LIGHT REFLECTOR-LH/RH X NN	2 \$ 70.00	
8	REAR BUMPER CARRIER ?	\$ 786.00	
9	REAR BUMPER SEAL ?	2 \$ 24.00	
10	REAR BUMPER GUIDE SECTION-LH/RH ?	2 \$ 74.00	
11	REAR BUMPER UPPER GUDIE SECTION-LH/RH ?	2 \$ 38.00	
12	REAR BUMPER SENSOR X	2 \$ 421.00	
13	REAR BUMPER SENSOR SEAL RING X {NN}	4 \$ 14.00	
14	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 5,683.00	
TOTAL LABOUR CHARGES		: \$ 2,502.00	
GRAND TOTAL		: \$ 8,185.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Lim Qiang - 82880282*
Surveyed Date : *03/10/18*
Authorised Date :
Excess Cost :
Liability : *before paint photos*
Remarks : *~~Not~~ Authorised*

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant