

22/03/2002

ASS. REC. BY:

REF:

CS/FCI1807986/Gqd307

Special Instruction:

Surveyor:

CWS

Gino Diana

ASSIGNMENT (Office)

From (Person):

Lurane juw

of

FCI

Date/Time:

3/10/18 @ 7:50pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5876X

Insured:

SHA 0649D

at Workshop m/s

Trans-Cab Auto

Tel:

6287 6666

of

No. 2 AMK St. 63

Policy No:

Claim No:

D18067254MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/10/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

9:03am @ 4/10/18

Person Contacted:

Zhe Wei

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHC 5876X-CC4/ASM18017911/wb3

DOA: 2/10/18

SHA 649D-CC4/ASM18017911/wb3

DOA: 2/10/18

05/10/18 @ 1:52pm revised to Lurane by email.

Lump Sum

\$82501- (Red:

37,411,71, 81%)

Surveillance

XHE

REF: FCI

3878K

ASSIGNMENT

From: Date: 4/10/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5876X

at Workshop m/s

of No. 2 AMK St-63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. f 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC5876X Yr Regn: 26 Jun 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / @ Prime Mover /

Truck / Trailer or

Make: Renault latitude c.c 1995

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 267180 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VFIABL15AUC 281589

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 04-10-18

Survey held at w/s 5:18pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 8250

350

350

MOTOR SURVEY ASSIGNMENT

Date	03-10-2018	Our Ref No. D18007254MFSH
Accident Date	02-10-2018	Claim Type. Third Party
Insured Vehicle	SHA0649D	Third Party Vehicle. SHC5876X
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 5 October 2018 1:52 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007254MFSH/1
Attachments: CSFCI18017986Gqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHC 5876X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 4 October 2018 9:09 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007254MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 3 October 2018 7:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007254MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

Denise Tay (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 1 April 2019 8:08 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao Cai Jie'; assignments
Subject: RE: REQUEST OF SURVEY REPORT-OUR REF:D18007254MFSH;ACCIDENT INVOLVING SHA0649D AND SHC5876X ON 02-10-2018

Dear Sir/Mdm,

Thank you for the email.

Dear Shiau Chan,

Kindly assist

FYNA Our Ref : CS/FCI18017986/Gqd3

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Sunday, 31 March 2019 8:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: REQUEST OF SURVEY REPORT-OUR REF:D18007254MFSH;ACCIDENT INVOLVING SHA0649D AND SHC5876X ON 02-10-2018

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards,
Motor Claims Department
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007254MFSH
Our Ref: CS/FCI18017986/Gqd3

Date: 05 October 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5876X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/10/2018 at the premises of M/s TRANS CAB . and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 53,863.02</u> .
Revised Estimate Amount	: <u>S\$ 10,686.06</u> .
"Check" Items Amount	: <u>S\$ 12,449.77</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the n/s portion. The undercarriage affected due to collision.



Yours faithfully

Guo Qiang
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5876X

Vehicle to be Exported: Yes

Intended Deregistration Date: 02 Oct 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002820

Chassis No.: VF1ABL15AUC281589

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 26 Jun 2015

First Registration Date: 26 Jun 2015

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Jun 2023

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$52,886.00

COE Rebate Amount: \$31,272.00

Total Rebate Amount: \$40,645.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/10/2018 10:29
Date Of Accident	02/10/2018 02:00
Exact Location Of Accident	JUNCTION OF BT BATOK WEST AVE 2 & BT BATOK CENTRAL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC5876X
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	KER SIONG LIM
NRIC No	S1238792Z
Date Of Birth	26/06/1957
Occupation	OUTDOOR
Date Of Driving Pass	26/11/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83177980
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 210A BUKIT BATOK STREET 21 #03-292
Postcode	651210
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 02/10/18 AT ABOUT 0200HRS I WAS TRAVELLING STRAIGHT ALONG BUKIT BATOK WEST AVE 2, THE TRAFFIC LIGHT AT THE JUNCTION WAS GREEN IN MY FAVOR SO I PROCEED. SUDDENLY I FELT A STRONG IMPACT ON THE LEFT SIDE OF MY TAXI. VEHICLE B(SHA649D) HAD COME OUT FROM BUKIT BATOK CENTRAL AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA649D
Vehicle Make/Model/Colour	CITY CAB
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Hand-drawn map of the Batok area. A vertical line is labeled "Batok West Ave" and a horizontal line is labeled "Batok Cent". A circle is drawn at the intersection, with an arrow pointing to it from the text "Batok Cent". There are also arrows pointing to the intersection from the text "SHA 649D" and "SHA 5876x".

Refer to GIA Report.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd**A 01810-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5876X

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5876X

VF1ABL15AUC281589

RENAULT

LATITUDE

2.10.2018

FCIL

PART		LIST	
1	DOOR PANEL REAR LH / <i>buc</i>	\$	2,844.66
1	DOOR GUIDE REAR LH <i>X NN</i>	\$	176.82
1	DOOR HINGE UPPER LH <i>- 501</i>	\$	274.50
1	DOOR HINGE LOWER LH <i>- 501</i>	\$	300.55
1	DOOR CHECK REAR LH <i>X NN</i>	\$	203.06
1	DOOR LOCK REAR LH <i>- 1m</i>	\$	908.75
1	DOOR HANDLE OUTER REAR LH <i>X</i>	\$	126.49
1	DOOR HANDLE CAP REAR LH <i>X</i>	\$	35.52
1	DOOR HANDLE SEAL REAR LH <i>X</i>	\$	7.89
1	DOOR HANDLE COVER REAR LH <i>X</i>	\$	13.22
1	DOOR HANDLE MODULE REAR LH <i>X</i>	\$	133.60
1	DOOR REGULATOR REAR LH <i>X</i>	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH <i>X</i>	\$	893.75
1	DOOR REGULATOR NUT REAR LH <i>X</i>	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y <i>X</i>	\$	6.31
1	DOOR FINISHER REAR LH <i>X</i>	\$	423.10
1	DOOR MOULDING REAR LH <i>X</i>	\$	176.82
1	DOOR MOULDING CLIP L70Y <i>X</i>	\$	5.92
1	DOOR MOULDING SCREW L70Y <i>X</i>	\$	6.91
1	DOOR CASING REAR LH <i>X</i>	\$	1,509.06
1	DOOR WATER SHIELD REAR LH <i>X</i>	\$	30.39
1	DOOR CASING CLIP <i>X</i>	\$	12.63
1	DOOR CASING LIGHT L70Y <i>X</i>	\$	48.74
1	DOOR FINISHER INNER REAR LH <i>X</i>	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH <i>X</i>	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH <i>X</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH <i>X</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH <i>X</i>	\$	20.33
1	DOOR GRAB HANDLE REAR LH <i>X NN</i>	\$	210.96

Trans-cab Auto Services Pte Ltd**AAD1810-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5876X

1	DOOR BLIND REAR LH	X	NN	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH	X	NN	\$	410.66
1	DOOR SEAL REAR LH	X		\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	X	NN	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH	X	NN	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH	X	NN	\$	115.64
1	FENDER PANEL REAR LH	bu c.		\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	X	NN	\$	671.45
1	WHEELARCH REAR LH	X		\$	543.47
1	ROCKER PANEL INNER GARNISH LH	X	NN	\$	466.51
1	ROCKER PANEL INNER LH	X		\$	1,024.79
1	ROCKER PANEL CENTER LH	bu c.		\$	990.25
1	WHEEL HOUSING PANEL REAR LH	X		\$	4,682.09
1	CHASSIS PANEL REAR LH L70Y	X	NN	\$	3,766.43
1	HEADLAMP LH	X		\$	1,184.43
1	BUMPER COVER REAR	X Repair.		\$	1,108.46
1	BUMPER LOWER REAR	X		\$	768.84
1	BUMPER BRACKET CTR REAR	X		\$	113.47
1	BUMPER BRACKET SIDE LH REAR	X	NN	\$	135.97
1	BUMPER RETAINER LH REAR	X		\$	44.99
1	FUEL FLAP L70Y	X		\$	343.57
1	DOOR PANEL FRT LH	X Repair.		\$	2,844.66
				\$	33,911.20
				10% \$	3,391.12
				\$	30,520.08

Special Nett

1	REAR DOOR STICKER '6555 3333'	✓ MCL	\$	80.00
1	DOOR CHECK BOLT ?	{ XNN	\$	22.69
1	DOOR GUIDE SCREW ?		\$	10.85
1	DOOR HINGE BOLT ?		\$	10.85
1	DOOR HINGE NUT RH ?		\$	14.60
1	DOOR CHECK BOLT ?		\$	22.69
1	DOOR CHECK NUT ?		\$	3.75
1	DOOR LOCK SCREW L70Y ?		\$	6.12
1	DOOR CATCH SCREW L70Y ?		\$	10.06
TOTAL			\$	181.63

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5876XLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AAD1810-036

Acknowledged by Repairer

Signature:

Date:

TOTAL PARTS \$ 30,701.71**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1200	6,000.00
Putty and spray painting of the affected portion.	\$	1000	6,000.00
To rust-proofing of the affected areas.	\$	60	170.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	60	380.00
To check steering geometry and computer wheel alignment	\$	60	220.00
To transfer of tire, rim and on wheel balancing.	\$	NN X	170.00
To Check Electrical Lighting Concerned.	\$	30	170.00
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	NN / X	380.00
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	NN / X	380.00
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	60 .	380.00

TOTAL \$ 14,250.00**Over All Total \$ 44,951.71****LUMP SUM (REPAIR DAY)****20 DAYS**

10 Days.

Lumpsum repair

After repair photos

AmoQing - 8288 0882

04/10/18.

53863-01

Trans-cab Auto Services Pte Ltd**AAD1810-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5876X

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5876X

VF1ABL15AUC281589

RENAULT

LATITUDE

2.10.2018

FCIL**SUPPLEMENTARY ESTIMATE**

	PART		LIST
1	KUCKLE ARM REAR LH <i>X NN</i>	\$	736.67
1	BRAKE DISC REAR L70Y <i>X</i>	\$	525.91
1	WHEEL HUB NUT L70Y <i>X NN</i>	\$	51.11
1	WHEEL HUB CAP L70Y <i>X</i>	\$	57.82
1	ABS SENSOR REAR LH <i>X</i>	\$	255.75
1	REAR AXLE L70Y <i>X</i>	\$	4,167.03
1	AXLE ARM LH <i>X</i>	\$	117.22
1	LOWER ARM REAR LH <i>X NN</i>	\$	905.99
1	ABSORBER REAR <i>X NN</i>	\$	389.75
1	STABILIZER BAR REAR LH <i>X NN</i>	\$	604.65
1	BRAKE CALIPER REAR LH <i>X NN</i>	\$	1,300.67
		\$	9,112.57
		10% \$	911.26
		\$	8,201.31

Special Nett

1	REAR LEFT TYRE RIM <i>- cut</i>	\$	150 380.00
1	REAR LEFT TYRE <i>-</i>	\$	100 330.00 <i>X</i>
TOTAL		\$	710.00

43863 02






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017986/Gqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 649D	Veh. Inspected	SHC 5876X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007254MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281589	Colour	RED	
Odometer	267180	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	5 mm	
L/H Front Tyre	215/60 R16	GITI	5 mm	
R/H Rear Tyre	215/60 R16	GITI	5 mm	
L/H Rear Tyre	215/60 R16	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2018	Inspection Date	04/10/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5876X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR PANEL REAR LH	BUCKLED	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	NOT NECESSARY	176.82	-
1	DOOR HINGE UPPER LH	BENT	274.50	274.50
1	DOOR HINGE LOWER LH	BENT	300.55	300.55
1	DOOR CHECK REAR LH	NOT NECESSARY	203.06	-
1	DOOR LOCK REAR LH	JAMMED	908.75	908.75
1	DOOR HANDLE OUTER REAR LH	NOT NECESSARY	126.49	-
1	DOOR HANDLE CAP REAR LH	NOT NECESSARY	35.52	-
1	DOOR HANDLE SEAL REAR LH	NOT NECESSARY	7.89	-
1	DOOR HANDLE COVER REAR LH	NOT NECESSARY	13.22	-
1	DOOR HANDLE MODULE REAR LH	NOT NECESSARY	133.60	-
1	DOOR REGULATOR REAR LH	NOT NECESSARY	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	NOT NECESSARY	893.75	-
1	DOOR REGULATOR NUT REAR LH	NOT NECESSARY	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	NOT NECESSARY	6.31	-
1	DOOR FINISHER REAR LH	NOT NECESSARY	423.10	-
1	DOOR MOULDING REAR LH	NOT NECESSARY	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR LH	NOT NECESSARY	1,509.06	-
1	DOOR WATER SHIELD REAR LH	NOT NECESSARY	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	NOT NECESSARY	48.74	-
1	DOOR FINISHER INNER REAR LH	NOT NECESSARY	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH	NOT NECESSARY	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH	NOT NECESSARY	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	NOT NECESSARY	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	NOT NECESSARY	20.33	-
1	DOOR GRAB HANDLE REAR LH	NOT NECESSARY	210.96	-
1	DOOR BLIND REAR LH	NOT NECESSARY	741.80	-
1	DOOR WHEATHERSTRIP REAR LH	NOT NECESSARY	410.66	-

Report Ref No. CS/FCI18017986/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR SEAL REAR LH	NOT NECESSARY	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH	NOT NECESSARY	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH	NOT NECESSARY	334.69	-
1	DOOR WAIST SEAL INNER REAR LH	NOT NECESSARY	115.64	-
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	NOT NECESSARY	671.45	-
1	WHEELARCH REAR LH	NOT NECESSARY	543.47	-
1	ROCKER PANEL INNER GARNISH LH	NOT NECESSARY	466.51	-
1	ROCKER PANEL INNER LH	NOT NECESSARY	1,024.79	-
1	ROCKER PANEL CENTER LH	BUCKLED	990.25	990.25
1	WHEEL HOUSING PANEL REAR LH	NOT NECESSARY	4,682.09	-
1	CHASSIS PANEL REAR LH L70Y	NOT NECESSARY	3,766.43	-
1	HEADLAMP LH	NOT NECESSARY	1,184.43	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	NOT NECESSARY	768.84	-
1	BUMPER BRACKET CTR REAR	NOT NECESSARY	113.47	-
1	BUMPER BRACKET SIDE LH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER LH REAR	NOT NECESSARY	44.99	-
1	FUEL FLAP L70Y	NOT NECESSARY	343.57	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	KNUCKLE ARM REAR LH (ADDITIONAL)	NOT NECESSARY	736.67	-
1	BRAKE DISC REAR L70Y (ADDITIONAL)	NOT NECESSARY	525.91	-
1	WHEEL HUB NUT L70Y (ADDITIONAL)	NOT NECESSARY	51.11	-
1	WHEEL HUB CAP L70Y (ADDITIONAL)	NOT NECESSARY	57.82	-
1	ABS SENSOR REAR LH (ADDITIONAL)	NOT NECESSARY	255.75	-
1	REAR AXLE L70Y (ADDITIONAL)	NOT NECESSARY	4,167.03	-
1	AXLE ARM LH (ADDITIONAL)	NOT NECESSARY	117.22	-
1	LOWER ARM REAR LH (ADDITIONAL)	NOT NECESSARY	905.99	-
1	ABSORBER REAR (ADDITIONAL)	NOT NECESSARY	389.75	-
1	STABILIZER BAR REAR LH (ADDITIONAL)	NOT NECESSARY	604.65	-
1	BRAKE CALIPER REAR LH (ADDITIONAL)	NOT NECESSARY	1,300.67	-

Report Ref No. CS/FCI18017986/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-4,302.38	-861.78
			38,721.40	7,756.06
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR STICKER '6555 3333' (SN)	NECESSARY	80.00	80.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
1	REAR LEFT TYRE RIM (SN) (ADDITIONAL)	CUT	380.00	150.00
1	REAR LEFT TYRE (ADDITIONAL)	CUT	330.00	100.00
			891.61	330.00
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR AND DOOR PANEL FRT LH.		6,000.00	1,200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,000.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI18017986/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
			14,250.00	2,470.00
GRAND TOTAL			53,863.01	10,556.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,250.00

Report Ref No. CS/FCI18017986/Gqd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.