

ASS. REC. BY:

REF:

CS/GAI18017989/Dsd34

Special Instruction:

Surveyor:

Bryen

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

31/10/18 @ 8.23pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 4295P

Insured:

EY 50P

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

CLMOMVP 000000869

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/10/18

CA / REV / REP. / REV 24 HRS

wup?

H.O.D. Endorsement:

Date/Time:

9:00am @ 4/10/18

Person Contacted:

Lynn

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHA 4295P- NSLINE13023928 / Y/gbc3

DOA: 17/12/2013

EY 50P- CC6/A-XA14022545 / Krm3s2

DOA: 28/11/2014


10/10/18

@ 15:20 p.m. revised PA to Rachel Tan via email.

ASSIGNMENT

08 June 2024

From: _____ Date: _____
 Estimated Cost: _____
 ODI / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Claim Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



Vehicle No: **SHA 4295P** Yr Bought: **2016 / June**
 Type: M/Gar / M/Cycle / Bus / Van / Lorry / **(Car)** Prime Mover /
 Truck / Trailer or
 Make: **Hyundai I40** CC: **1685**
 Color: **Blue** A/C: Insured / Std / HI / HA
 Sp. Reading: **314266** T/A Ratio: Insured / Std / HI / HA
 Eng No: **D4FDGU626550**
 Chassis: **KMHLB41UMGU090152**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brakes: Insured / Jammed / Leaked / Burnt or
 Mod: **(Car)** / S/Rim / STD / R/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: **8** days Res: Yes or No
 Lump Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Tyre Size: F: **205/60R16**
 R: **11**
 BS / DUH / EXNOVA / CY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Hankook**
 Front: _____ Rear: _____
 R/Bal: **S** mm R/Bal: **S** mm
 L/Bal: **S** mm L/Bal: **S** mm
 D.O.A. **02/10/2018** D.O.A. **04/10/2018**
 Survey held at **Ennami AMK**
 Gen. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
Front & Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Validated: IN / OUT

Date / Time	Action / Instruction
20/11/18	Great American EY50P Jiniper 2/S 13400/- with 8 days 7 rev
20/11/18	(\$8,675.80 Red - 39%) Confirmed Ls \$13,400/- @ 8 days with Bryan.

RECEIVED 20 NOV 2018

Date/Time, File Pass by: **20/11/18**
 1) **Typist**
 Date/Time, File Return to: _____
 2) _____
 Report Format: _____
 Lump Sum / L.B.E: (\$ **13,400/- Ls**)
 Days Of Repair: **8**
 Recurvey No. of Trip: **2**
 Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)
 Survey Fee: **450**
 Transportation: **450**
 Phone: _____
 Others: _____

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 22 October 2018 2:10 PM
To: 'Tan, Rachel'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Rachel,

This is a chain collision. The repair cost consist of front and rear damages, we will take note on your insured concern upon finalising.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]
Sent: Sunday, 21 October 2018 6:32 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Hi LKK

Any updates ?

Regards

Rachel Tan

Executive, Claims, Great American Insurance Company

Tel: 6804 7846

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, October 10, 2018 4:56 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: [External] RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Hi Rachel,

We will check and revert.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

Sent: Wednesday, 10 October 2018 3:55 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Hi

Please confirm on damages, \$16K? Our insured vehicle no visible damage.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Wednesday, October 10, 2018 3:20 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: [External] RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Rachel,

Enclosed preliminary revised of vehicle SHA 4295P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Thursday, 4 October 2018 9:11 AM

To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; ASSIGNMENTS@LKKAUTO.COM

Cc: 'SUR' <sur@lkkauto.com>

Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

Sent: Wednesday, 3 October 2018 8:23 PM

To: Chunni Motor <chunnimotor@gmail.com>

Cc: LKK Assignments <assignments@lkkauto.com>

Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

WP

Dear Sir. Noted on your request.

Dear LKK, please accept TP PRI assignment, attached estimates for reference.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Wednesday, October 3, 2018 3:41 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: [External] Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Rachel,

We agree to appoint LKK Auto Consultants P/L

Thank you

Regard,

Chunni Motor Work P/L

On Wed, Oct 3, 2018 at 3:30 PM Tan, Rachel <Rachel.Tan@sg.gaig.com> wrote:

WP

Dear Lynn

As requested, we append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd

5. LKK Auto Consultants

6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Ong, Joanna **On Behalf Of** General Claims

Sent: Wednesday, October 3, 2018 3:22 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: FW: [External] Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Hi Rachel,

FYNA. Thanks.

Joanna

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Wednesday, October 03, 2018 9:25 AM

To: General Claims <GeneralClaims@sg.gaig.com>

Subject: [External] Accident involving veh no: SHA 4295P & EY 50P on 02.10.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.


Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 10 October 2018 3:20 PM
To: 'Tan, Rachel'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869
Attachments: SHA 4295P - Preli Advise .pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SHA 4295P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 4 October 2018 9:11 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; ASSIGNMENTS@LKKAUTO.COM
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]
Sent: Wednesday, 3 October 2018 8:23 PM
To: Chunni Motor <chunnimotor@gmail.com>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

WP

Dear Sir. Noted on your request.

Dear LKK, please accept TP PRI assignment, attached estimates for reference.

Regards
Rachel Tan

Nivitha (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 3 October 2018 8:23 PM
To: Chunni Motor
Cc: LKK Assignments
Subject: RE: Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869
Attachments: 03102018091342.pdf

WP

Dear Sir. Noted on your request.

Dear LKK, please accept TP PRI assignment, attached estimates for reference.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Chunni Motor <chunnimotor@gmail.com>
Sent: Wednesday, October 3, 2018 3:41 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: [External] Re: FW: Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Dear Rachel,

We agree to appoint LKK Auto Consultants P/L

Thank you

Regard,
Chunni Motor Work P/L

On Wed, Oct 3, 2018 at 3:30 PM Tan, Rachel <Rachel.Tan@sg.gaig.com> wrote:

WP

Dear Lynn

As requested, we append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services

4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Ong, Joanna **On Behalf Of** General Claims

Sent: Wednesday, October 3, 2018 3:22 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: FW: [External] Accident involving veh no: SHA 4295P & EY50P on 02.10.18/ CLMOMVP000000869

Hi Rachel,

FYNA. Thanks.

Joanna

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Wednesday, October 03, 2018 9:25 AM

To: General Claims <GeneralClaims@sg.gaig.com>

Subject: [External] Accident involving veh no: SHA 4295P & EY 50P on 02.10.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVP000000869

Date: 10 October 2018

Our Ref: CS/GAI18017989/Dsd3

The Motor Claims Department
Great American Insurance Company

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 4295P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/10/2018 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>22,075.80</u> .
Revised Estimate Amount	: S\$ <u>16,929.32</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 8 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MCD018127790 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 02/10/2018 15:06
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2018 15:06
Date Of Accident	02/10/2018 11:00
Exact Location Of Accident	AYE TWDS BUONA VISTA AFTER CLEMENTI RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4295P
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	NOORDIN BIN BABA
NRIC No	S1414103J
Date Of Birth	27/03/1960
Occupation	OUTDOOR
Date Of Driving Pass	02/05/1979
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94881962
Fax Number	
Contact Number	
Email Address	NORDEN.BABA@GMAIL.COM

Address BLK 638 WOODLANDS RING ROAD
#07-43
Postcode 730638
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 3
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EY50P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JASPER HOE GEOK HENG
NRIC/Passport Number
Contact Number 96791511
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ5490T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SHAO XU
NRIC/Passport Number	
Contact Number	96740677
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02.10.2018 @ 11:00 Hrs

Reporting Centre Personnel's Signature
Name: *Rubini*
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02.10.2018 at about 11:00 hrs, I was travelling along AYE towards Buona Vista Rd with one female passenger on board.

I was travelling on the extreme right lane. I saw in front of my vehicles slowing down and stopped, so I follow too. Out of sudden, there was a loud impact coming from the rear portion and caused my taxi (A), to lose control and surge forward, and colliding onto veh (C) (SKZ 5490T) rear portion. My taxi (A) front and rear portion were damaged.

I assessed the damages to my taxi (A) and come to know that there were 3 vehicles involved in the chain accident.

No one was conveyed by the ambulance as no injury in this accident.

The parties involved in the accident are:

A - SHA 4295P.

B - EY 50P. Mr. Jasper Hoe Geok Heng. Hp : 9679 1511.

C - SKZ 5490T. Mr. Shao Xu. Hp : 9674 0677.

My female passenger, Ms Yong Poh Yoke. NRIC: S 1636170D. Hp : 9070 8379.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02.10.2018 @ 11:00 Hrs

Reporting Centre Personnel's Signature
Name: Rubbini
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

No Quirky by, LKK

VEHICLE NO : SHA 4295P

DATE : 2.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Great American

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>Crack</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>Crack</i>			\$ 39.50	✓
	Front Bumper Cover <i>Crack</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>to/in</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>Revised</i>			\$ 402.10	✓
	Front Bumper Lip <i>WHL</i>			\$ 54.90	X
	Front Bumper Bracket Top (LH/RH) <i>WHL</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>WHL</i>	\$	24.60	\$ 49.20	X
	Front Bumper Side Bracket <i>WHL</i>	\$	14.30	\$ 28.60	X
	Front Bumper Retainer Mounting <i>WHL</i>	\$	9.20	\$ 18.40	X
	Headlamp Support Top Cover <i>Crack</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>2x Crack</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>Crack mounting</i>	\$	1,388.00	\$ 2,776.00	✓
	Radiator <i>2x VSA</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>WHL</i>			\$ 792.95	X
	Radiator Bracket (RH/LH) <i>WHL</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>WHL</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken WHL</i>	\$	73.80	\$ 147.60	broken X
	Aircon Condenser <i>2x VSA</i>			\$ 927.50	✓
	Inter Cooler <i>2x VSA</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>WHL</i>			\$ 25.90	X
			9267.40		
			7413.92		
	SUB TOTAL			\$ 10,482.75	
	LESS 20%			\$ 2,096.55	
	DISCOUNTED TOTAL			\$ 8,386.20	
	Front Number Plate <i>Crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00	Nett ✓
			55.00		
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 400.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 50.00	WHL
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	WHL
			810.00		
	TOTAL LABOUR			\$ 1,980.00	

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>bst</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>defunct</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>HH</i>		\$ 142.30	\$ 284.60	X
	Boot Lid Hinge Cover (LH/RH) <i>HH</i>		\$ 158.00	\$ 316.00	X
	Boot Lid Lock Upper <i>bst</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>rev</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>huc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>huc</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	✓
	Licence Lamp (LH/RH) <i>o/s crack n/s src</i>		\$ 33.95	\$ 67.90	✓
	Boot Lid Trimboard <i>torn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>huc</i>			\$ 11.00	✓
	Bootlid Moulding <i>HH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>HH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>HH</i>			\$ 227.90	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>2x crack</i>			\$ 428.40	2 ✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>2x bst</i>	\$	80.30	\$ 160.60	2 ✓
	Rear Bumper Clip 10 pcs <i>huc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>HH</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>2x torn</i>			\$ 118.40	2 ✓
	Rear Bumper Under Cover <i>crack</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>o/s crack n/s HH</i>	\$	697.80	\$ 1,395.60	✓
	Rear Panel <i>2x dent</i>			\$ 526.70	2 ✓
	Rear Panel Garnish <i>2x defunct</i>			\$ 57.70	2 ✓
	Rear Panel Lower Panel <i>2x dent</i>			\$ 495.50	2 ✓
	Exhaust Pipe Insulator <i>HH</i>	\$	58.55	\$ 117.10	X
	Exhaust Silencer <i>2x bst</i>	\$	967.70	\$ 1,935.40	2 ✓
	Exhaust Pipe Hanger <i>HH</i>	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>huc photo taken</i>			\$ 730.10	X
			8946.65		
			7157.32	\$ 11,687.00	
				\$ 2,337.40	
				\$ 9,349.60	
	Boot Lid Comfort Logo & Tel No. Sticker <i>huc</i>			\$ 30.00	Nett ✓
	Rear No. Plate <i>crack</i>			\$ 25.00	Nett ✓
	Rear Bumper Rubber Mat <i>huc</i>			\$ 50.00	Nett ✓
			105.00		
				\$ 105.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	700/-
	Spray Painting Charge			\$ 800.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Remove/Refix Exhaust Pipe			\$ 300.00	HH
			16811.24		
			4513400/-		
				\$ 2,200.00	
				\$ 22,075.80	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18017989/Dsd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 12-12-2018	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	EY 50P	Veh. Inspected	SHA 4295P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000869	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	03/10/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU090152	Colour	BLUE
Odometer	314266	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/10/2018	Inspection Date	04/10/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4295P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR GRILLE	CRACKED	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	CRACKED	39.50	39.50
1	FRONT BUMPER COVER	CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	402.10	402.10
1	FRONT BUMPER LIP	NOT NECESSARY	54.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
2	FRONT BUMPER SIDE BRACKET @\$14.30	NOT NECESSARY	28.60	-
2	FRONT BUMPER RETAINER MOUNTING @\$9.20	NOT NECESSARY	18.40	-
1	HEADLAMP SUPPORT TOP COVER	CRACKED	222.60	222.60
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	CRACKED MOUNTING	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
2	RADIATOR GUARD @\$20.00	NOT NECESSARY	40.00	-
2	HORN UNIT (LH/RH) @\$73.80	NOT NECESSARY	147.60	-
1	AIRCON CONDENSER	BENT	927.50	927.50
1	INTER COOLER	BENT	1,032.50	1,032.50
2	INTER COOLER MOUNTING	NOT NECESSARY	25.90	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED	96.50	96.50
2	BOOT LID HINGE (LH/RH) @\$142.30	NOT NECESSARY	284.60	-
2	BOOT LID HINGE COVER (LH/RH) @\$158.00	NOT NECESSARY	316.00	-
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90

Report Ref No. CS/GAI18017989/Dsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT LID LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
2	LICENCE LAMP (LH/RH) @\$33.95	O/S CRACKED / N/S SERVICEABLE	67.90	33.95
1	BOOT LID TRIMBOARD	TORN	116.40	116.40
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	REAR BUMPER	DISTORTED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	CRACKED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	O/S CRACKED / N/S NOT NECESSARY	1,395.60	697.80
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	BENT	1,935.40	1,935.40
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
	LESS 20% DISCOUNT		-4,433.95	-3,642.81
			17,735.80	14,571.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	BROKEN	30.00	30.00
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO. PLATE (SN)	CRACKED	25.00	25.00

Report Ref No. CS/GAI18017989/Dsd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			160.00	160.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER.		2,000.00	1,200.00
	SPRAY PAINTING CHARGE.		1,050.00	700.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFILL AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	TUFF KOTE.		50.00	40.00
	REMOVE / REFILL EXHAUST PIPE.	NOT NECESSARY	300.00	-
			4,180.00	2,080.00
GRAND TOTAL			22,075.80	16,811.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,400.00

Report Ref No. CS/GAI18017989/Dsd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.