

REF:

CC3/ALH18017998 / A1ber

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No. 275041085254

Sum Insured:

Excess:

\$10007

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

130K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs

15 days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKV4680P. Yr Regn: 2015 Sept.

Type: ☒ Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5

cc: 1984

Colour:

Grey.

A/C: Insured / Std / NI / NA

Sp. Reading

36294.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No

WAUZZ28R7FA049538.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19.

R:

235/55R19.

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

04/10/18.

Survey held at

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

07 A1h.

5/10 - Report via merimen

5/10 @ 16:30pm. Authorise repair by A1h.

8/10 @ 9:02am - inform premium authorise repair excess \$10007

Part by part \$32,243.40 (Red: 29143.08; 47%)

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

21/2 Typist

Date/Time, File Return to?

21

Report Format:

Lump Sum / I.B.I. (\$

OD

32,243.40

☐ : Prel. Report☒ : Final Report

Days Of Repair:

15

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee

Transportation

\$ + RS \$

Photos

Others

TOTAL

200

10

210

View Received Message

This mail is associated with :

*SKV4680P (2750410852SG)

OD

Oct 2 2018 11:00AM

[HELLA ASIA SINGAPORE PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 22/11/2018 12:45 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$29650.50) - SKV4680P - Claim Handler: Loo, Tong Shing

Approved:29650.50:Upload LH fender support, closing element damage else supplementary labour and spray paint will not be allow.

DOCUMENTS SUMMARY

There are no documents.

178 - 183 .

Please refer to photo 178-183 for the repairs and respray of
LH fender support, closing element.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 05 Oct 2018

Preliminary Advice

Vehicle No	: SKV4680P	Accident Date	: 02/10/2018
Make	: AUDI Q5	Policy No.	:
Assignment Date	: 04/10/2018	Excess	: S\$1,000.00
Date of Inspection	: 04/10/2018	Est. Duration of Repair	: 12.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,856.00
Revised Amount	:S\$	24,550.50
Check Items (Estimated)	:S\$	15,037.00
Total	:S\$	39,587.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	84,305.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,695.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	5659M

Vehicle Details

Vehicle No.:	SKV4680P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QUATTRO (EU6)
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	CNC081068
Chassis No.:	WAUZZZ8R7FA049538
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$44,900.00
Original Registration Date:	18 Sep 2015
First Registration Date:	18 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$54,860.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Sep 2025
PARF Rebate Amount:	\$41,145.00

Intended COE Rebate Details

COE Expiry Date:	17 Sep 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$43,160.00
Total Rebate Amount:	\$84,305.00

The information contained herein is correct as at 05 Oct 2018

OK

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 8 October 2018 9:02 AM
To: Claims
Cc: SUR
Subject: RE: OD CLAIM FOR SKV 4680 P

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKV 4680P (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 5 October 2018 4:19 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SKV 4680 P

Dear All,

Any update?

Owner had been calling us and chase when is the approval to repair her car.

Please kindly assist.

Thanks.

Best Regards,

James Tan

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SKV4680P (2750410852SG)**

OD

Oct 2 2018 11:00AM

[HELLA ASIA SINGAPORE PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/10/2018 16:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$24550.50) - SKV4680P - Claim Handler: Loo, Tong Shing

Approved:24550.50:Re-inspection to be done for damage check and supplementary items / labour;

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2018 16:36
Date Of Accident	02/10/2018 11:45
Exact Location Of Accident	PIE (TUAS) TOH TUCK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV4680P
Insured/Policyholder	
Name Of Registered Owner	HELLA ASIA SINGAPORE PTE LTD
Co Reg No	200105659M
Email Address	KAREN.GOH@HELLA.COM
Mobile Phone No	
Alternative Phone No	OFFICE-88547341

Vehicle Particulars

Manufacturer	AUDI
Model	Q5 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100429418-03
Cover Note Number	

Driver

Name of Driver	GOH SOCK LING, KAREN
NRIC No	S8803857F
Date Of Birth	06/02/1988
Occupation	INDOOR
Date Of Driving Pass	16/04/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91169524
Fax Number	
Contact Number	
Email Address	KARENGOHS@GMAIL.COM

Address	BLK 1 LORONG 7 TOA PAYOH #01-69
Postcode	310001
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WAS EXITING PIE TO TOH TUCK AVENUE (TOWARDS COMMONWEALTH AVENUE). COLLISION HAPPENED AT FILTER LANE ENTERING TOH TUCK AVENUE. I SAW THAT THE ROAD WAS CLEAR, AND LORRY IN FRONT WAS MOVING AND ENTERING INTO THE MAIN ROAD OF TOH TUCK AVENUE. SO I FOLLOW SUIT. HE BRAKED SUDDENLY BUT MY CAR WAS UNABLE TO REACT ON TIME, THUS CRASHING ONTO THE RIGHT SIDE REAR LIGHT OF THE LORRY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1388A
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JEYARAMAN SARAVANAN
NRIC/Passport Number	G2613262U
Contact Number	96142987
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: James Hui
NRIC/FIN No: S8000260

SKETCH PLAN



A - SKY 4680?

B - GBE 1388 A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was exiting PE to Tol Truck Avenue (towards ~~eastbound~~^{concomitant} avenue).
Collision happened at after lane entering Tol Truck Avenue. I saw that
the road was clear, and lorry in front was moving and exiting into
the main road of Tol Truck Avenue so I drove out ~~fast~~. He looked suddenly
but my car was unable to react on time, thus crashing onto the
~~left~~^{right} side ~~behind~~ rear light of the lorry.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: James Tan
NRIC/FIN No. 99930262

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8803857F



GOH SOCK LING, KAREN
(WU SHULING)

吴淑玲

Race
CHINESE

Date of Birth: 06-02-1988 Sex: F

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S8803857F

Name

GOH SOCK LING, KAREN
(WU SHULING)

Birth Date: 06 Feb 1988

Issue Date: 03 Nov 2006



3304769

NRIC No. S8803857F



Blood Group: Date of issue: 10-02-2003

Address

APT BLK 1 LORONG 7 TOA PAYOH
#01-69
SINGAPORE 310001

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

VALID DATE

Class 2B	Motorcycles $\leq$ 200 CC	30 Mar 2008
Class 2A	Motorcycles between 200 CC and 400 CC	07 Jul 2007
Class 3	Motor cars $\leq$ 3500 kg w/o $\leq$ 7 passengers exclusive of the driver; and motor tractors/vehicles $\leq$ 2500 kg	16 Apr 2008

S8803857F

S / No. 9000269382



NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : HELLA ASIA SINGAPORE PTE LTD
Period of Insurance : 18 Sep 2018 To 17 Sep 2019
Engine No. : CNC081068
Chassis No. : WAUZZZ8R7FA049538

Vehicle No. : SKV4680P
Policy No. : 2100429418-03
Endorsement No. :
Issued Date : 04 Sep 2018

ABOUT THE COVER

Make/Model : AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)
Engine Capacity/Tonnage : 1,984.00 CC **Sum Insured** : Market Value
Driver Restriction : NA **Off Peak Car** : No **First Year of Registration** : 2015
Person or Classes of Persons Entitled to Drive* : **Insuring with COE/PAFF** : Yes

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ROLLAND ALEXIS FREDERIC MARIE - \$1000 (Own Damage), RADHIKA D/O MAKALINGAM - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125254

PREMIUM LEASING -AYF

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

50PPL

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 2100429418-03

Period of Insurance : 18 Sep 2018 to 17 Sep 2019

Issued Date : 04 Sep 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : HELLA ASIA SINGAPORE PTE LTD
 Address : 2 INTERNATIONAL BUSINESS PARK
 #02-12 THE STRATEGY
 SINGAPORE 609930
 Occupation/Nature of Business : Wholesale and Retail Trade

ABOUT THE VEHICLE

Registration No. : SKV4680P Engine Capacity/Tonnage : 1,984.00 CC
 Chassis No. : WAUZZZ8R7FA049538 Engine No. : CNC081068
 Seating Capacity : 5 First Year of Registration : 2015 Body Type : SUV
 Make/Model : AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)
 Hire Purchase Company/Employer's Loan : NA

ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No
 Driver Restriction : NA Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Loss of Use 1800cc - 2000cc Optional, PA Insured- \$100000, Fixture and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, Strike, Riots and Civil Commotions, In-Car Camera Express Waiver, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver
 ROLLAND ALEXIS FREDERIC MARIE - \$1000 (Own Damage), RADHIKA D/O
 MAKALINGAM - \$1000 (Own Damage)

PREMIUM

Premium	: \$	1,602.73
GST (7%)	: \$	112.19
Total	: \$	1,714.92

Your Premium includes the following discount(s):
 No Claim Discount - 50%

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1143/2018/GW
Date	:	3-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	HELLA ASIA SINGAPORE PTE LTD
Address	:	BLK 1 LORONG 7 TOA PAYOH
	:	#01-69
	:	Singapore 310001
Telephone	:	(HP) 68547341
Type of Claim	:	Own Damage Claims
Policy No.	:	2100429418 - 03
Vehicle No	:	SKV 4680 P
Model Code	:	Q5 2.0 TFSI qu
Model / Year	:	Sep-15
Engine No	:	CNC 081068
Chassis No	:	WAUZZZ8R7FA049538
Mileage	:	
Date In	:	2-Oct-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Oct-18
Place of Accident	:	PIE (TUAS) TOH TUCK EXIT

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 4680 P.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	NA	✓
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
3	To remove and renew aircon condenser, radiator, charge air cooler, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	✓
4	To dismantle and renew front bumper, both front fenders, both headlights and bonnet. Cut out and reweld lhs fender support and closing element. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$	9,800.00	3550 3250 - 3750
5	To respray front bumper, front lower spoiler, both front fender, bonnet, bonnet hinges, lhs fender top support, lhs front door and door cover. To carry out joint sealant works and stone chip treatment.	\$	6,100.00	3300 ✓
6	To carry out wheel alignment.	S/N \$	240.00	?
7	To carry out diagnostic check.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	\$ 18,404.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,237.00	✓ 1779.60
2	FIXING PARTS FOR FRONT BUMPER <i>3 pieces</i>	\$ 236.00	? 183.80
3	FRONT SPOILER <i>Rehd.</i>	\$ 540.00	✓ 431.60
4	CLOSING ELEMENT <i>Neu</i>	\$ 180.00	x
5	FOAM FILLER PIECE <i>Cracked</i>	\$ 97.00	✓ 77.60
6	PULL STRAP <i>Neu</i>	4 \$ 175.00	x
7	SECURING STRIP - LH/RH <i>24 only</i>	2 \$ 62.00	? ✓ 24.96
8	BUMPER COVER <i>Distorted</i>	\$ 109.00	✓ 87.20
9	AIR GUIDE GRILLE SATIN BLACK/CHROME - LH/RH <i>LH missing</i>	2 \$ 614.00 307.	245.20
10	SIDE REINFORCEMENT <i>Bent.</i>	\$ 571.00	✓ 456.80
11	COVER <i>Rehd.</i>	\$ 56.00	✓ 44.24
12	CAUTION STICKER <i>Neu</i>	\$ 12.00	✓ 9.28
13	SUPPORT - LH/RH <i>LH Dmgd</i>	2 \$ 50.00 25	19.92
14	GUIDE SECTION - LH/RH <i>Neu Dmgd.</i>	2 \$ 64.00	✓ 50.72
15	SENSOR <i>Neu</i>	4 \$ 842.00	? x
16	WIRING SET FOR BUMPER <i>Neu</i>	\$ 515.00	x 142.40
17	SIGNAL HORN - RH LOW TONE <i>Dmgd.</i>	\$ 178.00	✓
18	SIGNAL HORN - LH HIGH TONE <i>Dmgd.</i>	\$ 178.00	? 142.40
19	HORN BRACKET - RH LOW TONE <i>Neu</i>	\$ 22.00	? x
20	HORN BRACKET - LH HIGH TONE <i>Neu</i>	\$ 22.00	? x
SUB - TOTAL SPARE PARTS		\$ 6,760.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
21	FRONT FENDER - LH/RH LH Buckled, RH Repair	2 S	1,738.00	869. 695.20
22	ATTACHMENT PARTS FOR BOTH FENDERS	2 S	115.00	57.50 46
23	BRACKET - FRONT LH/RH LH Best	2 S	94.00	47. 36.92
24	BRACKET - CENTRE } LH Best	2 S	86.00	43 34.16
25	BRACKET - REAR	2 S	86.00	43. 34.16
26	FENDER BRACE - LH Best.	S	76.00	✓ 60.16
27	WHEEL HOUSING LINER - LH torn	S	231.00	✓ 184.80
28	ATTACHMENT PARTS FOR WHEEL HOUSING LINER Not nec	S	89.00	?
29	WHEEL SPOILER - FRONT LH Not nec	S	58.00	+
30	BONNET Distorted	S	3,562.00	✓ 2849.60
31	ATTACHMENT PARTS FOR BONNET nec	S	123.00	✓ 99.40
32	LID HINGE - LH/RH Best	2 S	180.00	? 142.56
33	BONNET CATCH HOOK Best.	S	122.00	? 97.60
34	GAS FILLED STRUT Not nec	2 S	209.00	?
35	BONNET MOUNTING Not nec	2 S	49.00	?
36	BONNET INNER STOP BUFFER Not nec	2 S	10.00	?
37	BONNET STOP BUFFER Not nec.	S	17.00	?
38	BONNET EDGE PROTECTION nec	S	24.00	✓ 17.80
39	BONNET LID LOCK WITH MICRO-SWITCH Dmgd	S	188.00	✓ 150.40
40	CONNECTOR HOUSING BRACKET Damaged	S	9.00	✓ 6.48
SUB - TOTAL SPARE PARTS		:	<u>\$ 7,066.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	CABLE HOLDER <i>new</i>	\$ 7.00	?
42	BONNET LID LOCK CABLE <i>new</i>	\$ 43.00	?
43	BONNET LOCK COVER <i>Damaged</i>	\$ 20.00	?
44	FRONT FENDER LINING-LH/RH <i>new</i>	2 \$ 334.00	?
45	HEADLIGHT MOUNTING-LH/RH <i>LH crushed</i>	2 \$ 206.00 103.82	40
46	HEADLIGHT -LH/RH <i>LH smashed</i>	2 \$ 4,028.00 2,414.19	31.70
47	HEADLIGHT CONTROL UNIT <i>Damaged</i>	\$ 1,018.00	?
48	HEADLIGHT POWER MODULE <i>Damaged</i>	\$ 501.00	?
49	GAS DISCHARGE LAMP <i>new</i>	\$ 394.00	?
50	RETAINING PLATE <i>crushed</i>	\$ 68.00	?
51	RADIATOR GRILLE <i>crushed</i>	\$ 1,556.00	✓
52	INSCRIPTION 'QUATTRO' <i>new</i>	\$ 83.00	✓
53	STRIKER PLATE <i>Damaged</i>	\$ 107.00	✓
54	HEADLIGHT LIFT CYLINDER-LH/RH <i>LH crushed</i>	2 \$ 340.00 174.13	9.20
55	HOSE ROLLERS FOR 5 M <i>new</i>	\$ 164.00	✓
56	WASH WATER RESERVOIR <i>new</i>	\$ 190.00	?
57	LOCK CARRIER WITH MOUNTING <i>crushed</i>	\$ 970.00	✓
58	A/C COMPRESSOR <i>new</i>	\$ 1,781.00	?
59	A/C CONDENSOR <i>Dented</i>	\$ 651.00	✓
60	PRESSURE SENDER <i>crushed</i>	\$ 165.00	?
SUB - TOTAL SPARE PARTS		\$ 13,434.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	VALVE <i>new</i>	\$ 46.00	?
62	COOLANT RADIATOR WITH OIL COOLER <i>Distorted</i>	\$ 1,206.00	? 964.80
63	RUBBER BUSH <i>new</i>	2 \$ 12.00	? 8.96
64	RUBBER BUSH-LOWER <i>new</i>	4 \$ 29.00	? 22.24
65	COOLANT CONCENTRATE 1.5 LTR <i>new</i>	4 \$ 133.00	✓ 65.28
66	RADIATOR AIR DUCT-LH/RH <i>new</i>	2 \$ 40.00	? 15.92
67	RADIATOR COVER <i>new</i>	\$ 27.00	? 20.88
68	RADIATOR SEALING STRIP <i>new</i>	\$ 20.00	? 15.44
69	TWIN FAN RING <i>new</i>	\$ 226.00	? 180.40
70	RADIATOR FAN <i>new</i>	2 \$ 1,439.00	? 1150.80
71	RADIATOR CONTROL UNIT <i>new</i>	\$ 740.00	?
72	CHARGE AIR COOLER <i>new</i>	\$ 492.00	✓
73	AIR FILTER <i>new</i>	\$ 269.00	?
74	INTAKE MANIFOLD <i>new</i>	\$ 67.00	?
75	INTAKE FRONT MANIFOLD <i>new</i>	\$ 32.00	? 29.04
76	AIR INTAKE BOOT <i>new</i>	\$ 95.00	?
77	ADAPTER <i>new</i>	\$ 10.00	?
78	ADAPTER COVER <i>new</i>	\$ 355.00	?
79	HALOGEN FOG LAMP-LH <i>new</i>	\$ 227.00	✓
80	FLAT CONTACT HOSEING <i>new</i>	\$ 43.00	✓ 32.64
SUB - TOTAL SPARE PARTS		\$ 5,508.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	WATER DEFLECTOR STIP-LH/RH <i>cut</i>	2 S	116.00 ✓ 92.32
82	SHOCK ABSORBER MOUNTING-LH <i>new</i>	S	75.00 +
83	SIDE MEMBER <i>repair</i>	S	1,268.00 ?
84	SIDE MEMBER REINFORCEMENT <i>new repair</i>	S	1,297.00 ?
85	SIDE MEMBER CROSS PANEL-LH <i>repair</i>	S	454.00 ?
86	FRONT DOOR COVER-LH <i>new</i>	S	449.00 +
87	FRONT NO. PLATE <i>Bent</i>	S/N S	25.00 ✓
88	ACRYLIC SEALNT <i>new</i>	S/N S	180.00 ? ✓
89	CAVITY WAX <i>new</i>	S/N S	140.00 ? ✓
90	STONE CHIP <i>new</i>	S/N S	180.00 ? X
91	SUNDRIES <i>new</i>	S	500.00 ? 235.52
TOTAL SPARE PARTS		:	\$ 37,452.00
TOTAL LABOUR		:	\$ 18,404.00
GRAND TOTAL		:	\$ 55,856.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

61786-46

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 04/10/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1143/2018/GW
Date	:	3-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

We took 15 days with added repairs

jb 19 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	HELLA ASIA SINGAPORE PTE LTD
Address	:	BLK 1 LORONG 7 TOA PAYOH #01-69 Singapore 310001
Telephone	:	(HP) 68547341
Type of Claim	:	Own Damage Claims
Policy No.	:	2100429418 - 03
Vehicle No	:	SKV 4680 P
Model Code	:	Q5 2.0 TFSI qu
Model / Year	:	Sep-15
Engine No	:	CNC 081068
Chassis No	:	WAUZZZ8R7FA049538
Mileage	:	
Date In	:	2-Oct-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Oct-18
Place of Accident	:	PIE (TUAS) TOH TUCK EXIT

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 4680 P .

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	NA	
2	To remove,check and reinstall front wire harness for headlights,horns,fog lamps,outside temperature sensor,headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
3	To remove and renew aircon condenser,radiator,charge air cooler,electrical fans and control unit.Pressurise cooling system.To carry out vacuum and regas.	S/N	\$ 1,400.00	\$ 1,400.00
4	To dismantle and renew front bumper,both front fenders,both headlights and bonnet.Cut out and reweld lhs fender support and closing element.Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.		\$ 9,800.00	\$ 3,750.00
5	To respray front bumper,front lower spoiler,both front fender,bonnet,bonnet hinges,lhs fender top support,lhs front door and door cover.To carry out joint sealant works and stone chip treatment.		\$ 6,100.00	\$ 3,300.00
6	To carry out wheel alignment.	S/N	\$ 240.00	
7	<i>Added labour charges - see attached</i>		\$ 2,700.00	\$ 2,050.00
8	To carry out diagnostic check.	S/N	\$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$ 21,104.00</u>	<u>\$ 11,364.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,237.00	\$ 1,789.60
2	FIXING PARTS FOR FRONT BUMPER	\$ 236.00	\$ 188.80
3	FRONT SPOILER	\$ 540.00	\$ 431.60
4	CLOSING ELEMENT	\$ 180.00	
5	FOAM FILLER PIECE	\$ 97.00	\$ 77.60
6	PULL STRAP	4 \$ 175.00	
7	SECURING STRIP -LH/RH	2 \$ 62.00	\$ 24.96
8	BUMPER COVER	\$ 109.00	\$ 87.20
9	AIR GUIDE GRILLE SATIN BLACK/CHROME - LH/RH	2 \$ 614.00	\$ 245.20
10	SIDE REINFORCEMENT	\$ 571.00	\$ 456.80
11	COVER	\$ 56.00	\$ 44.24
12	CAUTION' STICKER	\$ 12.00	\$ 9.28
13	SUPPORT - LH/RH	2 \$ 50.00	\$ 19.92
14	GUIDE SECTION - LH/RH	2 \$ 64.00	\$ 50.72
15	SENSOR	4 \$ 842.00	
16	WIRING SET FOR BUMPER	\$ 515.00	
17	SIGNAL HORN - RH LOW TONE	\$ 178.00	\$ 142.40
18	SIGNAL HORN - LH HIGH TONE	\$ 178.00	\$ 142.40
19	HORN BRACKET - RH LOW TONE	\$ 22.00	
20	HORN BRACKET - LH HIGH TONE	\$ 22.00	
SUB - TOTAL SPARE PARTS		\$ 6,760.00	\$ 3,710.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/l	\$	3,710.72
21	FRONT FENDER - LH/RH	2 \$	1,738.00 \$	695.20
22	ATTACHMENT PARTS FOR BOTH FENDERS	2 \$	115.00 \$	46.00
23	BRACKET - FRONT LH/RH	2 \$	94.00 \$	36.88
24	BRACKET - CENTRE	2 \$	86.00 \$	34.16
25	BRACKET - REAR	2 \$	86.00 \$	34.16
26	FENDER BRACE - RH	\$	76.00 \$	60.16
27	WHEEL HOUSING LINER - LH	\$	231.00 \$	184.80
28	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$	89.00	
29	WHEEL SPOILER - FRONT LH	\$	58.00	
30	BONNET	\$	3,562.00 \$	2,849.60
31	ATTACHMENT PARTS FOR BONNET	\$	123.00 \$	98.40
32	LID HINGE - LH/RH	2 \$	180.00 \$	142.56
33	BONNET CATCH HOOK	\$	122.00 \$	97.60
34	GAS FILLED STRUT	2 \$	209.00	
35	BONNET MOUNTING	2 \$	49.00	
36	BONNET INNER STOP BUFFER	2 \$	10.00	
37	BONNET STOP BUFFER	\$	17.00	
38	BONNET EDGE PROTECTION	\$	24.00 \$	18.88
39	BONNET LID LOCK WITH MICRO-SWITCH	\$	188.00 \$	150.40
40	CONNECTOR HOUSING BRACKET	\$	9.00 \$	6.48
SUB - TOTAL SPARE PARTS		\$	7,066.00 \$	8,166.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 8,166.00
41	CABLE HOLDER		\$ 7.00	
42	BONNER LID LOCK CABLE		\$ 43.00	
43	BONNET LOCK COVER		\$ 20.00	\$ 15.36
44	FRONT FENDER LINING-LH/RH	2	\$ 334.00	
45	HEADLIGHT MOUNTING-LH/RH	2	\$ 206.00	\$ 82.40
46	HEADLIGHT -LH/RH	2	\$ 4,828.00	\$ 1,931.20
47	HEADLIGHT CONTROL UNIT		\$ 1,018.00	\$ 814.40
48	HEADLIGHT POWER MODULE		\$ 501.00	\$ 400.40
49	GAS DISCHARGE LAMP		\$ 394.00	\$ 314.80
50	RETAINING PLATE		\$ 68.00	\$ 54.16
51	RADIATOR GRILLE		\$ 1,556.00	\$ 1,244.80
52	INSCRIPTION 'QUATTRO'		\$ 83.00	\$ 66.16
53	STRIKER PLATE		\$ 107.00	\$ 85.20
54	HEADLIGHT LIFT CYLINDER-LH/RH	2	\$ 348.00	\$ 139.20
55	HOSE ROLLERS FOR 5 M		\$ 164.00	\$ 131.20
56	WASH WATER RESERVOIR		\$ 190.00	
57	LOCK CARRIER WITH MOUNTING		\$ 970.00	\$ 776.00
58	A/C COMPRESSOR		\$ 1,781.00	
59	A/C CONDENSOR		\$ 651.00	\$ 520.40
60	PRESSURE SENDER		\$ 165.00	\$ 132.00
SUB - TOTAL SPARE PARTS			\$ 13,434.00	\$ 14,873.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 14,873.68
61	VALVE	\$ 46.00	
62	COOLANT RADIATOR WITH OIL COOLER	\$ 1,206.00	\$ 964.80
63	RUBBER BUSH	2 \$ 12.00	\$ 8.96
64	RUBBER BUSH-LOWER	4 \$ 29.00	\$ 22.24
65	COOLANT CONCENTRATE 1.5 LTR	4 \$ 133.00	\$ 65.28
66	RADIATOR AIR DUCT-LH/RH	2 \$ 40.00	\$ 15.92
67	RADIATOR COVER	\$ 27.00	\$ 20.88
68	RADIATOR SEALING STRIP	\$ 20.00	\$ 15.44
69	TWIN FAN RING	\$ 226.00	\$ 180.40
70	RADIATOR FAN	2 \$ 1,439.00	\$ 1,150.80
71	RADIATOR CONTROL UNIT	\$ 740.00	
72	CHARGE AIR COOLER	\$ 492.00	
73	AIR FILTER	\$ 269.00	
74	INTAKE MANIFOLD	\$ 67.00	
75	INTAKE FRONT MANIFOLD	\$ 32.00	\$ 25.04
76	AIR INTAKE BOOT	\$ 95.00	
77	ADAPTER	\$ 10.00	
78	ADAPTER COVER	\$ 355.00	
79	HALOGEN FOG LAMP-LH	\$ 227.00	
80	FLAT CONTACT HOSE	\$ 43.00	\$ 32.64
SUB - TOTAL SPARE PARTS :		\$ 5,508.00	\$ 17,376.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 4680 P.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 17,376.08
81	WATER DEFLECTOR STIP-LH/RH	2	\$ 116.00	\$ 92.32
82	SHOCK ABSORBER MOUNTING-LH		\$ 75.00	
83	SIDE MEMBER		\$ 1,268.00	
84	SIDE MEMBER REINFORCEMENT		\$ 1,297.00	
85	SIDE MEMBER CROSS PANEL-LH		\$ 454.00	
86	FRONT DOOR COVER-LH		\$ 449.00	
87	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
88	ACRYLIC SEALNT	S/N	\$ 180.00	\$ 180.00
89	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
90	STONE CHIP	S/N	\$ 180.00	
92	<i>Added parts - see atatched</i>		\$ 3,550.00	\$ 2,830.48
93	SUNDRIES		\$ 500.00	\$ 235.52
TOTAL SPARE PARTS		:	\$ 41,002.00	\$ 20,879.40
TOTAL LABOUR		:	\$ 21,104.00	\$ 11,314.00
GRAND TOTAL		:	\$ 62,106.00	\$ 32,193.40

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1143/2018/GW 11-Oct-18 Kee Siang 1-Jan SKV 4680 P AUDI Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
Parts			
1	REINFORCEMENT BEAM BRACKET LH <i>{ Best</i>	\$ 207.00	\$ ✓ 165.20
2	REINFORCEMENT BEAM BRACKET RH <i>{ Best</i>	\$ 207.00	\$ ✓ 165.20
3	SECURING PLATE LH <i>{ Dmgd</i>	\$ 41.00	\$ ✓ 32.48
4	SECURING PLATE RH <i>{ Dmgd</i>	\$ 41.00	\$ ✓ 32.48
5	SUPPORT FOR COOLANT RADIATOR <i>Dmgd</i>	\$ 66.00	\$ ✓ 52.48
6	FRONT FENDER UPPER RAIL CONNECTING PLATE <i>Best</i>	\$ 316.00	\$ ✓ 252.80
7	FRONT FENDER CLOSING ELEMENT LEFT LOWER <i>Dmgd</i>	\$ 454.00	\$ ✓ 363.20
8	FRONT FENDER RAIL BRACKET <i>Best</i>	\$ 16.00	\$ ✓ 12.48
9	AIR COND STICKER <i>Best</i>	\$ 7.00	\$ ✓ 4.88
10	AIR COND V-BELT <i>at D</i>	\$ 47.00	\$ ✓ 35.68
11	LED HEAT SINK <i>Dmgd</i>	\$ 889.00	\$ ✓ 710.80
12	HEADLIGHT HOSE <i>at</i>	\$ 28.00	\$ ✓ 21.76
13	HEADLIGHT RETAINING BRACKET <i>{ cracked</i>	\$ 21.00	\$ ✓ 16.40
14	HEADLIGHT SPACER	\$ 70.00	\$ ✓ 55.36
15	WATER RESERVOIR CONNECTING TUBE - ELBOW <i>{ Dmgd</i>	\$ 37.00	\$ ✓ 29.12
16	WATER RESERVOIR CONNECTING TUBE - STRAIGHT	\$ 23.00	\$ ✓ 17.92
17	COOLANT PRESSURE SENSOR <i>Dmgd</i>	\$ 172.00	\$ ✓ 137.60
18	AIR COND PRESSURE HOSE COMPRESSOR > CONDENS <i>Best</i>	\$ 329.00	\$ ✓ 262.80
19	AIR COND HOSE <i>Best</i>	\$ 483.00	\$ ✓ 386.00
20	LOCK CARRIER SUPPORT LH <i>{ Dmgd</i>	\$ 48.00	\$ ✓ 37.92
21	LOCK CARRIER SUPPORT RH <i>{ Dmgd</i>	\$ 48.00	\$ ✓ 37.92
		\$ 3,550.00	\$ 2,830.48
LABORS			
1	Cut out and reweld lhs fender support and closing element. <i>(inclusive \$250.00 for above parts, check items, deleted items)</i>	\$ 2,100.00	\$ 1,500.00 ✓
2	To respray lhs fender support and closing element.	\$ 600.00	\$ 550.00 ✓
	Labour	\$ 2,700.00	\$ 2,050.00
	Materials	\$ 3,550.00	\$ 2,830.48
TOTAL		\$ 6,250.00	\$ 4,880.48

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKV 4680 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1143/2018/MAS

7 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKV 4680 P, Audi Q5 2.0 TFSI

With reference to the above-mentioned vehicle, no. **SKV 4680 P**, claimant, **Hella Asia Singapore Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013431 – S\$33,430.44
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKV 4680 P

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6348 2223
Main Telefax: 6471 8733

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6348 2223
Telefax: 6471 1023

UBi Service Centre
55 Ubi Road 1
Singapore 408025
Telephone: 6384 2223
Telefax: 6471 1023

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customerservice@premiumcars.com.sg

6348 2223
6471 1234

INS TAX INVOICE

Company Reg. No: 199902271W
GST Reg. No. 199902271W

Page 1 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: 05 2.0 TFSI QU 8R000A (MY15) Chassis: WAUZZZ8R7FA049538 Engine: DNC 081068 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	N: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	N: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	N: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS, OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	488.00	1.00	488.00
S	BODYWORK	N: TO REMOVE AND RENEW AIRCON CONDENSER,RADIATOR AND ELECTRICAL FANS,PRESSUISE COOLING SYSTEM, TO CARRY OUT VACUUM AND REGAS	1400.00	1.00	1,400.00
S	BODYWORK	N: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDERS,LHS HEADLIGHT AND BONNET,CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	3750.00	1.00	3,750.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6396 2223
Main Telefax: 6471 8733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6396 2223
Telefax: 6471 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408863
Telephone: 6396 2223
Telefax: 6396 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6396 2223
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: 05 2.0 TFSI QU 8R00AA (MY15) Chassis: WAUZZZ8R7FA049538 Engine: DNC 001068 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	3300.00	1.00	3,300.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, BOTH FRONT FENDER, BONNET AND LHS FRONT DOOR. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	320.00	1.00	320.00
S	BODYWORK	TO SUPPLY ACRYLIC SEALANT AND CAVITY WAX M:	1500.00	1.00	1,500.00
S	BODYWORK	CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT M:	550.00	1.00	550.00
X	AN 90694802	(A) (SK) POP-RIVET Less 020%	2.00	1.40	2.24
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2223
Main Telefax: 6471 8723

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408625
Telephone: 6104 3337

Customer Service
Service Appointment:
24-hour breakdown service
6466 2323
6828 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: Q5 2.0 TFSI QU 8R00AA (MY15) Chassis: WAUZZZ8R7FA049538 Engine: CNC 001068 Dept: U

USB No.:

You have been assisted by :- UA-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A000006027	(V) (G) PLATE	1.00	454.00	363.20
X	A000063825	ATT. PARTS	1.00	123.00	98.40
X	A000941717	(A) (SK) HOSE	1.00	27.20	21.76
X	A000260710L	(A) (SK) PIPE	1.00	482.50	386.00
X	A000007134C	(A) (SK) BRACKET	1.00	206.50	165.20
X	A000260701B	(V) (G) HOSE	1.00	328.50	262.80
X	A000053651S T94	GRILLE	1.00	1556.00	1,244.80
X	A000941043D	HEADLAMP	1.00	2414.00	1,931.20
X	A000021105A	FENDER	1.00	669.00	695.20
X	A000021171K	WHEEL HOUS	1.00	231.00	184.80
X	A0K0121207A	COML	1.00	225.50	180.40
X	A000007061F GRU	FR. SPOILER	1.00	539.50	431.60
X	A0T0260403B	CONDENSER	1.00	650.50	520.40
X	A0K0121251AK	RADIATOR	1.00	1206.00	964.80
X	A000007001A	(V) (GER) COVER (09/10/	1.00	109.00	87.20
X	A000005594D	CARRIER	1.00	970.00	776.00
X	A0K0959455R	ELECTR FAN	1.00	666.50	533.20
X	A0K0959455T	ELECTR FAN	1.00	772.00	617.60

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone 6396 2222
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone 6396 2222
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone 6396 2222
Telefax 6475 1023

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6396 2222
6396 1222

Page 4 17:36

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: Q5 2.0 TFSI QU BR00AA (MY15) Chassis: MAJZZZ8R7FA049538 Engine: CMC 081068 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABR0807550E	(A) (SK) FDM INSERT (0	Less 020%	1.00	97.00	77.60
X	ABR0805303A	(A) (SK) PLATE	Less 020%	1.00	316.00	252.80
X	ABR0807113B	BEAM	Less 020%	1.00	571.00	456.80
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	20.40	65.28
X	ABR0823029H	(A) (SK) HOOD (08/10/20	Less 020%	1.00	3562.00	2,849.60
X	ABR0807065C GRU	COVER	Less 020%	1.00	2237.00	1,789.60
X	ABK0973703	HOUSING	Less 020%	1.00	14.20	11.36
X	A4D0807300	RIVET	Less 020%	6.00	2.10	10.08
X	A000979019EA	WIRES	Less 020%	1.00	20.20	16.16
X	A4G0955665	SUPPORT	Less 020%	2.00	18.20	29.12
X	ABR0807283C	GUIDE	Less 020%	1.00	31.70	25.36
X	ABR08098625	MOUNT KIT	Less 020%	1.00	57.50	46.00
X	ABR08098623	PARTS KIT	Less 020%	1.00	236.00	188.80
X	ABR0129617D	(A) (SK) MANIFOLD	Less 020%	1.00	31.30	25.04
X	A4H0121268	MOUNTING	Less 020%	2.00	11.10	17.76
X	ABK0805201	MOUNTING	Less 020%	2.00	32.00	52.48
X	ABR0805607B	MOUNTING	Less 020%	1.00	103.00	82.40
X	A4G8806305	(A) (SK) SPACER	Less 020%	2.00	34.60	55.36

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6828 2222
Main Telefax: 6471 3713

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408625
Telephone: 6384 1234

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumaudis.com.sg
6966 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954)	Regn Date: 18/09/2015	Mileage: 36295	WIP No.: 27111
Model: Q5 2.0 TFSI QU 8R00AA (MY15)	Chassis: WAUZZZ8R7FA049538	Engine: DMC 001068	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	ABR0853736C 22Z	INSCRIPTION "QUATTRO	Less 020%	1.00	66.16	66.16
X	ABR0821467A	BRACKET	Less 020%	1.00	36.88	36.88
X	ABR0807333A	SUPPORT	Less 020%	1.00	19.92	19.92
X	ABR0805500	(A) (SK) PLATE	Less 020%	1.00	32.48	32.48
X	ABR0807277C	STRIP	Less 020%	1.00	24.96	24.96
X	ABR0807284C	GUIDE	Less 020%	1.00	25.36	25.36
X	ABR0823301A	(A) (SK) HINGE	Less 020%	1.00	71.28	71.28
X	ABR0805528A	(A) (SK) SUPPORT	Less 020%	1.00	37.92	37.92
X	ABR0823302A	(A) (SK) HINGE	Less 020%	1.00	71.28	71.28
X	ABR0805527A	SUPPORT	Less 020%	1.00	37.92	37.92
X	ABR0821135	SUPPORT	Less 020%	1.00	60.16	60.16
X	ABR0823480B	HOOK	Less 020%	1.00	97.60	97.60
X	ABR0805499	PLATE	Less 020%	1.00	32.48	32.48
X	ABR0807133A	BRACKET	Less 020%	1.00	165.20	165.20
X	ABK0121331A	SEAL STRIP	Less 020%	1.00	15.44	15.44
X	ABK0121275C	MOUNTING	Less 020%	2.00	8.96	8.96
X	ABK0121276A	MOUNTING	Less 020%	2.00	4.48	4.48
X	ABK0820536D	BRACKET	Less 020%	1.00	12.48	12.48

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159988
Main Telephone: 6836 2222
Main Telefax: 6471 3933

Alexandra Service Centre
281 Alexandra Road
Singapore 159988
Telephone: 6888 2222
Telefax: 6475 1033

UBi Service Centre
55 Ubi Road 1
Singapore 408888
Telephone: 6388 2222
Telefax: 6388 2222

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6866 2323
8828 1233

INS TAX INVOICE

Company Reg. No: 199902271W
GST Reg. No. 199902271W

Page 6 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954)	Regn Date: 18/09/2015	Mileage: 36295	WIP No.: 27111
Model: Q5 2.0 TFSI QU BR00AA (MY15)	Chassis: WAUZZZ8R7FA049538	Engine: DNC 001068	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	ABK08235096	LOCK	1.00	158.00	158.40
X	A3B0919136A	BRACKET	1.00	6.10	6.48
X	ABP0823433A	BUMPER	2.00	4.70	7.52
X	ABR0821469	BRACKET	1.00	42.70	34.16
X	ABR0821471	BRACKET	1.00	42.70	34.16
X	ABR0853692B	PLATE	1.00	106.50	85.20
X	A4E0260749B	WASHER	1.00	4.20	3.36
X	A4E0260749A	WASHER	1.00	3.20	2.56
X	ABP4803593A	PLUG	2.00	17.70	28.32
X	ABT0823433B	(A) (SK) BUMPER	2.00	8.30	13.28
X	A7H0820896	SEAL	1.00	2.30	1.84
X	ABK2823746	(A) (SK) COVER	1.00	19.20	15.36
X	ABR0807681M BJI	GRILL	1.00	306.50	245.20
X	ABK0941597B	BALLAST	1.00	1018.00	814.40
X	ABR0941453A	PLATE	1.00	57.70	54.16
X	A3W0971838	TIE WRAP	1.00	1.00	0.80
X	ABD0803583L	PLUG	2.00	3.60	5.76
X	ABR0941355	(A) (SK) PLATE	1.00	20.50	16.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6386 2222
Main Telefax: 6471 3753

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6386 2222
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408941
Telephone: 6386 2222

Customer Service
Service Appointment: 6386 2222
24-hour Breakdown Service: 8828 1233
Email: customer.care@premiumcars.com.sg

INS TAX INVOICE
Company Reg. No: 199802271W
GST Reg. No. 199902271W

Page 7 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4688P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4688P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: Q5 2.0 TFSI DU 8R000A (MY15) Chassis: WAUZZZ87F0049538 Engine: CNC 081068 Dept: U

USB No.:

You have been assisted by :- UB-Jlayee (33)

		Details	Qty	Unit Price	Amount
X	A8T0951229C	(A) (SK) CLIP	1.00	21.50	17.20
X	A8R0955101A	CYLINDER	1.00	174.00	139.20
X	A03G906051E	PRESSSENS	1.00	172.00	137.60
X	A4H0959126B	PRESSSENS	1.00	165.00	132.00
X	A7P6955964A	HOSE	1.00	164.00	131.20
X	A8K0973704	HOUSING	1.00	11.90	9.52
X	A4G0955873	(A) (SK) PIECE	1.00	22.40	17.92
X	A000979940	CONNECTOR (WHITE)	2.00	9.00	14.40
X	A1J0973081	HOUSING (TECH)	1.00	6.40	5.12
X	A1J0973701A	HOUSING	1.00	11.20	8.96
X	A4D0971992	HOUSING	1.00	15.40	12.32
X	A8K0010520A	PLATE	1.00	11.60	9.28
X	A8T0010515	STICKER	1.00	6.10	4.88
X	A8R0121283P	(V) (SK) AIR DUCT (16/1	1.00	19.90	15.92
X	A8R0121292B	(A) (SK) COVER	1.00	26.10	20.88
X	A4G0907697D	POWER MOD	1.00	500.50	400.40
X	A8R0941475B	LED	1.00	888.50	710.80
X	A8T0951223	HORN	1.00	178.00	142.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6336 2223
Main Telefax: 6471 8733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6336 2223
Telefax: 6471 8733

Ubi Service Centre
55 Ubi Road 1
Singapore 408826
Telephone: 6386 2223

Customer Service
Service Appointment
24-Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6336 2223
6471 8733

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 8 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: Q5 2.0 TFSI QU 8R00AA (MY15) Chassis: WAUZZZ8R7FA049538 Engine: DNC 001068 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABT0951221	(A) (SK)HORN(08/10/20	Less 020%	1.00	178.00	142.40
X	ABR0807217B	COVER	Less 020%	1.00	55.30	44.24
X	AWHT000372	(A) (SK) BOLT	Less 020%	2.00	2.50	4.00
X	AWHT001506A	BOLT	Less 020%	2.00	1.40	2.24
X	AWHT001308	NUT	Less 020%	4.00	1.20	3.84
X	AN 0161857	POP-RIVET	Less 020%	12.00	2.90	27.84
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24
X	AN 90765701	RIVET	Less 020%	4.00	1.30	4.16
X	AN 0154374	SPEED NUT	Less 020%	2.00	1.10	1.76
X	AN 90798008	NUT	Less 020%	4.00	1.10	3.52
X	AN 10139301	CLIP (0.10)	Less 020%	4.00	5.70	18.24
X	AN 91118201	(A) (SK) BOLT	Less 020%	2.00	2.20	3.52
X	AN 91154701	BOLT	Less 020%	4.00	2.20	7.04
X	AN 91146301	BOLT	Less 020%	3.00	2.00	4.80
X	AN 10633202	SCREW	Less 020%	1.00	0.70	0.56
X	AN 10442003	BOLT	Less 020%	2.00	0.50	0.80
X	AN 91166901	BOLT	Less 020%	10.00	1.30	10.40
X	AN 10721805	GAS BULB	Less 020%	1.00	393.50	314.80

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119088
Main Telephone: 6346 2223
Main Telefax: 6471 2121

Alexandra Service Centre
281 Alexandra Road
Singapore 119088
Telephone: 6346 2223
Telefax: 6471 2121

Ubi Service Centre
55 Ubi Road 1
Singapore 408811
Telephone: 6346 1111

Customer Service
Service Appointment:
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 2323
6426 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 9 17:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013431 Date : 11/02/2019 Order : SKV4680P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKV4680P (V 24954) Regn Date: 18/09/2015 Mileage: 36295 WIP No.: 27111

Model: 05 2.0 TFSI QU BRBAA (MY15) Chassis: WAUZZZ8R7FA049538 Engine: DNC 001068 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	AN 91130001	(V) (G) SCREW	2.00	1.50	2.40
X	A06L903137A	RIBBED BELT	1.00	44.60	35.60
X	ABR0054327A 01C	DEFLECTOR	1.00	57.70	46.16
X	ABR0054328A 01C	DEFLECTOR	1.00	57.70	46.16
X	ABR0023126H	EDGING	1.00	23.60	18.88

Parts 20,534.40
Labour 0.00
Sublet 11,709.00
Menus 0.00
Lubricant 0.00

Sub-Total 31,243.40

7% GST 2,187.04

Grand Total 33,430.44

w/z

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SKV 4680 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1143/2018/JW
24 Oct 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ8R7FA049538
Vehicle Regn No. : **SKV 4680 P**
Vehicle Mileage : 36295 Km
Vehicle Owner : HELLA ASIA SINGAPORE PTE LTD
Certificate No : 2100429418-03
Policy Excess : \$1,070.00 (incl. of GST)
Accident Date : 2nd Oct 2018
Place : PIE (Tuas) Toh Tuck Exit
Repair Cost : \$ 33,430.44
WIP No. : 27111
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408899
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 9.45am
Date : 25/10/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8803857F



GOH SOCK LING, KAREN
(WU SHULING)

吴淑玲

Race

CHINESE

Date of Birth

06-02-1988

Country of Birth

SINGAPORE

Sex

F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8803857F

Name

GOH SOCK LING, KAREN
(WU SHULING)

Birth Date 06 Feb 1988

Issue Date 03 Nov 2006



3304780

NRIC No. S8803857F



Blood Group Date of issue

10-02-2003

Address

APT BLK 1 LORONG 7 TOA PAYOH
#01-69
SINGAPORE 310001

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 2B	Motorcycles $\leq$ 200 CC	03 Nov 2006
Class 2A	Motorcycles between 201 CC and 400 CC	27 Jul 2017
Class 3	Motor cars $\leq$ 2000 kg with $\leq$ 7 passengers, exclusive of the driver, and motor tractors/vehicles $\leq$ 2000 kg	16 Apr 2006

S8803857F

S / No. 9000269382



NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO-PROTECTOR PRIVATE VEHICLE

Name of Policyholder : HELLA ASIA SINGAPORE PTE LTD
Period of Insurance : 18 Sep 2018 To 17 Sep 2019
Engine No. : CNC081068
Chassis No. : WAUZZZ8R7FA049538

Vehicle No. : SKV4680P
Policy No. : 2100429418-03
Endorsement No. :
Issued Date : 04 Sep 2018

ABOUT THE COVER

Make/Model : AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ROLLAND ALEXIS FREDERIC MARIE - \$1000 (Own Damage), RADHIKA D/O MAKALINGAM - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408689 63682323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 5G Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125254

PREMIUM LEASING -AYF

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

88P411

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		04 Oct 2018 13:48 Edit Adj Rpt	S\$32,243.40 Edit Estimates	S\$32,243.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HELLA ASIA SINGAPORE PTE LTD , Co. Reg. No.: 200105659M, Tel: +6591169524								
Vehicle Reg. No.:	SKV4680P	Date of Loss:	02/10/2018 11:00 - :59 [36 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2750410852SG	Policy/Cover Note No.:	2100429418 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/10/2018]								
Driver/Custodian:	GOH SOCK LING, KAREN (30 / Female), NRIC: S8803857F, Tel: +6591169524								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (03/01/2019): Alert - Adj Mandate Approved (S\$33430.44) - SKV4680P - Claim Handler: Loo, Tong ... - AIG_SG (22/11/2018): Alert - Adj Mandate Approved (S\$29650.50) - SKV4680P - Claim Handler: Loo, Tong ... - AIG_SG (23/10/2018): Alert - Adj Mandate Maintained - SKV4680P - Claim Handler: Loo, Tong Shing - AIG_SG (05/10/2018): Alert - Adj Mandate Approved (S\$24550.50) - SKV4680P - Claim Handler: Loo, Tong ... - AIG_SG (05/10/2018): SKV4680P / OD / 02/10/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV4680P (2750410852SG)
 OD
 Oct 2 2018 11:00AM
 [HELLA ASIA SINGAPORE PTE LTD]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	05/10/18 11:46	Adjuster Immediate Advice													Load HTM			
2	22/10/18 14:04	Adjuster Immediate Advice													Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	05/10/18 10:47	General View													Load JPG	☒		
2	05/10/18 10:47	General View													Load JPG	☒		
3	05/10/18 10:47	General View													Load JPG	☒		
4	05/10/18 10:47	General View													Load JPG	☒		
5	05/10/18 10:47	General View													Load JPG	☒		
6	05/10/18 10:47	General View													Load JPG	☒		
7	05/10/18 10:47	General View													Load JPG	☒		
8	05/10/18 10:47	General View													Load JPG	☒		
9	05/10/18 10:47	General View													Load JPG	☒		
10	05/10/18 10:47	General View													Load JPG	☒		
11	05/10/18 10:47	General View													Load JPG	☒		
12	05/10/18 10:47	General View													Load JPG	☒		
13	05/10/18 10:47	General View													Load JPG	☒		
14	05/10/18 10:47	General View													Load JPG	☒		
15	05/10/18 10:47	General View													Load JPG	☒		
16	05/10/18 10:47	General View													Load JPG	☒		
17	05/10/18 10:47	General View													Load JPG	☒		
18	05/10/18 10:47	General View													Load JPG	☒		
19	05/10/18 10:47	General View													Load JPG	☒		
20	05/10/18 10:47	General View													Load JPG	☒		
21	05/10/18 10:47	General View													Load JPG	☒		
22	05/10/18 10:47	General View													Load JPG	☒		
23	05/10/18 10:47	General View													Load JPG	☒		
24	05/10/18 10:47	General View													Load JPG	☒		
25	05/10/18 10:47	General View													Load JPG	☒		
26	05/10/18 10:47	General View													Load JPG	☒		
27	05/10/18 10:47	General View													Load JPG	☒		
28	05/10/18 10:47	General View													Load JPG	☒		
29	05/10/18 10:47	General View													Load JPG	☒		
30	05/10/18 10:47	General View													Load JPG	☒		
31	05/10/18 10:47	General View													Load JPG	☒		
32	05/10/18 10:47	General View													Load JPG	☒		
33	05/10/18 10:47	General View													Load JPG	☒		
34	05/10/18 10:47	General View													Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	05/10/18 10:47	General View		☒
36	05/10/18 10:47	General View		☒
37	05/10/18 10:47	General View		☒
38	05/10/18 10:47	General View		☒
39	05/10/18 10:47	General View		☒
40	05/10/18 10:47	General View		☒
41	05/10/18 10:47	General View		☒
42	05/10/18 10:47	General View		☒
43	05/10/18 10:47	General View		☒
44	05/10/18 10:47	General View		☒
45	05/10/18 10:47	General View		☒
46	24/10/18 11:47	Reinspection Photo		☒
47	24/10/18 11:47	Reinspection Photo		☒
48	24/10/18 11:47	Reinspection Photo		☒
49	24/10/18 11:47	Reinspection Photo		☒
50	24/10/18 11:47	Reinspection Photo		☒
51	24/10/18 11:47	Reinspection Photo		☒
52	24/10/18 11:47	Reinspection Photo		☒
53	24/10/18 11:47	Reinspection Photo		☒
54	24/10/18 11:47	Reinspection Photo		☒
55	24/10/18 11:47	Reinspection Photo		☒
56	24/10/18 11:47	Reinspection Photo		☒
57	24/10/18 11:47	Reinspection Photo		☒
58	24/10/18 11:47	Reinspection Photo		☒
59	24/10/18 11:47	Reinspection Photo		☒
60	24/10/18 11:47	Reinspection Photo		☒
61	24/10/18 11:47	Reinspection Photo		☒
62	24/10/18 11:47	Reinspection Photo		☒
63	24/10/18 11:47	Reinspection Photo		☒
64	24/10/18 11:47	Reinspection Photo		☒
65	24/10/18 11:47	Reinspection Photo		☒
66	24/10/18 11:47	Reinspection Photo		☒
67	24/10/18 11:47	Reinspection Photo		☒
68	24/10/18 11:47	Reinspection Photo		☒
69	24/10/18 11:47	Reinspection Photo		☒
70	24/10/18 11:47	Reinspection Photo		☒
71	24/10/18 11:47	Reinspection Photo		☒
72	24/10/18 11:47	Reinspection Photo		☒
73	24/10/18 11:47	Reinspection Photo		☒
74	24/10/18 11:47	Reinspection Photo		☒
75	24/10/18 11:47	Reinspection Photo		☒
76	24/10/18 11:47	Reinspection Photo		☒
77	24/10/18 11:47	Reinspection Photo		☒
78	24/10/18 11:47	Reinspection Photo		☒
79	24/10/18 11:47	Reinspection Photo		☒
80	24/10/18 11:47	Reinspection Photo		☒
81	24/10/18 11:47	Reinspection Photo		☒
82	24/10/18 11:47	Reinspection Photo		☒
83	24/10/18 11:47	Reinspection Photo		☒
84	24/10/18 11:47	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	24/10/18 11:47	Reinspection Photo		☒
86	24/10/18 11:47	Reinspection Photo		☒
87	24/10/18 11:47	Reinspection Photo		☒
88	24/10/18 11:47	Reinspection Photo		☒
89	24/10/18 11:47	Reinspection Photo		☒
90	24/10/18 11:47	Reinspection Photo		☒
91	24/10/18 11:47	Reinspection Photo		☒
92	24/10/18 11:47	Reinspection Photo		☒
93	24/10/18 11:47	Reinspection Photo		☒
94	24/10/18 11:47	Reinspection Photo		☒
95	24/10/18 11:47	Reinspection Photo		☒
96	24/10/18 11:47	Reinspection Photo		☒
97	24/10/18 11:47	Reinspection Photo		☒
98	24/10/18 11:47	Reinspection Photo		☒
99	24/10/18 11:47	Reinspection Photo		☒
100	24/10/18 11:47	Reinspection Photo		☒
101	24/10/18 11:47	Reinspection Photo		☒
102	24/10/18 11:47	Reinspection Photo		☒
103	24/10/18 11:47	Reinspection Photo		☒
104	24/10/18 11:47	Reinspection Photo		☒
105	24/10/18 11:47	Reinspection Photo		☒
106	24/10/18 11:47	Reinspection Photo		☒
107	24/10/18 11:47	Reinspection Photo		☒
108	24/10/18 11:47	Reinspection Photo		☒
109	24/10/18 11:47	Reinspection Photo		☒
110	24/10/18 11:47	Reinspection Photo		☒
111	24/10/18 11:47	Reinspection Photo		☒
112	24/10/18 11:47	Reinspection Photo		☒
113	24/10/18 11:47	Reinspection Photo		☒
114	24/10/18 11:47	Reinspection Photo		☒
115	24/10/18 11:47	Reinspection Photo		☒
116	24/10/18 11:47	Reinspection Photo		☒
117	24/10/18 11:47	Reinspection Photo		☒
118	24/10/18 11:47	Reinspection Photo		☒
119	24/10/18 11:47	Reinspection Photo		☒
120	24/10/18 11:47	Reinspection Photo		☒
121	24/10/18 11:47	Reinspection Photo		☒
122	24/10/18 11:47	Reinspection Photo		☒
123	24/10/18 11:47	Reinspection Photo		☒
124	24/10/18 11:47	Reinspection Photo		☒
125	24/10/18 11:47	Reinspection Photo		☒
126	24/10/18 11:47	Reinspection Photo		☒
127	24/10/18 11:47	Reinspection Photo		☒
128	24/10/18 11:47	Reinspection Photo		☒
129	24/10/18 11:47	Reinspection Photo		☒
130	24/10/18 11:47	Reinspection Photo		☒
131	24/10/18 11:47	Reinspection Photo		☒
132	24/10/18 11:47	Reinspection Photo		☒
133	24/10/18 11:47	Reinspection Photo		☒
134	24/10/18 11:47	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
135	24/10/18 11:47	Reinspection Photo		☒
136	24/10/18 11:47	Reinspection Photo		☒
137	24/10/18 11:47	Reinspection Photo		☒
138	24/10/18 11:47	Reinspection Photo		☒
139	24/10/18 11:47	Reinspection Photo		☒
140	24/10/18 11:47	Reinspection Photo		☒
141	24/10/18 11:47	Reinspection Photo		☒
142	24/10/18 11:47	Reinspection Photo		☒
143	24/10/18 11:47	Reinspection Photo		☒
144	24/10/18 11:47	Reinspection Photo		☒
145	24/10/18 11:47	Reinspection Photo		☒
146	24/10/18 11:47	Reinspection Photo		☒
147	24/10/18 11:47	Reinspection Photo		☒
148	24/10/18 11:47	Reinspection Photo		☒
149	24/10/18 11:47	Reinspection Photo		☒
150	24/10/18 11:47	Reinspection Photo		☒
151	24/10/18 11:47	Reinspection Photo		☒
152	24/10/18 11:47	Reinspection Photo		☒
153	24/10/18 11:47	Reinspection Photo		☒
154	24/10/18 11:47	Reinspection Photo		☒
155	24/10/18 11:47	Reinspection Photo		☒
156	24/10/18 11:47	Reinspection Photo		☒
157	24/10/18 11:47	Reinspection Photo		☒
158	24/10/18 11:47	Reinspection Photo		☒
159	24/10/18 11:47	Reinspection Photo		☒
160	24/10/18 11:47	Reinspection Photo		☒
161	24/10/18 11:47	Reinspection Photo		☒
162	24/10/18 11:47	Reinspection Photo		☒
163	24/10/18 11:47	Reinspection Photo		☒
164	24/10/18 11:47	Reinspection Photo		☒
165	24/10/18 11:47	Reinspection Photo		☒
166	24/10/18 11:47	Reinspection Photo		☒
167	24/10/18 11:47	Reinspection Photo		☒
168	24/10/18 11:47	Reinspection Photo		☒
169	24/10/18 11:47	Reinspection Photo		☒
170	24/10/18 11:47	Reinspection Photo		☒
171	24/10/18 11:47	Reinspection Photo		☒
172	24/10/18 11:47	Reinspection Photo		☒
173	24/10/18 11:47	Reinspection Photo		☒
174	24/10/18 11:47	Reinspection Photo		☒
175	24/10/18 11:47	Reinspection Photo		☒
176	24/10/18 11:47	Reinspection Photo		☒
177	24/10/18 11:47	Reinspection Photo		☒
178	20/12/18 16:56	Reinspection Photo		☒
179	20/12/18 16:56	Reinspection Photo		☒
180	20/12/18 16:56	Reinspection Photo		☒
181	20/12/18 16:56	Reinspection Photo		☒
182	20/12/18 16:56	Reinspection Photo		☒
183	20/12/18 16:56	Reinspection Photo		☒
184	20/12/18 16:56	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
185	20/12/18 16:56	Reinspection Photo		☒
186	20/12/18 16:56	Reinspection Photo		☒
187	20/12/18 16:56	Reinspection Photo		☒
188	20/12/18 16:56	Reinspection Photo		☒
189	20/12/18 16:56	Reinspection Photo		☒
190	20/12/18 16:56	Reinspection Photo		☒
191	20/12/18 16:56	Reinspection Photo		☒
192	20/12/18 16:56	Reinspection Photo		☒
193	20/12/18 16:56	Reinspection Photo		☒
194	20/12/18 16:56	Reinspection Photo		☒
195	20/12/18 16:56	Reinspection Photo		☒
196	20/12/18 16:56	Reinspection Photo		☒
197	20/12/18 16:56	Reinspection Photo		☒
198	20/12/18 16:56	Reinspection Photo		☒
199	20/12/18 16:56	Reinspection Photo		☒
200	20/12/18 16:56	Reinspection Photo		☒
201	20/12/18 16:56	Reinspection Photo		☒
202	20/12/18 16:56	Reinspection Photo		☒
203	20/12/18 16:56	Reinspection Photo		☒
204	20/12/18 16:56	Reinspection Photo		☒
205	20/12/18 16:56	Reinspection Photo		☒
206	20/12/18 16:56	Reinspection Photo		☒
207	20/12/18 16:56	Reinspection Photo		☒
208	20/12/18 16:56	Reinspection Photo		☒
209	20/12/18 16:56	Reinspection Photo		☒
210	20/12/18 16:56	Reinspection Photo		☒
211	20/12/18 16:56	Reinspection Photo		☒
212	20/12/18 16:56	Reinspection Photo		☒
213	20/12/18 16:56	Reinspection Photo		☒
214	20/12/18 16:56	Reinspection Photo		☒
215	20/12/18 16:56	Reinspection Photo		☒
216	20/12/18 16:56	Reinspection Photo		☒
217	20/12/18 16:56	Reinspection Photo		☒
218	20/12/18 16:56	Reinspection Photo		☒
219	20/12/18 16:56	Reinspection Photo		☒
220	20/12/18 16:56	Reinspection Photo		☒
221	20/12/18 16:56	Reinspection Photo		☒
222	20/12/18 16:56	Reinspection Photo		☒
223	20/12/18 16:56	Reinspection Photo		☒
224	20/12/18 16:56	Reinspection Photo		☒
225	20/12/18 16:56	Reinspection Photo		☒
226	20/12/18 16:56	Reinspection Photo		☒
227	20/12/18 16:56	Reinspection Photo		☒
228	20/12/18 16:56	Reinspection Photo		☒
229	20/12/18 16:56	Reinspection Photo		☒
230	20/12/18 16:56	Reinspection Photo		☒
231	20/12/18 16:56	Reinspection Photo		☒
232	20/12/18 16:56	Reinspection Photo		☒
233	20/12/18 16:56	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 10:44	Certificate of Insurance	 Load PDF	
2	05/10/18 10:44	Driver's Driving License nirc	 Load PDF	
3	05/10/18 10:44	estimate	 Load PDF	
4	05/10/18 10:44	Singapore Accident Statement	 Load PDF	
5	22/10/18 13:58	SUPPLEMENTARY	 Load PDF	
6	03/01/19 10:14	ESTIMATE MARKING	 Load PDF	
7	21/02/19 14:10	Workshop Invoice	 Load PDF	
8	21/02/19 14:10	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/10/18 17:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/10/18 17:29	Accident Photo	 Load JPG	☒
2	02/10/18 17:29	Accident Photo	 Load JPG	☒
3	02/10/18 17:29	Accident Photo	 Load JPG	☒
4	02/10/18 17:29	Accident Photo	 Load JPG	☒
5	02/10/18 17:29	Accident Photo	 Load JPG	☒
6	02/10/18 17:29	Accident Photo	 Load JPG	☒
7	02/10/18 17:29	Accident Photo	 Load JPG	☒
8	02/10/18 17:29	Accident Photo	 Load JPG	☒
9	02/10/18 17:29	Accident Photo	 Load JPG	☒
10	02/10/18 17:29	Accident Photo	 Load JPG	☒
11	02/10/18 17:29	Accident Photo	 Load JPG	☒
12	02/10/18 17:29	Accident Photo	 Load JPG	☒
13	02/10/18 17:29	Accident Photo	 Load JPG	☒
14	02/10/18 17:29	Accident Photo	 Load JPG	☒
15	02/10/18 17:29	Accident Photo	 Load JPG	☒
16	02/10/18 17:29	ACCIDENT SCENE	 Load JPG	☒
17	02/10/18 17:29	ACCIDENT SCENE	 Load JPG	☒
18	02/10/18 17:29	ACCIDENT SCENE	 Load JPG	☒
19	02/10/18 17:29	ACCIDENT SCENE	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/10/18 17:05	Sketch Plan	 Load JPG	☒
2	02/10/18 17:05	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18017998/ATBE2

Date: 21/02/2019

REFERENCE

Insured/Claimant: HELLA ASIA SINGAPORE PTE LTD

Policy No: 2100429418

Date of Loss: 02/10/2018

Nature of Claim: OD

Claim No: 2750410852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV4680P

Make & Model: AUDI Q5, 2.0 (A)

Reg. Date: 18/09/2015 (Man. Year: 2014)

Colour: Grey

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: CNC081068

Chassis No: WAUZZZ8R7FA049538

Odometer: 36294 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Tyre Size: 235/55 R19

Rear Left Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,282.48	20,879.40	19,403.08	48.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,104.00	11,364.00	9,740.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,386.48	32,243.40	29,143.08	47.47
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	60,386.48	31,243.40	29,143.08	48.26
+ GST 7.00/7.00% (S\$)	4,227.05	2,187.04	2,040.01	48.26
Nett Amount (S\$)	64,613.53	33,430.44	31,183.09	48.26

INSPECTION

Date of Assignment: 04/10/2018

Date Inspected: 04/10/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,237.00 FS	*1,789.60 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Damaged	236.00 FS	*188.80 FS
3	1		*FRONT SPOILER	Deformed	540.00 FS	*431.60 FS
4	1		*CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
5	1		*FOAM FILLER PIECE	Cracked	97.00 FS	*77.60 FS
6	4		*PULL STRAP	Not Necessary	175.00 FS	*- FS
7	1		*SECURING STRIP - LH/RH	N/S Damaged	62.00 FS	*24.96 FS
8	1		*BUMPER COVER	Distorted	109.00 FS	*87.20 FS
9	1		*AIR GUIDE GRILLE SATIN BLACK / CHROME - LH/RH	N/S Missing	614.00 FS	*245.20 FS
10	1		*SIDE REINFORCEMENT	Bent	571.00 FS	*456.80 FS
11	1		*COVER	Deformed	56.00 FS	*44.24 FS
12	1		*CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
13	1		*SUPPORT - LH/RH	N/S Damaged	50.00 FS	*19.92 FS
14	2		*GUIDE SECTION - LH/RH	Damaged	64.00 FS	*50.72 FS
15	4		*SENSOR	Not Necessary	842.00 FS	*- FS
16	1		*WIRING SET FOR BUMPER	Not Necessary	515.00 FS	*- FS
17	1		*SIGNAL HORN - RH LOW TONE	Damaged	178.00 FS	*142.40 FS
18	1		*SIGNAL HORN - LH HIGH TONE	Damaged	178.00 FS	*142.40 FS
19	1		*HORN BRACKET - LH HIGH TONE	Not Necessary	22.00 FS	*- FS
20	1		*FRONT FENDER - LH/RH	N/S Buckled / O/S Repair	1,738.00 FS	*695.20 FS
21	1		*ATTACHMENT PARTS FOR BOTH FENDERS	N/S Necessary	115.00 FS	*46.00 FS
22	1		*BRACKET - FRONT LH / RH	N/S Bent	94.00 FS	*36.88 FS
23	1		*BRACKET - CENTRE	N/S Bent	86.00 FS	*34.16 FS
24	1		*BRACKET - REAR	N/S Bent	86.00 FS	*34.16 FS
25	1		*FENDER BRACE	Bent	76.00 FS	*60.16 FS
26	1		*WHEEL HOUSING LINER - LH	Torn	231.00 FS	*184.80 FS
27	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	89.00 FS	*- FS
28	1		*WHEEL SPOILER - FRONT LH	Not Necessary	58.00 FS	*- FS
29	1		*BONNET	Distorted	3,562.00 FS	*2,849.60 FS
30	1		*ATTACHMENT PARTS FOR BONNET	Necessary	123.00 FS	*98.40 FS
31	2		*LID HINGE - LH/RH	Bent	180.00 FS	*142.56 FS
32	1		*BONNET CATCH HOOK	Bent	122.00 FS	*97.60 FS
33	2		*GAS FILLED STRUT	Not Necessary	209.00 FS	*- FS
34	2		*BONNET MOUNTING	Not Necessary	49.00 FS	*- FS
35	2		*BONNET INNER STOP BUFFER	Not Necessary	10.00 FS	*- FS
36	1		*BONNET STOP BUFFER	Not Necessary	17.00 FS	*- FS
37	1		*BONNET EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
38	1		*BONNET LID LOCK WITH MICRO - SWITCH	Damaged	188.00 FS	*150.40 FS
39	1		*CONNECTOR HOUSING BRACKET	Damaged	9.00 FS	*6.48 FS
40	1		*CABLE HOLDER	Not Necessary	7.00 FS	*- FS
41	1		*BONNET LID LOCK CABLE	Not Necessary	43.00 FS	*- FS
42	1		*BONNET LOCK COVER	Damaged	20.00 FS	*15.36 FS
43	2		*FRONT FENDER LINING - LH/RH	Not Necessary	334.00 FS	*- FS
44	1		*HEADLIGHT MOUNTING - LH/RH	N/S Cracked	208.00 FS	*82.40 FS
45	1		*HEADLIGHT - LH/RH	N/S Smashed	4,828.00 FS	*1,931.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*HEADLIGHT CONTROL UNIT	Damaged	1,018.00 FS	*814.40 FS
47	1		*HEADLIGHT POWER MODULE	Damaged	501.00 FS	*400.40 FS
48	1		*GAS DISCHARGE LAMP	Damaged	394.00 FS	*314.80 FS
49	1		*RETAINING PLATE	Cracked	68.00 FS	*54.16 FS
50	1		*RADIATOR GRILLE	Cracked	1,556.00 FS	*1,244.80 FS
51	1		*INSCRIPTION QUATTRO	Necessary	83.00 FS	*66.16 FS
52	1		*STRIKER PLATE	Damaged	107.00 FS	*85.20 FS
53	1		*HEADLIGHT LIFT CYLINDER - LH/RH	N/S Cracked	348.00 FS	*139.20 FS
54	1		*HOSE ROLLERS FOR 5 M	Cut	164.00 FS	*131.20 FS
55	1		*WASH WATER RESERVOIR	Not Necessary	190.00 FS	*- FS
56	1		*LOCK CARRIER WITH MOUNTING	Cracked	970.00 FS	*776.00 FS
57	1		*A/C COMPRESSOR	Not Necessary	1,781.00 FS	*- FS
58	1		*A/C CONDENSOR	Dented	651.00 FS	*520.40 FS
59	1		*PRESSURE SENDER	Cracked	165.00 FS	*132.00 FS
60	1		*VALVE	Not Necessary	46.00 FS	*- FS
61	1		*COOLANT RADIATOR WITH OIL COOLER	Distorted	1,206.00 FS	*964.80 FS
62	2		*RUBBER BUSH	Necessary	12.00 FS	*8.96 FS
63	4		*RUBBER BUSH - LOWER	Necessary	29.00 FS	*22.24 FS
64	4		*COOLANT CONCENTRATE 1.5 LTR	Necessary	133.00 FS	*65.28 FS
65	2		*RADIATOR AIR DUCT - LH/RH	Cracked	40.00 FS	*15.92 FS
66	1		*RADIATOR COVER	Cracked	27.00 FS	*20.88 FS
67	1		*RADIATOR SEALING STRIP	Cut	20.00 FS	*15.44 FS
68	1		*TWIN FAN RING	Cracked	226.00 FS	*180.40 FS
69	2		*RADIATOR FAN	Cracked	1,439.00 FS	*1,150.80 FS
70	1		*RADIATOR CONTROL UNIT	Not Necessary	740.00 FS	*- FS
71	1		*CHARGE AIR COOLER	Not Necessary	492.00 FS	*- FS
72	1		*AIR FILTER	Not Necessary	269.00 FS	*- FS
73	1		*INTAKE MANIFOLD	Not Necessary	67.00 FS	*- FS
74	1		*AIR INTAKE BOOT	Not Necessary	95.00 FS	*- FS
75	1		*ADAPTER	Not Necessary	10.00 FS	*- FS
76	1		*ADAPTER COVER	Not Necessary	355.00 FS	*- FS
77	1		*HALOGEN FOG LAMP - LH	Not Necessary	227.00 FS	*- FS
78	1		*FLAT CONTACT HOSE	Cracked	43.00 FS	*32.64 FS
79	2		*WATER DEFLECTOR STRIP - LH/RH	Cut	116.00 FS	*92.32 FS
80	1		*SHOCK ABSORBER MOUNTING - LH	Not Necessary	75.00 FS	*- FS
81	1		*SIDE MEMBER	Repair	1,268.00 FS	*- FS
82	1		*SIDE MEMBER REINFORCEMENT	Repair	1,297.00 FS	*- FS
83	1		*SIDE MEMBER CROSS PANEL - LH	Repair	454.00 FS	*- FS
84	1		*FRONT DOOR COVER - LH	Not Necessary	449.00 FS	*- FS
85	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
86	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
87	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
88	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
89	1		*SUNDRIES	Necessary	500.00 FS	*235.52 FS
90	1		*REINFORCEMENT BEAM BRACKET LH	Bent	165.20 FS	*165.20 FS
91	1		*REINFORCEMENT BEAM BRACKET RH	Bent	165.20 FS	*165.20 FS
92	1		*SECURING PLATE LH	Damaged	32.48 FS	*32.48 FS
93	1		*SECURING PLATE RH	Damaged	32.48 FS	*32.48 FS
94	1		*SUPPORT FOR COOLANT RADIATOR	Damaged	52.48 FS	*52.48 FS
95	1		*FRONT FENDER UPPER RAIL CONNECTING PLATE	Bent	252.80 FS	*252.80 FS
96	1		*FRONT FENDER CLOSING ELEMENT LEFT LOWER	Damaged	363.20 FS	*363.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
97	1		*FRONT FENDER RAIL BRACKET	Bent	12.48 FS	*12.48 FS
98	1		*AIR COND STICKER	Necessary	4.88 FS	*4.88 FS
99	1		*LED HEAT SINK	Damaged	710.80 FS	*710.80 FS
100	1		*HEADLIGHT HOSE	Cut	21.76 FS	*21.76 FS
101	1		*HEADLIGHT RETAINING BRACKET	Cracked	16.40 FS	*16.40 FS
102	1		*HEADLIGHT SPACER	Cracked	55.36 FS	*55.36 FS
103	1		*WATER RESERVOIR CONNECTING TUBE - ELBOW	Damaged	29.12 FS	*29.12 FS
104	1		*WATER RESERVOIR CONNECTING TUBE - STRAIGHT	Damaged	17.92 FS	*17.92 FS
105	1		*COOLANT PRESSURE SENSOR	Damaged	137.60 FS	*137.60 FS
106	1		*AIR COND PRESSURE HOSE COMPRESSOR > CONDENS	Bent	262.80 FS	*262.80 FS
107	1		*AIR COND HOSE	Bent	386.00 FS	*386.00 FS
108	1		*LOCK CARRIER SUPPORT LH	Damaged	37.92 FS	*37.92 FS
109	1		*LOCK CARRIER SUPPORT RH	Damaged	37.92 FS	*37.92 FS
110	1		*HORN BRACKET - RH LOW TONE	Not Necessary	22.00 FS	*- FS
111	1		*INTAKE FRONT MANIFOLD	Damaged	32.00 FS	*25.04 FS
112	1		*AIR COND V-BELT	Cut	35.68 FS	*35.68 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	40,282.48	20,879.40
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, CHARGE AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BOTH HEADLIGHTS AND BONNET. CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,800.00	3,750.00
4	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, BOTH FRONT FENDER, BONNET, BONNET HINGES, LHS FENDER TOP SUPPORT, LHS FRONT DOOR AND DOOR COVER. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT	New	6,100.00	3,300.00
5	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
7	CUT OUT AND REWELD LHS FENDER SUPPORT AND CLOSING ELEMENT	New	2,100.00	1,500.00
8	TO RESPRAY LHS FENDER SUPPORT AND CLOSING ELEMENT	New	600.00	550.00
Gross Labour Cost (S\$)			21,104.00	11,364.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >