

22/03/2002

ASS. REC. BY:

REF:

CG/FCI18017999/Gdpnz

Special Instruction:

Survivor:

All

ASSIGNMENT (Office)

From (Person):

CWS Karen Tan

of

FCL

Date/Time:

04.10.2018 1204pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5616 P

Insured:

SHM 3896L

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Silk 7 Sin Ming Ind Est # 01-76

Policy No:

Claim No:

DIS007255MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

H.O.D. Endorsement:

Date/Time:

04.10.2018 157pm

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 5616P - X

SHM 3896L - CG/FCI18004279 / Vrd32

DIA: 01/10/2018

05/10/18 @ 2.01p revised to Karen Tan by email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Alan's united
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW5616P Yr Regn: 07 Nov 2014
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes C200 c.c. 1991
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 85264 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD2050422R002952
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: W45/35ZR19
 R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

04-10-18

Survey held at

W/S

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 20/11 Action / Instruction: Final w/ \$7307 with BOSS (Red 3029.20, 29%)
no lump sum

RECEIVED 03 DEC 2018

[Signature]

30/11/2018

Date/Time, File Pass to?

1) 02/12/18

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

☐ : S + RS, \$ _____

☐ : Photos

☐ : Others

Report Format :

Lump Sum / I.B.I. (\$) 78 7307

TOTAL

170

50

50

91

361



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007255MFSH
Our Ref: CS/FCI18017999/Gqb

Date: 05 October 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 5616P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/10/2018 at the premises of M/s ALAN'S UNITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 10,336.20 .
Revised Estimate Amount	: S\$ 6,520.60 .
"Check" Items Amount	: S\$ 3,415.60 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-10-2018	Our Ref No. D18007255MFSH
Accident Date	02-10-2018	Claim Type. Third Party
Insured Vehicle	SHA3896L	Third Party Vehicle. SKW5616P
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 0	Fax No. 64596550
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 5 October 2018 2:01 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007255MFSH/1
Attachments: CSFCI18017999Gqb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKW 5616P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 4 October 2018 1:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007255MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 4 October, 2018 12:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007255MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6526A
Vehicle Details	
Vehicle No.:	SKW5616P
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27492030168137
Chassis No.:	WDD2050422R002952
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$37,545.00
Original Registration Date:	07 Nov 2014
First Registration Date:	07 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$34,563.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2024
PARF Rebate Amount:	\$25,922.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$73,010.00
COE Rebate Amount:	\$44,434.00
Total Rebate Amount:	\$70,356.00

The information contained herein is correct as at 05 Oct 2018

OK

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:	S8846526A
Owner ID Type:	Singapore NRIC
Owner Name:	LEE KIAT FONG, ALEXANDER
Registered Address:	APT BLK 32 CASSIA CRESCENT #03-70 SINGAPORE 390032
Mailing Address:	-
Birth Date:	19 Nov 1988

Vehicle Particulars

Vehicle No.:	SKW5616P
Previous Vehicle No.:	SKE533Y
Effective Date of Ownership:	13 Oct 2015
Original Regn Date:	07 Nov 2014
Registration Date:	07 Nov 2014
Year of Manufacture:	2014
Vehicle Type:	Passenger Motor Car
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	WDD2050422R002952
Engine No.:	27492030168137
Engine Capacity / Power Rating:	1991 cc / -
Maximum Power Output:	135.0 kW (181 bhp)
Propellant:	Petrol
Max Unladen Weight:	1465 kg
Maximum Laden Weight:	2030 kg
Open Market Value:	\$37,545.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2024
Minimum PARF Benefit:	\$17,281.00
No. of Transfers:	1
IU Label No.:	1125509018
COE No.:	2014100103000293Z
COE Expiry Date:	06 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Registration Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium:	\$73,010.00 / -
Actual QP Paid:	\$73,010.00
QP (Regn Cat):	\$73,010.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$73,010.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$17,545.00 (140%)
Actual ARF Paid:	\$34,563.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	134.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category B.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

GARAGE R PERFORMANCE CENTRE PTE LTD
8 TAGGORE DRIVE
SINGAPORE 787624.

DATE : 03.10.2018

ATTN: MR. JASON LIN

by FAX - 64539123

STATEMENT OF ACCOUNT AS AT 30 SEPTEMBER 2018

date	invoice	vehicle no.	make / model	amount	balance
23.08.18	134384 X	SLR 4509S	HONDA FREED	\$ 321.00 X	
					\$ 321.00
08.09.18	134559	SFL 8226D	T/ AE86	\$ 192.60.	
14.09.18	134631	SKR 7713E	M/BENZ CLS350	492.20 /	
18.09.18	134656	SKN 8313R	NISSAN GTR	267.50 /	
	134669	SLB 313U	LAND ROVER	1,134.20 /	
21.09.18	134707	SLU 2949U	H/ TYPE R	428.00 /	
22.09.18	134710	GBA 5389S	SUZUKI	235.40 /	
29.09.18	134795	SJK 9000P	MINI ONE	1,433.80 /	
		***	*****	***	\$ 4,183.70

Mr: AC Dept
Please fax Invoice NO. 134384

TOTAL :						\$ 4,504.70
Current	1 Month	2 Month	3 Month	4 Month	5 Month	
\$ 4,183.70	\$ 321.00	\$ -	\$ -	\$ -	\$ -	

* Your prompt settlement will be much appreciated.

* If you do not agree with the above, please notify us immediately.


 ALAN'S UNITED AUTO PTE LTD

#282 P.001/001

03/10/2018 13:45

To: GARAGE R PERFORMANCE

64596550

From: Alan's United Auto Pte Ltd

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05856

Vehicle Insured : SHA3896L
Accident Date : 02-Oct-2018

Date : 03-Oct-2018

Our Ref : 218161 (FIRST) / CHAN

PAGE : 1

LEE KIAT FONG ALEXANDER
BLK 32 CASSIA CRESCENT
#03-70
Singapore 390032

ESTIMATED COST OF REPAIR FOR M/BENZ C200 SKW5616P

1 pc	N/s tailamp	R / CRA	795.00	/
1 pc	N/s tailamp lower bracket	X / CRA	32.00	/
1 pc	N/s rear boot side garnish	- at	49.00	/
1 pc	Rear bumper fascia	- CRA	1,845.00	/
1 pc	Rear n/s bumper side retainer	- re	54.00	/
2 pcs	Rear bumper side chrome	/ MCL @ S\$ 98.00	196.00	/
1 pc	Rear n/s bumper parking sensor	- Pms	306.00	/
1 pc	Rear bumper lower spoiler	/ re	229.00	/
4 pcs	Rear lower spoiler rivet	/ MCL @ S\$ 5.00	20.00	/
1 pc	Rear lower spoiler chrome	- BR.	260.00	/
2 pcs	Lower spoiler parking sensor	/ IPC @ S\$306.00	612.00	306
1 pc	Rear exhaust silencer box	- MC ST PM	1,217.00	/
4 pcs	Rear exhaust mounting	- MC ST PM @ S\$ 41.00	164.00	/
1 pc	Rear exhaust heat seal	- 8 NN	179.00	X
1 pc	Rear exhaust side heat seal	- R / BUC	79.00	/
1 pc	Rear exhaust pipe protector	- R / CRA	98.00	/
1 pc	Rear exhaust box joint ring	- 8 NN	37.00	X
1 pc	Rear bumper reinforcement	- ST	688.00	/
1 pc	Rear bumper inner parts	- R / CRA	92.00	/
1 pc	Rear end panel	- X	1,499.00	X
1 pc	Rear spare tyre panel	- R / Repair	567.00	X
			9,018.00	6430
Less 10% :			901.80	5787
			8,116.20	

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHA3896L

Page : 2

To remove inner trim ,rear seat,
trim board and carpet

60 120.00

To apply undersealing

N 7 100.00

To remove and renew exhaust
silencer box

60 100.00

To putty and spray replaced parts

800 900.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600-800 1,000.00

Total : S\$10,336.20
=====

Singapore Dollars Ten Thousand Three Hundred
and Thirty Six and Cents Twenty Only

7307

6 Days -

part by part.

best of paint photos.

Guo Qian - 8288 0282

04/10/18.


5/10/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017999/Gqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3896L	Veh. Inspected	SKW 5616P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007255MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	04/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES C200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2050422R002952	Colour	SILVER	
Odometer	85264	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 ZR19	YOKOHAMA	6 mm	
L/H Front Tyre	245/35 ZR19	YOKOHAMA	6 mm	
R/H Rear Tyre	245/35 ZR19	YOKOHAMA	6 mm	
L/H Rear Tyre	245/35 ZR19	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2018	Inspection Date	04/10/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5616P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S TAILLAMP	CRACKED	795.00	795.00
1	N/S TAILLAMP LOWER BRACKET	CRACKED	32.00	32.00
1	N/S REAR BOOT SIDE GARNISH	CUT	49.00	49.00
1	REAR BUMPER FASCIA	CRACKED	1,845.00	1,845.00
1	REAR N/S BUMPER SIDE RETAINER	DEFORMED	54.00	54.00
2	REAR BUMPER SIDE CHROME @\$98.00	NECESSARY	196.00	196.00
1	REAR N/S BUMPER PARKING SENSOR	DAMAGED	306.00	306.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	229.00	229.00
4	REAR LOWER SPOILER RIVET @\$5.00	NECESSARY	20.00	20.00
1	REAR LOWER SPOILER CHROME	BROKEN	260.00	260.00
2	LOWER SPOILER PARKING SENSOR @\$306.00	DAMAGED (1 PC ONLY)	612.00	306.00
1	REAR EXHAUST SILENCER BOX	BENT	1,217.00	1,217.00
4	REAR EXHAUST MOUNTING @\$41.00	NECESSARY	164.00	164.00
1	REAR EXHAUST HEAT SEAL	NOT NECESSARY	179.00	-
1	REAR EXHAUST SIDE HEAT SEAL	BUCKLED	79.00	79.00
1	REAR EXHAUST PIPE PROTECTOR	CRACKED	98.00	98.00
1	REAR EXHAUST BOX JOINT RING	NOT NECESSARY	37.00	-
1	REAR BUMPER REINFORCEMENT	BENT	688.00	688.00
1	REAR BUMPER INNER PARTS	CRACKED	92.00	92.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,499.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	567.00	-
	LESS 10% DISCOUNT		-901.80	-643.00
			8,116.20	5,787.00
LABOUR				
	TO REMOVE INNER TRIM, REAR SEAT, TRIM BOARD AND CARPET.		120.00	60.00
	TO APPLY UNDERSEALING.	NOT NECESSARY	100.00	-
	TO REMOVE AND RENEW EXHAUST SILENCER BOX.		100.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	800.00

Report Ref No. CS/FCI18017999/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SPARE TYRE PANEL.		1,000.00	600.00
			2,220.00	1,520.00
	GRAND TOTAL		10,336.20	7,307.00
RECOMMENDED COST OF REPAIRS				7,307.00

Report Ref No. CS/FCI18017999/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

No. : 05856

Date : 03-Oct-2018

PAGE : 1

Vehicle Insured : SHA3896L
Accident Date : 02-Oct-2018

Our Ref : 218161 (FIRST) / CHAN

LEE KIAT FONG ALEXANDER
BLK 32 CASSIA CRESCENT
#03-70
Singapore 390032

ESTIMATED COST OF REPAIR FOR M/BENZ C200 SKW5616P

1 pc	N/s tailamp	2 - CRA	795.00
1 pc	N/s tailamp lower bracket	2 - CRA	32.00
1 pc	N/s rear boot side garnish	1 - at	49.00
1 pc	Rear bumper fascia	1 - CRA	1,845.00
1 pc	Rear n/s bumper side retainer	1 - re	54.00
2 pcs	Rear bumper side chrome	1 - MC @ S\$ 98.00	196.00
1 pc	Rear n/s bumper parking sensor	1 - pm	306.00
1 pc	Rear bumper lower spoiler	1 - re	229.00
4 pcs	Rear lower spoiler rivet	1 - MC @ S\$ 5.00	20.00
1 pc	Rear lower spoiler chrome	1 - BR	260.00
2 pcs	Lower spoiler parking sensor	1 - IPC @ S\$ 306.00	612.00
1 pc	Rear exhaust silencer box	1 - BT @ S\$ 41.00	1,217.00
4 pcs	Rear exhaust mounting	1 - NN	164.00
1 pc	Rear exhaust heat seal	1 - Bul	179.00
1 pc	Rear exhaust side heat seal	1 - CRA	79.00
1 pc	Rear exhaust pipe protector	1 - NN	98.00
1 pc	Rear exhaust box joint ring	1 - ST	37.00
1 pc	Rear bumper reinforcement	1 - CRA	688.00
1 pc	Rear bumper inner parts	1 - CRA	92.00
1 pc	Rear end panel	1 - Repair.	1,499.00
1 pc	Rear spare tyre panel	1 - Repair.	567.00
			9,018.00
Less 10% :			901.80

8,116.20

Good Qul.
10/10/18

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SHA3896L

To remove inner trim, rear seat,
trim board and carpet

60 120.00

To apply undersealing

NW X 100.00

To remove and renew exhaust
silencer box

60 100.00

800 900.00

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

~~600-800~~ 1,000.00

Total : S\$10,336.20
=====

Singapore Dollars Ten Thousand Three Hundred
and Thirty Six and Cents Twenty Only

6 Days -

part by part.

best all paint photos.

Guo Qiang - 8288 0282

04/10/18.