



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 08.10.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>

Tanpin 97495749
'wp'
11/10/18 @ 2pm
02 days
Resurvey after repair
sur@lkkant.com

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2503L HONDA GRACE HYBRID (2017)

To Supply

1) 1pc	Front bumper	\$	655.60	dl
2) 1set	Front bumper clip	\$	20.00	ae
3) 1pc	Front bumper tow hook cover	\$	14.80	Rp
Sub total parts		\$	690.40	
Less: 20% discount		\$	(138.08)	
		\$	552.32	

L/charges

1) To remove front bumper. Replace front bumper & the above parts. Align & adjust front bumper.	\$	200.00 ✓
2) To putty, respray painting front bumper.	\$	250.00 ²⁰⁰
Sub total L/charges		<u>\$ 450.00</u>
Estimated Grand Total		<u>\$ 1,002.32</u>