




## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Service Pte Ltd</b>	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 03/10/2018

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB1562Z
Case Reference Number	BUS/09/18/1037
Registration Date	23/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Muhammad Shamim Bin Abdullah
Type of Accident	Head On
Accident Date and Time	25/09/2018 2:15 PM
Accident Reported Date and Time	25/09/2018 5:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098151
Special Instruction to ARC, if any	SMB1562Z - LEFT FRONT PORTION DAMAGED SJN41878B - INSURED WITH AIG - RIGHT FRONT PORTION DAMAGED
Prepared Date and Time	02/10/2018 2:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,085.43</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Tan Ah Leong	
ARC / Surveyor Sign Off Date	02/10/2018 2:21 PM	
Signature		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	



### SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/10/2018

User ID : GohKK2

Total Labour	\$1,060.00	795
--------------	------------	-----

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	600
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$708.00</b>	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4005301			SMRT LOGO STICKER	1.00	\$75.00	0.00	\$75.00	Replace	ARC
6009375			LOCK CAM	1.00	\$120.00	10.00	\$108.00	Replace	BROKEN
6010153	Body	F01001-CW264	COVER, HEADLAMP-FRT LH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	SPR CRA
6010304	VE	8-25101-6539	HEADLAMP, LH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	SCR
6010306	VE	81-25320-6111	FLASHER, AUX HEADLAMP, LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	BROKEN
<b>Total</b>					<b>\$3,677.70</b>		<b>\$3,317.43</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

NA2 LKK  
 3/10/18 1100  
 PIP  
 BEFORE PAINT PHOTO  
 2 DAYS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: