



Case Details

Case Reference Number : TAX/09/18/2144
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4278D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-3975-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Lonpac Insurance Bhd
 Accident Date and Time : 29/09/2018 05:00 AM
 Vehicle Age(In Months) : 10

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation									Surveyor Approval			
BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair ✕ RP
One Time Key In			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Given ✕ XSUL
One Time Key In			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace ✕ BT
One Time Key In			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Given ✕ XSUL
One Time Key In			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Given ✕ XSUL
One Time Key In			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Not Given ✕ XSUL
One Time Key In			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace ✕ NSC
Total Spare Part Cost								1,109.85		Surveyor Total	80.32	
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,109.85		Final Sur Total	80.32	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT RH PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
Total:		378.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO WASH AND VACUUM	60.00	0	NN
Total:		140.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,109.85	80.32
Total Labour Cost	338.00	200.00
Total Spray Painting	378.00	200.00
Other	140.00	0.00
Overall Total	1,965.85	480.32
Lump Sum Repair Option		
Lump Sum Total	0.00	480.32
Surveyor Approved Amount		480.32
No of Repair Days*	3	2
Remarks	-	PART BY PART REPAIR 2 DAYS AFTER REPAIR PHOTOS
Surveyor Name		Naz
Signature		
Survey Date	04/10/2018	Save Clear

NAZ LKK
 4/10/18 1600
 P/P
 2 DAYS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer