

INS. CASE OWNER:

CC 3, LPL 180 (8023, K1ja3n2)

LKK:  
IDAC:

Surveyor:

Ank

DOI:

ASSIGNMENT

3-10-18

Date / Time:

3-10-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 7885 H

Claim No.:

Name of Insured:

Guy Warren Food Supply Pte

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

1/10/18

Place of Accident:

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SHC 6818 H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/10

Guy

SHC 6818 H. NA/INTL 002122/1/102; POA. 10/10/18  
GBB 7885 H. 651/ACU 11205531/16 XX; NA/INTL 11/10/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

1/10

Sent By:

Guy

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3-1-19

Confirm with:

GARY

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1,391. x x

Loss of Rental (LOR):

SS

219.88

( 2 days) 109.94

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

80 (\$ 40 x 2 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.22

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

1,692.88

Global Sum SS:

1,692

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,692. x x

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

x

Payee 3: (Strike if N.A.)

SS

Name 3:

x

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

H2B  
COPY SENT  
m/19

08/11/13

Surveyor: Kalvin

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 6818H Yr Regn: 4 Oct 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai 230 c.c. 1582Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 109206 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TMA02814VHJ141898Gen. Cond: Good / 60 / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195 / 65 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 2/10/18 D.O.I. 3/10/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/10/18 Checked L/S \$1300 / 30%Lump sumR(\$2,597.01/67%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/LPC18018023/K1ja3

Date: 05/10/2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 6818H**

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.10.2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi have the following to report:-

Workshop Estimate Amount	: S\$	3,897.01
Revised Estimate Amount	: S\$	1,300.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	1,300.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion




**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

 <b>PREMIER TAXIS</b>	<b>HIRER / <u>RELIEF</u> SUPER RELIEF</b>
VEHICLE NO.	SHC 6818H
CONTACT NO.	9021 3326
NEW MAILING ADDRESS (if any)	✓

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S20211191



Name

SUBRAMANIAM S/O  
MARIYAPPAN

Race

INDIAN

Date of birth

03-12-1953

Sex

M

Country of birth

MALAYSIA

S20211191



NRIC No. S20211191



Date of issue

29-12-2011

Address

APT. BLK 662 CHOA CHU KANG CRESCENT  
#09-271  
SINGAPORE 680662

4813151

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 06 Dec 1974



License No: S20211191

NP 428A

Land Transport Authority

**VOCATIONAL LICENCE**

Portrait photo of Subramaniam S/O M

Licence No : S20211191

Name : SUBRAMANIAM S/O M

Issue Date : 8/2/2012

Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number** : 5095103893

**Cover** : Third Party

1. Index mark and Registration Number of Vehicle : **SHC6818H**  
Chassis Number : TMAD281UVHJ141898
2. Name of Policyholder : **PREMIER TAXIS PTE. LTD.**
3. Effective Date of Insurance : **20 Oct 2017**
4. Expiry Date of Insurance : **19 Oct 2018**
5. Persons or Classes of Persons entitled to drive\*
  - (a) The Policyholder.
  - (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use\*
  - (a) Use as a Taxi.
  - (b) Use for social domestic and pleasure purposes.

**This Policy does not cover**

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: UNITED OVERSEAS BANK LIMITED
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : **HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)**  
Date of Issue : **16 Oct 2017 17:13 hrs**

**For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED**

Countersigned By:



**Authorised Officer**



**Chief Executive**

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H

Owner ID Type: Company

Owner Name: PREMIER TAXIS PTE. LTD.

Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address: -

Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHC6818H

Previous Vehicle No.: -

Effective Date of Ownership: 04 Oct 2017

Original Regn Date: 04 Oct 2017

Registration Date: 04 Oct 2017

Year of Manufacture: 2017

Vehicle Type: Public Transport Taxi (Motor Car)

Vehicle Scheme: Taxi (Company)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: HYUNDAI

Vehicle Model: I30 GDH 1.6 TCI SDR DCT

Primary Colour: Silver

Secondary Colour: -

Passenger Capacity: 4

Chassis No.: TMAD281UVHJ141898

Engine No.: D4FBHZ172977

Engine Capacity/Power Rating: 1582 cc / -

Maximum Power Output: 100.0 kW (134 bhp)

Propellant: Diesel

Max Unladen Weight: 1496 kg

Maximum Laden Weight: 1940 kg

Open Market Value: \$19,970.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Oct 2025

Minimum PARF Benefit: \$7,482.00

No. of Transfers: 0

IU Label No.: 1050709824

COE No.: 2017100401003696K

COE Expiry Date: 03 Oct 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)

Quota Premium (QP) / Prevailing Quota Premium: - / \$42,564.00

PQP Paid: \$34,052.00

QP (Regn Cat): -

OPC Cash Rebate Eligibility: No

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
 Owner ID Type: Company  
 Owner Name: PREMIER TAXIS PTE. LTD.  
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
 Mailing Address: -  
 Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHC6818H  
 Previous Vehicle No.: -  
 Effective Date of Ownership: 04 Oct 2017  
 Original Regn Date: 04 Oct 2017  
 Registration Date: 04 Oct 2017  
 Year of Manufacture: 2017  
 Vehicle Type: Public Transport Taxi (Motor Car)  
 Vehicle Scheme: Taxi (Company)  
 Vehicle Attachment 1: Air-Con (Taxi)  
 Vehicle Attachment 2: -  
 Vehicle Attachment 3: -  
 Vehicle Make: HYUNDAI  
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
 Primary Colour: Silver  
 Secondary Colour: -  
 Passenger Capacity: 4  
 Chassis No.: TMAD281UVHJ141898  
 Engine No.: D4FBHZ172977  
 Engine Capacity/Power Rating: 1582 cc / -  
 Maximum Power Output: 100.0 kW (134 bhp)  
 Propellant: Diesel  
 Max Unladen Weight: 1496 kg  
 Maximum Laden Weight: 1940 kg  
 Open Market Value: \$19,970.00  
 PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 03 Oct 2025  
 Minimum PARF Benefit: \$7,482.00  
 No. of Transfers: 0  
 IU Label No.: 1050709824  
 COE No.: 2017100401003696K  
 COE Expiry Date: 03 Oct 2025  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)  
 Quota Premium (QP) / Prevailing Quota Premium: - / \$42,564.00  
 PQP Paid: \$34,052.00  
 QP (Regn Cat): -  
 OPC Cash Rebate Eligibility: No



# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

3-Oct-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHC 6818 H

1 pc	Tailgate lower garnish <i>X repair</i>	\$	362.61
1 pc	Emblem I30 <i>- neu</i>	\$	27.80
1 pc	Emblem CRDI <i>- neu</i>	\$	29.40
1 pc	Emblem Hyundai <i>X in</i>	\$	29.40
1 pc	Rear bumper <i>X Adjust</i>	\$	811.11
1 pc	Rear bumper sponge <i>X see</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>X see</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>X see</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>X see</i>	\$	104.40
		\$	2,338.76
	Less 20%	\$	467.75
		\$	1,871.01

### S/NETT

1 set	Rear bumper clips <i>- neu</i>	\$	48.00
1 set	Reverse sensor <i>- slat</i>	\$	280.00 <i>200</i>
1 set	Tailgate stickers <i>- neu</i>	\$	100.00
1 set	Lower tailgate garnish clips <i>X neu</i>	\$	38.00
1 pc	Rear number plate with casing <i>X see</i>	\$	50.00
	Sundry	\$	50.00 <i>X 1</i>
	To dismantle and replace reverse sensor and test system	\$	80.00 <i>30</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	180.00 <i>X 1</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same, etc	\$	650.00 <i>200</i>
	To putty and spray painting on the rear bumper, tailgate lower garnish,	\$	400.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels	\$	150.00 <i>X 1</i>
	Total	\$	3,897.01

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*8/10/18*  
*what 415 \$1500 / 762.*

*Ka/In 16/11/18*  
*3/10/18 1415h.*  
*3 days*  
*P.P*  
*Before Paint photo*



## Mei Kwan (LKKAUTO)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 8 October, 2018 11:04 AM  
**To:** Mei Kwan (LKKAUTO); MT\_Claim\_SG  
**Cc:** Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBB7885H (OI : LPC - TBA) AND SHC6818H (TP : LKK REF - CC3/LPC18018023/K1ja3) on 02/10/2018  
**Attachments:** SAS2482902.PDF  
  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
  
**Categories:** HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report that you have requested.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 8 October, 2018 10:34 AM  
**To:** MT\_Claim\_SG  
**Cc:** GERALD POH WEE BIN; ONG LI LI; ericwoo; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving GBB7885H (OI : LPC - TBA) AND SHC6818H (TP : LKK REF - CC3/LPC18018023/K1ja3) on 02/10/2018

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 6818H at M/s Premier Automotive Services Pte Ltd – Changi on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

***To check availability of the case handler, you may contact the undersigned.***

## Mei Kwan (LKKAUTO)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 8 October, 2018 11:04 AM  
**To:** Mei Kwan (LKKAUTO); MT\_Claim\_SG  
**Cc:** Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving GBB7885H (OI : LPC - TBA) AND SHC6818H (TP : LKK REF - CC3/LPC18018023/K1ja3) on 02/10/2018  
**Attachments:** SAS2482902.PDF  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report that you have requested.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 8 October, 2018 10:34 AM  
**To:** MT\_Claim\_SG  
**Cc:** GERALD POH WEE BIN; ONG LI LI; ericwoo; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving GBB7885H (OI : LPC - TBA) AND SHC6818H (TP : LKK REF - CC3/LPC18018023/K1ja3) on 02/10/2018

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 6818H at M/s Premier Automotive Services Pte Ltd – Changi on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

***To check availability of the case handler, you may contact the undersigned.***

**Gary Shi**

---

**From:** Gary Shi  
**Sent:** Tuesday, 15 January, 2019 2:00 PM  
**To:** 'Joy Irene (LKKAUTO)'  
**Cc:** AccReport; Admin A  
**Subject:** RE: LOD / Accident involving SHC6818G & GBB7885H on 02.10.18 (Lonpac case)  
**Attachments:** SHC6818G - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6818G, our client agreed to direct settle the above claims at \$1692.00

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to your surveyor.

Kindly let us have your settlement sum of S\$1692.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi  
Senior Executive, Claims  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511**  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]  
**Sent:** Tuesday, 15 January, 2019 12:15 PM  
**To:** Gary Shi  
**Cc:** AccReport; Admin A  
**Subject:** RE: LOD / Accident involving SHC6818G & GBB7885H on 02.10.18 (Lonpac case)

WITHOUT PREJUDICE

Dear Gary,

DV and ATA attached for your necessary action.

Thank you.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC18018023/K1ja3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 23-01-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 7885H	Veh. Inspected	SHC 6818H
Policy No.	Z18VC05000543	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020987	Excess (\$)	0.00
Assign From		Assign Date	03/10/2018

## 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	TMAD281UVHJ141898	Colour	SILVER
Odometer	109206	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	02/10/2018	Inspection Date	03/10/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6818H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE LOWER GARNISH	TO REPAIR SEE LABOUR	362.61	-
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NOT NECESSARY	29.40	-
1	REAR BUMPER	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	SERVICEABLE	104.40	-
	LESS 20% DISCOUNT		-467.75	-173.67
			1,871.01	694.64
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET TAILGATE STICKERS (SN)	NECESSARY	100.00	100.00
1	SET LOWER TAILGATE GARNISH CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	50.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			566.00	348.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	30.00
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF TAILGATE LOWER GARNISH .		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE LOWER GARNISH .		400.00	360.00

Report Ref No. CC3/LPC18018023/K1ja3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			1,460.00	590.00
GRAND TOTAL			3,897.01	1,632.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CC3/LPC18018023/K1ja3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.