



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



EQ INSURANCE COMPANY LTD		NAME : Mdm Ratna Djojokusumo Santosa		WIP : 38328	
5 Maxwell Road		ADDRESS : 19 Cairnhill Circle		EXCESS :	
#17-00 Tower Block		#18-06		DATE: 2-Oct-18	
MND Complex, Singapore 069110		Singapore 229768			
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKG7979M	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ97ZDL040043	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	Panamera	DATE REG.:		POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY		REVISED	PRICES	
1	FRONT FENDER LHS <i>Aluminium.</i>	1	P970-503-031-02-GRV	?	\$ 1,531.80
2	BRACKET LHS, FRONT FENDER	1	P970-504-355-04-GRV	?	\$ 383.50
3	RIVET, FRONT FENDER	3	P999-591-712-40-	?	\$ 3.60
4	FRONT BUMPER	1	P970-505-911-41-	de ✓	\$ 2,076.00
5	RIVET, FRONT BUMPER	2	PN -038-549-4 -	net ✓	\$ 1.00
6	SENSOR PEDESTRAIN	1	P150-919-275-C -G2L	?	\$ 256.90
7	GASKET, SENSOR	1	P7PP-919-133- -	?	\$ 4.30
8	RETAINER FRAME LHS, FRONT BUMPER	1	P970-505-563-02-1E0	net ✓	\$ 88.50
9	FRONT BUMPER <i>clip</i>	2	P999-190-104-30-	do net ✓	\$ 2.40
10	TAPPING SCREW, FRONT BUMPER	2	P9A7-007-517-00-	net ✓	\$ 1.60
11	RETAINER LHS, FRONT BUMPER	1	P970-505-535-02-	net ✓	\$ 40.00
12	SPEED NUT, RETAINER	2	P999-507-309-02-	net ✓	\$ 4.20
13	HEADLAMP LHS	1	P970-631-169-06-	env ✓	\$ 2,625.60
14	BRACKET LWR LHS, HEADLAMP	1	P970-631-073-02-	?	\$ 200.40
15	LAMP LHS, SIDE TURN	1	P970-631-081-04-	?	\$ 571.10
16	CLAMP, SIDE TURN	1	P999-507-143-01-	?	\$ 1.90
TOTAL PARTS					\$ 7,792.80
LESS 10%					\$ 779.28
TOTAL PARTS COST					\$ 7,013.52
Labour Description					
1	TO REPLACE FRONT BUMPER, FRONT FENDER LH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>1560</i>			2340.	\$ 4,680.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER LH. <i>2400.</i>			\$ 2,950.00	
3	TO SUPPLY THE REVERSE SENSORS.			380.	\$ 500.00
4	TO APPLY SPECIAL COATING.			NETT	TBA
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	\$ 250.00

6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT ✓	\$ 600.00
7	SUNDRIES.	NETT 50	\$ 100.00
		TOTAL LABOUR	\$ - \$ 9,080.00
		TOTAL PARTS	\$ - \$ 7,013.52
		TOTAL	\$ - \$ 16,093.52
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 97495749
- WP
11/10/18 @ 4pm
Resurvey before paint
5 days
surelkkauto.com