



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 03.10.2018

FWD Singapore Pte. Ltd.
6 Temasek Boulevard
Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE HONDA VEZEL ~~SL14988D (2016)~~

To Supply

1) 1pc	Right front fender	\$	580.00	bt ✓
2) 1pc	Right front fender cowling	\$	150.00	x
3) 1set	Right front fender cowling clip	\$	40.00	x
4) 1pc	Right front fender garnish	\$	160.00	ad ✓
5) 1pc	Right front door	\$	1,080.50	bt ✓
6) 1pc	Right front door top hinge	\$	68.00	Ky ✓
7) 1pc	Right front door lower hinge	\$	58.00	HA ✓
8) 1pc	Right front door checker	\$	65.00	x
9) 1pc	Right front door regulator gear with motor	\$	382.90	x

Sub total Parts	\$	2,584.40
Less: 20% discount	\$	516.88
	\$	2,067.52

L/charges

1) To tuff kote	\$	50.00	30.
2) To transfer right front door mechanism parts, door handle, trim board	\$	50.00	40
3) To cut/welding right front fender, knock right front door pillar, remove & replace right front door & right front fender. Adjust & align right front door & right front fender	\$	700.00	400

- 4) To putty, respray painting right front fender & right front door inlet
& outer. To polish

\$ 700.00 ⁴⁰⁰

Sub total L/charges	\$	1,500.00
Estimated Total	\$	<u>3,567.52</u>

Pauline 97495747
WP

4/10/15 @ 1615

Very after repair.

su0@lhlabs.com.

3-4 days