

Trans-cab Auto Services Pte Ltd

AAD1809-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 67S

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Shence notify
following:
survey by ... by painting
survey dan ... part(s) during resurvey
• parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Vehicle modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SHD 67S

KL1LA69RJB095999

CHEVROLET

EPICA 2.0

25.9.2018

AIA

PART**LIST**

1	1	Front Bumper / cut	\$	1,202.00
2	1	Front Bumper Lower Absorber X	\$	180.00
3	1	Front Bumper Reinforcement X	\$	356.00
4	1	Front Bumper Retainer RH X	\$	102.00
5	1	Front Bumper Retainer LH X	\$	102.00
6	1	Front Bumper Lower Grille X	\$	78.00
7	1	Front Bumper Lower Stiffener X	\$	134.37
8	1	Front Bumper Bracket LH X	\$	10.00
9	1	Front Bumper Bracket RH X	\$	10.00
10	1	Bumper Fog Lamp Cover RH X	\$	32.40
11	1	Bumper Fog Lamp Cover LH X	\$	32.40
12	1	Headlamp LH / sub	\$	816.00
13	1	Headlamp LH inner panel X NN	\$	611.16
14	1	Front Fender LH X Repair	\$	837.60
15	1	Front Fender Liner LH X - cut	\$	47.00
16	1	Front Fender Inner Wheel House Panel LH X	\$	1,437.00
17	1	Front Shock Absorber Assy LH X	\$	216.17
18	1	Front Shock Absorber Top Mounting LH X	\$	48.32
19	1	Front Lower Arm LH X	\$	283.00
20	1	Front Knuckle Arm LH X	\$	230.00
21	1	Front Hub Unit X	\$	376.00
22	1	Front Disc Brake LH X	\$	157.55
23	1	Front Strut Bar Bracket LH X	\$	235.01
24	1	Front Stabilizer Bar X	\$	234.00
25	1	Front Stabilizer Bar Link LH X	\$	51.79
26	1	Front Stabilizer Bar Bracket LH X	\$	105.75
27	1	Front Stabilizer Bar Bush LH X	\$	66.00
28	1	Front Beam A - Impact LH X	\$	214.00

Trans-cab Auto Services Pte Ltd

AAD1809-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 67S

TOTAL	\$	8,205.52
10%	\$	820.55
	\$	7,384.97

Specical Nett

1	1 Set	Front Fender Liner clip LH	✓	\$	30.00
2	1 Set	Louver Cowl Top clip	X	\$	30.00
3	1	Front right tyre rim	X	\$	380.00
4	1	Front right tyre	X	\$	330.00
TOTAL					\$ 770.00

TOTAL PARTS	\$	8,154.97
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned. \$ 30 170.00

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 400 3,500.00

Putty and spray painting of the affected portion. \$ 400 3,200.00

To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair. \$ X 440.00

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. \$ X 380.00

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ X 380.00

To dismantle and refit front end suspension, undercarriage parts, final checking and testing. \$ X 380.00

TOTAL	\$	8,450.00
Over All Total	\$	16,604.97
Repair Days		7 Days

4 Days.

Lumpsum repair

After repair photos.

Car Air - 8288082

03/10/18.

Trans-cab Auto Services Pte Ltd**AAD1809-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 67S

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 67S

KL1LA69RJB095999

CHEVROLET

EPICA 2.0

25.9.2018

		PART			LIST
1	1	Front Bumper	\$		1,202.00
2	1	Front Bumper Lower Absorber	\$		180.00
3	1	Front Bumper Reinforcement	\$		356.00
4	1	Front Bumper Retainer RH	\$		102.00
5	1	Front Bumper Retainer LH	\$		102.00
6	1	Front Bumper Lower Grille	\$		78.00
7	1	Front Bumper Lower Stiffener	\$		134.37
8	1	Front Bumper Bracket LH	\$		10.00
9	1	Front Bumper Bracket RH	\$		10.00
10	1	Bumper Fog Lamp Cover RH	\$		32.40
11	1	Bumper Fog Lamp Cover LH	\$		32.40
12	1	Headlamp LH	\$		816.00
13	1	Headlamp LH inner panel	\$		611.16
14	1	Front Fender LH	\$		837.60
15	1	Front Fender Liner LH	\$		47.00
16	1	Front Fender Inner Wheel House Panel LH	\$		1,437.00
17	1	Front Shock Absorber Assy LH	\$		216.17
18	1	Front Shock Absorber Top Mounting LH	\$		48.32
19	1	Front Lower Arm LH	\$		283.00
20	1	Front Knuckle Arm LH	\$		230.00
21	1	Front Hub Unit	\$		376.00
22	1	Front Disc Brake LH	\$		157.55
23	1	Front Strut Bar Bracket LH	\$		235.01
24	1	Front Stabilizer Bar	\$		234.00
25	1	Front Stabilizer Bar Link LH	\$		51.79
26	1	Front Stabilizer Bar Bracket LH	\$		105.75
27	1	Front Stabilizer Bar Bush LH	\$		66.00
28	1	Front Beam A - Impact LH	\$		214.00

Trans-cab Auto Services Pte Ltd

AAD1809-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 675

TOTAL	\$	8,205.52
10%	\$	820.55
	\$	7,384.97

Specical Nett

1	1 Set	Front Fender Liner clip LH	\$	30.00
2	1 Set	Louver Cowl Top clip	\$	30.00
3	1	Front right tyre rim	\$	380.00
4	1	Front right tyre	\$	330.00
TOTAL			\$	770.00

TOTAL PARTS	\$	8,154.97
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00
Putty and spray painting of the affected portion.	\$	3,200.00
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00

TOTAL	\$	8,450.00
Over All Total	\$	16,604.97
Repair Days		7 Days