

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 04/10/2018
TP Vehicle No. : SKN-8719-D
To : **AXA INSURANCE SINGAPORE PTE LTD**
Attn : **Motor Claim Department**

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : ANG WEE LIANG, RYMAN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5079182867-02
Vehicle No. : SLB-5449-D
Make & Model : TOYOTA COROLLA AXIO 1.5G A

Accident Date: 02/10/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR FENDER RH	\$902.76	X
1	REAR DOOR RH	\$0.00	X
1	REAR BUMPER	\$0.00	X
1	REAR BUMPER SIDE RETAINER RH	\$85.00	X
1	REAR WINDSCREEN MOULDING	\$185.60	X
Sub Total		\$1,173.36	
Discount 25% on Parts		(\$293.34)	
		\$880.02	

Special Nett

1	REAR WINDSCREEN SEALANT	\$60.00	X
1	REAR WINDSCREEN INNER SEAL	\$50.00	X
Sub Total		\$110.00	

Labour & Misc

LABOUR TO FACILIATE REPAIR	\$1,000.00	600
TO SPRAY PAINTING ON AFFECTED AREAS	\$1,000.00	600
TO REINSTALL REAR WINDSCREEN	\$120.00	X
TO RUST PROOF AFFECTED AREA	\$80.00	X
TO REMOVE UPHOISTERY AND SEAT TO ASSIST WORK	\$150.00	80
Sub Total	\$2,350.00	1280

Not Allowed when p/p 1280/- 11/10/18 take photo after repair

Sub Total

GST 7%

Total

4 day

LKK Auto **\$3,340.02** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display **\$3,573.82** (s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: