

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

QBE Insurance International Ltd
60 Anson Road
#11-01 Mapletree Anson
Singapore 079914
Tel: 6477 1243 Fax: 6534 5356

Not Authorized
11/10/18 8 2600h
Recovery After Paint

DEAR SIR / MADAM,

Date: 10/10/2018

Page : 1 of 2

ACCIDENT REPAIR ON: SJP2921B

MODEL : TOYOTA CAMRY 2.0

POLICY NO : GA267912/1

CHASSIS NO : MR053BK4107042121

YEAR OF MAKE : 2009

DATE / TIME OF ACCIDENT: 01/10/2018 Time : 1631Hrs

LOCATION : ALONG LORNIE RD TWDS BRADDELL DIRECTION

THIRD PARTY VEHICLE NO : SKS893J

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Bootlid	1	960.00	R	960.00 X
2	Bootlid emblem	1	65.00	R	65.00 —
3	Bootlid lettering "CAMRY"	1	65.00	R	65.00 —
4	Bootlid lettering "2.0"	1	54.00	R	54.00 —
5	Bootlid outer chrome moulding	1	360.00	Sm	360.00 X
6	Bootlid reflector lamp LH	1	465.00	Sm	465.00 X
7	Bootlid reflector lamp RH	1	465.00	Sm	465.00 X
8	Bootlid lock assy <i>349.70</i>	1	405.00	R	405.00 ✓
9	Bootlid stopper LH	1	9.00	Sm	9.00 X
10	Bootlid stopper RH	1	9.00	Sm	9.00 X
11	Bootlid inner trim board	1	525.00	Sm	525.00 X
12	Bootlid hinge LH	1	150.00	R	150.00 X
13	Bootlid hinge RH	1	150.00	R	150.00 X
14	Bootlid weatherstrip	1	150.00	Sm	150.00 X
15	Rear tail lamp assy LH	1	465.00	Sm	465.00 X
16	Rear tail lamp assy RH	1	465.00	Sm	465.00 X
17	Rear tail lamp lower bracket LH	1	36.00	Sm	36.00 X
18	Rear tail lamp lower bracket RH	1	36.00	Sm	36.00 X
19	Rear bumper	1	540.00	CMP	540.00 —
20	Rear bumper side retainer LH	1	84.00	Div	84.00 —
21	Rear bumper side retainer RH	1	84.00	Div	84.00 —
22	Rear bumper reflector LH	1	66.00	Sm	66.00 X
23	Rear bumper reflector RH	1	66.00	Sm	66.00 X
24	Rear bumper reinforcement	1	345.00	R	345.00 ✓
25	Rear end panel	1	535.00	R	535.00 ✓
26	Rear end panel lock striker	1	36.00	R	36.00 X
27	Rear end panel top garnish <i>339.10</i>	1	450.00	R	450.00 ✓
28	Rear exhaust silencer box	1	695.00	R	695.00 X
29	Rear exhaust silencer rubber	1	66.00	Sm	66.00 X

30	Rear fender inner shield LH	1	225.00	225.00	✓
31	Rear fender inner shield RH	1	225.00	225.00	✓
				238 Sub-Total:	8,251.00
				Less : 10% discount	825.10
				Total Parts after 10% discount :	7,425.90

Special Nett Items

1	Anti-rust coating	3	80.00	240.00	30%
2	Rear Bumper Clips	10	3.00	30.00	✓
3	Rear Fender Shield Clips	10	4.50	45.00	✓
4	Bootlid trim board clips	6	4.50	27.00	✓
5	Rear tail lamp clips	6	6.00	36.00	✓
6	Rear bumper sensor set	1	250.00	250.00	✓
7	Rear end panel garnish clips	4	4.50	18.00	✓
8	Rear end panel seal	1	100.00	100.00	30%
9	Rear number plate with casing	1	80.00	80.00	✓

Total Parts: 8,251.90

ACCIDENT VEHICLE OF : SJP2921B

Page : 2 of 2

Labour Charges For RearPortion

1	Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts.	1,250.00	60%
2	Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities	1,250.00	60%
3	Provide skill labour to disconnect and check electrical wiring	80.00	20%
4	Provide skill labour to dismantle and transfer bootlid fitting and facilitate repair	150.00	✓
5	Provide skill labour to remove and replace rear bumper sensor.	80.00	50%
6	Provide skill labour to remove and refit rear end panel lining and garnish	120.00	60%
7	Provide skill labour to remove and replace exhaust pipe/system to new	100.00	✓
8	Provide skill labour to mount vehicle onto chassis alignment bench	300.00	✓

Total Labour:

3,330.00

Total Parts & Labour: 11,581.90

GST 7%: 810.73

Grand Total: 12,392.63

Estimate Repair Duration

10 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: