

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHC 5308U

AAD1810-014

10/17
 Tyre spul @
 behind rear

Vehicle No.:	SHC 5308U
Chassis No.:	VF1ABL15AUC276795
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	29.9.2018
Third Party Insurer :	AXA

	PART		LIST
1	BUMPER COVER FRT / <i>Cut</i>	\$	1,259.42
1	BUMPER SPOILER FRT X <i>gna</i>	\$	181.75
1	BUMPER ABSORBER FRT X <i>gna</i>	\$	394.68
1	BUMPER RETAINER FRT RH / <i>re</i>	\$	150.77
1	BUMPER SUPPORT FRT X	\$	123.88
1	BUMPER UNDERTRAY FRT X	\$	472.83
1	BUMPER GRILLE LOWER FRT X	\$	266.80
1	BUMPER FOG LAMP GRILLE RH X	\$	207.21
1	BUMPER BEAM FRT X	\$	914.08
1	HEADLAMP RH / <i>gpa</i>	\$	1,184.43
1	HEADLAMP PANEL FRT RH X	\$	152.15
1	HEADLAMP LH X	\$	1,184.43
1	HEADLAMP PANEL FRT LH X	\$	152.15
1	FENDER PANEL FRT RH X <i>repair.</i>	\$	783.83
1	WHEELARCH FRT RH X	\$	278.84
1	FENDER BRACKET LOWER RH X	\$	15.79
1	FENDER INSULATOR RH X	\$	130.84
1	DOOR PANEL FRT RH X	\$	2,844.66
1	RADIATOR GRILLE X	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' X	\$	225.36
1	RADIATOR GRILLE FRAME X	\$	1,353.75
1	RADIATOR FAN COWLING X	\$	820.54
1	RADIATOR FAN MOTOR LH X	\$	967.36
1	RADIATOR FAN MOTOR RH X	\$	1,479.46
1	FRAME FULL SUPPORT PANEL X	\$	615.90
1	FRAME FULL SUPPORT BRACKET X	\$	89.79
1	DOOR MIRROR ASSY RH X	\$	1,483.40
1	DOOR PANEL FRT RH X	\$	2,844.66
1	BONNET X	\$	1,941.63
1	BONNET INSULATOR X	\$	405.73

Frt RH fender liner. / mis.

Trans-cab Auto Services Pte Ltd

AAD1810-014

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5308U

1	BONNET STRUT LH	X		\$	88.61
1	BONNET STRUT RH	X		\$	88.61
1	BONNET HINGE LH	X		\$	348.31
1	BONNET HINGE RH	X		\$	348.31
1	BONNET LOCK	X		\$	305.48
1	BONNET CABLE	X		\$	119.19
1	BONNET CABLE COVER	X		\$	161.03
1	BONNET SEAL OUTER	X		\$	92.36
1	BONNET SEAL INNER	X		\$	157.28
1	SUBFRAME OUTER FRT	X		\$	2,652.45
1	SUBFRAME BRACKET OUTER LH	X		\$	92.36
1	SUBFRAME BRACKET OUTER RH	X		\$	92.36
1	ENGINE UNDERTRAY	X		\$	564.98
1	A/C CONDENSER	X		\$	2,020.37
1	A/C CONDENSER GARNISH LH UPPER	X		\$	39.67
1	A/C CONDENSER GARNISH RH UPPER	X		\$	39.67
1	A/C CONDENSER GARNISH LH	X		\$	58.81
1	A/C CONDENSER GARNISH RH	X		\$	59.60
1	LOWER ARM RH	?		\$	685.76
1	KUNCKLE ARM RH	?		\$	846.98
1	ABSORBER FRT RH	X	AN	\$	360.54
1	STABILIZER BAR FRT	?		\$	604.65
1	DRIVESHAFT RH	X		\$	1,747.45
1	WIPER RESERVOIR	X		\$	348.25
1	WIPER RESERVOIR NECK	X		\$	136.11
1	WIPER RESERVOIR MOTOR	X		\$	270.06

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Special Nett

1SET	BUMPER CLIP FRT	/ MCL		\$	66.00
1	BUMPER BRACKET CLIP FRT RH	X		\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	X		\$	10.50
1SET	BUMPER GRILLE LOWER CLIP	X		\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	X		\$	70.00

Trans-cab Auto Services Pte Ltd

AAD1810-014

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5308U

2	FRAME FULL SUPPORT PANEL NUT	X	NN	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X		\$	30.00
1SET	WHEELARCH CLIP FRT RH	-KC		\$	30.50
6	BONNET INSULATOR CLIP L70Y	X		\$	7.30
2	BONNET STRUT L70Y	X		\$	88.61
2	BONNET CABLE CLIP L70Y	X		\$	6.31
2	BONNET CABLE COVER SCREW L70Y	X		\$	10.85
1	WINDSCREEN SEALANT	X		\$	253.80
1	FRONT WINDSCREEN MOULDING	X		\$	120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	X		\$	100.00
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	X		\$	80.00
1	FRONT RIGHT DOOR STICKER '6555-3333'	X		\$	50.00
1	FRONT RIGHT TYRE	-TN		\$	330.00
1	FRONT RIGHT TYRE RIM	-BT		\$	380.00

TOTAL \$ 1,734.88

TOTAL PARTS \$ 35,001.68

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	400
Putty and spray painting of the affected portion.	\$	4,000.00	400
To rust-proofing of the affected areas.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X NN
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	X NN

Trans-cab Auto Services Pte Ltd

AAD1810-014

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5308U

To Check Electrical Lighting Concerned.	\$	170.00	30
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	170.00	X

} MN

TOTAL \$ 11,090.00

Over All Total \$ 46,091.68

LUMP SUM (REPAIR DAY)

15 DAYS

5 Days.
 Lumpsum repair
 After repair photos.
 Gmo Ricap - 8880282
 03/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: