

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L**AAD1810-033**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9796L

VF1ABL15AUC277285

RENAULT

LATITUDE

1.10.2018

AIG

PART**LIST**

1	BUMPER COVER FRT	✓ cat	\$	1,259.42
1	BUMPER SPOILER FRT	X } nn	\$	181.75
1	BUMPER ABSORBER FRT	X } nn	\$	394.68
1	BUMPER RETAINER FRT LH	✓ re	\$	151.41
1	BUMPER SUPPORT FRT	X	\$	123.88
1	BUMPER RETAINER FRT RH	X	\$	150.77
1	BUMPER SUPPORT FRT	X	\$	123.88
1	BUMPER UNDERTRAY FRT	X } nn	\$	472.83
1	BUMPER GRILLE LOWER FRT	X	\$	266.80
1	BUMPER FOG LAMP GRILLE LH	X	\$	207.21
1	BUMPER BEAM FRT	X	\$	914.08
1	HEADLAMP LH	✓ scr	\$	1,184.43
1	HEADLAMP PANEL FRT LH	X } nn	\$	152.15
1	FENDER PANEL FRT LH	X repair	\$	783.83
1	WHEELARCH FRT LH	X	\$	278.84
1	FENDER BRACKET LOWER LH	X	\$	15.79
1	FENDER INSULATOR LH	X	\$	130.84
1	DOOR PANEL FRT LH	X	\$	2,844.66
1	RADIATOR GRILLE	X	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	X	\$	225.36
1	RADIATOR GRILLE FRAME	X	\$	1,353.75
1	RADIATOR FAN COWLING	X	\$	820.54
1	RADIATOR FAN MOTOR LH	X	\$	967.36
1	RADIATOR FAN MOTOR RH	X	\$	1,479.46
1	RADIATOR GRILLE FRAME	X	\$	1,353.75
1	FRAME FULL SUPPORT PANEL	X	\$	615.90
1	FRAME FULL SUPPORT BRACKET	X	\$	89.79
1	AIR CLEANER BOX	X	\$	464.20
1	AIR CLEANER HOSE	X	\$	175.85

Trans-cab Auto Services Pte Ltd**AAD1810-033**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L

1	LOWER ARM LH L70Y	X		\$	685.76
1	KUNCKLE ARM LH L70Y	X		\$	846.98
1	ABSORBER FRT LH L70Y	X		\$	360.54

TOTAL	\$	20,784.28
10%	\$	2,078.43
	\$	18,705.85

Special Nett

1SET	BUMPER CLIP FRT	/	MC	\$	66.00
1	BUMPER BRACKET CLIP FRT LH	X		\$	12.00
1	BUMPER SUPPORT CLIP FRT LH	X		\$	10.50
1SET	BUMPER GRILLE LOWER CLIP	X		\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	X		\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	X		\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X		\$	30.00
1SET	WHEELARCH CLIP FRT RH	/	MC	\$	30.50
1	FRONT LEFT TYRE	X		\$	300.00
1	FRONT LEFT TYRE RIM	X		\$	380.00

\$	988.00
-----------	---------------

TOTAL PARTS	\$	19,693.85
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,500.00 400

Putty and spray painting of the affected portion.

\$ 3,000.00 400

To rust-proofing of the affected areas.

\$ 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L**AAD1810-033**

To check steering geometry and computer wheel alignment	\$	220.00	X	} nn
To transfer of tire, rim and on wheel balancing.	\$	170.00	X	
To Check Electrical Lighting Concerned.	\$	170.00	30	
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X	} nn
To vacuum, replace, refix and recharge air condenser	\$	380.00	X	
To replace, refix and top up coolant for radiator	\$	170.00	X	
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X	
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	X	
TOTAL	\$	9,090.00		
Over All Total	\$	28,783.85		

LUMP SUM (REPAIR DAY)**10 DAYS**

4 Days -

Lumpsum Repair.

After repair photos.

Gano Qiy - 82880282

03/10/18

LKK & Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: