

INS. CASE OWNER:

CC3, CT1 180 18061, Gwp3n2

LKK: IDAC:

Surveyor:

Xarl

ASSIGNMENT DOI: 3-10-18

Date / Time:

3-10-18

Registered in Meritum:

Pre-assign / CCU / FTE

SPB 3475C



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP: D.O.A: 27/09/18

Make / Model :

Excess Sec II :SS

Place of Accident :

Is driver the owner? ( YES / NO ) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHD 9974P



INSRS: WSP: Trans-Cab Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
10/10	Non-Reporting ltr (1st):	
11/11	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 11-07
11-07-19 @ 5:30	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 5/10 Sent By: [Signature]

FINALIZATION Date/Time: Confirm with: Confirm by: XGQ

Repair Cost: 1/3 S\$1,950 ( 2 days) Reduction: 93 % Email  Call

FINAL SETTLEMENT Date/Time: 19-07-19 Confirm with: WANYH Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 31 If NO or B 28, Ass. Lia :

Repair Cost: w/651 S\$2,086.50 O/D REPAIR ENDED TP.

Loss of Rental (LOR): S\$ 291.96 ( 3 days) x +99.33

Loss of Use (LOU): S\$ - (\$ x days)

Loss of Income (LOI): S\$ 150.00 (\$50 x 3 days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search S\$ 1.49

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$2,541.95 Global Sum S\$:

FINAL PAYMENT Date/Time: 23-07-19 Confirm with: Email  Call

Payee 1: S\$2,541.95 Name 1: TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT SH-19

Signature: Xml.

REF:

3878K

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans-cab  
of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 9974P Yr Regn: 05 Jun 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: red A/C: Insured / Std / NI / NA

Sp. Reading: 508558 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFIABLISAUC 278 291

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi:  NI / S/Rim / STD A/Rim or

Tyre Size: F: 245/60R16  
R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. \_\_\_\_\_ D.O.I. 03-10-18

Survey held at w/s 5:40pm

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	45: +1,950 (RED: +21,857.01 92%)

Date/Time, File Pass to?

 : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

1)

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2)

Add Fee:  Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

\$ - RS. \$

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ )

TOTAL

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

#### Vehicle Details

Vehicle No.:	SHD9974P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001627
Chassis No.:	VF1ABL15AUC278291
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

#### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$9,373.00

#### Intended COE Rebate Details

COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,417.00
<b>Total Rebate Amount:</b>	<b>\$35,790.00</b>

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Sep 2018

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9974P
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001627
Chassis No.:	VF1ABL15AUC278291
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,279.00
<b>Total Rebate Amount:</b>	<b>\$35,652.00</b>
Message	
<p>Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>	

The information contained herein is correct as at 04 Oct 2018

OK

**Trans-cab Auto Services Pte Ltd**

**AAD1809-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P** *China Taiping Insurance*

Vehicle No.:	<b>SHD 9974P /</b>
Chassis No.:	VF1ABL15AUC278291
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	27.9.2018
Third Party Insurer :	<b>CHINA TAIPING</b>

PART		LIST
1	1 BUMPER COVER REAR <i>RE</i>	\$ 1,108.46
2	1 BUMPER LOWER REAR <i>CA</i>	\$ 768.84
3	1 BUMPER BRACKET CTR REAR X	\$ 113.47
4	1 BUMPER BRACKET SIDE RH REAR X	\$ 135.97
5	1 BUMPER RETAINER RH REAR X	\$ 44.99
6	1 BUMPER REFLECTOR RH X	\$ 43.61
7	1 BUMPER BRACKET SIDE LH REAR X	\$ 135.97
8	1 BUMPER RETAINER LH REAR X	\$ 44.99
9	1 BUMPER REFLECTOR LH X	\$ 43.61
10	1 BUMPER BEAM REAR X	\$ 777.52
11	1 BUMPER BEAM BRACKET LH REAR X	\$ 225.95
12	1 BUMPER BEAM BRACKET RH REAR X	\$ 225.95
13	1 OUTER PANEL REAR (End Panel) X <i>repair</i>	\$ 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM X	\$ 404.56
15	1 TAILLAMP RH X	\$ 552.55
16	1 TAILLAMP PANEL RH X	\$ 986.70
17	1 TAILLAMP LH X	\$ 552.55
18	1 TAILLAMP PANEL LH X	\$ 986.70
19	1 BOOT REAR X	\$ 2,872.68
20	1 BOOT FINISHER X	\$ 470.06
21	1 BOOT WHEATERSTRIP X	\$ 323.05
22	1 BOOT REFLECTOR LAMP LH X	\$ 493.35
23	1 BOOT REFLECTOR LAMP RH X	\$ 493.35
24	1 BOOT BADGE 'RENAULT' X	\$ 225.36
25	1 BOOT BADGE X	\$ 225.36
26	1 BOOT STRUT LH X	\$ 276.08
27	1 BOOT STRUT RH X	\$ 276.08
28	1 BOOT HINGE LH X	\$ 367.84
29	1 BOOT HINGE RH X	\$ 367.84

**Trans-cab Auto Services Pte Ltd**

**AAD1809-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P**

30	1 BOOT INNER TRIM	X	} <i>nn</i>	\$	586.45
31	1 BOOT SWITCH	X		\$	168.13
32	1 BOOT LOCK	X		\$	202.67
33	1 BOOT LOCK CATCH	X		\$	74.40

	<b>\$</b>	<b>16,046.87</b>
<b>10%</b>	<b>\$</b>	<b>1,604.69</b>
	<b>\$</b>	<b>14,442.19</b>

*17*

**Special Nett**

1	1SET PARKING AID	<i>pm</i>	} <i>nn</i>	\$	700.00	<i>200</i>
2	1SET REAR BUMPER CLIP	<i>mc</i>		\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	X		\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X		\$	10.00	
5	1SET BUMPER RETAINER RH CLIP RR	X		\$	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	X		\$	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	X		\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	<i>4mc</i>		\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	<i>4mc</i>		\$	66.00	
10	1 BOOT STICKER "Trans-cab"	X		\$	80.00	
11	1 BOOT STICKER "6555-3333"	X		\$	80.00	
12	1 EXHAUST MOUNTING REAR	X		\$	17.82	
13	2 REAR WINDSCREEN SEALANT	X		\$	80.00	
14	1 WINDSCREEN MOULDING	X		\$	100.00	
15	1 REAR WINDSCREEN INNER SPONGE SEAL	X		\$	100.00	

**TOTAL \$ 1,404.82**

**TOTAL PARTS \$ 15,847.01**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>200</i>

**Trans-cab Auto Services Pte Ltd**

AAD1809-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P**

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	X

**TOTAL \$ 7,960.00**

**Over All Total \$ 23,807.01**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**LUMP SUM ( REPAIR DAY)**

**10 DAYS**

2 Days.  
Lump sum repair  
after repair photos  
Gua Qian - 8288 0282  
03/10/18.

23806.99

## Mei Kwan (LKKAuto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Tuesday, 9 October, 2018 11:20 AM  
**To:** Mei Kwan (LKKAuto); Claims Dept of CTI  
**Cc:** Lucas Lee; Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SKB3475C (OI : CTI - SNM18D04676C02/5) and SHD9974P (TP : LKK REF - CC3/CTI18018061/Gua3) on 27/09/2018

**Attachments:** MNA118126106-SKB3475C.pdf

**Categories:** HMK

Dear Mei Kwan,

As requested, attached a copy of our insured's GIA report for your perusal.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 8 October, 2018 10:23 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving SKB3475C (OI : CTI - TBA) and SHD9974P (TP : LKK REF - CC3/CTI18018061/Gua3) on 27/09/2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18018061/Gea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 13-08-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 3475C	Veh. Inspected	SHD 9974P
Policy No.	DMPCSN3021231806	Coverage (\$)	0.00
Claim No.	SNM18D04676C02/5	Excess (\$)	0.00
Assign From		Assign Date	03/10/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278291	Colour	RED
Odometer	508558	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	5 mm
L/H Front Tyre	215/60 R16	GITI	5 mm
R/H Rear Tyre	215/60 R16	GITI	5 mm
L/H Rear Tyre	215/60 R16	GITI	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/09/2018	Inspection Date	03/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9974P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER REAR	DEFORMED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	NOT NECESSARY	113.47	-
1	BUMPER BRACKET SIDE RH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER RH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR RH	NOT NECESSARY	43.61	-
1	BUMPER BRACKET SIDE LH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER LH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR LH	NOT NECESSARY	43.61	-
1	BUMPER BEAM REAR	NOT NECESSARY	777.52	-
1	BUMPER BEAM BRACKET LH REAR	NOT NECESSARY	225.95	-
1	BUMPER BEAM BRACKET RH REAR	NOT NECESSARY	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	NOT NECESSARY	404.56	-
1	TAILLAMP RH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL RH	NOT NECESSARY	986.70	-
1	TAILLAMP LH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL LH	NOT NECESSARY	986.70	-
1	BOOT REAR	NOT NECESSARY	2,872.68	-
1	BOOT FINISHER	NOT NECESSARY	470.06	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	323.05	-
1	BOOT REFLECTOR LAMP LH	NOT NECESSARY	493.35	-
1	BOOT REFLECTOR LAMP RH	NOT NECESSARY	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	NOT NECESSARY	276.08	-
1	BOOT STRUT RH	NOT NECESSARY	276.08	-
1	BOOT HINGE LH	NOT NECESSARY	367.84	-
1	BOOT HINGE RH	NOT NECESSARY	367.84	-
1	BOOT INNER TRIM	NOT NECESSARY	586.45	-

Report Ref No. CC3/CT118018061/Gea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT SWITCH	NOT NECESSARY	168.13	-
1	BOOT LOCK	NOT NECESSARY	202.67	-
1	BOOT LOCK CATCH	NOT NECESSARY	74.40	-
	LESS 10% DISCOUNT		-1,604.69	-187.73
			14,442.17	1,689.57
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	DAMAGED	700.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NECESSARY	22.00	22.00
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,404.82	354.00
	<b><u>LABOUR</u></b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	200.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF OUTER PANEL REAR (END PANEL).		3,000.00	200.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	40.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,960.00	440.00
	<b>GRAND TOTAL</b>		<b>23,806.99</b>	<b>2,483.57</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,950.00</b>

Report Ref No. CC3/CT118018061/Gea3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.