

**Trans-cab Auto Services Pte Ltd**

**AAD1809-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P** China Taiping Insurance

Vehicle No.:	<b>SHD 9974P /</b>
Chassis No.:	VF1ABL15AUC278291
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	27.9.2018
Third Party Insurer :	<b>CHINA TAIPING</b>

PART		LIST
1	1 BUMPER COVER REAR / <i>RE</i>	\$ 1,108.46
2	1 BUMPER LOWER REAR / <i>CA</i>	\$ 768.84
3	1 BUMPER BRACKET CTR REAR X	\$ 113.47
4	1 BUMPER BRACKET SIDE RH REAR X	\$ 135.97
5	1 BUMPER RETAINER RH REAR X	\$ 44.99
6	1 BUMPER REFLECTOR RH X	\$ 43.61
7	1 BUMPER BRACKET SIDE LH REAR X	\$ 135.97
8	1 BUMPER RETAINER LH REAR X	\$ 44.99
9	1 BUMPER REFLECTOR LH X	\$ 43.61
10	1 BUMPER BEAM REAR X	\$ 777.52
11	1 BUMPER BEAM BRACKET LH REAR X	\$ 225.95
12	1 BUMPER BEAM BRACKET RH REAR X	\$ 225.95
13	1 OUTER PANEL REAR (End Panel) X <i>repair.</i>	\$ 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM X	\$ 404.56
15	1 TAILLAMP RH X	\$ 552.55
16	1 TAILLAMP PANEL RH X	\$ 986.70
17	1 TAILLAMP LH X	\$ 552.55
18	1 TAILLAMP PANEL LH X	\$ 986.70
19	1 BOOT REAR X	\$ 2,872.68
20	1 BOOT FINISHER X	\$ 470.06
21	1 BOOT WHEATERSTRIP X	\$ 323.05
22	1 BOOT REFLECTOR LAMP LH X	\$ 493.35
23	1 BOOT REFLECTOR LAMP RH X	\$ 493.35
24	1 BOOT BADGE 'RENAULT' X	\$ 225.36
25	1 BOOT BADGE X	\$ 225.36
26	1 BOOT STRUT LH X	\$ 276.08
27	1 BOOT STRUT RH X	\$ 276.08
28	1 BOOT HINGE LH X	\$ 367.84
29	1 BOOT HINGE RH X	\$ 367.84

**Trans-cab Auto Services Pte Ltd**

**AAD1809-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P**

30	1 BOOT INNER TRIM	X	} nn	\$	586.45
31	1 BOOT SWITCH	X		\$	168.13
32	1 BOOT LOCK	X		\$	202.67
33	1 BOOT LOCK CATCH	X		\$	74.40

	\$	<b>16,046.87</b>
10%	\$	<b>1,604.69</b>
	\$	<b>14,442.19</b>

**Special Nett**

1	1SET PARKING AID	/ pm	} nn	\$	700.00	200
2	1SET REAR BUMPER CLIP	/ ncc		\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	X		\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X		\$	10.00	
5	1SET BUMPER RETAINER RH CLIP RR	X		\$	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	X		\$	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	X		\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	= 4 ncc		\$	22.00	
9	1SET BUMPER LOWER REAR CLIP			\$	66.00	
10	1 BOOT STICKER "Trans-cab"	X		\$	80.00	
11	1 BOOT STICKER "6555-3333"	X		\$	80.00	
12	1 EXHAUST MOUNTING REAR	X		\$	17.82	
13	2 REAR WINDSCREEN SEALANT	X		\$	80.00	
14	1 WINDSCREEN MOULDING	X		\$	100.00	
15	1 REAR WINDSCREEN INNER SPONGE SEAL	X		\$	100.00	

**TOTAL \$ 1,404.82**

**TOTAL PARTS \$ 15,847.01**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	200

**Trans-cab Auto Services Pte Ltd**

AAD1809-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9974P**

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	X

**TOTAL \$ 7,960.00**

**Over All Total \$ 23,807.01**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**LUMP SUM ( REPAIR DAY) 10 DAYS**

2 Days.  
lump sum repair  
after repair photos  
Gno Ricoy - 8288 0282  
03/10/18.