

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg
Our Ref: EST304/18/TP
Your Ref: TP claim against

ESTIMATE

5-Oct-18

AXA Insurance Singapore Pte Ltd
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sir/Ms,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not follow
plan
2/5 to 2500/2
5 dy.
5/10/18
take photo after repair*

Re: Estimated cost of repair to Toyota Vios no: SGH6824A

Date of accident: 04-10-2018

Parts supply:

1 pc Boot
2 pcs Boot hinges @\$45.80
1 pc Boot weatherstrip
1 pc Boot inner lock
1 pc Boot emblem - Logo
1 pc Boot emblem- 1.5
1 pc Boot emblem - E
1 pc Boot emblem - VVTi
1 pc Boot emblem - VIOS
1 pc Boot centre garnish
2 pcs Boot rear no. plate lamp @\$42.50
2 pcs Taillamps @\$179.90
2 pcs Taillamp clips @\$10.00
2 pcs Taillamp panel @\$168.90
1 pc Rear bumper
2 pcs Rear bumper retainers @\$45.60
2 pcs Rear bumper brackets @\$72.60
8 pcs Rear bumper clips @\$3.50
1 pc Rear L/h air duct
1 pc Rear end panel
1 pc Rear end panel garnish
1 pc Rear spare tyre board
2 pcs Rear fender trim board @\$213.50
12 pcs Rear fender inner trim board clips @\$3.50

201/300	SS	480.90	—
u		91.60	x
u		75.90	—
u		55.60	—
u		35.60	—
u		18.50	—
u		8.90	—
u		30.94	—
u		23.30	—
u		85.60	x
u		85.00	x
o/sce		359.80	pic
u		20.00	x
u		337.80	x
u/100		361.90	—
u		91.20	—
u		145.20	x
u		28.00	—
u		35.60	x
u-1500		731.11	—
u		89.60	—
u		99.60	x
u		427.00	x
u		42.00	x
		3,760.65	

*2211.38
1658.51*

Less 25%: (940.16)

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.
To respray affected part.
To remove & refit rear reverse sensor
To remove & refit of wirings.

	700.00	600
	1,200.00	900
	60.00	50
	30.00	20
SS	4,810.49	

3228.51