

Trans-cab Auto Services Pte Ltd**AAD1810-052**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7893M

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7893M

KL1LA69RJB108889

CHEVROLET

EPICA 2.0

2.10.2018

III

		PART		LIST
1	1	Front Side View Mirror Assy RH	X <i>NN</i>	\$ 1,191.00
2	1	Rear Door RH (Panel A-RR DR LH)	<i>Bmc</i>	\$ 1,133.00
3	1	Rear door weatherstrip - Inner	X	\$ 41.40
4	1	Rear door weatherstrip - 2nd Frame	X	\$ 25.90
5	1	Rear door top hinge	X	\$ 35.00
6	1	Rear door bottom hinge	X	\$ 35.00
7	1	Rear door inner lock	X	\$ 425.00
8	1	Rear door check / arrestor	X	\$ 65.00
9	1	Rear door lock striker / latch	X	\$ 120.00
10	1	Rear door outer weatherstrip moulding	X	\$ 85.00
11	1	Side Rocker Panel Garnish RH	X	\$ 236.40
12	1	Rear Fender RH	<i>Bmc</i>	\$ 1,145.00
13	1	Rear Fender Inner Trim RH	X	\$ 418.44
14	1	Front Side Rocker Panel Garnish RH	X	\$ 236.40
15	1	Front Side Rocker Panel Outer RH	X	\$ 600.00
16	1	Front Side Rocker Panel Inner RH	X	\$ 519.30
17	1	Rear Bumper	<i>CEA</i>	\$ 1,202.00
18	1	Rear Bumper Beam	X	\$ 239.94
19	1	Rear Bumper Centre Absorber	X	\$ 260.00
20	1	Rear Bumper Side Retainer RH	<i>ce</i>	\$ 68.76
21	1	Rear Bumper Side Retainer LH	X <i>NN</i>	\$ 68.76
22	1	Rear Bumper Reflectors RH	X	\$ 119.74
23	1	Rear Bumper Reflectors LH	X	\$ 119.74
24	1	Rear Bumper Tow Hook Cover	X	\$ 93.00
25	1	Rear End Panel Outer	X	\$ 623.76
26	1	Rear End Panel Inner Trim	X	\$ 263.84
27	1	Rear Tail Lamp RH	<i>CEA</i>	\$ 479.30

Trans-cab Auto Services Pte Ltd**AAD1810-052**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7893M

28	1	Rear Tail Lamp Inner Panel RH	<i>X Nh</i>	\$	359.00
----	---	-------------------------------	-------------	----	--------

TOTAL	\$	10,209.68
10%	\$	1,020.97
	\$	9,188.71

Special Nett

1 Set	Front Bumper Fastener Clip	<i>X</i>	\$	24.00
1 Set	Front licence plate with holder	<i>X</i>	\$	192.00
1 Set	Radiator Grille clip	<i>X</i>	\$	35.00
1 Set	Front Fender Liner clip	<i>X</i>	\$	30.00
1	Front Fender RR Bracket RH	<i>X</i>	\$	7.10
1	Rear Wheel Rim Hub Cap RH	<i>X</i>	\$	166.30
1	Front right tyre	<i>X</i>	\$	220.00
1	Front Tyre Rim RH	<i>X</i>	\$	350.00
1	Front door sticker 'Trans-cab'	<i>X</i>	\$	80.00
1Set	Rear Fender Inner Trim Clip RH	<i>McC</i>	\$	30.00
1	Rear door sticker '6555-3333'	<i>McC</i>	\$	80.00
TOTAL			\$	1,214.40

TOTAL PARTS	\$	10,403.11
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	<i>30</i> 170.00
---	----	------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>800</i> 4,500.00
---	----	---------------------

Putty and spray painting of the affected portion.	\$	<i>600</i> 4,000.00
---	----	---------------------

Towing Fees.	\$	<i>?</i> 120.00
--------------	----	-----------------

Trans-cab Auto Services Pte Ltd**AAD1810-052**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7893M

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	X	380.00
To check steering geometry and computer wheel alignment	\$	NN X	220.00
To transfer of tire, rim and on wheel balancing.	\$	X	170.00
To rust-proofing of the affected areas.	\$	60	170.00
To check steering geometry and computer wheel alignment	\$	NN X	220.00
To transfer of door fittings, attachment and perform water seepage test.	\$	60	170.00
To transfer of fender fittings, attachment and perform water seepage test.	\$	60	170.00
TOTAL	\$		10,290.00
Over All Total	\$		20,693.11

6 Days.

Repair Days (Lump Sum)**15 days**

Lumpsum repair.

After repair photos.

Gino Qicup

05/10/18.

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: