

ASS. REC. BY:

REF:

CS/CTI18018100/Dcd3

72

Special Instruction:

Surveyor:

menmen

FROM (Person):

Bryan
Chong Boon Sen

ASSIGNMENT (Office)

of

CTI

Date/Time:

5/10/180

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 2947R

Insured:

YM 5951H

at Workshop m/s

cheng hwe Motor

Tel:

6755 6142

of

Blk 1019 # 61-374/382 Yishun Ind. Park A

Policy No:

DMCVSN/720241801

Claim No:

8NM18D04727C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/10/18

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

2:27pm @ 5/10/18

Person Contacted:

Effeda


Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 2947R-X
	YM 5951H-CS/CTI1 7009897/bxx
	Don: 19/5/17

ASSIGNMENT

05E March 2023

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 located: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Given: _____ Consistent? Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 55D2947R Yr Reg: 2008, H.Y.
 Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vios CC: 1497
 Color: Green A/C: Insured / Std / Nil / NA
 Sp. Branding: 128702 T/Ratio: Insured / Std / Nil / NA
 Eng No: 1N2K666853
 Ch No: MR053HY9305041463
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In Order / Jammed / Leaked / Burnt or
 Brakes: ☒ In Order / Jammed / Leaked / Burnt or
 Mod: Nil / ☒ STD / A/Rim or
 Tyre Size: F: 185/60R15
 R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin

Front: _____ Rear: _____
 R/Bal: 5' mm R/Bal: 5' mm
 L/Bal: 5' mm L/Bal: 5' mm
 D.O.A: 01/10/2018 D.O.I: 05/10/2018
 Survey held at: Cheng Hoe Yishan
 Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
 H/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 25/2 Action / Instruction: Check Taping YM 5951H
 Confirmed final big \$1049.99 with Efforda. (Red 1049.96, 92)
 RECEIVED 25 FEB 2019

Date/Time, For (next to):
☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Survey Fee:
 Transportation: _____
) \$ + RB, or
) Photos
) Other

Report Format: TP
 Lump Sum / (B): (\$ 1,049.99)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018 Sendback Est	05 Oct 2018 12:15 S\$1,079.39	05 Oct 2018 14:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ISLAND TOWING EXPRESS , Co. Reg. No.: S00000000		
Main Claimant:	R.SRIMITHA , ID: S7705487A		
Vehicle Reg. No.:	SJD2947R	Date of Loss:	01/10/2018 08:00 - :59 [126 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04727C02	Policy/Cover Note No.:	DMCVSN1720241801
Vehicle Reg. No. (Insured):	YM5951H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/10/2018]		
Driver/Custodian (Insured):	VASILY CHUPLY (/ Male)		
Adj Asg. Remarks:	EST \$1154.95, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to On eMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5487A

Vehicle Details

Vehicle No.:	SJD2947R
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Green
Manufacturing Year:	2007
Engine No.:	1NZX666853
Chassis No.:	MR053HY9305041463
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,917.00
Original Registration Date:	17 Mar 2008
First Registration Date:	17 Mar 2008
Transfer Count:	2
Actual ARF Paid:	\$13,917.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details


COE Expiry Date:	16 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,637.00
COE Rebate Amount:	\$17,504.00
Total Rebate Amount:	\$17,504.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Oct 2018

OK



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

-

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA
Policy No:		Date of Loss:	01/10/2018
Vehicle Reg. No.:	SJD2947R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	R.SRIMITHA	Driver (Insured):	VASILY CHUPLY
Make/Model:	TOYOTA VIOS, 1.5 G (A)	Vehicle Reg. Date:	17/03/2008
Vehicle Colour:	BEIGE		
Engine No:	1NZX666853	Chassis No:	MR053HY9305041463
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	450.00
Miscellaneous Items	150.00
Labour	479.39
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,079.39
+ GST 7.00% (S\$)	75.56
Nett Amount (S\$)	1,154.95

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 05 Oct 2018)
Parts: 143 **TOYOTA VIOS 1.5 G (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **Cheng Hoe Motor Pte Ltd/SJD2947R/05/10/2018 12:15**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*L/DOOR MIRROR	0.00	0.00	*230.00 F
2	1	NA	*L/F DOOR MOULDING	0.00	0.00	*38.00 F
3	1	NA	*L/F DOOR TRIM CHROME	0.00	0.00	*12.00 F
4	1	NA	*L/F DOOR WINDOW	0.00	0.00	*105.00 F
5	1	NA	*L/F OUT WINDOW SEAL	0.00	0.00	*35.00 F
6	1	NA	*L/OUT DR MIRROR CVR	0.00	0.00	*30.00 F

F=Franchise part.

Total Parts (S\$) **450.00**

Cheng Hoe Motor Pte Ltd/SJD2947R/05/10/2018 12:15. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	SUNDRY PARTS	100.00
2	1	TOWING	50.00

Sub Total (S\$) **150.00****Estimates on Labour**

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	252.00
2	Total Paint Materials	New	76.19
3	Total Panel/Mechanical Labour	New	151.20

Gross Labour Cost (S\$) **479.39**

Cheng Hoe Motor Pte Ltd/SJD2947R/05/10/2018 12:15. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761

SJD2947R
TP/china

Claim Reference:
Assessment Number: CSJD2947
Version: CHENGHOE/1
Date Calculated: 05/10/2018 05:05

Full Report - V1
Registration: SJD2947R
Printed: 05/10/2018 12:06

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	01/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP/CHINA	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	G
Model Sheet Number:	YF3 03
Registration:	SJD2947R
Registration Month:	March
Registration Year:	2008
VIN Number:	MR053HY9305041463
Manufacture Year:	2007
Odometer:	Not Known
Colour:	
Engine Number:	1NZX666853
Fuel Level:	%

Model Specs

FROM 03/2007	AIR CONDITIONING
FOG LAMPS	SIDE MOULDINGS
1.5 LTR 80 KW	ABS
TYRES 175/65 TR 14	EQUIPMENT "G" GRADE
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	05/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJD2947


Version: CHENGHOE/1

Date Calculated: 05/10/2018 05:05


Full Report - V1

Registration: SJD2947R

Printed: 05/10/2018 12:06



All



Addresses

Repairer

Name : CHENG HOE MOTOR PL

Address :

BLK 1019 YISHUN IND PARK A

#01-374

Post Code : 768761

Cost Summary

Total Labour	\$403.20
Total Paint/Material	\$76.19
Total Parts	\$550.00
Total of Additional Costs	\$50.00
Excess:	TBA
Grand Total Exc GST:	\$1,079.39
7 % GST:	\$75.56
Grand Total Inc GST:	\$1,154.95

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR

Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
670301)	R + R LEFT FRONT DOOR TRIM	2.0	8.40 ✓
670301A)	DOOR TRIM/S (COMPOSITE WORK)	2.0	8.40 ✓
671011)	R + R LEFT FRONT DOOR WINDOW	2.0	8.40 ✓
NO NUMBER	R + R L/F DOOR MOULDING	2.0	8.40 ✓
752051)	R + R LEFT MIRROR	1.0	4.20 ✓
1000	CTRL LOCK & POWER WINDOW	15.0* 10	63.00 42.00
1000	CHECK SIDE MIRROR SYSTEM	12.0* 10	50.40 42.00

LABOUR COST

Total Work Units

36.0 121.80

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

3.6HRS

\$151.20

Paint Labour

6.0HRS

\$252.00

Total Labour

9.6HRS

\$403.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number Description

WU

Cost Price (\$)

- TWO COAT METALLIC

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJD2947

Version: CHENGHOE/1

Date Calculated: 05/10/2018 05:05

Full Report - V1

Registration: SJD2947R

Printed: 05/10/2018 12:06

	- PREPARE OFF VEHICLE		
1681	L/F DOOR MOULDING NEW PART PAINT K1R	3.0	
1745	L/OUT DR MIRROR CVR NEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
LABOUR COST - PAINT			
	TIME(PAINT)	30.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	60.0	
	Total Paintwork Labour	6.0HRS	\$252.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting - Plastic K1R		\$5.41
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$33.18
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$76.19
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$76.19

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1737	1	L/DOOR MIRROR	87940 0D340	broken	0%	230.00* ✓
1681	1	L/F DOOR MOULDING	75732 0D969	Nee	0%	38.00* ✓
1685	1	L/F DOOR TRIM CHROME	75794 0D030	Nee	0%	12.00* ✓
1519	1	L/F DOOR WINDOW	68120 0D111	broken	0%	105.00* ✓
1625	1	L/F OUT WINDOW SEAL	68210 0D090	Nee	0%	35.00* ✓
1745	1	L/OUT DR MIRROR CVR	87945 0D903	broken	0%	30.00* ✓
f: OEM Parts		Sub Total				\$450.00
g: Original		Sundry Parts Nee (Fixed)				\$100.00 ✓
h: Secondhand		Total Parts				\$550.00
p: Parallel						
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
TOWING Nee SPECIALIST 24	0%	\$50.00 ✗ ✓
Total Extras		\$50.00

Final Calculation

Total Parts		\$550.00 ✓
Labour		
Total Panel/Mechanical		\$151.20
Total Paintwork		\$252.00 ✓
Total Labour		\$403.20
Additional Costs		
Corr Prot Materials External		\$0.00
Corr Prot Materials Internal		\$0.00
Cost of Specialist		\$50.00 ✗
Total of Additional Costs		\$50.00 ✗
Total Paint/Material Costs		\$76.19 ✓
Grand Total Excludes GST		\$1,079.39
GST @ 7%		\$75.56

Audatex System Using Manufacturer Times

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJD2947

Version: CHENGHOE/1

Date Calculated: 05/10/2018 05:05

Full Report - V1

Registration: SJD2947R

Printed: 05/10/2018 12:06

Grand Total Includes GST

\$1,154.95

Assessment Notes

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

Claim Reference:
Assessment Number: CSJD2947
Version: CHENGHOE/1
Date Calculated: 27/11/2018 03:41

Full Report - V1
Registration: SJD2947R
Printed: 27/11/2018 11:41

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	01/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP/CHINA	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	G
Model Sheet Number:	YF3 03
Registration:	SJD2947R
Registration Month:	March
Registration Year:	2008
VIN Number:	MR053HY9305041463
Manufacture Year:	2007
Odometer:	Not Known
Colour:	
Engine Number:	1NZX666853
Fuel Level:	%

Model Specs

FROM 03/2007	AIR CONDITIONING
FOG LAMPS	SIDE MOULDINGS
1.5 LTR 80 KW	ABS
TYRES 175/65 TR 14	EQUIPMENT "G" GRADE
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	05/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	


CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJD2947
Version: CHENGHOE/1
Date Calculated: 27/11/2018 03:41

Full Report - V1
Registration: SJD2947R
Printed: 27/11/2018 11:41



All



Addresses

Repairer

Name : CHENG HOE MOTOR PL
Address :
BLK 1019 YISHUN IND PARK A
#01-374
Post Code : 768761

Cost Summary

Total Labour	\$373.80
Total Paint/Material	\$76.19
Total Parts	\$550.00
Total of Additional Costs	\$50.00
Excess:	TBA
Grand Total Exc GST:	\$1,049.99
7 % GST:	\$73.50
Grand Total Inc GST:	\$1,123.49

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
670301)	R + R LEFT FRONT DOOR TRIM	2.0	8.40
670301A)	DOOR TRIM/S (COMPOSITE WORK)	2.0	8.40
671011)	R + R LEFT FRONT DOOR WINDOW	2.0	8.40
NO NUMBER	R + R L/F DOOR MOULDING	2.0	8.40
752051)	R + R LEFT MIRROR	1.0	4.20
1000	CTRL LOCK & POWER WINDOW	10.0*	42.00
1000	CHECK SIDE MIRROR SYSTEM	10.0*	42.00

LABOUR COST

Total Work Units	29.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.9HRS	\$121.80
Paint Labour	6.0HRS	\$252.00
Total Labour	8.9HRS	\$373.80

PAINT WORK

Guide Number Description

- TWO COAT METALLIC

Time Basis 10 WU = 1 HR. Price = \$42.00/HR
WU Cost Price (\$)

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJD2947
Version: CHENGHOE/1
Date Calculated: 27/11/2018 03:41

Full Report - V1
Registration: SJD2947R
Printed: 27/11/2018 11:41

	- PREPARE OFF VEHICLE		
1681	L/F DOOR MOULDING NEW PART PAINT K1R	3.0	
1745	L/OUT DR MIRROR CVR NEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
LABOUR COST - PAINT			
	TIME(PAINT)	30.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	60.0	
	Total Paintwork Labour	6.0HRS	\$252.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting - Plastic K1R		\$5.41
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$33.18
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$76.19
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$76.19

PARTS

Price Valid: 01/06/2015					
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1737	1	L/DOOR MIRROR	87940 0D340		0% 230.00*
1681	1	L/F DOOR MOULDING	75732 0D969		0% 38.00*
1685	1	L/F DOOR TRIM CHROME	75794 0D030		0% 12.00*
1519	1	L/F DOOR WINDOW	68120 0D111		0% 105.00*
1625	1	L/F OUT WINDOW SEAL	68210 0D090		0% 35.00*
1745	1	L/OUT DR MIRROR CVR	87945 0D903		0% 30.00*
f: OEM Parts			Sub Total		\$450.00
g: Original			Sundry Parts	(Fixed)	\$100.00
h: Secondhand			Total Parts		\$550.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
TOWING	0%	\$50.00
SPECIALIST		
Total Extras		\$50.00

Final Calculation

Total Parts		\$550.00
Labour		
Total Panel/Mechanical	\$121.80	
Total Paintwork	\$252.00	
Total Labour		\$373.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
Total of Additional Costs		\$50.00
Total Paint/Material Costs		\$76.19
Grand Total Excludes GST		\$1,049.99
GST @ 7 %		\$73.50

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJD2947

Version: CHENGHOE/1

Date Calculated: 27/11/2018 03:41

Full Report - V1

Registration: SJD2947R

Printed: 27/11/2018 11:41

Grand Total Includes GST

\$1,123.49

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: CSJD2947
Version: CHENGHOE/2
Date Calculated: 25/02/2019 05:08

Full Report - V1
Registration: SJD2947R
Printed: 25/02/2019 13:11

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	01/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP/CHINA	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Vios
Sub Model:	G
Model Sheet Number:	YF3 03
Registration:	SJD2947R
Registration Month:	March
Registration Year:	2008
VIN Number:	MR053HY9305041463
Manufacture Year:	2007
Odometer:	Not Known
Colour:	
Engine Number:	1NZX666853
Fuel Level:	%

Model Specs

FROM 03/2007	AIR CONDITIONING
FOG LAMPS	SIDE MOULDINGS
1.5 LTR 80 KW	ABS
TYRES 175/65 TR 14	EQUIPMENT "G" GRADE
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	05/10/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: CSJD2947

Registration: SJD2947R

Version: CHENGHOE/2

Printed: 25/02/2019 13:11

Date Calculated: 25/02/2019 05:08


Assessment Notes

Claim Reference:


Assessment Number: CSJD2947

Version: CHENGHOE/2

Date Calculated: 25/02/2019 05:08

Registration: SJD2947R
Printed: 25/02/2019 13:11

All

**Addresses****Repairer**

Name : CHENG HOE MOTOR PL

Address :

BLK 1019 YISHUN IND PARK A

#01-374

Post Code : 768761

Cost Summary

Total Labour	\$373.80
Total Paint/Material	\$76.19
Total Parts	\$550.00
Total of Additional Costs	\$50.00
Excess:	TBA
Grand Total Exc GST:	\$1,049.99
7 % GST:	\$73.50
Grand Total Inc GST:	\$1,123.49

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR**Repair /****Guide Number Repair Details**

	WU	Cost Price (\$)
670301) R + R LEFT FRONT DOOR TRIM	2.0	8.40
670301A) DOOR TRIM/S (COMPOSITE WORK)	2.0	8.40
671011) R + R LEFT FRONT DOOR WINDOW	2.0	8.40
NO NUMBER R + R L/F DOOR MOULDING	2.0	8.40
752051) R + R LEFT MIRROR	1.0	4.20
1000 CTRL LOCK & POWER WINDOW	10.0*	42.00
1000 CHECK SIDE MIRROR SYSTEM	10.0*	42.00

LABOUR COST**Total Work Units**

Corrosion Protection External Labour

Corrosion Protection Internal Labour

Sub Total

Paint Labour

Total Labour

29.0

0.0HRS

0.00

0.0HRS

0.00

2.9HRS

\$121.80

6.0HRS

\$252.00

8.9HRS

\$373.80

PAINT WORK**Guide Number Description**

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

	WU	Cost Price (\$)
- TWO COAT METALLIC		
- PREPARE OFF VEHICLE		
1681 L/F DOOR MOULDING NEW PART PAINT K1R	3.0	

1745	L/OUT DR MIRROR CVR NEW PART PAINT K1R	3.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	24.0	
LABOUR COST - PAINT			
	TIME(PAINT)	30.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	60.0	
	Total Paintwork Labour	6.0HRS	\$252.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting - Plastic K1R		\$5.41
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$33.18
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$76.19
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$76.19

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1737	1	L/DOOR MIRROR	87940 0D340		0% 230.00*
1681	1	L/F DOOR MOULDING	75732 0D969		0% 38.00*
1685	1	L/F DOOR TRIM CHROME	75794 0D030		0% 12.00*
1519	1	L/F DOOR WINDOW	68120 0D111		0% 105.00*
1625	1	L/F OUT WINDOW SEAL	68210 0D090		0% 35.00*
1745	1	L/OUT DR MIRROR CVR	87945 0D903		0% 30.00*
f: OEM Parts			Sub Total		\$450.00
g: Original			Sundry Parts	(Fixed)	\$100.00
h: Secondhand			Total Parts		\$550.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
TOWING	0%	\$50.00
SPECIALIST		
Total Extras		\$50.00

Final Calculation

Total Parts		\$550.00
Labour		
Total Panel/Mechanical	\$121.80	
Total Paintwork	\$252.00	
Total Labour		\$373.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
Total of Additional Costs		\$50.00
Total Paint/Material Costs		\$76.19
Grand Total Excludes GST		\$1,049.99
GST @ 7 %		\$73.50
Grand Total Includes GST		\$1,123.49

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018100/DCD3N2

Date: 25/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1720241801
Claimant Vehicle No :	SJD2947R	Insured Vehicle No :	YM5951H
Date of Loss:	01/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04727C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2947R	Engine No:	1NZX666853
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Chassis No:	MR053HY9305041463
Reg. Date:	17/03/2008 (Man. Year: 2007)	Odometer:	128702 km
Colour:	Green		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	450.00	450.00	0.00	0.00
Miscellaneous Items	150.00	150.00	0.00	0.00
Labour	479.39	449.99	29.40	6.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,079.39	1,049.99	29.40	2.72
+ GST 7.00/7.00% (S\$)	75.56	73.50	2.06	2.73
Nett Amount (S\$)	1,154.95	1,123.49	31.46	2.72

INSPECTION

Date of Assignment:	05/10/2018	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	05/10/2018	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2019)
 Parts: 143 TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJD2947R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/DOOR MIRROR	Broken	230.00 F	*230.00 F
2	1	NA	*L/F DOOR MOULDING	Necessary	38.00 F	*38.00 F
3	1	NA	*L/F DOOR TRIM CHROME	Necessary	12.00 F	*12.00 F
4	1	NA	*L/F DOOR WINDOW	Broken	105.00 F	*105.00 F
5	1	NA	*L/F OUT WINDOW SEAL	Necessary	35.00 F	*35.00 F
6	1	NA	*L/OUT DR MIRROR CVR	Broken	30.00 F	*30.00 F
F=Franchise part.						
Total Parts (S\$)					450.00	450.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	SUNDRY PARTS (Necessary)	100.00	100.00
2	1	TOWING	50.00	50.00
Sub Total (S\$)			150.00	150.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	252.00	252.00
2	Total Paint Materials	New	76.19	76.19
3	Total Panel/Mechanical Labour	New	151.20	121.80
Gross Labour Cost (S\$)			479.39	449.99

Report was unsubmitted during this print-out.

< END OF ESTIMATES >