

15/02/10

INS. CASE OWNER:

CC 4 / LPC1801

8105, D Wb 3m

LKK

IDAC:

Surveyor:

Brynn

DOI:

ASSIGNMENT

8/10/18

Date / Time:

4/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBC 17875

Claim No.:

18/18/18/VLOS/000005

Name of Insured:

PENTA MHTMHT M

Policy No.:

218VPL0500100

Insured Tel No.:

HP:

Make / Model:

M560M

Excess Sec II :SS

D.O.A.:

7/1/18

Place of Accident:

BISHAW RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: young sin uloon

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

5497887H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Crewell
mno

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Date/ Time	STAGE	DATE / PIC
7/10/18	Non-Reporting ltr (1st):	
7/10/18	Non-Reporting ltr (2nd):	
7/10/18	Non-Reporting ltr (Final):	
7/10/18	Notification ltr (if non-pickup):	
7/10/18	Call OI:	
7/10/18	After call ltr to OI:	
05/12/18	Documentation Check List:	Handler Typist
05/12/18	Notification ltr (if non-pickup):	
05/12/18	After call ltr to OI:	
05/12/18	Authorisation To Act:	
05/12/18	Release Voucher:	
05/12/18	Final Repair Bill:	
05/12/18	Car Rental Invoice:	
05/12/18	Towing Invoice:	
05/12/18	LTA / GIA:	
05/12/18	Medical Bill:	
05/12/18	PIR:	
05/12/18	Mandate/Reject Instruction:	
05/12/18	LOD:	
05/12/18	Payment Breakdown Form:	
05/12/18	Post-Repair Photos:	
05/12/18	Others:	

PRELIMINARY ADVICE	Date/Time: 16/10/18	Sent By: BG
26/05/19	- 26/05/19 P.V. TP ACCEPTED OFFER.	
FINALIZATION	Date/Time: 21/05/19	Confirm with: 21/05/19
Repair Cost: 419	SS 2,300.00 (3 days) Reduction: 54 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 21/05/19	Confirm with: 21/05/19
Final Liability:	% 100 (Agreed/ Assessed) BOLA S/N No.:	20
Repair Cost:	SS 2,300.00	
Loss of Rental (LOR):	SS (days)	
Loss of Use (LOU):	SS 360.00 x 3 days	
Loss of Income (LOI):	SS (5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]	
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS (e.g. Tow/ Independent)	
Legal Cost	SS	
Total:	SS 2,660.00	Global Sum SS: -
FINAL PAYMENT	Date/Time: 21/05/19	Confirm with: 21/05/19
Payee 1:	SS 2,660.00	Name 1: CREWELL AUTO SERVICE
Payee 2: (Strike if N.A.)	SS	Name 2: -
Payee 3: (Strike if N.A.)	SS	Name 3: -

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: 450.00

REF: LPC

ASSIGNMENT

From: Date: 08/10/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGY 7883H

at Workshop m/s

Carewell Auto

of

160 Sin Ming Drive #03-21

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

(Policy Condition)

2-30pm

owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

231%

10%

Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGY 7883H Yr Regn: Feb 2010

Type: ☒ M. Car / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E250

C.C.

1796

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

210929

T/Radio: Insured / Std / NI / NA

Eng/No:

27186030019549

C/No:

WDD2120472A129310

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

225/55 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal.

S'

mm

R/Bal.

S'

mm

L/Bal.

S'

mm

L/Bal.

S'

mm

D.O.A.

21/09/2018

D.O.I.

08/10/2018

Survey held at

Carewell Auto 160 Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Lonec GBC 17873

05/12/18 Jinar 2/5 23001 - with 3 days of rep

(Rev: \$2,705.00 / 54%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18018105/Dhb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-10-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 1787S	Veh. Inspected	SGY 7883H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/09/2018	Inspection Date	08/10/2018	
Survey held at	CAREWELL AUTO SERVICE BLK 176 SIN MING DRIVE #02-06 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18018105/Dhb3

Date: 16.10.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGY7883H


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.10.2018 at the premises of M/s Carewell Auto Service and have the following to report:-

Workshop Estimate Amount	: S\$	5,005.00
Revised Estimate Amount	: S\$	3,353.00
"Check" Items Amount	: S\$	790.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser



CAREWELL AUTO SERVICE

160 Sin Ming Drive #03-21 Singapore 575722

Tel: 6459 9926 Fax: 6459 9928

Email: carewell@singnet.com.sg

Our Ref:

Date: 02nd Oct 2018

Your Ref:

Mr Toh Hea Yam

Vehicle No. SGY7883H

Model No. Mercedes Benz W212/E250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Re: Estimates and Miscellaneous Charges

1.	1 pc Rear Bumper Assy	distorted	S\$ 1,603-00	✓
2.	1 pc Rear Bumper Reinforcement	2 NH	790-00	✗
3.	2pcs Rear Bumper Brackets	broken	33-00	✓ 136.00
4.	1 pc Rear Bumper Centre Chrome Moulding	CRANE	171-00	✓
5.	2pcs Rear Bumper Side Chrome Mouldings	H/L	256-00	✓
6.	1 pc Rear LHS Tail Lamp Assy	Nat	612-00	✗
7.	2pcs Parktronics	Distorted NH	690-00	✗
Sub-Total			S\$ 4,155-00	

2166.00
10% 1949.40

Labour Charges

To knock, remove and install the damaged parts

according to conditions.

S\$ 450-00 300/- 600.00

To putty primer and spray paint Rear Bumper

S\$ 400-00 250/- 300/-

Total S\$ 5,005-00

08/10/2018 @ 1430h

W/A Author
P/Part: 45000

3 days

Tel: 64599926

Fax: 64599928

Email: carewell@singnet.com.sg

Web: www.carewell.com.sg

2549.40
10% 452300/-

97237799

Phao 1/4 spray
with damaged parts.

LKK Auto

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 4 October, 2018 5:44 PM
To: carewell@singnet.com.sg; assignments@lkkauto.com; admin-d@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018
Attachments: 02102018163348.pdf

Without Prejudice

Dear Sir/Mdm

As spoken with your Jessy, please let us know if you require us to conduct the TP survey. If so, please liaise with LKK Auto Consultants Pte Ltd.

Dear Catherine/Nivitha

Please follow up with workshop.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

05-10-2018 @ 10:44am
Francis veh not in

From: Charlotte Chew [mailto:charlotte.chew@income.com.sg]
Sent: Thursday, 4 October, 2018 2:00 PM
To: carewell@singnet.com.sg
Cc: ONG LI LI
Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Without prejudice

Dear Hea Yam

Our investigation shows that GBC1787S had hit onto SGY7883H. This is confirmed by the reports of 3 vehicles SGM7400G, FBE8491M and SGY7883H.

We are unable to accept any liability.

Thank you.

Charlotte Chew
Senior claims executive
Motor Insurance
T +65 6430 7924
www.income.com.sg

 income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers

 in with you

From: mtreg
Sent: Thursday, 4 October 2018 10:46 AM
To: 'carewell@singnet.com.sg'; Charlotte Chew
Subject: FW: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Dear Sir/Mdm

We have registered the claim.
Claim no. MT/1012896-002
Officer-in-charge –Charlotte Chew

Josephine Cheah
Snr Administrator, Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

*'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.
Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'*

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Tuesday, October 02, 2018 4:57 PM
To: carewell@singnet.com.sg
Cc: MT_Claim_SG <mt_claim@lonpac.com>; NTUC Income Motor Dept <motor@income.com.sg>
Subject: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to the above chain collision.

As spoken, according to our Insured, the motorcycle FBE8491M had collided onto your client's vehicle.

Please direct your client's claim to his insurer NTUC Income under MCF.

Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Cc NTUC Income – pls take over (your insured FBE8491M)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 17 October 2018 10:10 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Vic (LKKAUTO)
Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G> GBC1787S>FBE8491M>SGY7883H on 21/9/2018
Attachments: 17102018095728.pdf; 17102018100010.pdf; 17102018100457.pdf

Dear Shu Pei,

We attached copy of our insured's GIA report together with the police reports of the various parties involved in the chain collision.

Based on the third party reports, it would appeared that our insured had hit into vehicles, FBE8491E and SGY7883H.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 17 October, 2018 9:38 AM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Vic (LKKAUTO)
Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SGY 7883H at M/s Carewell Auto Service on a WP basis and TP repairer purposed for a direct settlement.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 5 October 2018 10:46 AM

To: 'ONG LI LI' <llong@lonpac.com>; Admin A <admin-a@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>

Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision
SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Dear Li Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Thursday, 4 October, 2018 5:44 PM

To: carewell@singnet.com.sg; assignments@lkkauto.com; admin-d@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision
SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Without Prejudice

Dear Sir/Mdm

As spoken with your Jessy, please let us know if you require us to conduct the TP survey. If so, please liaise with LKK Auto Consultants Pte Ltd.

Dear Catherine/Nivitha

Please follow up with workshop.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Charlotte Chew [<mailto:charlotte.chew@income.com.sg>]
Sent: Thursday, 4 October, 2018 2:00 PM
To: carewell@singnet.com.sg
Cc: ONG LI LI
Subject: RE: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision
SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Without prejudice

Dear Hea Yam

Our investigation shows that GBC1787S had hit onto SGY7883H. This is confirmed by the reports of 3 vehicles SGM7400G, FBE8491M and SGY7883H.

We are unable to accept any liability.

Thank you.

Charlotte Chew
Senior claims executive
Motor Insurance
T +65 6430 7924
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

From: mtreg
Sent: Thursday, 4 October 2018 10:46 AM
To: 'carewell@singnet.com.sg'; Charlotte Chew
Subject: FW: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision
SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Dear Sir/Mdm

We have registered the claim.
Claim no. MT/1012896-002
Officer-in-charge –Charlotte Chew

Josephine Cheah
Snr Administrator, Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.

Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Tuesday, October 02, 2018 4:57 PM

To: carewell@singnet.com.sg

Cc: MT_Claim_SG <mt_claim@lonpac.com>; NTUC Income Motor Dept <motor@income.com.sg>

Subject: Your Ref: SGY7883H Our Ref: 18/18/18/VC05/020935 Chain collision

SGM7400G>GBC1787S>FBE8491M>SGY7883H on 21/9/2018

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to the above chain collision.

As spoken, according to our Insured, the motorcycle FBE8491M had collided onto your client's vehicle.

Please direct your client's claim to his insurer NTUC Income under MCF.

Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Cc NTUC Income – pls take over (your insured FBE8491M)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18018105/Dhb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-04-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 1787S	Veh. Inspected	SGY 7883H
Policy No.	Z18VPC05000102	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020935	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/10/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2120472A129310	Colour	SILVER
Odometer	210929	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	MICHELIN	5 mm
L/H Front Tyre	225/55 R18	MICHELIN	5 mm
R/H Rear Tyre	225/55 R18	MICHELIN	5 mm
L/H Rear Tyre	225/55 R18	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2018	Inspection Date	08/10/2018
Survey held at	160 SIN MING DRIVE #03-21		
Repairer	CAREWELL AUTO SERVICE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 7883H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSY	DISTORTED	1,603.00	1,603.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	790.00	-
2	REAR BUMPER BRACKETS	BROKEN	136.00	136.00
1	REAR BUMPER CENTRE CHROME MOULDING	CRACKED	171.00	171.00
2	REAR BUMPER SIDE CHROME MOULDINGS	NECESSARY	256.00	256.00
1	REAR LHS TAIL LAMP ASSY	NOT NECESSARY	612.00	-
2	PARKTRONICS	NOT NECESSARY	690.00	-
	LESS 10% DISCOUNT		-	-216.60
			4,258.00	1,949.40
<u>LABOUR</u>				
	TO KNOCK ,REMOVE AND INSTALL THE DAMAGED PARTS ACCORDING TO CONDITIONS.		450.00	300.00
	TO PUTTY PRIMER AND SPRAY PAINT REAR BUMPER.		400.00	300.00
			850.00	600.00
GRAND TOTAL			5,108.00	2,549.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/LPC18018105/Dhb3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.