



## CAREWELL AUTO SERVICE

160 Sin Ming Drive #03-21 Singapore 575722

Tel: 6459 9926

Fax: 6459 9928

Email: carewell@singnet.com.sg

Our Ref:

Date: 02<sup>nd</sup> Oct 2018

Your Ref:

Mr Toh Hea Yam

Vehicle No. SGY7883H

Model No. Mercedes Benz W212/E250

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Re: Estimates and Miscellaneous Charges

1.	1 pc Rear Bumper Assy	<i>distorted</i>	S\$ 1,603-00	✓
2.	1 pc Rear Bumper Reinforcement	<i>?</i>	790-00	?
3.	2pcs Rear Bumper Brackets	<i>broken</i>	33-00	✓
4.	1 pc Rear Bumper Centre Chrome Moulding	<i>crack</i>	171-00	✓
5.	2pcs Rear Bumper Side Chrome Mouldings	<i>hit</i>	256-00	✓
6.	1 pc Rear LHS Tail Lamp Assy	<i>hit</i>	612-00	X
7.	2pcs Parktronics	<i>Dem</i>	690-00	✓

Sub-Total S\$ 4,155-00

Labour Charges

To knock, remove and install the damaged parts

according to conditions.

S\$ 450-00 *300/-*

To putty primer and spray paint Rear Bumper

S\$ ~~400-00~~ *250/-* *300/-*

Total S\$ 5,005-00

*08/10/2018 @ 1430h*

*Not Author*  
*P/Part. ~~Hit~~*

*3 days*

Tel: 64599926

Fax: 64599928

Email: carewell@singnet.com.sg

Web: www.carewell.com.sg

*97237799*

*Photo by spray  
with damaged parts.*

*LKK Auto*