

ASS. REC. BY:

REF:

CS/FCI 8018137/A8bn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): WNS Eileen Lee of FCI Date/Time: 05/10/2018 4:23pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GJA 3005T Insured: SHA 7168Dat Workshop m/s S.D. Car Care Tel: 6749 6155of 2 Kaki Bukit Ave 2 #01-29Policy No: _____ Claim No: D18007257MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02.10.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 05/10/2018

Person Contacted:

Ah Boy

H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>SJA 3005T - NBA / ENK 18017857 / Y</u>	<u>DUA: 02/10/2018</u>
	<u>SHA 7168D - CCL / AXA 15016943 / Alwa 343</u>	<u>DUA: 05/07/2015</u>
<u>8/10/18</u>	<u>Email FCI informed pending est from repaired</u>	

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJA300ST Yr Regn: 2007 Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Vios C.C. 1497
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 240439 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MROS3HY9305040896

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15
 R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 06 mm R/Bal. 06 mm
 L/Bal. 06 mm
 D.O.A. _____ D.O.I. 05/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
<u>21/12/18</u>	<u>Confirmed 4S \$6,700/- @ 12 days with Adrian.</u>
	<u>(\$10,251.08 Red 61%)</u>
	<u>MV: 251K</u>
	<u>PV: 173K</u>
	<u>Nett: 7.7K</u>
	<u>MV - \$25,000.00</u>
	<u>LTA - \$17,323.00</u>
	<u>Nett - \$7,677.00</u>

RECEIVED 21 DEC 2018

Date/Time, File Pass to? 21/12/18
 1) Typ: 3r
 Date/Time, File Return to? _____
 2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 12Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: _____

Lump Sum / I.B.I: (\$ 6,700/- L/S)6x15 = 90170 + 905050117477

MOTOR SURVEY ASSIGNMENT

Date	03-10-2018	Our Ref No. D18007257MFSH
Accident Date	02-10-2018	Claim Type. Third Party
Insured Vehicle	SHA7168D	Third Party Vehicle. SJA3005T
Survey Location	2 Kaki Bukit Avenue 2 #01-29 Kaki Bukit Autohub	
Contact Person.	AH BOY	
Contact No.	67496155/ 67455102	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	S.D. CAR CARE CENTRE	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 8 October 2018 1:51 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007257MFSH/1, SJA 3005T

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJA 3005T on 5/10/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 8 October 2018 9:51 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007257MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 5 October, 2018 4:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007257MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!

POST AN AD NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

This Rolls Royce Silver Shadow 2 Will Steal Hearts.



\$80k 12 Months Rebuilt. Full
Chassis Sandblasted & Epoxy
Coated.No Stones Unturn
Direct Owner StarAd



HIN LUNG AUTO

Ho Bee Group

One Stop Car Hub

Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category

Save Search

Print

« Back (1 2 3 4) Next »

Sort by Date Posted

20 results/page

73 vehicles

Search

vios

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

vios

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



☐ Toyota Vios 1.5A E (COE till
08/2022)

\$22,500

\$5,800 /yr

23-Aug-2007

1,497 cc

Sedan

Available

Beautiful And Well Maintained Vehicle, Reliable And Excellent Fuel Efficiency, Call For More Enquiries! In House Loan Available!

★ Posted: 28-Sep-2018 Tags: 2007 Toyota Vios, 2007 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD



☐ Toyota Vios 1.5A J (COE till
10/2022)

\$24,000

\$5,980 /yr

10-Oct-2007

1,497 cc

168,000 km

Sedan

Available

Just Serviced And Owner Wanted To Continue Driving, But Upgrade Another Bigger Car To Cater For More Family Needs. Please Call And View.
Condition Is Very Good And Would Expect Very Low Maintenance Fo...

★ Posted: 25-Sep-2018 Tags: 2007 Toyota Vios, 2007 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ Toyota Vios 1.5M E Sports
(COE till 01/2023)

\$26,500

\$6,140 /yr

29-Jan-2008

1,497 cc

86,800 km

Sedan

Available

Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.

Carro

★ Posted: 17-Aug-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

CONSIGNMENT



☐ Toyota Vios 1.5A E (COE till
04/2023)

\$31,800

\$7,060 /yr

07-Apr-2008

1,497 cc

138,000 km

Sedan

Available

Low Down Payment Of 45K For Sporty Toyota Vios, Very Fuel Efficient! A Practical, Stylish And Comfortable Car That You Wouldn't Want To Miss! Buy
It From Us With A Peace Of Mind, Trade In Welcome. Be ...

Tay Motor & Credit Pte Ltd

★ Posted: 21-Sep-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an
approval in 2 days without effort! Enquire today.



☐ Toyota Vios 1.5A G (COE till
04/2023)

\$26,800

\$5,870 /yr

30-Apr-2008

1,497 cc

103,000 km

Sedan

Available

Consignment Unit. Excellent Condition And Low Mileage Done. Accident Free. Sheltered Parking. No Repair Needed. Viewing By Appointment Only.

★ Posted: 27-Sep-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

CONSIGNMENT



☐ Toyota Vios 1.5A E (COE till
05/2023)

\$27,800

\$6,040 /yr

13-May-2008

1,497 cc

Sedan

Available

Elegant Beige, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House
Loan Packages Available.

Prime Motor & Leasing

★ Posted: 11-Sep-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

SHORTLISTED HISTORY

Compare

☐ Toyota Vios 1.5A E (New 5-yr
COE)

\$28,888

\$5,770 /yr

25-Jun-2008

1,497 cc

138,000 km

Sedan

Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4644H
Vehicle Details	
Vehicle No.:	SJA3005T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E MANUAL
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX664022
Chassis No.:	MR053HY9305040896
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,886.00
Original Registration Date:	03 Dec 2007
First Registration Date:	03 Dec 2007
Transfer Count:	0
Actual ARF Paid:	\$13,075.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,282.00
COE Rebate Amount:	\$17,323.00
Total Rebate Amount:	\$17,323.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Oct 2018

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5033254335-09

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SJA3005T**
Chassis Number : **MR053HY9305040896**
2. Name of Policyholder : **CHEW CHONG TIN HENRY**
3. Effective Date of Insurance : **03 Dec 2017**
4. Expiry Date of Insurance : **02 Dec 2018**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
 - (b) Use for racing, pace-making, reliability trial or speed-testing.
 - (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (d) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: CHEW CHONG TIN HENRY
NAMED DRIVER (1)	: CHEW BEE LAY JEAN
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DBS BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : INCOME - MAIN SERVICING (00000600057)
Date of Issue : 10 Nov 2017 13:07 hrs
Reprint : 10 Nov 2017 13:07 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

S.D CAR CARE CENTRE

Blk 2, Kaki Bukit Avenue 2, #01-29, (Kaki Bukit AutoHub), Singapore 417921

H/P: 9616 1359 (Ah Boon) / 9650 7403 (Ah Boy)

Tel: 6749 6155 / 6745 5102 / Fax: 6742 9003

TP 1st Cap.
Shirley.

Vehicle number: SJA3005T

Vehicle Made & Model: TOYOTA VIOS

Qty	List Items	Amount \$
1	Rear boot lid <i>Buckled</i>	665.90 ✓
1	Rear boot logo <i>new</i>	42.60 ✓
1	Rear boot emblem "E" <i>new</i>	48.85 ✓
1	Rear boot moulding <i>new</i>	286.95 +
1	Rear boot inner lock <i>Damaged</i>	289.55 ✓
1	Rear boot lock striker <i>new</i>	75.15 +
1	Rear boot w/strip <i>new</i>	162.82 ✓
2	Rear boot hinges - L/R @ 68.50 <i>new</i>	137.00 +
1	Rear bumper <i>Distorted</i>	486.90 ✓
2	Rear bumper reflectors - L/R @ 126.20 <i>crushed</i>	252.40 ✓
2	Rear bumper side retainers @ 89.65 <i>new</i>	179.30 ✓
2	Rear bumper side brackets - L/R @ 82.50 <i>new</i>	165.00 +
6	Rear bumper clips @ 4.50 <i>new</i>	27.00 ✓
1	Rear end panel <i>Distorted</i>	777.25 ✓
1	Rear end panel trim <i>Deformed</i>	126.20 ✓
1	Rear exhaust silencer <i>Repair</i>	569.95 +
1	Rear exhaust chrome pipe <i>Bent</i>	120.65 ✓
2	Rear exhaust mountings @ 28.60 <i>new</i>	57.20 X
1	Rear floor board <i>Torn</i>	156.20 ✓
1	Rear floor sponge - CTR <i>new</i>	142.60 X
2	Rear floor sponge - L/R @ 132.60 <i>Deformed</i>	265.20 ✓
1	Rear floor panel <i>Repair</i>	781.65 X
1	Rear fender - RH <i>Repair</i>	891.90 X
2	Rear fender inner trims - L/R @ 280.60 <i>new</i>	561.20 +
10	Rear fender inner trim clips @ 4.50	45.00 +
2	Rear taillamps - L/R @ 481.65 <i>crushed</i>	963.30 597
2	Rear taillamp panels - L/R @ 186.90 <i>Repair</i>	373.80 X
1	Front bumper <i>Deformed</i>	512.60 ✓
1	Front bumper tow cover <i>new</i>	28.60 X
1	Front bumper grille - CTR <i>new</i>	89.95 X
2	Front bumper fog lamps - L/R @ 281.60 <i>new</i>	563.20 X
2	Front bumper fog lamp covers - L/R @ 86.50 <i>new</i>	173.00 X
1	Front bumper top guide <i>Deformed</i>	142.60 ✓
1	Front bumper reinforcement <i>Bent</i>	480.90 33620
2	Front bumper reinforcement stays - L/R @ 135 <i>new</i>	270.00 X

Vehicle number: SJA3005T

Vehicle Made & Model: TOYOTA VIOS

2	Front bumper side retainers @ 42.50 <i>new</i>	83.00 ✓
10	Front bumper clips @ 4.50 <i>new</i>	45.00 <i>30</i>
1	Front bumper logo <i>new</i>	68.50 ✓
1	Front bonnet <i>new</i>	891.90 <i>x</i>
1	Front bonnet lock <i>new</i>	126.60 <i>x</i>
1	Front grille <i>crushed</i>	281.90 ✓
1	Front grille chrome moulding <i>ext</i>	126.40 ✓
2	Front headlamps - L/R @ 561.90 <i>crushed</i>	1,123.80 ✓
2	Front headlamp side garnishes - L/R @ 48.60 <i>new</i>	97.20 <i>x</i>
1	Front support panel <i>Repis</i>	860.90 <i>x</i>
2	Horns @ 98.60 <i>new</i>	197.20 <i>x</i>
Sub-total		14,814.77
Less 25%		3,703.69
Total List		11,111.08

Special Nett Items

1 set	Front no. plate <i>Bent</i>	60.00 ✓
1	Rear reverse camera <i>new</i>	450.00 <i>x</i>
1 set	Rear reverse sensor <i>damaged</i>	280.00 <i>200</i>
Total Special Nett		790.00

Labour Charges

To check front & rear electrical wiring	80.00 <i>60</i>
To remove, refix rear exhaust systems	100.00 <i>80</i>
To re-seal anti-rust	150.00 <i>50</i>
To remove, refix interior upholstery to facilitate repair works	120.00 <i>60</i>
To remove, refix rear reverse sensor & camera	120.00 <i>80</i>
To remove, refix A/C condenser & refill A/C gas	180.00 <i>x</i>
To respray painting & etc	1,800.00 <i>1300</i>
Panel beating, cut, weld, remove & replacing above parts	2,500.00 <i>1400</i>
Total Labour	5,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

16,951.08

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018137/Asbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7168D	Veh. Inspected	SJA 3005T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007257MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	05/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305040896	Colour	SILVER	
Odometer	240439	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2018	Inspection Date	05/10/2018	
Survey held at	BLK 2, KAKI BUKIT AVE 2 #01-29			
Repairer	S D CAR CARE CENTRE			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 3005T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	665.90	665.90
1	REAR BOOT LOGO	NECESSARY	42.60	42.60
1	REAR BOOT EMBLEM "E"	NECESSARY	48.85	48.85
1	REAR BOOT MOULDING	NOT NECESSARY	286.95	-
1	REAR BOOT INNER LOCK	DAMAGED	289.55	289.55
1	REAR BOOT LOCK STRIKER	NOT NECESSARY	75.15	-
1	REAR BOOT W/STRIP	CUT	162.82	162.82
2	REAR BOOT HINGES-L/R @\$68.50	NOT NECESSARY	137.00	-
1	REAR BUMPER	DISTORTED	486.90	486.90
2	REAR BUMPER REFLECTORS-L/R @\$126.20	CRACKED	252.40	252.40
2	REAR BUMPER SIDE RETAINERS @\$89.65	NECESSARY	179.30	179.30
2	REAR BUMPER SIDE BRACKETS-L/R @\$82.50	NOT NECESSARY	165.00	-
6	REAR BUMPER CLIPS @\$4.50	NECESSARY	27.00	27.00
1	REAR END PANEL	DISTORTED	777.25	777.25
1	REAR END PANEL TRIM	DEFORMED	126.20	126.20
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	569.95	-
1	REAR EXHAUST CHROME PIPE	BENT	120.65	120.65
2	REAR EXHAUST MOUNTINGS @\$28.60	NOT NECESSARY	57.20	-
1	REAR FLOOR BOARD	TORN	156.20	156.20
1	REAR FLOOR SPONGE-CTR	NOT NECESSARY	142.60	-
2	REAR FLOOR SPONGE-L/R @\$132.60	DEFORMED	265.20	265.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	781.65	-
1	REAR FENDER-RH	TO REPAIR SEE LABOUR	891.90	-
2	REAR FENDER INNER TRIMS-L/R @\$280.60	NOT NECESSARY	561.20	-
10	REAR FENDER INNER TRIM CLIPS @\$4.50	NOT NECESSARY	45.00	-
2	REAR TAILLAMPS-L/R @\$481.65	CRACKED	963.30	597.00
2	REAR TAILLAMP PANELS-L/R @\$186.90	TO REPAIR SEE LABOUR	373.80	-
1	FRONT BUMPER	DEFORMED	512.60	512.60

Report Ref No. CS/FCI18018137/Asbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER TOW COVER	NOT NECESSARY	28.60	-
1	FRONT BUMPER GRILLE-CTR	NOT NECESSARY	89.95	-
2	FRONT BUMPER FOG LAMPS-L/R @\$281.60	NOT NECESSARY	563.20	-
2	FRONT BUMPER FOG LAMP COVERS-L/R @\$86.50	NOT NECESSARY	173.00	-
1	FRONT BUMPET TOP GUIDE	DEFORMED	142.60	142.60
1	FRONT BUMPER REINFORCEMENT	BENT	480.90	336.20
2	FRONT BUMPER REINFORCEMENT STAYS-L/R @\$135.00	NOT NECESSARY	270.00	-
2	FRONT BUMPER SIDE RETAINERS @\$42.50	NECESSARY	83.00	83.00
10	FRONT BUMPER CLIPS @\$4.50	NECESSARY	45.00	30.00
1	FRONT BUMPER LOGO	NECESSARY	68.50	68.50
1	FRONT BONNET	NOT NECESSARY	891.90	-
1	FRONT BONNET LOCK	NOT NECESSARY	126.60	-
1	FRONT GRILLE	CRACKED	281.90	281.90
1	FRONT GRILLE CHROME MOULDING	CUT	126.40	126.40
2	FRONT HEADLAMPS-L/R @\$561.90	CRACKED	1,123.80	1,123.80
2	FRONT HEADLAMP SIDE GARNISHES-L/R @\$48.60	NOT NECESSARY	97.20	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	860.90	-
2	HORNS @\$98.60	NOT NECESSARY	197.20	-
	LESS 25% DISCOUNT		-3,703.69	-1,725.71
			11,111.08	5,177.11
	SPECIAL NETT ITEMS			
1	SET FRONT NO PLATE (SN)	BENT	60.00	60.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			790.00	260.00
	LABOUR			
	TO CHECK FRONT & REAR ELECTRICAL WIRING.		80.00	60.00
	TO REMOVE,REFIX REAR EXHAUST SYSTEMS.		100.00	80.00
	TO RE-SEAL ANTI-RUST.		150.00	50.00
	TO REMOVE,REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS.		120.00	60.00

Report Ref No. CS/FCI18018137/Asbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REFIX REAR REVERSE SENSOR & CAMERA.	NOT NECESSARY	120.00	80.00
	TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS.		180.00	-
	TO RESPRAY PAINTING & ETC.		1,800.00	1,300.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER,REAR FLOOR PANEL,REAR FENDER-R/H,REAR TAILLAMP PANELS-L/R AND FRONT SUPPORT PANEL.		2,500.00	1,400.00
			5,050.00	3,030.00
GRAND TOTAL			16,951.08	8,467.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CS/FCI18018137/Asbn2

MARKET VALUE: \$25,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$17,323.00=NETT VALUE: \$7,677.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.