

Surround Marcus  
9

REF:

ASSIGNMENT

MSIA/ C03/MSH18018151/Agbn2

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/10/18

have G.I.A

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

10/10/18

2340

RECEIVED 08 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.F. (\$

NER-TP

22000

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

Photos

Others

TOTAL

300

10

310

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 10 October 2018 2:34 PM  
**To:** Christina Wong; Hasrianah Binte Hassan  
**Cc:** KKLau; SUR; Accounts (LKKAUTO)  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 05/10/2018, SKQ 146T (TP VEHICLE), SLS 6587S (OI VEHICLE)  
**Attachments:** SKQ146 GIA.pdf

Dear Christina and Hasrianah,

Please be informed that we had inspected the vehicle SKQ 146T M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883 on 08/10/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                       |
|----------------------------|-----------------------|
| Date Of Report             | 06/10/2018 10:38      |
| Date Of Accident           | 05/10/2018 15:30      |
| Exact Location Of Accident | ALONG AYE TOWARDS MCE |
| Country/State of Loss      | SINGAPORE             |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKQ146T              |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | WANG GUANGNING       |
| NRIC No                     | S2690084J            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-90666017 |
| Alternative Phone No        | OFFICE-90666017      |

### Vehicle Particulars

|  |                |
|--|----------------|
| Manufacturer   | AUDI           |
| Model  | A6 2.0 TFSI MU |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO             |
| If No, Please state action to be taken                                       | THIRD PARTY    |
| Vehicle Category   | PRIVATE CAR    |

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | GA003884/1            |
| Cover Note Number         |                       |

### Driver

|                      |                        |
|----------------------|------------------------|
| Name of Driver       | WANG GUANGNING         |
| NRIC No              | S2690084J              |
| Date Of Birth        | 04/10/1964             |
| Occupation           | INDOOR                 |
| Date Of Driving Pass | 29/11/1995             |
| Driving Experience   | 22 YEARS AND 10 MONTHS |
| Gender               | MALE                   |
| Mobile Number        | (LOCAL) +65-90666017   |
| Fax Number           |                        |
| Contact Number       | OFFICE-90666017        |
| Email Address        | NOEMAIL                |

Address 1G CANTONMENT ROAD #11-83 SPORE 085701

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1  
NAME: XIE YA  
GENDER: FEMALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS6587S

Vehicle Make/Model/Colour AUDI A6 2.0 TFSI MU

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

|                                     |  |
|-------------------------------------|--|
| Vehicle Registration Number         | SJU4961X                               |
| Vehicle Make/Model/Colour           | HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR |
| Details Of Properties               |  |
| Vehicle Category                    | PRIVATE CAR                            |
| Name of Driver                      |  |
| NRIC/Passport Number                |  |
| Contact Number                      |  |
| Address                             |  |
| Postcode                            |  |
| Insurance Company Name              |  |
| Nature Of Damage                    |  |
| No. Of Passenger (Including Driver) |  |

**DETAILS OF OTHER VEHICLE PROPERTY 3**

|                                     |  |
|-------------------------------------|--|
| Vehicle Registration Number         | SKF1976R                                     |
| Vehicle Make/Model/Colour           | B.M.W. M5 D/AB SR ABS HID DSC NAV HUD RR/ENT |
| Details Of Properties               |  |
| Vehicle Category                    | PRIVATE CAR                                  |
| Name of Driver                      |  |
| NRIC/Passport Number                |  |
| Contact Number                      |  |
| Address                             |  |
| Postcode                            |  |
| Insurance Company Name              |  |
| Nature Of Damage                    |  |
| No. Of Passenger (Including Driver) |  |

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

2018.10.5


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

2018.10.5

Reporting Centre Personnel's Signature  
Name: Suhaimi  
NRIC/FIN No.: S8040377A

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5/10/18 at 15.30hrs I was driving my vehicle A along  
 Ave towards MCE. vehicle C stop I follow suit.  
 suddenly vehicle B hit on my rear portion and cause  
 my car to push forward and hit on vehicle D. There  
 were 4 cars involved in an accident.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

5/10/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

05/10/2018

Reporting Centre Personnel's Signature

Name: Suhaimi

NRIC/Fin No: 58040377A

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0084J

### Vehicle Details

Vehicle No.: SKQ146T

Vehicle to be Exported: No

Intended Deregistration Date: 08 Oct 2018

Vehicle Make: AUDI

Vehicle Model: A6 2.0 TFSI MU

Primary Colour: White

Manufacturing Year: 2014

Engine No.: CDN402759

Chassis No.: WAUZZZ4G6EN106937

Maximum Power Output: 132.0 kW (177 bhp)

Open Market Value: \$38,209.00

Original Registration Date: 28 Oct 2014

First Registration Date: 28 Oct 2014

Transfer Count: 0

Actual ARF Paid: \$40,493.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Oct 2024

PARF Rebate Amount: \$30,369.00

### Intended COE Rebate Details

COE Expiry Date: 27 Oct 2024

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$72,002.00

COE Rebate Amount: \$43,568.00

**Total Rebate Amount: \$73,937.00**

The information contained herein is correct as at 08 Oct 2018

OK



Get \$5150 ZALORA Gift Card  
with Maybank Credit Cards



ZALORA

APPLY NOW &gt;

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2000 Downpayment Monthly  
From \$568 Onwards. Lowest  
3.18% P.A. @ Gv Cars Financing  
GV Credit Pte Ltd StarAd

PRIME MOTOR &amp; LEASING

[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

audi a6

Advanced Search Submit

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

audi a6

Any

Any


2014

Any

Any

Any

Available



Audi A6 2.0A TFSI MU

\$93,955

\$13,040 /yr

14-May-2014

1,984 cc

87,000 km


Luxury

Available

1 Ownership With Low Mileage Done. Very Well Maintained Unit. Almost New In Condition. Low Down Payment Can Be Arranged. Viewing And Test Drive Is Available.

Posted: 06-Oct-2018

Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi A6 Avant 2.0A TFSI MU

\$90,800

\$12,790 /yr

28-Feb-2014

1,984 cc

92,000 km

Stationwagon

Available


Graded B by **STP**

Reasonable Offer Will Be Consider! Consumer Who Want A Little Luxury In Their Family Wagon, The Audi A6 Avant Will Not Disappoint. Must Act Fast Before It Gone.

Universe Motoring

Posted: 06-Oct-2018

Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi A6 2.0A TFSI MU

\$96,800

\$12,690 /yr

30-Jul-2014

1,984 cc

41,000 km


Luxury

Available

1 Owner Only! Very Good Condition! Low Mileage Done! No Repairs Needed! Like New Condition! View To Believe! 100% Accident Free! Bank Loan Or In House Loan Available! High Trade In Welcome! Call Me No...

Posted: 06-Oct-2018

Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi A6 2.0A TFSI MU

\$103,800

\$13,710 /yr

17-Oct-2014

1,984 cc

57,810 km


Luxury

Available

Up To 90% In-House Loan And Balloon Scheme Available, High COE At \$72180, No Gimmicks! Full Audi Service Record, 1 Owner, Upgraded Wooden Trimming, Paddle Shift, Keyless Entry/Start, Auto HID Lights W...

Posted: 30-Sep-2018


Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi presents 'Fifth Ring' in Milan

Audi presents the exclusive installation 'Fifth Ring' at this year's Milan Design Week, highlighting the Audi Aicon design vision and the Audi A6.

Read this article



Audi A6 2.0A TFSI MU

\$95,999

\$14,300 /yr

25-Jan-2014

1,984 cc

32,000 km

Luxury


Available

1 Owner! 32kkm Mileage Done Only! Sporty Blue Exterior/Grey Interior. Premium Pre-Owned 110 Points Certification. Flexible Finance Package And Trade In, Please SMS/Call Mobile Now For Viewing Appointm...

Premium Automobiles

Posted: 25-Sep-2018

Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi A6 2.0A TFSI MU

\$106,999

\$13,980 /yr

15-Dec-2014

1,984 cc

88,000 km

Luxury

Available

New Arrival!Solid Grey On Black Special 2.48% Banks Interest Rate! Peace Of Mind With Certified Premium Preowned 110 Points Check. 1 Owner Well Taken Care Of And In Immaculate Condition, Smooth Engine...

Premium Automobiles

Posted: 24-Sep-2018

Tags: 2014 Audi A6, 2014 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Compare

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-46/48/50  
SINGAPORE 417883

Not Authorised  
H/Aln  
8/10/18  
2/5 #22,000  
Sig.

VEHICLE NO: SKQ 146T

| QTY   | PARTICULAR                           |                  |        |                |
|-------|--------------------------------------|------------------|--------|----------------|
| 1 PCS | BOOTLID                              | 2455.12          | DD/3uc | \$3,966.20     |
| 1 PCS | BOOTLID REAR LOGO                    |                  | nu     | \$100.85       |
| 1 PCS | BOOTLID 'A6' EMBLEM                  | 88.20            | nu     | \$102.30       |
| 1 PCS | BOOTLID '2.0T' EMBLEM                |                  | nu     | \$88.50        |
| 1 PCS | BOOTLID INNER LOCK                   |                  | twi    | \$315.50       |
| 1 PCS | BOOTLID LOCK STRIKER                 |                  | 11     | \$105.20 X     |
| 1 PCS | BOOTLID WEATHERSTRIP                 | 240.50           | twi    | \$266.20       |
| 2 PCS | BOOTLID REFLECTORS @\$1005.00        | 495.00 X 2 = 990 | cm     | \$2,010.00     |
| 1 PCS | BOOTLID INNER TRIM                   |                  | 11     | \$488.25 X     |
| 1 SET | BOOTLID INNER TRIM CLIPS             |                  | 11     | \$50.00 X      |
| 2 PCS | BOOTLID LICENCE PLATE LAMPS @\$95.00 |                  | 11     | \$190.00 X     |
| 1 PCS | REAR BUMPER                          | 2315.00          | 715    | \$2,665.00     |
| 1 PCS | REAR BUMPER LOWER SKIRTING           | 345.00           | de     | \$695.00       |
| 1 PCS | REAR BUMPER SPONGE                   |                  | nu     | \$210.30 X     |
| 1 PCS | REAR BUMPER REINFORCEMENT            | 699.00           | DD     | \$935.00       |
| 2 PCS | REAR BUMPER BRACKETS @\$145.00       |                  | 31     | \$290.00       |
| 2 PCS | REAR BUMPER SIDE HOLDERS @\$135.00   |                  | 31     | \$270.00       |
| 4 PCS | REAR BUMPER PDC SENSORS @\$313.75    | 185 X 4 = 740    | shold  | \$1,255.00     |
| 1 PCS | REAR BUMPER PDC SENSOR WIRE          |                  | cm     | \$285.60       |
| 1 PCS | REAR BUMPER TOW COVER                |                  | 70 in  | \$45.00        |
| 1 PCS | REAR BUMPER TOP RETAINER             |                  | cm     | \$165.00       |
| 1 PCS | REAR END PANEL                       |                  | Body   | \$580.60       |
| 1 PCS | REAR END PANEL EXTENSION LOWER       | 245.12           | 245.00 | \$315.00       |
| 1 PCS | REAR END PANEL TOP GARNISH           |                  | twi    | \$295.00       |
| 2 PCS | TAILLAMPS @\$1205.00                 | 711.00           | 15cm   | \$2,410.00 12C |
| 1 PCS | REAR END PANEL INNER MEMBER          |                  | 2      | \$495.00 X     |
| 1 PCS | REAR EXHAUST N/S                     |                  | 2      | \$1,685.00 X   |
| 1 PCS | REAR EXHAUST O/S                     |                  | 2      | \$1,595.00 X   |
| 1 PCS | REAR EXHAUST HEATSHIELD              |                  | 11     | \$185.00 X     |
| 1 PCS | REAR FLOOR PANEL                     |                  | 2      | \$1,150.00 X   |
| 1 PCS | REAR FLOOR PANEL TOP BOARD           |                  | 11     | \$825.30 X     |
| 2 PCS | REAR FENDERS @\$3650.00              |                  | 2      | \$7,300.00 X   |
| 2 PCS | REAR FENDER INNER TRIMS @\$366.20    |                  | 11     | \$732.40 X     |
| 2 PCS | FRONT SEABELTS @\$920.00             | 820 X 2 = 1640   | Actib  | \$1,840.00     |
| 1 SET | HEADREST REPAIR KIT                  |                  | Actib  | \$245.00       |
| 1 PCS | BATTERY CABLE                        | 182.35           | Actib  | \$252.00       |
| 1 PCS | BONNET                               |                  | 2      | \$3,145.00 X   |
| 1 PCS | BONNET LOCK                          |                  | 11     | \$185.50 X     |
| 1 PCS | BONNET SEAL                          |                  | 11     | \$88.00 X      |

|       |  |          |             |      |
|-------|--|----------|-------------|------|
| 1 PCS | BONNET INSULATOR                               | 17       | \$260.55    | X    |
| 1 SET | BONNET INSULATOR CLIPS                         | 17       | \$50.00     | X    |
| 2 PCS | BONNET HINGES @\$115.00                        | 17       | \$230.00    | X    |
| 1 PCS | FRONT BUMPER                                   | 10/10-17 | \$2,655.00  | —    |
| 2 PCS | FRONT SIDE <i>retainers</i> @\$105.00          | 34       | \$210.00    | —    |
| 1 PCS | FRONT BUMPER SPONGE                            | 17       | \$205.00    | X    |
| 1 PCS | FRONT BUMPER REINFORCEMENT                     | 34       | \$955.00    | —    |
| 2 PCS | FRONT BUMPER REINFORCEMENT STAYS @\$145.00     | 17       | \$290.00    | X    |
| 1 PCS | FRONT GRILLE                                   | 17       | \$1,255.00  | —    |
| 1 PCS | FRONT GRILLE LOGO                              | 17       | \$100.85    | X    |
| 2 PCS | FRONT PDC SENSORS @\$315.00                    | 17       | \$630.00    | —    |
| 2 PCS | HEADLAMP ASSYS @\$6800.0                       | 17       | \$13,600.00 | —    |
| 1 PCS | FRONT SUPPORT PANEL                            | 17       | \$1,055.00  | X    |
| 1 PCS | AIR CON CONDENSER                              | 17       | \$1,265.00  | X    |
| 1 PCS | RADIATOR                                       | 17       | \$1,350.00  | X    |
| 1 PCS | RADIATOR FAN ASSY                              | 17       | \$1,385.00  | X    |
| 1 PCS | HORN UNIT                                      | 17       | \$110.00    | X    |
| 1 PCS | TURBO COOLER                                   | 17       | \$820.00    | X    |
|       |  |          | \$64,249.10 |      |
|       | S.NETT   |          |             |      |
| 1 PCS | REAR LICENCE PLATE W/HOLDER                    | 34       | \$50.00     | 40   |
| 1 PCS | REAR END PANEL SEALANT                         | 17       | \$50.00     | ✓    |
| 1 PCS | REAR WINDSCREEN SEALANT                        | 17       | \$50.00     | X    |
| 1 SET | REAR EXHAUST CHROME                            | 17       | \$200.00    | X    |
| 1 PCS | REAR FLOOR PANEL INSULATOR                     | 17       | \$280.00    | X    |
| 1 PCS | FRONT LICENCE PLATE                            | 34       | \$50.00     | 20   |
| 1 BOT | RADIATOR COOLANT                               | 17       | \$50.00     | X    |
|       | LABOUR CHRAGES:                                |          |             |      |
|       | TO CHECK WIRING                                |          | \$80.00     | 30   |
|       | TO DISMANTLE & REPLACING PDC SENSOR            |          | \$100.00    | 50   |
|       | TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY   |          | \$150.00    | 100  |
|       | TO DISMANTLE & REFIX REAR EXHAUST              |          | \$150.00    | 60   |
|       | TO DISMANTLE & REFIX REAR WINDSCREEN           | 17       | \$150.00    | X    |
|       | TO TRANSFER BOOTLID MECHANISM                  |          | \$150.00    | 80   |
|       | TO SPRAY RUST PROOFING                         |          | \$150.00    | 80   |
|       | TO RESET AIR BAG PROGRAMME                     |          | \$380.00    | 200  |
|       | TO REFILL AIR CON GAS                          |          | \$150.00    | 100  |
|       | TO MOUNT VEHICLE ON CAR O-LINER                | 17       | \$380.00    | X    |
|       | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED |          | \$3,800.00  | 1400 |
|       | REPLACING PARTS                                |          |             |      |
|       | TO PUTTY & SPRAY PAINTING                      |          | \$3,500.00  | 1600 |
|       | TOTAL  |          | \$74,119.10 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28184.35  
22547

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18018151/UQBN2

Date: 12/11/2018

## REFERENCE

|                   |                                      |                      |           |
|-------------------|--------------------------------------|----------------------|-----------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | A80455229 |
| Claimant:         | SKQ146T                              | Insured Vehicle No : | SLS6587S  |
| Vehicle No :      |                                      | Nature of Claim:     | TP        |
| Date of Loss:     | 05/10/2018                           | Claim No:            | 572547    |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SKQ146T                      | Engine No:  | CDN402759         |
| Make & Model:               | AUDI A6, 2.0 TFSI MU (A)     | Chassis No: | WAUZZZ4G6EN106937 |
| Reg. Date:                  | 28/10/2014 (Man. Year: 2014) | Odometer:   | 29469 km          |
| Colour:                     | White                        |             |                   |
| Engine Capacity:            | 1984 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/55R17    | Rear Tyre Size:  | 225/55R17    |
| Front Left Side:  | Pirelli 7 mm | Rear Left Side:  | Pirelli 7 mm |
| Front Right Side: | Pirelli 7 mm | Rear Right Side: | Pirelli 7 mm |

The above values represent the remaining tyre treads depth.

## COST OF CLAIMS

|  | Repairer's       | Adjuster's       | Difference       | Diff %       |
|--|------------------|------------------|------------------|--------------|
| Parts                                    | 64,979.10        | 24,484.36        | 40,494.74        | 62.32        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 9,140.00         | 3,700.00         | 5,440.00         | 59.52        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>74,119.10</b> | <b>28,184.36</b> | <b>45,934.74</b> | <b>61.97</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>22,000.00</b> |                  |              |
| <b>(S\$)</b>                             | <b>74,119.10</b> | <b>22,000.00</b> | <b>52,119.10</b> | <b>70.32</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>5,188.34</b>  | <b>1,540.00</b>  | <b>3,648.34</b>  | <b>70.32</b> |
| <b>Nett Amount (S\$)</b>                 | <b>79,307.44</b> | <b>23,540.00</b> | <b>55,767.44</b> | <b>70.32</b> |

## INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 07/11/2018               |  |
| Date Inspected:             | 08/10/2018 Inspected At: | Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50<br>Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 8.0 days                 |  |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|   |  |
|---|--|
| <b>Part Source:</b> MRM-SG                                  | Version: 1.0 (Last Synchronised: 12 Nov 2018)  |
| <b>Parts:</b> 143   | AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's                                   | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SKQ146T) |  |
| <b>Validity:</b>  | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>  | Items/values not in reference catalogue are prefixed with an asterisk *.   |

## Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition      | Repairer's | Amount       |
|-----|-----|----------|---------------------------------|----------------|------------|--------------|
| 1   | 1   |          | *BOOTLID                        | Dented/Buckled | 3,966.20 F | *2,455.12 FL |
| 2   | 1   |          | *BOOTLID REAR LOGO              | Necessary      | 100.85 F   | *100.85 FL   |
| 3   | 1   |          | *BOOTLID A6 EMBLEM              | Necessary      | 102.30 F   | *88.20 FL    |
| 4   | 1   |          | *BOOTLID 2.0T EMBLEM            | Necessary      | 88.50 F    | *88.50 FL    |
| 5   | 1   |          | *BOOTLID INNER LOCK             | Twisted        | 315.50 F   | *315.50 FL   |
| 6   | 1   |          | *BOOTLID LOCK STRIKER           | Not Necessary  | 105.20 F   | *- FL        |
| 7   | 1   |          | *BOOTLID WEATHERSTRIP           | Twisted        | 266.20 F   | *240.50 FL   |
| 8   | 2   |          | *BOOTLID REFLECTORS             | Cracked        | 2,010.00 F | *990.00 FL   |
| 9   | 1   |          | *BOOTLID INNER TRIM             | Not Necessary  | 488.25 F   | *- FL        |
| 10  | 1   |          | *SET BOOTLID INNER TRIM CLIPS   | Not Necessary  | 50.00 F    | *- FL        |
| 11  | 2   |          | *BOOTLID LICENCE PLATE LAMPS    | Not Necessary  | 190.00 F   | *- FL        |
| 12  | 1   |          | *REAR BUMPER                    | Distorted      | 2,665.00 F | *2,315.00 FL |
| 13  | 1   |          | *REAR BUMPER LOWER SKIRTING     | Deformed       | 695.00 F   | *345.00 FL   |
| 14  | 1   |          | *REAR BUMPER SPONGE             | Not fitted     | 210.30 F   | *- FL        |
| 15  | 1   |          | *REAR BUMPER REINFORCEMENT      | Dented         | 935.00 F   | *699.00 FL   |
| 16  | 2   |          | *REAR BUMPER BRACKETS           | Bent           | 290.00 F   | *290.00 FL   |
| 17  | 2   |          | *REAR BUMPER SIDE HOLDERS       | Bent           | 270.00 F   | *270.00 FL   |
| 18  | 4   |          | *REAR BUMPER PDC SENSORS        | Shorted        | 1,255.00 F | *740.00 FL   |
| 19  | 1   |          | *REAR BUMPER PDC SENSOR WIRE    | Cracked        | 285.60 F   | *285.60 FL   |
| 20  | 1   |          | *REAR BUMPER TOW COVER          | Torn           | 45.00 F    | *45.00 FL    |
| 21  | 1   |          | *REAR BUMPER TOP RETAINER       | Cracked        | 165.00 F   | *165.00 FL   |
| 22  | 1   |          | *REAR END PANEL                 | Badly Dented   | 580.60 F   | *580.60 FL   |
| 23  | 1   |          | *REAR END PANEL EXTENSION LOWER | Badly Dented   | 315.00 F   | *245.12 FL   |
| 24  | 1   |          | *REAR END PANEL TOP GARNISH     | Twisted        | 295.00 F   | *295.00 FL   |
| 25  | 1   |          | *TAILLAMPS                      | N/s Cracked    | 2,410.00 F | *711.00 FL   |
| 26  | 1   |          | *REAR END PANEL INNER MEMBER    | Repair         | 495.00 F   | *- FL        |
| 27  | 1   |          | *REAR EXHAUST N/S               | Repair         | 1,685.00 F | *- FL        |
| 28  | 1   |          | *REAR EXHAUST O/S               | Repair         | 1,595.00 F | *- FL        |
| 29  | 1   |          | *REAR EXHAUST HEATSHIELD        | Not Necessary  | 185.00 F   | *- FL        |
| 30  | 1   |          | *REAR FLOOR PANEL               | Repair         | 1,150.00 F | *- FL        |
| 31  | 1   |          | *REAR FLOOR PANEL TOP BOARD     | Not Necessary  | 825.30 F   | *- FL        |
| 32  | 2   |          | *REAR FENDERS                   | Repair         | 7,300.00 F | *- FL        |
| 33  | 2   |          | *REAR FENDER INNER TRIMS        | Not Necessary  | 732.40 F   | *- FL        |
| 34  | 2   |          | *FRONT SEATBELTS                | Activated      | 1,840.00 F | *1,640.00 FL |
| 35  | 1   |          | *SET HEADREST REPAIR KIT        | Activated      | 245.00 F   | *245.00 FL   |
| 36  | 1   |          | *BATTERY CABLE                  | Activated      | 252.00 F   | *182.35 FL   |
| 37  | 1   |          | *BONNET                         | Repair         | 3,145.00 F | *- FL        |
| 38  | 1   |          | *BONNET LOCK                    | Not Necessary  | 185.50 F   | *- FL        |
| 39  | 1   |          | *BONNET SEAL                    | Not Necessary  | 88.00 F    | *- FL        |
| 40  | 1   |          | *BONNET INSULATOR               | Not Necessary  | 260.55 F   | *- FL        |
| 41  | 1   |          | *SET BONNET INSULATOR CLIPS     | Not Necessary  | 50.00 F    | *- FL        |
| 42  | 2   |          | *BONNET HINGES                  | Not Necessary  | 230.00 F   | *- FL        |
| 43  | 1   |          | *FRONT BUMPER                   | Dented/Torn    | 2,655.00 F | *2,335.00 FL |
| 44  | 2   |          | *FRONT SIDE RETAINERS           | Bent           | 210.00 F   | *210.00 FL   |

Report was unsubmitted during this print-out.



| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 45  | 1   |          | *FRONT BUMPER SPONGE              | Not fitted    | 205.00 F    | *- FL        |
| 46  | 1   |          | *FRONT BUMPER REINFORCEMENT       | Bent          | 955.00 F    | *775.20 FL   |
| 47  | 2   |          | *FRONT BUMPER REINFORCEMENT STAYS | Not Necessary | 290.00 F    | *- FL        |
| 48  | 1   |          | *FRONT GRILLE                     | Cracked       | 1,255.00 F  | *1,255.00 FL |
| 49  | 1   |          | *FRONT GRILLE LOGO                | Not Necessary | 100.85 F    | *- FL        |
| 50  | 2   |          | *FRONT PDC SENSORS                | Shorted       | 630.00 F    | *370.00 FL   |
| 51  | 2   |          | *HEADLAMP ASSYS                   | Cracked       | 13,600.00 F | *7,379.68 FL |
| 52  | 1   |          | *FRONT SUPPORT PANEL              | Not Necessary | 1,055.00 F  | *- FL        |
| 53  | 1   |          | *AIR CON CONDENSER                | Not Necessary | 1,265.00 F  | *- FL        |
| 54  | 1   |          | *RADIATOR                         | Not Necessary | 1,350.00 F  | *- FL        |
| 55  | 1   |          | *RADIATOR FAN ASSY                | Not Necessary | 1,385.00 F  | *- FL        |
| 56  | 1   |          | *HORN UNIT                        | Not Necessary | 110.00 F    | *- FL        |
| 57  | 1   |          | *TURBO COOLER                     | Not Necessary | 820.00 F    | *- FL        |
| 58  | 1   |          | *REAR LICENCE PLATE W/HOLDER      | Bent          | 50.00 FS    | *40.00 FS    |
| 59  | 1   |          | *REAR END PANEL SEALANT           | Necessary     | 50.00 FS    | *50.00 FS    |
| 60  | 1   |          | *REAR WINDSCREEN SEALANT          | Not Necessary | 50.00 FS    | *- FS        |
| 61  | 1   |          | *SET REAR EXHAUST CHROME          | Serviceable   | 200.00 FS   | *- FS        |
| 62  | 1   |          | *REAR FLOOR PANEL INSULATOR       | Not Necessary | 280.00 FS   | *- FS        |
| 63  | 1   |          | *FRONT LICENCE PLATE              | Bent          | 50.00 FS    | *20.00 FS    |
| 64  | 1   |          | *BOT RADIATOR COOLANT             | Not Necessary | 50.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                  |                  |
|---|------------------|------------------|
| <b>Sub Total (\$\$)</b>                           | <b>64,979.10</b> | <b>25,767.22</b> |
| - List Item Discount on L Items 0.00/5.00% (\$\$) | 0.00             | 1,282.86         |
| <b>Total Parts (\$\$)</b>                         | <b>64,979.10</b> | <b>24,484.36</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's | Amount   |
|-------------------------|--|----------|------------|----------|
| <b>Labour Items</b>     |  |          |            |          |
| 1                       | TO CHECK WIRING  | New      | 80.00      | 30.00    |
| 2                       | TO DISMANTLE & REPLACING PDC SENSOR                            | New      | 100.00     | 50.00    |
| 3                       | TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY                   | New      | 150.00     | 100.00   |
| 4                       | TO DISMANTLE & REFIX REAR EXHAUST                              | New      | 150.00     | 60.00    |
| 5                       | TO DISMANTLE & REFIX REAR WINDSCREEN                           | New      | 150.00     | -        |
| 6                       | TO TRANSFER BOOTLID MECHANISM                                  | New      | 150.00     | 80.00    |
| 7                       | TO SPRAY RUST PROOFING   | New      | 150.00     | 80.00    |
| 8                       | TO RESET AIR BAG PROGRAMME                                     | New      | 380.00     | 200.00   |
| 9                       | TO REFILL AIR CON GAS  | New      | 150.00     | 100.00   |
| 10                      | TO MOUNT VEHICLE ON CAR O-LINER                                | New      | 380.00     | -        |
| 11                      | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED REPLACING PARTS | New      | 3,800.00   | 1,400.00 |
| 12                      | TO PUTTY & SPRAY PAINTING                                      | New      | 3,500.00   | 1,600.00 |
| Gross Labour Cost (S\$) |  |          | 9,140.00   | 3,700.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;