



Case Details

Case Reference Number : TAX/10/18/2007

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : American Home Assurance Company

Type of Repair : Accident Repair

Estimation ID : EST-3986-ID

Accident Date and Time : 02/10/2018 09:45 AM

Vehicle Registration Number : SHB5253Z

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 11

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval		
BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace
One Time Key In			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace
Total Spare Part Cost								1,303.28		Surveyor Total	1,303.28	
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								1,303.28		Final Sur Total	1,303.28	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	RESPRAY MIRROR COVER RH	180.00	50	
Total:		180.00	50.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO WASH AND VACUUM	60.00	0	NN
2	TO REPLACE SUNDRY PARTS	100.00	0	NN
3	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
4	TO REMOVE AND REFIX WING MIRROR	120.00	30	
Total:		360.00	50.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,303.28	1,303.28
Total Labour Cost	0.00	0.00
Total Spray Painting	180.00	50.00
Other	360.00	50.00
Overall Total	1,843.28	1,403.28
Lump Sum Repair Option		
Lump Sum Total	0.00	1,403.28
Surveyor Approved Amount		1,403.28
No of Repair Days*	2	1
Remarks	-	PART BY PART REPAIR 1 DAY BEFORE PAINT PHOTOS
Surveyor Name		Naz
Signature		
Survey Date	04/10/2018	

Save Clear

NAZ LKK
4/10/18 1615
PIP
BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: