

INS. CASE OWNER:

CC 6, ~~47~~ 180 18156, Upas 4

LKK:
IDAC:

Surveyor:

UUS

DOI:

ASSIGNMENT

8-10-18

Date / Time:

8-10-18

Registered in Meritum:

Pre-assign / CCU / FTZ



Insured Vehicle No. : SKZ 6199D

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : \$\$ D.O.A : 7-10-18

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (VL: YES / NO)

Insured Liability : % Final ? Yes / No

SJX 1450H



INSRS:
WSP: *pastech*
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time

SJX 1450H - X : SKZ 6199D - X

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:

11/10/18

CTI instruction to redirect claim to AXA

After call ltr to OI:
Documentation Check List: Handler Typist

9/11/18

submit independent to TP UKRP

Notification ltr (if non-pickup)

19/11/18

File pass to Mei bee to close

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$\$

(days) Reduction:

%

Email Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

IF NO or B 28, Ass. Lia :

Repair Cost:

\$\$

Loss of Rental (LOR):

\$\$

(days)

Loss of Use (LOU):

\$\$

(\$ x days)

Loss of Income (LOI):

\$\$

(\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search

\$\$

Medical:

\$\$

Disbursement:

\$\$

(e.g. Tow/ Independent)

Legal Cost

\$\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format: *Independent*

3) Survey fee: *\$866.00*

Total:

\$\$

Global Sum \$\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email Call

Payee 1:

\$\$

Name 1:

Payee 2: (Strike if N.A.)

\$\$

Name 2:

Payee 3: (Strike if N.A.)

\$\$

Name 3:

Successor vehicle

REF:

CT1/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SJX1450H
 at Workshop m/s: Ry.
 of _____
 Insured: SKZ 6199D
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

7	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 34
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJX1450H Yr Regn: 19/5/10
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda accord CC: 1997
 Colour: Beige A/C: Insured / Std / NI / NA
 Sp. Reading: 12128 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRMCP16309P020137
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or ok
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 8 mm L/Bal: 6 mm
 D.O.A: 7/10/18 D.O.I: 8/10/18
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
ols of 6 of steel
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
have video L7A 23650 hrs 7mth.
have GIA Rep 11k next 10350
independent.
8/11/18 d/s # 10300 contact with Alan.
CRed \$ 23286.94/69%

Date/Time File Pass to? : Prel. Report
 : Final Report
 Date/Time File Return to? _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 Photos: OSP
 Others: 29/11/18

170. + 375
50 + 50
171.00
80.00
866.00

TOTAL

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

Not Authorized
 n/le
 8/10/18
 2/5 # 10300/1
 Sdy.

VEHICLE NO: SJX 1450H

QTY	PARTICULAR				
1 PCS	BONNET	899.50		Bull	\$1,422.30
2 PCS	BONNET HINGES @\$88.50			Bull/tur	\$177.00
1 PCS	BONNET LOCK	102.50		tur	\$165.30
1 PCS	BONNET RUBBER			acc	\$110.20
1 PCS	BONNET INSULATOR	145.30		ac	\$211.40
1 SET	BONNET INSULATOR CLIPS			acc	\$39.00
1 PCS	FRONT GRILLE			17	\$692.30
1 PCS	FRONT GRILLE LOGO			17	\$38.80
1 PCS	FRONT BUMPER	620.50		Dis	\$845.20
2 PCS	FRONT BUMPER SIDE HOLDERS @\$45.00			o/s Bull	\$90.00
1 SET	FRONT BUMPER CLIPS			acc	\$35.00
1 PCS	FRONT BUMPER BEAM			tur	\$315.20
1 PCS	FRONT BUMPER FOG LAMP O/S			5/20	\$288.50
1 PCS	FRONT BUMPER LICENCE PLATE HOLDER	68.50		cut	\$145.00
1 PCS	FRONT SUPPORT PANEL			Bull/tur	\$899.20
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	296.40		torn	\$366.20
1 SET	FRONTSUPPORT PANEL TOP GARNISH CLIPS			acc	\$30.00
2 PCS	FRONT FENDERS @\$845.20	607.70 x 2 = 1215.40	Body/acc	o/s Bull	\$1,690.40
2 PCS	FRONT FENDER INNER SHIELDS @\$255.10	116.60		o/s Bull	\$450.20
1 SET	FRONT FENDER INNER SHIELD CLIPS			acc	\$40.00
1 PCS	FRONT FENDER INNER SIDE PANEL O/S			Bull/ID	\$366.50
1 PCS	FRONT FENDER INNER SIDE GARNISH O/S			torn	\$88.20
1 PCS	WIPER WASHER TANK			Dis	\$365.20
1 PCS	WIPER WASHER TANK MOTOR			5/20	\$245.00
2 PCS	HEADLAMPS @\$1850.00	890.50		o/s 5/20	\$3,700.00
2 PCS	HEADLAMP LOWER BRACKETS \$85.00	48.60		o/s Bull	\$170.00
1 PCS	AIR CON CONDENSER			17	\$981.10
1 PCS	AIR CON FAN ASSY			17	\$650.00
1 PCS	RADIATOR	1283.00		holder/acc	\$1,850.00
1 PCS	RADIATOR FAN ASSY			17	\$650.00
1 PCS	FRONT SHOCK ABSORBER O/S			Bull	\$425.00
1 PCS	FRONT LOWER ARM O/S	337.10		5/20	\$499.50
1 PCS	FRONT KNUCKLE ARM O/S	362.80		5/20	\$655.20
1 PCS	FRONT KNUCKLE ARM BEARING O/S	188.00		acc	\$350.00
1 PCS	FRONT DRIVESHAFT O/S			17	\$1,450.00
1 PCS	FRONT DOOR O/S			17	\$1,120.30
1 PCS	REAR DOOR O/S	845.30		o/s Bull	\$1,050.20
1 PCS	REAR FENDER O/S			17	\$899.50
1 PCS	REAR BUMPER			17	\$705.00

202

1 PCS REAR BUMPER SIDE RETAINER O/S
 1 SET REAR BUMPER CLIPS
 1 PCS ABS PUMP

(207)

11 \$45.00 X
 11 \$30.00 ✓
 11 \$2,880.00 X
 \$27,226.90

1 PCS set FRONT BUMPER SENSOR
 1 PCS FRONT LICENCE PLATE W/HOLDER
 1 PCS FRONT SPORT RIM O/S
 1 PCS REAR SPORT RIM O/S

shell \$280.00 200
 SCR \$50.00 40
 cut \$650.00 450
 cut \$650.00 450

LABOUR CHARGES:

TOWING CHARGE
 TO CHECK WIRING
 TO DISMANTLE & REPLACING FRONT BUMPER SENSOR
 TO REFILL AIR CON GAS
 TO CONDUCT WHEEL ALIGNMENT
 TO SPRAY RUST PROOFING
 TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE
 TO MOUNT VEHICLE ON CAR O-LINER
 LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED
 REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

\$150.00 100
 \$100.00 30
 \$100.00 50
 \$150.00 100
 \$100.00 80
 \$150.00 120
 \$300.00 150
 11 \$380.00 2
 \$1,500.00 1200
 \$1,800.00 1600

TOTAL \$33,586.90

I hereby agree to have you notify
 the Receiver of the following:

- To receive notification only per the
- To display damage & notify third party
- Facts once all subject to
- Third party survey on a "without prejudice" basis
- No other conditions are placed
- Supplementary terms must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10491
 838280
 179628

I hereby agree to have you notify
 the Receiver of the following:

- To receive notification only per the
- To display damage & notify third party
- Facts once all subject to
- Third party survey on a "without prejudice" basis
- No other conditions are placed
- Supplementary terms must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9011Z
Vehicle Details	
Vehicle No.:	SJX1450H
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0L
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	R20A32800143
Chassis No.:	MRHCP16309P020137
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,878.00
Original Registration Date:	19 May 2010
First Registration Date:	19 May 2010
Transfer Count:	2
Actual ARF Paid:	\$31,878.00 <i>15939</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2020
PARF Rebate Amount:	\$17,532.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$6,118.00
Total Rebate Amount:	\$23,650.00

The information contained herein is correct as at 08 Oct 2018

OK



Find the best Business Broadband deals online & save now!
High-speed and affordable bandwidth to grow your business effectively.

Sign up now



honda accord Price Range Depreciation 2010 Vehicle Type Submit Advanced Search

Home > Used Cars > ValueCars Auto Traders > Honda Accord 2.0A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

BRAND NEW FLEET AVAILABLE FOR RENT / LEASE

CALL: 8482 3003

MarkLogic

KNOW NOSQL NOW!

Enterprise NoSQL DUMMIES

FREE BOOK

GET IT NOW >

Honda Accord 2.0A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error

Car Details

Price	\$35,000
Depreciation	\$11,390 /yr <small>View models with similar depreciation</small>
Reg Date	01-Jul-2010 <small>(1yr 8mths 22days COE left)</small>
Manufactured	2009
Mileage	111,912 km (13.5k /yr)
Transmission	Auto
Engine Cap	1,997 cc
Road Tax	\$1,210 /yr
Power	115.0 kW (154 bhp) <small>View specs of the Honda Accord (2008-2013)</small>
Curb Weight	1,505 kg
Features	5 Speed Automatic, ABS, Digital Climate Aircon Controls, Auto Headlights And Rain Sensors, Cruise Control, Superior 2.0L I-VTEC Engine.
Accessories	Factory Fitted CD/Audio System With Steering Controls, Rear Aircon, Fog Lights, Electric Leather Seats, Sports Rims, Reverse Sensors.
Description	Flexible Loan And Down Payment Available! Silver Honda Accord 2.0A! Reliable And Problem Free Honda Luxury Sedan! Low Mileage 112k Km! Safe Purchased! High ARF \$30.6k! High Paper Value \$24.7K! High Export Value! Come View And We Discuss Further Thanks!
COE	\$45,501
OMV	\$30,624
ARF	\$30,624
Dereg Value	\$24,709 as of today (change)
No. of Owners	2
Type of Veh	Luxury Sedan
Category	FAAF Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 02-Oct-2018 | Last Updated on: 08-Oct-2018

Tags: Honda Accord, Honda accord, 2010 Honda Accord, 2010 honda accord, Honda, Accord, accord, Used Honda



Location Map Price Analysis

Seller Information

Company	ValueCars Auto Traders <small>dealer's profile</small> <small>41 vehs sold 15 vehs available</small>	
Address	61 Ubi Avenue 2 #02-06 <small>Search cars nearby this location</small>	
Location	Automobile Megamart	
Office No	68410062	
Contact Person(s)	Alex	96370341
	Audrey	96528922
	Richard	88222308

Useful Services

STA Vehicle Inspection

Afraid of lemons? Request to have this car evaluated professionally.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

Compare



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



honda accord Price Range Depreciation 2010 Vehicle Type Submit

Advanced Search

Home > Used Cars > Direct Owners > Honda Accord 2.0A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



FORTYTWO

UP TO 50% DINING FURNITURE



100 DAY FREE RETURNS

SHOP NOW

Compare

Honda Accord 2.0A

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist Add to Compare Add a Note Report Error

More Actions Share

Car Details

Price	\$40,000	
Depreciation	\$11,650 /yr	View models with similar depreciation
Reg Date	10-Nov-2010 (2yrs 1mth 1day COE left)	
Manufactured	2010	
Mileage	-	
Transmission	Auto	
Engine Cap	1,997 cc	
Road Tax	\$1,210 /yr	
Power	115.0 kW (154 bhp)	View specs of the Honda Accord (2008-2013)
Curb Weight	1,505 kg	
Features	I-VTEC 16 Valve Engine, 156 BHP At 6,300Rpm, Torque 189Nm At 4,300Rpm, Top Speed 190Km/H 5 Speed Auto+ Dual O/Drive, 4 New Tyres, Road Tax Nov 2018.	
Accessories	LED Scoff Plate/Ambience+Cabin Lights All Round Interior Double Layer Sound Proofing Bluetooth Interface/Reverse Camera/Smart Key With Boot Release.	
Description	1 Careful Owner! Car Loan Can Be Arranged. 2 Front Plus 2 Front Seats With Airbags/Traction Control/Multi Function Steering/Auto HID Headlights/Rain Sensing Wipers/Retractable Mirrors LED Indicators/Front Plus Reverse Sensors/Auto Climate Control/Navigation/Leather Steering/Seats/Louvre Front Discs Plus New Brake Pads. No Dealers. Reserved For True Honda Cars Upgrader/Enthusiasts Only.	
COE	\$44,600	
OMV	\$31,301	
ARF	\$31,301	
Dereg Value	\$28,104 as of today (change)	
No. of Owners	1	
Type of Veh	Luxury Sedan	
Category	PARF Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER



Seller Information

Contact Person(s) Michael
Contact No. 96823027
Enquiry Contact Seller

USEFUL FORMS

- Indemnity form
- Receipt
- M01
- Sales agreement
- Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally. Vehicle Evaluation

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 11 October 2018 4:38 PM
To: Nancy Lam; Jason Fastech Auto (jason@fastechauto.com.sg)
Cc: Hsiao Tong (LKKAuto); Admin A; Marcus Chua (LKKAuto)
Subject: ACCIDENT INVOLVING SJX1450H (MSIG) / SKZ6199D (AXA) AND SFY5285 (CTI) ON 07.10.2018 *** LKK REF: CC6/CTI18018156/Upa3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that this case fall under bola multiple chain collision.

Kindly redirect this case to SKZ6199D which insured by AXA.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
- FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 ON BEHALF OF TAN TOO WEE	Ref : CC6/TP18018156/Upa3q2 Date : 30-11-2018 Code : TP130		
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	SJX 1450H	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	08/10/2018	
2. Vehicle Particulars & Condition			
Make & Model	HONDA ACCORD (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MRHCP16309P020137	Colour	BEIGE
Odometer	121128	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT & O/S REAR PORTION.THE UNDERCARRIAGE AND CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/10/2018	Inspection Date	08/10/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 1450H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	1,422.30	899.50
20	BONNET HINGES @\$88.50	BENT / TWISTED	177.00	177.00
1	BONNET LOCK	TWISTED	165.30	102.50
1	BONNET RUBBER	NECESSARY	110.20	110.20
1	BONNET INSULATOR	DEFORMED	211.40	145.30
1	SET BONNET INSULATOR CLIPS	NECESSARY	39.00	39.00
1	FRONT GRILLE	NOT NECESSARY	692.30	-
1	FRONT GRILLE LOGO	NOT NECESSARY	38.80	-
1	FRONT BUMPER	DISTORTED	845.20	620.50
2	FRONT BUMPER SIDE HOLDERS @\$45.00	O/S BENT	90.00	45.00
1	SET FRONT BUMPER CLIPS	NECESSARY	35.00	35.00
1	FRONT BUMPER BEAM	TWISTED	315.20	315.20
1	FRONT BUMPER FOG LAMP O/S	BROKEN	288.50	288.50
1	FRONT BUMPER LICENCE PLATE HOLDER	CUT	145.00	68.50
1	FRONT SUPPORT PANEL	BENT / TWISTED	899.20	899.20
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	366.20	296.40
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	30.00	30.00
2	FRONT FENDERS @\$845.20	BADLY DENTED / BUCKLED	1,690.40	1,215.40
2	FRONT FENDER INNER SHIELDS @\$255.10	O/S TORN	450.20	116.60
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	40.00	40.00
1	FRONT FENDER INNER SIDE PANEL O/S	BADLY DENTED	366.50	366.50
1	FRONT FENDER INNER SIDE GARNISH O/S	TORN	88.20	88.20
1	WIPER WASHER TANK	DISTORTED	365.20	365.20
1	WIPER WASHER TANK MOTOR	BROKEN	245.00	245.00
2	HEADLAMPS @\$1850.00	O/S BROKEN	3,700.00	890.50
2	HEADLAMP LOWER BRACKETS @\$48.60	O/S BENT	170.00	48.60
1	AIR CON CONDENSER	NOT NECESSARY	981.10	-
1	AIR CON FAN ASSY	NOT NECESSARY	650.00	-
1	RADIATOR	HOLDER CRACKED	1,850.00	1,283.00
1	RADIATOR FAN ASSY	NOT NECESSARY	650.00	-

Report Ref No. CC6/TP18018156/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SHOCK ABSORBER O/S	SERVICEABLE	425.00	-
1	FRONT LOWER ARM O/S	BENT	499.50	337.10
1	FRONT KNUCKLE ARM O/S	BENT	655.20	362.80
1	FRONT KNUCKLE ARM BEARING O/S	NECESSARY	350.00	185.00
1	FRONT DRIVESHAFT O/S	NOT NECESSARY	1,450.00	-
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,120.30	-
1	REAR DOOR O/S	DENTED / BENT	1,050.20	845.30
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	899.50	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	705.00	-
1	REAR BUMPER SIDE RETAINER O/S	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	ABS PUMP	NOT NECESSARY	2,880.00	-
	LESS 20% DISCOUNT		-	-2,098.20
			27,226.90	8,392.80
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER SENSOR (SN)	SHORTED	280.00	200.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	SCRATCHED	50.00	40.00
1	FRONT SPORT RIM O/S (SN)	CUT	650.00	450.00
1	REAR SPORT RIM O/S (SN)	CUT	650.00	450.00
			1,630.00	1,140.00
	LABOUR			
	TOWING CHARGE.		150.00	100.00
	TO CHECK WIRING .		100.00	30.00
	TO DISMANTLE & REPLACING FRONT BUMPER SENSOR .		100.00	50.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO CONDUCT WHEEL ALIGNMENT .		100.00	80.00
	TO SPRAY RUST PROOFING .		150.00	120.00
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		300.00	150.00
	TO MOUNT VEHICLE ON CAR O-LINER .	NOT NECESSARY	380.00	-

Report Ref No. CC6/TP18018156/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING , CUT , WELD , STRAIGHTENED REPLACING PARTS INCLUSIVE OF THE REPAIR OF FRONT DOOR O/S , REAR FENDER O/S AND REAR BUMPER. TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			1,800.00	1,600.00
			4,730.00	3,430.00
GRAND TOTAL			33,586.90	12,962.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,300.00

Report Ref No. CC6/TP18018156/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.