1	ASS. REC. BY:		REF: C3/VG	U8018158 /N	laber Isi	occial Instruction:		
	Surveyor :			NMENT (Office			4	
	From (Person):	Yee Per Li	of	EFIL		Date/Time:	18102018	212pm
	Estimated Cost:			Bill to:				
		TP RES / OD R	es/eva/inv/i Smb 51		Insured	: X	E 3027	
,	at Workshop m		SMRT		Tel		5 1982	
	of	Ь		Ind Park El				
	Policy No:				lo: XE302	IT /SL/pl	l	
	Sum Insured:			Exces				
	Make of Veh:					D.O.A.	7052018	
	(Client's Record) CA / REV / Date/Time: 0	REP. / REV 24 5102018 248pm	HRS 'Wpi 1Person Conta	09:10:20 cted: Kuk	ors Khobn	H.O.D. Endo	orsement:	
	Date/Time	Action/Instruction	(V) ES					
		Smg Botou	- X			141		
		XE 3021 -	NA/AWATEUG	1801/hU	D(A:	DUA: 27042016		
	12/10/18@	4.59pm 10	used to 5	tere cin	by en	<i>خا</i> .	-10,1-0,1	

PET.	
ameyor: NAZ	241
ASS	SIGNMENT
	Veh No: SMB 50724 Yr Regn: 1 JUL 2015
From: Date:	Type: M.Car / M.Cycle (Bus) Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Make: ALEXANDER DENNIS ENVIRENCE C.C 8,849
To Inspect Vehicle No:	A/C: (Instr. d / Std / NI / NA
at Workshop m/s	COIOUI MILTI (OL OLIZZI)
of	Sp.Reading 262,390
Insured:	Eng/No: 2 / 210 FEME 2943
	C/No: SFD76CLR5EMT L3943
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No. Excess:	Steering Inorder / Jammed / Leaked / Burnt or
Sum insured.	Brake: (Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	Tyre Size: F: 305/70 R22.5
	R: (1
(Policy Condition)	- LANG / OUTSII / PIR / SUMI /
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	
Bal, or Market Value:	× Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. — mm
GIA / PR Seem.	D.O.A. 17/9/18 U.O.I. 9/10/18
. 2 Val. Ves or No	Survey held at SMRT LVCODLANDS
Lum Sum: % 3 Val.: Yes of No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	0510 0/1
venicle. III 7	The U/C / Chassis frame / Body Structure affected due to collision
Date:Person Contacted:	
Date / Time Action / Instruction	13 CT1 L/S
212119 FLIGHTED LIMPSIM REPAI	IR \$6500.0076 DAYS
(Red \$ 13112.39, 67%)	
RECEIVE	ED 1 4 MAN 2019
3100001	
	Days Of Repair:
Dale/Time, File Pass to? : Preli: Report	Resurvey No. of Trip: Survey Fee: 350
1) 14/3 MM4 : Final Report	Transportation:
Date/Time, File Return to?	Fee: : Site Insp (\$)
2)	: Interview (\$) Pholos
Seri	: Tech. Invs (\$), others
Report Format:	:Weekend (\$
Lump Sum / 1, B.1: (\$ 6500)	TOTAL 350

Catherine Chong (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Monday, 8 October, 2018 2:12 PM

To:

'admin-d@lkkauto.com'

Cc:

survey@jpknights.com

Subject:

OI: XE302T / TP: SMB5072U/LKK / DOA: 17/09/2018

Attachments:

XE302T - SAS.pdf; SMB5072U - SAS.pdf; SMB5072U - ESTIMATE.pdf; SMB5072U -

PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from SMRT AUTOMOTIVE SERVICES PTE LTD,

ADDRESS

: WOODLANDS SMRT DEPOT

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

PERSON TO CONTACT

KOK KHOON @ 9645 1982

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards. Yee Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985 DID : +65 6829 9194 Tel : +65 6829 9199 Fax +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date:	08.10.2018		Sent via Fax	
			Selic via rax	9
Our Reference:	XE 302T/SL/pl		or	
Your Reference:	SMB 5072U			
To:	SMRT AUTOMOTIVE SER	VICES PTE LTD	Email	GohKK2@smrt.com.sg
Pre-Repair Su	rvey (PRS) Acknowledgement			
Vehicle For Inspe				
Insured's Vehicle	XE 302T			
Date Of Accident	17.09.2018			
We acknowledge	receipt of your request for PRS on:	08.10.2018		
			<u>u</u> Normania a b	
the liet bel	th "State Courts Practice Directions	s Amendment No.1 of	2016", do sele	ct an assessor from
the list below an	d indicate your selection in the box	marked *.	3	* LKK
			Ļ	
AIS	Automobile Inspection Services Pte Ltd	I LBS	L.B.S Auto Cons	ultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consu	Itants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services	
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd	
Your reques We acknow ✓ Our Insured	at for inspection does not have your clied to inspection does not have your clied to inspection does not have your clied ledge your interest for direct settlement is driver has not reported the accident to OFFICER-IN-CHARGE - STEVE LIM	nt's GIA report, kindly fo t, we will assess & rever	orward a copy.	
repared by:				
gnature:	De.	Pei Li	6829 919	ciamis@eigo.com.sg
Briatait				FAX: 6829 9247
ssessor use only: ssignment Date: ssignment Time: emarks:		Workshop use onl Assessor attended Date: Time Inspector: Vehicle not availab Kindly acknowledg	workshop on:	ted date and time. resence for the above job .
		Workshop Acknow Note: Our Inspection	ledgement & Sta	mp. t admission to liability basis.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 17 October 2018 4:59 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'; 'Steve Lim'

Cc:

assignments; SUR

Subject:

RE: XE302T / TP: SMB5072U/LKK / DOA: 17/09/2018

Attachments:

CSEGI18018158Nqb.pdf

Dear Steve,

Enclosed herewith preliminary advice of SMB 5072U.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 8 October 2018 2:50 PM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: XE302T / TP: SMB5072U/LKK / DOA: 17/09/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Monday, 8 October, 2018 2:12 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: survey@jpknights.com

Subject: OI: XE302T / TP: SMB5072U/LKK / DOA: 17/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS

: WOODLANDS SMRT DEPOT

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: XE302T/SL/pl

Date: 17th October 2018

Our Ref: CS/EGI18018158/Nqd3

Without Prejudice

The Motor Claims Department ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SMB 5072U .

We thank you for the instruction on _08/10/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/10/2018 at the premises of M/s _____ and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	19,612.39	
Revised Estimate Amount	: S\$	7,220.93	16
"Check" Items Amount	: S \$	1,469.51	
Market Value	: <u>S</u> \$	-	
Salvage Value	: <u>S</u> \$	-	
Nett Value	: <u>S</u> \$		

Description of Damage:

The vehicle sustained damages at the

rear o/s portion.

nearside front offside

Comments/ Present Status:

Damages consistent.

Days of repair: 6 days.

We have NOT authorise repair.

Yours faithfully

Naz

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	18/09/2018 17:09
Date Of Accident	17/09/2018 09:40
Exact Location Of Accident	SENOKO RD - BEF BS47151 (AFT SCANIA S'PORE)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMB5072U
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	ALEXANDER DENNIS
Model	ENVIRO500-8.8 D (A)
Exact Purpose for which vehicle was being used a time of accident	t
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	
Driver	
Name of Driver	NG KWEE TIONG
NRIC No	S1395482H
Date Of Birth	19/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	11/07/2008
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	

NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

~

Insurance Company of Driver's Own Vehicle

÷

NO

NO

NO

20

NO

NO

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING SERVICE 981 ALONG SENOKO ROAD. THERE WERE VEHICLES PARKED ON THE ALONG THE LEFT SIDE OF BOTH DIRECTION OF THE ROAD HENCE MAKING THE LANES IN BOTH DIRECTION NARROW WHERE ONLY ONE VEHICLE COULD PASS AT A TIME. WHILE DRIVING THROUGH THE NARROW LANES, A LORRY (XE302T) WAS SEEN TRYING TO SQUEEZE THROUGH WHILE MY BUS WAS ALREADY HALFWAY THROUGH. I HEARD A SOUND FROM THE REAR OF MY BUS AND REALISED THE LORRY HAD GRAZED THE RIGHT REAR PORTION OF MY BUS. I DID NOT EXCHANGE DETAILS WITH THE THIRD PARTY DRIVER

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

PENDING DOWNLOAD

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE302T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name

ERGO INSURANCE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Date & Time:

\$ 10 S (1) S

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Reporting Centre Personnel's Signature Name: BALQISH


NRIC/FIN No.: S8340325Z

SKETCH PLAN

(R) SMB50724

B XE3027

Senoko Road - Bef BS 47151 (aft Scavia Singapone)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER	ТО	REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signat Date & Time; Driver's Signature

Driver's Signature (If driver is not the policyholder) Date & Time: STE USD A SHEET OF SH

Reporting Centre Personnel's Signature Name: BALQISH

NRIC/FIN No.: S8340325Z



. .

Page 1 of 2

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Date Generated : 07/10/2018
User ID : GohKK2

Accident Reporting Number : 68662672

	Section A - Ac	cident Details	
Desirtation Number	SMB5072U		HARLING THE PARTY OF THE PARTY
Registration Number	BUS/09/18/1024		
Case Reference Number			
Registration Date	01/07/2015		
Company Type	SMRT Buses Ltd		
fake	ALEXANDER DENNIS		
fodel	ENVIRO 500		E 6200
ame of Driver	Ng Kwee Tiong		an Indiana
ype of Accident	Side Swipe		
ccident Date and Time	17/09/2018 9:40 AM		Detail 1
ccident Reported Date and Time	17/09/2018 2:19 PM		The second secon
Surveyor Required?	No		900 (491/3)
urvey by			- 1 W M - 1 =
ehicle is Towed Back?	No		
owed Back Date and Time			
eplacement Vehicle issued?	No		
ob Card Number			ton the same of th
pecial Instruction to ARC, if any	ERGO INSURANCE PT	E LTD	
repared Date and Time	05/10/2018 7:44 AM		
hassis Number			
ileage			
Vark Shop			
epair Completion Date and Time			
ummary of Repair Estimates	Quotation from ARC		
	assument them Area	Adjusted by Survey	or, if applicable
otal Labour Cost	\$3,710.00	Adjusted by Survey	or, if applicable
HIM DESIGNATION AND A			or, if applicable
otal Spray Cost	\$3,710.00	\$0.00	Or, if applicable
otal Spray Cost otal Spare Part Cost	\$3,710.00 \$928.00	\$0.00 \$0.00	Or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost	\$3,710.00 \$928.00 \$10,164.12	\$0.00 \$0.00 \$0.00	Or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST	\$3,710.00 \$928.00 \$10,164.12 \$900.00	\$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Labour Cost otal Spray Cost otal Sprae Part Cost otal Other Cost OTAL COST ump Sum Total umpber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 8:0 Kok Khoon Goh 06/10/2018 8:18 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 \$50 Kok Khoon Goh	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost DTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 8-0 Kok Khoon Goh 06/10/2018 8:18 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 \$0 Kok Khoon Goh 06/10/2018 8:18 AM	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	or, if applicable
otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 \$0 Kok Khoon Goh 06/10/2018 8:18 AM	S0 00 Substituting the state of th	or, if applicable
otal Spray Cost otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date gnature	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 8-0 Kok Khoon Goh 06/10/2018 8:18 AM	SO 00	
otal Spray Cost otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature uotation Number uotation Date voice Amount	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 \$0 Kok Khoon Goh 06/10/2018 8:18 AM	So 00	
otal Spray Cost otal Spray Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature uotation Number uotation Date voice Amount	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 8-0 Kok Khoon Goh 06/10/2018 8:18 AM	SO 00	
otal Spray Cost otal Spare Part Cost otal Spare Part Cost otal Other Cost OTAL COST ump Sum Total umber of Repair Days repared / Adjusted By RC / Surveyor Sign Off Date ignature uotation Number uotation Date voice Amount	\$3,710.00 \$928.00 \$10,164.12 \$900.00 \$15,702.12 \$15,700.00 \$0 Kok Khoon Goh 06/10/2018 8:18 AM	So 00	



Part 2 - Spray Painting & Panel Beating Related Works

Total Labour

SMRT Accident Vehicle Repair Estimates

\$3,710.00

SMRT Automotive Service Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number | 68662672

Date Generated: 07/10/2018

User ID

: GohKK2

Job Scope				Quotation fr	rom ARC	Adjusted by Surveyor, if applicable			
PROVIDE LABOREPAIR ITEMS		AL TO PUTTY A	ND RESPRAY ABOVE	\$928.00		\$ 700			
Total Spray Pa	inting & Panel Bea	ating		\$928.00					
Part 3 - Other	Costs - Acciden	t and Accident	Repair Related Expens	se					24-54
Job Scope				Quotation fr	om ARC	-		Adjusted by Surveyo	r, if applicable
TO ALIGN CHA	SSIS	1 - 1		\$400.00				\$200	
1.00.0.100.00.100.00.100.00	ST-PROOFING ON	AFFECTED ARE	EA .	\$400.00				\$150	
	RING AND SYSTEM		7,01	\$100.00				\$ 30	
Total Other Costs				\$900.00				4 3	
Part 4 - Spare	Parts / Material	Usage						1 3 4 1 1	
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			REAR PILLAR RH	1.00	\$1,500.00	10.00	\$1,350.00	Replace	RT
			REAR EXTERIOR DOME	1.00	\$8,605.23	10.00	\$7,744.71	Replace	X
6011069	VE	31155514	POD, TAIL LIGHT: R/H, FOR ADL E500 DD BUS	1.00	\$1,703.25	10.00	\$1,532.92	Replace	/CRA
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	/ NE
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	/NBC
4006313	CONSUMABLE	SIKA® Primer- 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	-NEC
5011116	GLASS	7210007N100	GLASS:MAIN BODY,4MM,FOR ADL E500 DD BUS	1.00	\$251.12	10.00	\$226.01	Replace	/ceA
5011099	VE	7612002L21	LIGHT, REVERSE LED, F OR ADL E500 DD BUS	1.00	\$861.86	10.00	\$775.67	Replace	?
6011100	VE	7612001L21	LAMP:LED,STOP-TAIL- FLASHER,ADL E500 DD	1.00	\$362.39	10.00	\$326,15	Replace	2
3011101	VE	7611003L21	LAMP:LED.LH,STOP- TAIL-INDICATOR,ADL E500	1.00	\$408.54	10.00	\$367.69	Replace	?
Total					\$13,889.39		\$12,705,15		

NAZ LKIL LYMP SWM 6 DAYS CHECK ITEM PHOTOS AFTER REPAIR PHOTOS.

Stock Number Part Name

Portion

List Price \$

Quantity

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis

Surveyor Check

- · No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Discount (%) Final Price (\$) ARC Check

Total



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated : 12/03/2019


User ID


: CatherineLee

	Section A - Accident	Details					
Registration Number	SMB5072U						
Case Reference Number	BUS/09/18/1024						
Registration Date	1/7/2015						
Company Type	SMRT Buses Ltd						
Make	ALEXANDER DENNIS						
Model	ENVIRO 500						
Name of Driver	Ng Kwee Tiong	Ng Kwee Tiong					
Type of Accident	Side Swipe						
Accident Date and Time	17/9/2018 9:40 AM						
Accident Reported Date and Time	17/9/2018 2:19 PM						
Is Surveyor Required?	Yes						
Survey by							
Vehicle is Towed Back?	No						
Towed Back Date and Time							
Replacement Vehicle issued?	No						
Job Card Number	24098396						
Special Instruction to ARC,if any	ERGO INSURANCE PTE LTD						
Prepared Date and Time	5/10/2018 7:44 AM						
Chassis Number	SFD76CLR5EMTL3943						
Mileage							
Work Shop							
Repair Completion Date and Time							
CONTRACTOR OF THE PARTY OF THE	Section B - Summary of Reg	pair Estimates					
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$3,710.00	\$2,650.00					
Total Spray Cost	\$928.00	\$700.00					
Total Spare Part Cost	\$10,164.12	\$2,792.74					
Total Other Cost	\$900.00	\$380.00					
TOTAL COST	\$15,702.12	\$6,522.74					
Lumo Sum Total	\$15,700.00	\$6.500.00					

Section B - Summary of Repair Estimates							
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$3,710.00	\$2,650.00					
Total Spray Cost	\$928.00	\$700.00					
Total Spare Part Cost	\$10,164.12	\$2,792.74					
Total Other Cost	\$900.00	\$380.00					
TOTAL COST	\$15,702.12	\$6,522.74					
Lump Sum Total	\$15,700.00	\$6,500.00					
Number of Repair Days	8.0	6.0					
Prepared / Adjusted By	Kok Khoon Goh	Naz					
ARC / Surveyor Sign Off Date	06/10/2018 8:18 AM	11/10/2018 11:25 AM					
Signature	*	M					
Remarks		LUMP SUM REPAIR. 6 DAYS. CHECKED ITEMS PHOTOS. AFTER REPAIR PHOTOS.					

Section C - Quotation and Accident Invoice Details						
Quotation Number	Invoice Number					
Quotation Date	Invoice Date					
Invoice Amount	Prepared Date					









SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number; 68662623

Accident Reporting Number : 68662672

Date Generated: 12/03/2019

: CatherineLee

10000		HE TYCH	Section	on D - Deta	ils of Repair E	stimates	COL TUR			
Part 1 - Labou	r Works	Topic to be								
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable		
	INSTALL ALL ABO	VE ITEMS AND	REPAIR OTHERS	\$3,710.00				\$2,650.00		
Total Labour	ECTED AREAS.			\$3,710.00				\$2,650.00		
Part 2 - Spray	Painting & Pane	el Beating Rela	ted Works	Part San	To Destrict to	15 P 16 P				
Job Scope				Quotation fo	rom ARC	SUMMEN		Adjusted by Surveyo	r, if applicable	
		AL TO PUTTY A	ND RESPRAY ABOVE	\$928.00				\$700.00		
REPAIR ITEMS Total Spray Pai	inting & Panel Be	ating		\$928.00				\$700.00		
			Repair Related Expens	e				See to the second	A PURIETY PAR	
Job Scope				Quotation for	rom ARC	18/ TEMP		Adjusted by Surveyo	r, if applicable	
TO APPLY RUST-PROOFING ON AFFECTED AREA				\$400.00				\$150.00		
TO CHECK WIRING AND SYSTEM FUNCTION TO ALIGN CHASSIS				\$100.00 \$400.00				\$30.00 \$200.00		
Part 4 - Spare	Parts / Material	Usage	REE WAS ALL PROP	THE YEAR						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (5)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	Replace N	
6011101	VE	7611003L21	LAMP:LED,LH,STOP- TAIL-INDICATOR,ADL E500	0.00	\$408.54	0.00	\$0.00	Replace	Check X 5 UL	
			REAR PILLAR RH	1.00	\$1,500.00	10.00	\$1,350.00	Replace	Replace / B T	
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace /NEC	
6011099	VE	7612002L21	LIGHT, REVERSE: LED, F OR ADL E500 DD BUS	0.00	\$861.86	0.00	\$0.00	Replace	Check XSVC	
4006313	CONSUMABLE	SIKA® Primer- 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace - NYEL	
6011100	VE	7612001L21	LAMP:LED,STOP-TAIL- FLASHER,ADL E500 DD	0.00	\$362.39	0.00	\$0.00	Replace	Check X 5UL	
			REAR EXTERIOR DOME	1.00	\$8,605.23	100.00	\$0.00	Replace	Repair X R	
6011116	GLASS	7210007N100	GLASS:MAIN BODY,4MM,FOR ADL E500 DD BUS	1.00	\$251.12	10.00	\$226.01	Replace	Replace / CR K	
6011069	VE	31155514	POD,TAIL LIGHT:R/H,FOR ADL E500 DD BUS	1.00	\$1,703.25	10.00	\$1,532.92	Replace	Replace / CLK	
Total					\$13,889.39		\$3,490.93			
Added Spare	Parts / Material	Usage After Su	rveyor Signed off			THE LET	Senders.			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
			THE PART OF THE PARTY.		E STATE OF THE PARTY OF THE PAR	10 10 10 10 10 10 10 10 10 10 10 10 10 1	The second second			

PARTS LESS 20% \$2792.74 198612 \$2.650.00 SIRMY \$ 700

19612.39

OTHER COSTS

\$ 380

Page 2 of 2

TOTAL

\$6522.74

LISTOTAL \$ 6,500 /6 DMS.

CONFIRMED LIMPSOM REPAIR \$6,500 /6 DAYS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref:

CS/EGI18018158/Nqbe2

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE

Date: 18-03-2019

	01 SUNTEC TOW SAPORE 038985	ER FIVE	Date: 18-03-2019			
01140	37 II OTTE 000000		Code: EGI			
1.	Transaction of	Policy Particula	ars :- THIRD PARTY CLA	IM		
	Insured Veh.	XE 302T	Veh. Inspected	SMB 5072U		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	XE302T/SL/pl	Excess (\$)	0.00		
	Assign From	YEE PEI LI	Assign Date	08/10/2018		
2.	Switz V	Vehicle Pa	articulars & Condition			
	Make & Model	ALEXANDER DENNIS ENVIRO500	c.c	8849		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	SFD76CLR5EMTL3943	Colour	MULTI COLOUR		
	Odometer	263390	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	FAIR				
3.	e a riske i iz	Con	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	305/70 R22.5	FIRENZA	7 mm		
	L/H Front Tyre	305/70 R22.5	FIRENZA	7 mm		
	R/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	7/7 mm		
	L/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	7/7 mm		
4.		Descri	ption of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.						
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/09/2018	Inspection Date	09/10/2018		
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD					
		60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.	Remarks					
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. CE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estima	ate Days of Repair	nershing the same		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Day	/S		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 5072U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR PILLAR RH	BENT	1,500.00	1,500.00
1	GLASS : MAIN BODY, 4MM, FOR ADL E500 DD BUS	CRACKED	251.12	251.12
1	POD, TAIL LIGHT : R/H, FOR ADL E500 DD BUS	CRACKED	1,703.25	1,703.25
1	LAMP : LED, LH, STOP-TAIL-INDICATOR, ADL E500	SERVICEABLE	408.54	
1	LIGHT, REVERSE : LED, FOR ADL E500 DD BUS	SERVICEABLE	861.86	-
1	LAMP : LED, STOP-TAIL-FLASHER, ADL E500 DD	SERVICEABLE	362.39	-
1	REAR EXTERIOR DOME	TO REPAIR SEE LABOUR	8,605.23	-
	LESS 10% DISCOUNT		-	-345.44
			13,692.39	3,108.93
	SPECIAL NETT ITEMS			
6	ADHESIVE : DIRECT GLAZING @\$37.00 (SN)	NECESSARY	222.00	222.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
			382.00	382.00
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR EXTERIOR DOME.		3,710.00	2,650.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		928.00	700.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		400.00	150.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		100.00	30.00
	TO ALIGN CHASSIS.		400.00	200.00
			-	-
			5,538.00	3,730.00
	GRAND TOTAL		19,612.39	7,220.93

RECOMMENDED COST OF LUMP SUM REPAIRS	6,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EGI18018158/Nqbe2





Report Ref No. CS/EGI18018158/Nqbe2

M

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.