

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6581 P

1 pc	Rear bumper <i>X Rep</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X SC</i>	\$ 206.00
1 pc	Rear bumper side bracket o/s <i>X SC</i>	\$ 29.00
1 pc	Rear bumper reflector O/s <i>X SC</i>	\$ 46.00
		<hr/>
		\$ 977.00
Less 10%		\$ 97.70
		<hr/>
		\$ 879.30

S/NETT

1 set	Rear bumper clips <i>X</i>	\$ 48.00
Sundry		\$ 50.00 <i>X 27</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 <i>X 27</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>X 27</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$ 550.00 <i>100</i>
To putty and spray painting on rear bumper		\$ 200.00 <i>180</i>
		<hr/>
		\$ 2,027.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalua 10/10/18

9/10/18 1000 hrs

2 Dps

4/5

After Repair photo

all 16/10/18
PP \$280/2018
11