

23/03/2012

ASS. REC. BY:

REF:

CS/ALL18018163 / As bnz

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

Mohd. Muzni

From (Person):

Syazirinda

of

ALL

Date/Time:

08-10-2018 1:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHU 9873U

Insured:

STV 3438S

at Workshop m/s

Reliable Carz

Tel:

8166 9757

of

8 Kaki Bukit Ave 4 #05-50

Policy No:

Claim No:

6618043512561003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

08/10/2018 2:19pm

Person Contacted:

Jason

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHU 9873U - NO/INC/18018079/R3

DQA: 05-10-2018

STV 3438S - NA/ATA/18018202/H4

DQA: 05-10-2018

19/11/18

Confirmed 21s \$1,400/- @ 4 days with Adrian

(\$3,343.39 Red - 71%)

REF: **PAH****ASSIGNMENT**From: _____ Date: **10-10-2018**

Estimated Cost: _____

OD / **(P)** / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SLU 9873U**at Workshop m/s: **Reliable Carz**of: **8 Kuki Bukit Ave 4 #05-50**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SG49873U** Yr Regn: **2007 May**Type: **(M) Can** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Uva** c.c **1497**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **134533** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MROS3HY9305007241**Gen. Cond: **(Good)** Fair / Poor / BurntSteering: **(Inorder)** Jammed / Leaked / Burnt orBrake: **(Inorder)** Jammed / Leaked / Burnt orModi: **(Nil)** S/Rim / STD A/Rim orTyre Size: F: **195/65R15**R: **195/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Newton**

Front

Rear

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. _____ D.O.I. **10/10/18**Survey held at **Reliable**Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or**Front m/s.**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

19/11/181) **Typist**

Date/Time, File Return to?

2) _____

☐

Preli. Report

☒

Final Report

Days Of Repair: **4**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I: (\$) **1,400/- 415****250
20****270**

- Pre repair inspection request - SGU9873U VS SJV3438S (OI) DOA 05/10/2018

From: Azlan, Syazairdina
 To: admin-a@kkauto.com, assignments@kkauto.com
 Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi
 Sent: Monday, 8 October, 2018 1:44:20 PM
 Attachments: 20181005175606.pdf; SGU9873U VS SJV3438S.pdf

Hi,

Please refer to the enclosed request from VISION LAW LLC.

Claim no : 6618043512SG003
 Case Owner : KAI JYE WUI
 If you have any queries/concerns, please let us know.
 Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,
 Syaza Irdina Azlan
 AIG
 Express Claims Adjuster II
 SG Claims Operations | AIG Shared Services

From: Azlan, Syazairdina
 Sent: Monday, October 08, 2018 9:03 AM
 To: jactan@visionlawllc.com
 Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi
 Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJV3438S AND SGU9873U ON 05/10/2018

Without Prejudice

Your Reference : SGU9873U
 Our Reference : 6618043512SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Fong Soon Yee | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon Han Xin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
 AIG
 Express Claims Adjuster II
 SG Claims Operations | AIG Shared Services

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]
 Sent: Friday, October 05, 2018 5:53 PM

To: Azlan, Syazairdina

Subject: RE: - PRE-REPAIR INSPECTION - SGU 9873 U ON 05/10/2018

Dear Azlan,

Enclosed herewith copy of the LTA search for your attention. Please let us hear from you.

Regards

Jacqueline Tan
Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]

Sent: Friday, 5 October, 2018 4:38 PM

To: jactan@visionlawllc.com

Cc: ct-admin@visionlawllc.com

Subject: RE: - PRE-REPAIR INSPECTION - SGU 9873 U ON 05/10/2018



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือข้อความที่ปลอดภัยซึ่งควรเปิดไฟล์แนบเพื่ออ่านได้โปรดอย่าเผยแพร่

이것은안전하고암호화된메시지입니다.그것을읽으려면첨부와
일을업니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-10-12 16:38 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual(s) named. If you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com
To: jactan@visionlawllc.com
Cc: ct-admin@visionlawllc.com

Subject: RE: AIGENCRYPT - PRE-REPAIR INSPECTION - SGU 9873 U ON 05/10/2018

Date: Fri, 5 Oct 2018 08:38:10 +0000

Hi,

Kindly confirm vehicle number of our insured.



Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Azlan, Syazairdina

Sent: Friday, October 05, 2018 3:57 PM

To: ct-admin@visionlawllc.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - SGU 9873 U ON 05/10/2018

Hi,

Kindly confirm vehicle number of our insured.



Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Abu Kassim, Noor Mariesa

Sent: Friday, October 05, 2018 3:30 PM

To: Azlan, Syazairdina

Subject: FW: Scan Image

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: Friday, October 05, 2018 3:24 PM

To: Abu Kassim, Noor Mariesa; reliablecarzpl@gmail.com

Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-ISHEN
PAUL YAP TAI SAN
ANJALLI DO MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNRUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEE LEE

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ **HEAD OFFICE**
TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com
BRANCH
TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.R28.108282.18
Your Ref: 6618043512SG003

8 October 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 069046
Attention: Motor Claims Department

BY FAX: 6415 3727

syazairdina.azlan@aig.com.

Dear Sirs,

ACCIDENT INVOLVING SGU 9873 U & SJV 9438 S ON 05 OCTOBER 2018 ALONG MACKENZIE ROAD AT ABOUT 1000 HOURS

We refer to your letter dated 8 October 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Mr Adrian Ling from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Reliable Carz Pte Ltd
8 Kaki Bukit Avenue 4
#05-50 Premier @Kaki Bukit
Singapore 415875
Contact Person: Jason 8166-9797

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SGU 9873 U - By Email: reliablecarzpl@gmail.com

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Vehicle No.: SGU 9873U

Model: TOYOTA VIOS Shirley

REF: RC3118

QTY DESCRIPTION

List Items:

- 1 Front bumper *rehab*
- 2 Front bumper retainer @ 64.07 *per LH*
- 1 Front bumper lower grille *new*
- 1 Head lamp LH *crushed*
- 1 Front fender LH *Repair*
- 1 Front fender liner LH *new*
- 1 Support panel *Repair*
- 1 Front fog lamp LH *new*
- 1 Front fog lamp cover LH *new*
- 1 Front bumper reinforcement *Best*
- 1 Front grille assy *Not in*
- 1 Front emblem *new*

AMOUNT (\$\$)

479.19 ✓
128.14 *64.07*
79.29 *X*
440.26 ✓
301.15 *X*
156.87 *X*
812.35 ✓
231.97 *X*
70.71 *X*
336.20 ✓
350.34 *X*
42.77 ✓

1362.49

1021.86

25
Less 20% (685.85)
Subtotal 2743.39

Special Nett Items:

- 1 Front bumper clip (set) *new*
- 1 Front fender liner clip (set) *new*

60

60.00 *30*
60.00 *30*

Subtotal 120.00

Labour Charges:

- To check wiring system
- To knocking, jacking and repair on above parts
- To spray painting on affected area

730

80.00 *30*
800.00 *300*
1000.00 *400*

Subtotal 1880.00

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged parts clearly

• Parts prices are subject to confirmation

• Third party survey is on "without Prejudice" basis

• No illegal modification is allowed

• Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

4,743.39

Total: 1811.86

2/5 1 HK

Adrian Lim

2/5 10/10/18

04 pages

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18018163/ASBN2

Date: 21/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994658
 Claimant Vehicle No: SGU9873U Insured Vehicle No: SJV3438S
 Date of Loss: 05/10/2018 Nature of Claim: TP Claim No: 6618043512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGU9873U
 Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX562675
 Reg. Date: 30/05/2007 (Man. Year: 2007) Chassis No: MR053HY9305007241
 Colour: Black Odometer: 134533 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Neuton 6 mm Rear Left Side: Neuton 6 mm
 Front Right Side: Neuton 6 mm Rear Right Side: Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 2,863.39 | 1,081.87 | 1,781.52 | 62.22 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,880.00 | 730.00 | 1,150.00 | 61.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,743.39 | 1,811.87 | 2,931.52 | 61.80 |
| Approved Total (Overridden) (S\$) | | 1,400.00 | | |
| Nett Amount (S\$) | 4,743.39 | 1,400.00 | 3,343.39 | 70.49 |

INSPECTION

Date of Assignment: 08/10/2018
 Date Inspected: 10/10/2018 Inspected At: Reliable Craaz Pte Ltd (HQ)
 8 KAKI BUKIT AVENUE 4, #05-50
 Singapore 4157875
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|------------|------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 479.19 FL | *479.19 FL |
| 2 | 1 | | *FRONT BUMPER RETAINER | N/s Necessary | 128.14 FL | *64.07 FL |
| 3 | 1 | | *FRONT BUMPER LOWER GRILLE | Not Necessary | 79.29 FL | *- FL |
| 4 | 1 | | *HEAD LAMP LH | Cracked | 440.26 FL | *440.26 FL |
| 5 | 1 | | *FRONT FENDER LH | Repair | 301.15 FL | *- FL |
| 6 | 1 | | *FRONT FENDER LINER LH | Not Necessary | 156.87 FL | *- FL |
| 7 | 1 | | *SUPPORT PANEL | Repair | 812.35 FL | *- FL |
| 8 | 1 | | *FRONT FOG LAMP LH | Not Necessary | 231.97 FL | *- FL |
| 9 | 1 | | *FRONT FOG LAMP COVER LH | Not Necessary | 70.71 FL | *- FL |
| 10 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 336.20 FL | *336.20 FL |
| 11 | 1 | | *FRONT GRILLE ASSY | Not Necessary | 350.34 FL | *- FL |
| 12 | 1 | | *FRONT EMBLEM | Necessary | 42.77 FL | *42.77 FL |
| 13 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 60.00 FS | *30.00 FS |
| 14 | 1 | | *SET FRONT FENDER LINER CLIP | Necessary | 60.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 3,549.24 | 1,422.49 |
| - List Item Discount on L Items 20.00/25.00% (\$\$) | 685.85 | 340.62 |
| Total Parts (\$\$) | 2,863.39 | 1,081.87 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO CHECK WIRING SYSTEM | New | 80.00 | 30.00 |
| 2 | TO KNOCKING,JACKING AND REPAIR ON ABOVE PARTS | New | 800.00 | 300.00 |
| 3 | TO SPRAY PAINTING ON AFFECTED AREA | New | 1,000.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,880.00 | 730.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >