



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631-1188

ESTIMATE

Account Detail	Account No	Customer Detail
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	Mr Ang Kee Teck Vincent (Hong Q 175A Yung Kuang Road #18-09 Singapore 611175 Mobile: 83998213
	Document No 0	
	Document Date 09/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	26/10/2017	SLT3295Z	20845	17111	7DS/SLT3295Z/01101
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W00J008152	2ZROA26913	60	Sam San Joi	03/10/2018 14.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLJ269Y ACC DATE:01/10/2018 DRIVE IN:03/10/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				169.50
3	B	BP-ECU TO RESET ECU AND REPROGRAMME				134.00
4	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST TO REPAIR				339.00
5	S	BP-SUBLET REPLACE REAR BUMPER STRAIGHTEN & ALIGN REAR RH ACCIDENT AFFECTED AREAS				2034.00
6	S	BP-SUBLET RESPRAY JOB ON REAR RH ACCIDENT AFFECTED AREAS				1668.00
7	1	T52159-68907 REAR BUMPER COVER,	1.00	581.20		581.20
8	2	T52575-68020 R/R SIDE BPR RETAINER	1.00	45.10		45.10
9	3	T52155-68030 R/RR BUMPER SUPPORT	1.00	95.30		95.30
10	4	T58307-68031 REAR LOWER FLR PANEL,	1.00	526.40		526.40
11	5	T52181-68010 ARM, RR BUMPER	1.00	52.80		52.80
12	6	SPZ061-12010 22 3RO SENSOR	1.00	151.60		151.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle 	Parts Labour Materials Lubrication/Fluid Others	5,826.90
		1,452.40 164.00 4,210.50 0.00 0.00	GST 7.00% Less 407.80 0.00
			Amount Due 6,234.70

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SLT3295Z

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company



Borneo Moto