



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLW4092U

Date of Accident : 04 October 2018

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

*Not Authorised
to be paid before survey
2 day
8/10/18*

Mr Tan Chuan Heong

Date : 05 October 2018

Estimate To Repair EV200P - B.M.W 530I SE AUTO

Chassis No : WBAJA520X0G885579

*LKK - Marcus
08/10/18 @ 1200hr*

S/No	Quantity	Description	Amount
		NETT ITEMS	
01	1 pc	rear bumper	\$ 1,411.30
02	2 ps	rear bumper parking sensor @ \$359.60	\$ 719.20
03	1 pc	rear bumper carrier	\$ 793.55
04	1 pc	rear bumper inner top frame	\$ 70.65
05	1 pc	rear bumper energy absorber foam	\$ 86.90
06	1 pc	rear bumper lower splashshield cover	\$ 96.90
07	1 pc	exhaust box heat shield	\$ 176.50
08	2 ps	rear bumper side retainers @ \$77.55	\$ 155.10
			\$ 3,510.10
		Less 10 %	\$ 351.01
			\$ 3,159.09
		LABOUR & MISC. CHARGES	
01		To reinstall of rear bumper parking sensor and simulation test.	\$ 150.00
02		To check electrical lighting concerned.	\$ 50.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00
04		Putty and spray painting of the affected portion.	\$ 550.00
			\$ 1,300.00
		Total	\$ 4,459.09

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: