

INS. CASE OWNER:

CC & EQ11801 8168, 4/10/18

LKK:
IDAC:

Surveyor:

MARLUS

DOI:

ASSIGNMENT

8/10/18

Date / Time:

8/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 5607L

Name of Insured:

Sheng Qun Transport & Construction PLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

7/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: KETVEL RANACHATHIRAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

OMCFHE18-000111

Make / Model:

ISUZU

Place of Accident:

TPE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLS 1371E



INSRS:

WSP:

Tel:

Liability:

RMKS:

progressive



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

7/10/18
TH

SLS 1371E

XD 5607L

H2R

HEAD TO REAR.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

25.2.19 JOY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

21.2.19

Confirm with:

DENEZA

Email

Call

Final Liability:

%

100

(A free / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

4,387

Loss of Rental (LOR):

SS

700

(7 days)

100

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

36.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

5,123.45

Global Sum SS:

5,120.74

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5,120.74

Name 1:

PROGRESSIVE AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
12/6/19pk
h/6/18
bw

DATE OF WORK

REF:

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res: Yes or No

Lum Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn: 9.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

L/Bal:

D.O.A

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3 - OOA

4

5

6 / S

7 / S

8 - DOIM

9 T

10 W

11 T

40ms

R(\$3,616.32 / 47%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

Date/Time: File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + R5.00

Photo

Other

Total

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ118018168/Uub3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 08-10-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5607L	Veh. Inspected	SLS 1371E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/10/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/10/2018	Inspection Date	08/10/2018
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 488933 TEL : (665) 62563561 FAX : (665) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118018168/Uub3

Date: 16.10.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLS1371E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.10.2018 at the premises of M/s Progressive Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	7,716.32
Revised Estimate Amount	: S\$	4,100.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Net Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

Not Advised
1/5 # 4100
Hdy.
Whysb. After 10p-

M/S : EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

Estimate No: EST0000716
Date: 06 Oct 2018
Policy No: DMPPHQ18-006169
Veh Reg No: SLS1371E
Make/Model: HYUNDAI ELANTRA
Chassis No: KMHD841CMJU542771
Engine No: G4FGHU778554
Reg. Date: 09-09-2017

TEL: 6223 9433 FAX: 6224 3903
ATTN: Motor Claim Department
Your Ref No: SLS1371E
Claim Type: Third Party
Accident Date: 03-10-2018
TP Veh Reg No: XD5607L

Estimate Repair Cost For Vehicle No :SLS1371E

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
SLS1371E HYUNDAI ELANTRA				
List Price				
1 Rear Boot Lid 1048	body 20	1 PC	1582.00 ✓	
2 Rear Boot Lock	201	1 PC	139.00 ✓	
3 Rear Boot Lock Catch	17	1 PC	36.00 X	
4 Rear Boot Rubber	201	1 PC	129.00 ✓	
5 Rear Boot Emblem (Elantra)	201	1 PC	48.00 ✓	
6 Rear Boot Emblem (S)	201	1 PC	20.00 ✓	
7 Rear Boot Centre Logo	201	1 PC	39.00 ✓	
8 Rear Boot Hinge	17	2 PC	222.00 X	
9 Rear Boot Reflector Lamp	201	2 PC	662.00 ✓	
10 Rear Boot Lock Handle Sensor	17	1 PC	180.00 X	
11 Rear Boot Inner Cover Board	17	1 PC	189.00 X	
12 Rear Boot Inner Cover Board Clipse	17	8 PC	44.00 X	
13 Rear Tail Lamp	0/5 201	2 PC	764.00 12L	
14 Rear Tail Lamp Clipse	17	2 PC	16.00 X	
15 Rear End Panel	20	1 PC	491.00 ✓	
16 Rear End Panel Top Garnish	17	1 PC	69.80 X	
17 Rear End Panel Top Garnish Clipse	17	3 PC	16.50 X	
18 Rear Spare Tyre Cover Board	17	1 PC	311.00 X	
19 Rear Bumper	20	1 PC	459.50 ✓	
20 Rear Bumper Reinforcement	201	1 PC	329.50 ✓	
21 Rear Bumper Side Retainer	201	2 PC	82.00 ✓	
22 Rear Bumper Lower Pad	201/201	1 PC	280.10 ✓	
23 Rear Bumper Clipse	201	10 PC	55.00 ✓	
24 Rear Number Plate Lamp	17	2 PC	56.00 X	4164.1
			6,220.40	
		Less 20%	1,244.08	4,976.32
Special Net				
25 Rear Number Plate	201	1 PC	50.00 40	
26 Rear Bumper Sensor	201	1 PC	300.00 200	
			350.00	350.00

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

TEL: 6223 9433 FAX: 6224 3903
ATTN: Motor Claim Department
Your Ref No: SLS1371E
Claim Type: Third Party
Accident Date: 03-10-2018
TP Veh Reg No: XD5607L

Estimate No: EST0000716
Date: 06 Oct 2018
Policy No: DMPPHQ18-006169
Veh Reg No: SLS1371E
Make/Model: HYUNDAI ELANTRA
Chassis No: KMHD841CMJU542771
Engine No: G4FGHU778554
Reg. Date: 09-09-2017

Estimate Repair Cost For Vehicle No :SLS1371E

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Labour				
27 Panel Beating	1,200.000	1 PC	1,200.00	600
28 Check Wiring	80.0000	1 PC	80.00	20
29 Rust Proofing	80.0000	1 PC	80.00	60
30 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
31 Spray Painting	950.0000	1 PC	950.00	850
			2,390.00	2,390.00
			Total	SS 7,716.32

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SIXTEEN AND CENTS THIRTY TWO ONLY

For PROGRESSIVE AUTO PTE LTD

Progressive Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

Tel: 68444620 Fax: 68444625

AUTHORISED SIGNATURE

17.10.18

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[* > Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 6771W

Vehicle Details

Vehicle No.: SLS1371E
Vehicle to be Exported: No
Intended Deregistration Date: 04 Oct 2018
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Blue
Manufacturing Year: 2017
Engine No.: G4FGHU778554
Chassis No.: KMHDB41CMJU542771
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$12,674.00
Original Registration Date: 09 Sep 2017
First Registration Date: 09 Sep 2017
Transfer Count: 0
Actual ARF Paid: \$12,674.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Sep 2027
PARF Rebate Amount: \$9,505.00

Intended COE Rebate Details

COE Expiry Date: 08 Sep 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,900.00
COE Rebate Amount: \$38,300.00
Total Rebate Amount: \$47,805.00

The information contained herein is correct as at 04 Oct 2018

OK

Nivitha (LKK Auto)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 5 October 2018 2:54 PM
To: assignments
Cc: sur@lkkauto.com
Subject: FW: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

2:56pm @ 5/10/18
person @ Mandy
vehicle in

Dear LKK,

Kindly assist with PRS and DS for this matter.

Thank you.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t.

From: Progressive Auto [mailto:claims@progressiveauto.sg]
Sent: Friday, October 5, 2018 2:44 PM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Subject: Re: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear Justin,

Kindly be informed that we choose No.6 LKK Auto Consultants Pte Ltd.

Thank you.

Best Regards,
Mandy Sin
Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6
AutoBay #02-48/50
Singapore 417883
Tel: 6844 4620

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Fri, Oct 5, 2018 at 2:18 PM Justin Wong <justin.wong@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Mandy,

For future pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We refer to your email on PRI dated today.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd	4) Priority Services

L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070 Contact Person: Jasmine
11) Infiniti Appraisal Service Tel: 9009 9001 , 96684818 Fax: 6458 7432 Contact Person: Cedric / Edward	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Progressive Auto [<mailto:claims@progressiveauto.sg>]

Sent: Friday, October 5, 2018 1:42 PM

To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>

Cc: Janet Tan <janet.tan@eqinsurance.com.sg>

Subject: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear Officer-In-Charge,

Good day.

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 03/10/18 at about 0805 hours along ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI involving our client's SLS 1371 E and XD 5607 L driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop :Progressive Auto Pte Ltd

Address: No.1 Kaki Bukit Ave 6
AutoBay #02-48/50
Singapore 417883

Telephone no. : 6844 4620

Best Regards,
Mandy Sin

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email

including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

Total Control Panel

[Login](#)

To: janet.tan@eqinsurance.com.sg

[Remove this sender from my allow list](#)

From: claims@progressiveauto.sg

You received this message because the sender is on your allow list.

Shu Pei (LKKAuto)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Wednesday, 17 October 2018 10:26 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Thin Thin (LKKAuto)
Subject: RE: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR
Attachments: OI GIA - XD5607L.PDF

Dear Shu Pei,

Please find OI's GIA report.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, October 17, 2018 9:01 AM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

WITHOUT PREJUDICE

Dear Justin,

We refer to the above matter.

We have inspected TP vehicle SLS 1371E at M/s Progressive Auto Pte Ltd on a WP basis and TP repairer purposed for a direct settlement.

Enclosed for your perusal is:
- TP's GIA report

- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeij@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 5 October 2018 2:59 PM

To: 'Justin Wong' <justin.wong@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Wong [<mailto:justin.wong@eqinsurance.com.sg>]

Sent: Friday, 5 October 2018 2:54 PM

To: assignments <assignments@lkkauto.com>

Cc: sur@lkkauto.com

Subject: FW: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear LKK,

Kindly assist with PRS and DS for this matter.

Thank you.

Regards,

Justin Wong

Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Progressive Auto [<mailto:claims@progressiveauto.sg>]

Sent: Friday, October 5, 2018 2:44 PM

To: Justin Wong <justin.wong@eqinsurance.com.sg>

Subject: Re: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear Justin,

Kindly be informed that we choose No.6 LKK Auto Consultants Pte Ltd.

Thank you.

Best Regards,

Mandy Sin

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax: 6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email

including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Fri, Oct 5, 2018 at 2:18 PM Justin Wong <justin.wong@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Mandy,

For future pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We refer to your email on PRI dated today.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561

Fax: 67480361 Contact Person: Elson/Elgene	Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070 Contact Person: Jasmine
11) Infiniti Appraisal Service Tel: 9009 9001 , 96684818 Fax: 6458 7432 Contact Person: Cedric / Edward	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Progressive Auto [<mailto:claims@progressiveauto.sg>]

Sent: Friday, October 5, 2018 1:42 PM

To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>

Cc: Janet Tan <janet.tan@eqinsurance.com.sg>

Subject: ACCIDENT INVOLVING SLS 1371 E & XD 5607 L ON 03/10/18 ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI AT ABOUT 0805 HOUR

Dear Officer-In-Charge,

Good day,

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 03/10/18 at about 0805 hours along ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI involving our client's SLS 1371 E and XD 5607 L driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop :Progressive Auto Pte Ltd

Address: No.1 Kaki Bukit Ave 6
AutoBay #02-48/50
Singapore 417883

Telephone no. : 6844 4620

Best Regards,
Mandy Sin

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant

or guaran'ee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

Total Control Panel

[Login](#)

To: janet.tan@eqinsurance.com.sg

[Remove](#) this sender from my allow list

From: claims@progressiveauto.sg

You received this message because the sender is on your allow list.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Progressive Auto Pte Ltd
Business Reg. No. 200712509E
GST Reg. No. 200712509E
Tel: 6844 4620 Fax: 6844 4625
Email: claims@progressiveauto.sg

Date : 25/10/2018

BY E-MAIL

Your ref: XD5607L

Our ref: SLS1371E

WITHOUT PREJUDICE

M/S EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block, MND Complex, Tower Block MND
Singapore 069110

Dear Sir/Madam,

ACCIDENT INVOLVING : (SLS1371E & XD5607L) ALONG TPE IN BETWEEN PUNGGOL TWDS CHANGI
DOA: 03/10/2018 TIME: 0805 HOURS

We refer to the above matter and write on behalf of WHEELY CAR SERVICES, the registered owner of SLS1371E in respect of the above accident.

We are instructed that the above accident was caused by your insured's negligent driving/ or management of your insured vehicle. Your insured's vehicle XD5607L collided onto the rear portion of our client's vehicle SLS1371E. As a result of the accident, our client has been put to loss and expenses, particulars of which are as follows:-

1. Cost of repair (\$4100 + 7% GST)	\$	4,387.00
2. Loss of Rental (8 days x \$150)	\$	1,200.00
3. Buy 3rd Party's GIA Report	\$	29.00
4. LTA search	\$	7.45
5. Incidentals	\$	88.00

Total Amount: \$ 5,711.45

Enclosed are the following documents for your perusal.


- 1) Driver's driving license/ Identity card
- 2) Certificate of Insurance
- 3) GIA report
- 4) LTA Search (XD5607L)
- 5) Original repair claim
- 6) Car Rental Agreement/ Receipt (UL - 3233)

Our company is the authorized workshop of any of the GIA member companies and we are writing in purely for amicable sake.

The demand herein is in respect of our client's for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice any claim in respect of personal injuries.

Kindly acknowledge receipt of the above said documents within 7 days and your favourable reply is deeply appreciated.

Yours faithfully,


Bereza



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQJ18018168/Ujb3

25 FEBRUARY 2019

SHENG QIN TRANSPORT & CONSTRUCTION PTE LTD

421 Tagore Industrial Avenue

#04-06/07

TAGORE 8

Singapore 787805

Dear Sir/Madam,

ACCIDENT INVOLVING XD 5607L AND SLS 1371E ON 03/10/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Joy Irene

MOB: 6841 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

C.C. EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)

LETTER OF AUTHORIZATION

DATE : 3/10/2018

To : _____

RE: ACCIDENT INVOLVING VEHICLE NO. SL51371E & XD5607L

ALONG TPE In Between Punggol
Twds Changi ON 03/10/2018

I/WE Wheely Car Services of (NRIC / ROC NO.) 53316771W

OF 428 Yishun Ave 11 #07-162 S(762428)

Owner of vehicle no. SL51371E in consideration of M/S **PROGRESSIVE AUTO PTE LTD**

Repairing my / our vehicle SL51371E at my / our instruction and hereby authorize

PROGRESSIVE AUTO PTE LTD to demand claim settle receive whatever amount settled / payable by the Insurance Company and / or third party or to commence legal proceeding. If necessary, under my name, for the cost of repairs, car rental and / or loss of use, etc and to their appointing Solicitor to act for me / us in respect of the said accident / claim and all claimed and / or settled shall belong to them absolutely.

I further agree and undertake to indemnify them against the above mentioned claim cost which may arisen therewith.

Signature of Owner : _____
(Company's chop - if any)



Name of Owner : Wheely Car Services

NRIC No : 53316771W

PROGRESSIVE AUTO PTE LTD

Business Reg. No: 200712509E

GST Reg. No: 200712509E

No 1 Kaki Bukit Ave 6 AutoBay

#02-48/50 Singapore 417883

Date: 25/10/2018

WHEELY CAR SERVICES

C/O NO 1 KAKI BUKIT AVENUE 6

AUTOBAY #02-48/50

SINGAPORE 417883

MOTOR VEHICLE NO: SLS1371E HYUNDAI ELANTRA

REPAIR CLAIM

\$ 4,100.00

LUMP SUM

Sub- total \$ 4,100.00

7% GST: \$ 287.00

Total: \$ 4,387.00

SINGAPORE DOLLARS:

FOUR THOUSAND THREE HUNDRED AND EIGHTY-
SEVEN DOLLARS ONLY

TP-SLS1371E

VEHICLE RENTAL AGREEMENT

No. RA 3233

HIRER'S PARTICULARS Name: <u>Wheely Car Services</u> Address: _____ Contact Person: _____ Tel: _____		Vehicle No: <u>8LF5529E</u> Replace Veh No: _____ Mileage Out: _____ Mileage Out: _____ Make & Model: <u>Honda</u> Make & Model: _____ Auto / Manual: <u>Verel</u> Auto / Manual: _____ OUT: Date <u>4/10/2018</u> OUT: Time <u>2:15pm</u> HIRE EXPIRY <u>11/10/18</u> TIME EXPIRY <u>5:30pm</u>																												
DRIVER'S PARTICULARS Name: <u>Lim Kah Sen, Jason</u> Address: <u>439 Yishun Avenue 11 #12-416</u> <u>Singapore 760439</u> Tel No: _____ H/P No: <u>8448 2977</u> P.P. / I.C. No: <u>88603086A</u> D/L NO: _____ Date of Birth: <u>25/01/1986</u> Date of Issue / Expiry: _____ Nationality: <u>S'pore</u> Pl. Of Issue: <u>12/03/2009</u> Occupation: _____ Driving Exp: _____		RENTAL CHARGES <table border="1"> <tr> <td>Daily</td> <td><u>8 days @ \$150</u></td> <td><u>1,200.00</u></td> </tr> <tr> <td>Weekly</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Monthly</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Hours</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Others</td> <td>@ \$</td> <td></td> </tr> <tr> <td>CDW</td> <td>@ \$</td> <td></td> </tr> <tr> <td>PAI</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Delivery Service</td> <td></td> <td></td> </tr> <tr> <td colspan="2">SUB-TOTAL \$</td> <td><u>1,200.00</u></td> </tr> </table>		Daily	<u>8 days @ \$150</u>	<u>1,200.00</u>	Weekly	@ \$		Monthly	@ \$		Hours	@ \$		Others	@ \$		CDW	@ \$		PAI	@ \$		Delivery Service			SUB-TOTAL \$		<u>1,200.00</u>
Daily	<u>8 days @ \$150</u>	<u>1,200.00</u>																												
Weekly	@ \$																													
Monthly	@ \$																													
Hours	@ \$																													
Others	@ \$																													
CDW	@ \$																													
PAI	@ \$																													
Delivery Service																														
SUB-TOTAL \$		<u>1,200.00</u>																												
Refundable Deposits: _____ Cash/Net/Cheque/VISA/MC Cards No.: _____ (A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES <div style="text-align: center;"> <p>FRONT</p> <p>LEFT</p> <p>RIGHT</p> <p>REAR</p> </div>		<div style="text-align: center;"> <p>OUT</p> <p>IN</p> </div>																												
ACCESSORIES CHECK <table border="0"> <tr> <td><input type="checkbox"/> Ashtray</td> <td><input type="checkbox"/> Cig Lighter</td> <td><input type="checkbox"/> S / Tyre</td> </tr> <tr> <td><input type="checkbox"/> STD Tools</td> <td><input type="checkbox"/> Jack</td> <td><input type="checkbox"/> Hub Caps</td> </tr> <tr> <td><input type="checkbox"/> Radio / Cass</td> <td><input type="checkbox"/> CD / Cartridges</td> <td><input type="checkbox"/> S / RIM</td> </tr> </table>		<input type="checkbox"/> Ashtray	<input type="checkbox"/> Cig Lighter	<input type="checkbox"/> S / Tyre	<input type="checkbox"/> STD Tools	<input type="checkbox"/> Jack	<input type="checkbox"/> Hub Caps	<input type="checkbox"/> Radio / Cass	<input type="checkbox"/> CD / Cartridges	<input type="checkbox"/> S / RIM	EXTENSION Collection Service _____ Misc. _____ ESTIMATED TOTAL RENTAL \$ _____ Sales Person Code: _____ Hirer is responsible for the first \$ <u>3,500.00</u> excess for collision / damage to first party. (i.e) ULTIMATE CAR RENTAL Vehicles (including windscreen) and also first \$ <u>2,500.00</u> excess for collision/damage to third party's vehicles for each and every accident / damage. <u>Additional Excess today \$3,500.00</u> HIRER's Signature _____ Additional Driver's Signature _____																			
<input type="checkbox"/> Ashtray	<input type="checkbox"/> Cig Lighter	<input type="checkbox"/> S / Tyre																												
<input type="checkbox"/> STD Tools	<input type="checkbox"/> Jack	<input type="checkbox"/> Hub Caps																												
<input type="checkbox"/> Radio / Cass	<input type="checkbox"/> CD / Cartridges	<input type="checkbox"/> S / RIM																												

We agree to the terms and conditions above, overleaf and that all information given is true and correct in all respect. My/Our Driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- VEHICLES IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY ULTIMATE CAR RENTAL.
- IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER:
 - shall report all accidents involving the said vehicle to the Owner immediately
 - shall take immediate steps to complete and sign Form Mar 1 (Motor Accident Report form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is reported to the owner)
 - shall report to the police within 24 hours from the occurrence, the following types of accidents:
 - injury case;
 - non-injury case involving a Government vehicles or damage to Government property;
 - non-injury case involving a foreign vehicle (to obtain their motor insurance, policy, Passport No./Name of the driver, Vehicle number, Log card and Vehicle road tax information);
 - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE - THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" FILLING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO ULTIMATE CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	DEPOSIT REFUND
11/10/18	5:30pm				

SIGNATURE OF HIRER/DRIVER



TAX INVOICE

Our Ref No: GR-18-154257

Date of Request: 05/10/2018

Your Ref No: MBHH18128586

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6 #02-48/50
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Date of Accident: 03/10/2018

Vehicle No: SLS1371E

Place of Accident: ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI

Involving Vehicle No: XD5607L

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XD5607L	ALONG TPE IN BETWEEN PUNGGOL TOWARDS CHANGI	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-153707

Date of Request: 04/10/2018

Your Ref No: MBHH18128586

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6 #02-48/50
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 03/10/2018

Place of Accident: LONG TPE IN BETWEEN PUNGGOL TO

Client Vehicle No: SLS1371E

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 04 Oct 2018 / 13:37:07

Receipt Date/Time : 04 Oct 2018 / 13:37:07

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181004-001143

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - XD5607L				
As at 03 Oct 2018/08:05:00				
Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - XD5607L			
	Enquiry Fee	7.00	0.49	7.49
	20181004133559382863			
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20181004133611578	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/06/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	XD 5607L	(Insd Veh)	Your Ref. No. : DMCFHQ18-000111
	SLS 1371E	(TP Veh)	Our Ref. No. : CC4/EQI18018168/Ujb3q2
Date of Accident	3/10/2018		

Liability	100%	
Final Repair Cost	: \$ 4,387.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 700.00	7 days
Others:	: \$ 36.45	
	: \$	
	5,123.45	
Final Settlement Sum	: \$ 5,120.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	PROGRESSIVE AUTO PTE LTD	: \$ 5,120.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18018168/Ujb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 18-06-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5607L	Veh. Inspected	SLS 1371E	
Policy No.	DMCFHQ18-000111	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JUSTIN	Assign Date	08/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMJU542771	Colour	BLUE	
Odometer	36875	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	03/10/2018	Inspection Date	08/10/2018	
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1371E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BADLY DENTED	1,582.00	1,048.00
1	REAR BOOT LOCK	TWISTED	139.00	139.00
1	REAR BOOT LOCK CATCH	NOT NECESSARY	36.00	-
1	REAR BOOT RUBBER	TWISTED	129.00	129.00
1	REAR BOOT EMBLEM (ELANTRA)	NECESSARY	48.00	48.00
1	REAR BOOT EMBLEM (S)	NECESSARY	20.00	20.00
1	REAR BOOT CENTRE LOGO	NECESSARY	39.00	39.00
2	REAR BOOT HINGE @\$111.00	NOT NECESSARY	222.00	-
2	REAR BOOT REFLECTOR LAMP @\$331.00	CRACKED	662.00	662.00
1	REAR BOOT LOCK HANDLE SENSOR	NOT NECESSARY	180.00	-
1	REAR BOOT INNER COVER BOARD	NOT NECESSARY	189.00	-
8	REAR BOOT INNER COVER BOARD CLIPSE @\$5.50	NOT NECESSARY	44.00	-
2	REAR TAIL LAMP @\$382.00	O/S CRACKED	764.00	382.00
2	REAR TAIL LAMP CLIPSE @\$8.00	NOT NECESSARY	16.00	-
1	REAR END PANEL	DENTED	491.00	491.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	69.80	-
3	REAR END PANEL TOP GARNISH CLIPSE @\$5.50	NOT NECESSARY	16.50	-
1	REAR SPARE TYRE COVER BOARD	NOT NECESSARY	311.00	-
1	REAR BUMPER	DENTED	459.50	459.50
1	REAR BUMPER REINFORCEMENT	BENT	329.50	329.50
2	REAR BUMPER SIDE RETAINER @\$41.00	NECESSARY	82.00	82.00
1	REAR BUMPER LOWER PAD	DEFORMED / WARPED	280.10	280.10
10	REAR BUMPER CLIPSE @\$5.50	NECESSARY	55.00	55.00
2	REAR NUMBER PLATE LAMP @\$28.00	NOT NECESSARY	56.00	-
	LESS 20% DISCOUNT		-1,244.08	-832.82
			4,976.32	3,331.28
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00

Report Ref No. CC4/EQI18018168/Ujb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
			350.00	240.00
	LABOUR			
	PANEL BEATING.		1,200.00	600.00
	CHECK WIRING.		80.00	20.00
	RUST PROOFING.		80.00	60.00
	TO REMOVE & REPLACE BUMPER SENSOR .		80.00	50.00
	SPRAY PAINTING.		950.00	850.00
			2,390.00	1,580.00
GRAND TOTAL			7,716.32	5,151.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CC4/EQ118018168/Ujb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.