

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

Not Advised
L/S # 4100
H. J.
Whight. After 10/18

M/S : EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

TEL: 6223 9433 FAX: 6224 3903
ATTN: Motor Claim Department
Your Ref No: SLS1371E
Claim Type: Third Party
Accident Date: 03-10-2018
TP Veh Reg No: XD5607L

Estimate No: EST0000716
Date: 06 Oct 2018
Policy No: DMPPHQ18-006169
Veh Reg No: SLS1371E
Make/Model: HYUNDAI ELANTRA
Chassis No: KMHD841CMJU542771
Engine No: G4FGHU778554
Reg. Date: 09-09-2017

Estimate Repair Cost For Vehicle No :SLS1371E

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
SLS1371E HYUNDAI ELANTRA				
List Price				
1 Rear Boot Lock 1048	1582.000	1 PC	1582.00	
2 Rear Boot Lock	139.0000	1 PC	139.00	
3 Rear Boot Lock Catch	36.0000	1 PC	36.00	
4 Rear Boot Rubber	129.0000	1 PC	129.00	
5 Rear Boot Emblem (Elantra)	48.0000	1 PC	48.00	
6 Rear Boot Emblem (S)	20.0000	1 PC	20.00	
7 Rear Boot Centre Logo	39.0000	1 PC	39.00	
8 Rear Boot Hinge	111.0000	2 PC	222.00	
9 Rear Boot Reflector Lamp	331.0000	2 PC	662.00	
10 Rear Boot Lock Handle Sensor	180.0000	1 PC	180.00	
11 Rear Boot Inner Cover Board	189.0000	1 PC	189.00	
12 Rear Boot Inner Cover Board Clipse	5.5000	8 PC	44.00	
13 Rear Tail Lamp	382.0000	2 PC	764.00	
14 Rear Tail Lamp Clipse	8.0000	2 PC	16.00	
15 Rear End Panel	491.0000	1 PC	491.00	
16 Rear End Panel Top Garnish	69.8000	1 PC	69.80	
17 Rear End Panel Top Garnish Clipse	5.5000	3 PC	16.50	
18 Rear Spare Tyre Cover Board	311.0000	1 PC	311.00	
19 Rear Bumper	459.5000	1 PC	459.50	
20 Rear Bumper Reinforcement	329.5000	1 PC	329.50	
21 Rear Bumper Side Retainer	41.0000	2 PC	82.00	
22 Rear Bumper Lower Pad	280.1000	1 PC	280.10	
23 Rear Bumper Clipse	5.5000	10 PC	55.00	
24 Rear Number Plate Lamp	28.0000	2 PC	56.00	
			6,220.40	
Less 20%			1,244.08	4,976.32
Special Net				
25 Rear Number Plate	50.0000	1 PC	50.00	
26 Rear Bumper Sensor	300.0000	1 PC	300.00	
			350.00	350.00

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

TEL: 6223 9433 FAX: 6224 3903
ATTN: Motor Claim Department
Your Ref No: SLS1371E
Claim Type: Third Party
Accident Date: 03-10-2018
TP Veh Reg No: XD5607L

Estimate No: EST0000716
Date: 06 Oct 2018
Policy No: DMPPHQ18-006169
Veh Reg No: SLS1371E
Make/Model: HYUNDAI ELANTRA
Chassis No: KMHD841CMJU542771
Engine No: G4FGHU778554
Reg. Date: 09-09-2017

Estimate Repair Cost For Vehicle No :SLS1371E

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
27 Panel Beating	1,200.000	1 PC	1,200.00	600
28 Check Wiring	80.0000	1 PC	80.00	20
29 Rust Proofing	80.0000	1 PC	80.00	60
30 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
31 Spray Painting	950.0000	1 PC	950.00	850
			2,390.00	2,390.00
			Total	S\$ 7,716.32

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SIXTEEN AND CENTS THIRTY TWO ONLY

For PROGRESSIVE AUTO PTE LTD

Progressive Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

Tel: 68444620 Fax: 68444625

AUTHORISED SIGNATURE

5197.4

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: