

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1155/2018/PH
Date : 10-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. SLJ 6533 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Michael Chong @ Chong Chuan Wen
Address : BLK 778 Bedok Reservoir Road
#15-24
Singapore 479254
Telephone : (HP) 97762981
Type of Claim : Third Party Claims
Policy No. : 1700059602-01
Vehicle No : **SLR 9942 K**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Sep-17
Engine No : CVK 043104
Chassis No : WAUZZZF51JA022067
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Oct-18
Place of Accident : Along PIE after Kallang Bahru exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9942 K .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor.Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper.Re-organize rear crash management components.Reinstall all parts removed.	\$ 1,050.00 500.	
3	To respray rear bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9942 K .

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>Bye</i>	\$ 2,190.00	+
2	REAR BUMPER FIXING PARTS <i>3 new</i>	\$ 142.00	+
3	REAR BUMPER SECURING STRIP	\$ 191.00	+
4	REAR BUMPER TRIM CHROME <i>cond</i>	\$ 878.00	✓
5	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 70.00	+
6	REAR BUMPER CARRIER <i>2 new</i>	\$ 786.00	+
7	REAR SENSOR	2 \$ 421.00	+
8	REAR SENSOR SEAL RING	4 \$ 14.00	+
9	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES - FRONT		\$ 4,992.00	
TOTAL LABOUR CHARGES - FRONT		\$ 2,502.00	
GRAND TOTAL		\$ 7,494.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 12/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : the authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant