

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 10/10/2018

Reference: SLM1989E
OPEL ASTRA
Make: HB 1.4 AT

To Whom It May Concern

Dear Sir,

TP Lon Pac.
Xiao Tony

RE: VEHICLE :SLM1989E
CHASSIS NO.:W0LB6EC2HG018341
ENGINE NO.:B1162547GSGX0306

Name of insured :Yee Ziliang Sidney
Date of accident.: 06/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Front Bumper	\$ 1,660.00
2	1	Front Radiator Grille Moulding, Base	\$ 458.00
3	1	Front Radiator Grille Chrome Moulding - RH	\$ 218.00
4	1	Front Radiator Grille Chrome Moulding - LH	\$ 218.00
5	1	Front Opel Emblem	\$ 100.00
6	1	Front Bumper Lower Grille	\$ 144.00
7	2	Front Bumper Forward Sensor	\$ 220.00
8	1	LHF Headlamp	\$ 1,160.00
9	1	LHF Foglamp Cover	\$ 75.00
10	1	LHF Foglamp	\$ 434.00
11	1	Front Bumper Absorber	\$ 154.00
12	1	Front Bumper Reinforcement Bar	\$ 798.00
13	1	LHF Bumper Bracket - Guide	\$ 65.00
14	1	LHF Fender	\$ 568.00
15	1	LHF Fender Liner	\$ 145.00

2820
2538

Parts Total: \$ 6,417.00
Less 10%: \$ 641.70
Total : \$ 5,775.30

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 1,950.00	650
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 1,650.00	550
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 65.00	30
4	S.R.S. Reset of system	\$ 325.00	x
5	To refocus headlamp	\$ 130.00	+
6	To remove and refit front sensor	\$ 130.00	80

1310

Labour Total : \$ 4,250.00

Others

Other Description

No.	Qty		Price (SGD)
<u>Front portion</u>			
1	10	Front bumper clip <i>new</i>	\$ 65.00
2	10	Front radiator grille clip <i>new new</i>	\$ 65.00
3	3	Front fender liner clip <i>new new</i>	\$ 19.50

30

Other Total: \$ 149.50

GRAND TOTAL: \$ 10,174.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

 Suhaimi O.

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

Adrian Lim,
P/P 12/10/18.

03 Apr.

total: 3878

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>
--