



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Adrian LKK

- ALG

Wau2224L69D028832

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 04/10/2018

Estimated repair cost for vehicle no: SLC9496K AUDI Q7 3.6 A '09

CHASSIS: WAUZZZ4L69D028832

05/10/2018

78 ALG.
Xiao Tong

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$4,292.65 <i>x</i>
2	2	Rear Boot Lid Hinge <i>3.6</i>	\$115.05	\$230.10 <i>x</i>
3	2	Rear Boot Lid Shock Absorber <i>Steel</i>	\$87.35	\$174.70 <i>x</i>
4	1	Rear Boot Lid Emblem Logo <i>2</i>		\$93.65 <i>✓</i>
5	1	Rear Boot Lid Q7 Logo <i>new</i>		\$72.30 <i>✓</i>
6	1	Rear Boot Lid 3.6 Logo		\$72.30 <i>✓</i>
7	1	Rear Boot Lid Quattro Logo		\$72.30 <i>✓</i>
8	1	Rear Boot Lid Inner Lock		\$160.00 <i>+</i>
9	1	Rear Boot Lid Inner Rubber		\$145.85 <i>+</i>
10	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$1,261.00 <i>+</i>
11	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$100.00 <i>+</i>
12	1	Rear Boot Lid Windscreen Moulding		\$155.00 <i>x</i>
13	1	Rear Bumper <i>Defend</i>		\$2,250.85 <i>✓</i>
14	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>20</i>
15	2	Rear Bumper Side Retainer <i>new</i>	\$45.10	\$90.20 <i>✓</i>
16	2	Rear Bumper Side Reflector <i>LH covered, RH cut</i>	\$269.90	\$539.80 <i>✓</i>
17	1	Rear Bumper Lower <i>3.6</i>		\$791.00 <i>✓</i>
18	1	Rear Bumper Lower Cover <i>Defend</i>		\$353.85 <i>✓</i>
19	4	Rear Bumper Reverse Sensor <i>2 pieces damaged</i>	\$194.75	\$779.00 <i>388.50</i>
20	4	Rear Bumper Reverse Sensor Holder Seal Rubber <i>new</i>	\$6.50	\$26.00 <i>+</i>
21	1	Rear Bumper Centre Guide <i>covered</i>		\$285.00 <i>✓</i>
22	1	Rear Bumper Reinforcement <i>Bent</i>		\$993.55 <i>✓</i>
23	1	Rear End Panel Assy <i>Repair</i>		\$974.30 <i>+</i>
24	1	Rear End Panel Top Garnish <i>3.6</i>		\$314.45 <i>+</i>
25	1	Rear End Panel Lock Sensor <i>new</i>		\$164.75 <i>+</i>
26	1	Rear End Panel Buzzer Sensor Switch <i>new</i>		\$125.25 <i>+</i>
27	1	Rear Exhaust <i>Repair</i>		\$2,791.55 <i>+</i>
28	1	Rear Centre Exhaust <i>new</i>		\$1,433.15 <i>+</i>
29	1	Rear Exhaust Chrome Pipe <i>3.6</i>	\$348.55	\$348.55 <i>+</i>
30	1	Rear Exhaust Aluminium Cover <i>new</i>		\$462.55 <i>+</i>
31	4	Rear Exhaust Mounting	\$84.05	\$336.20 <i>+</i>

6034-30
5132-58

Subtotal :- \$19,688.80

Labour charges

To remove & refit rear windscreen	\$150.00 X
Gum	\$50.00 X
To remove & refit boot lid auto lock motor	\$280.00 X
To remove & refit reverse sensor	\$100.00 60
To remove & refit cushion & trim board	\$380.00 X
To remove & refit rear & centre exhaust	\$380.00 100
To check wiring	\$100.00 30
Tuff kote	\$150.00 X
Towing fee	\$100.00 X
Panel beating	\$2,000.00 650
Spray painting	\$1,800.00 800

Subtotal :- \$5,490.00

Total:- \$25,178.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 7372.58
L/S: S.G.K.
04 Days.
S.G.K.
ospy.